

UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

PRC

AUG 3 1984

Docket Nos.: 50-445

and 50-446

MEMORANDUM FOR:

The Atomic Safety and Licensing Board

for Comanche Peak, Units 1 and 2 (P. Bloch, W. Jordan, K. McCollom)

FROM:

Darrell G. Eisenhut, Director

Division of Licensing

SUBJECT:

BOARD NOTIFICATION: ALLEGATIONS RELATING TO IMPROPER CONSTRUCTION PRACTICES ON COMANCHE PEAK 4IN CONDENSERS

(BOARD NOTIFICATION NO. 84-124)

This Notification is provided in accordance with NRC procedures regarding Board Notifications.

The enclosed letter to Texas Utilities Electric Company dated June 19, 1984, transmitted a portion of a transcribed interview with the alleger and requested an assessment of the extent that the Texas Utilities' quality control program was implemented during condenser unit fabrication and installation, a summary of the test results that will reflect existing leak rates, and an evaluation of the impact of any expected condenser tube leakage on the ability to maintain satisfactory steam generator secondary side water chemistry.

Texas Utilities responded to the above request in a letter dated July 9, 1984, also enclosed. The staff is currently evaluating that response. The ASLB will be kept advised.

The parties to the proceeding are being informed by copy of this memorandum.

Darrent Gl Ersenmut, Director

Division of Licensing

Enclosures: As stated

cc: ACRS (10)

Parties to the Proceeding

See next page

8408070455

N005

DISTRIBUTION LIST FOR BOARD NOTIFICATION

Comanche Peak Units 1&2 Docket Nos. 50-445/446

Peter B. Bloch, Esq. Mr. John T. Collins Mr. James E. Cummins Mrs. Juanita Ellis Billie Pirner Garde Ellen Ginsberg, Esq.

Renea Hicks, Esq.
Dr. W. Reed Johnson
Dr. Walter H. Jordan
Dr. Kenneth A. McCollom
Thomas S. Moore, Esq.
Nicholas S. Reynolds, Esq.

Alan S. Rosenthal, Esq. Mr. Lanny Alan Sinkin Mr. Michael D. Spence Robert A. Wooldridge, Esq.

Atomic Safety and Licensing Board Panel Atomic Safety and Licensing Appeal Panel Docketing and Service Section Document Management Branch

Mr. Homer C. Schmidt
Mr. H. R. Rock
Mr. A. T. Parker
William A. Burchette, Esq.
Mr. David R. Pigott, Esq.
Mrs. Nancy H. Williams

ACRS Members

Dr. Robert C. Axtmann Mr. Myer Bender Dr. Max W. Carbon Mr. Jesse C. Ebersole Mr. Harold Etherington Dr. William Kerr Dr. Harold W. Lewis Dr. J. Carson Mark Mr. William M. Mathis Dr. Dade W. Moeller Dr. David Okrent Dr. Milton S. Plesset Mr. Jeremiah J. Ray Dr. Paul C. Shewmon Dr. Chester P. Siess Mr. David A. Ward

6-19-84

In Reply Refer To: Dockets: 50-445 50-446

Texas Utilities Electric Company ATTN: M. D. Spence, President, TUGCO Skyway Tower 400 North Olive Street Lock Box 81 Dalias, Texas 75201

Gentlemen:

The attached enclosures are matters relating to alleged improper construction practices involving the Comanche Peak Steam Electric Scation main condensers (Units 1 and 2) expressed by an alleger during an interview conducted on August 24, 1983 by members of the NRC Office of Investigation Field Office, Region IV. Although the condenser units are components within the BOP classification, the allegations expressed raise concern as to the quality of workmanship that could impact on reactor safety.

You are requested to provide this office in writing within 20 days, your assessment of the extent that your quality control program was previously implemented during condenser unit fabrication and installation; a summary of test results that will reflect existing leak rates; and an evaluation of the impact of any expected condenser tube leakage on your ability to maintain satisfactory steam generator secondary side water chemistry.

The response directed by this letter is not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Sincerely,

R. L. Bangart, Director
Region IV Comanche Peak Task Force

Enclosures:
Alleger's Recorded Statements:
1. Pages 22 through 28
2. Pages 38 through 51, including
Exhibits 1, 2, 3, 4, 5A, 5B,
and 6

See page 2

5407090148 PDR

cc:
Texas Utilities Electric Company
ATTN: B. R. Clements, Vice
President, Nuclear
Skyway Tower
400 North Olive Street
Lock Box 81
Dallas, Texas 75201

bcc to DMB (IEO1)

bcc distrib. by RIV: RPB1 RPB2 RRI-OPS RRI-CONST. D. Hunnicutt J.T. Collins, RA R. F. Denise, DRSP RIV File R. L. Bangart, D/TF S. Treby, ELD T. Westerman, EO Juanita Ellis, CASE Renea Hicks, EP Billie Pirner Garde, GAP Texas State Dept. Health R. Herr, OI W. Brown, RC 7. Spepolits

Texas Utilities Electric Company ATTN: H. C. Schmidt, Manager Nuclear Services Skyway Tower 400 North Olive Street Lock Box 81 Dallas, Texas 75201 know now far you want to get into this, you know, as a fine line. Are you talking about extremely bad. Like the concensers, for instance, we took air nammers and sledge hammers and beat tubes. That is a no-no. Anybody would know that. You take a copper-nickle tube about as thick as your wedding band and you take a 16 pound sledge hammer and drive them. We put ice on to shrink them and put them in the condenser. That is a no-no. You are supposed to ease them in with our hand so they can expand.

MR. GRIFFIN: Was that particular instance in your testimony or in your affidavit?

No.

MR. GRIFFIN: That is new?

No, it is all new. We split tubes, belling the tubes and flaring them. We split tube sheets. I reported a tube sheet split to westinghouse. They said on, my God, you know, yeah, yeah, yeah, and all this stuff. The next day we had a meeting and we all went there and there must have been 45 or 50 people.

MR. GRIFFIN: When was this?

This was a couple of years

ago.

MR. GRIFFIN: Where are these tube sheets?

They are in the condensers.

TAYLOE ASSOCIATES
1625 | STREET, N.W. - SUITE 1004
WASHINGTON, D.C. 20006
(202) 293-2950

. .

3 4

5

6

-

8

10

11

12

13

14

15

16

18

19

20

21

22 23

24

westninghouse, and they go that is not a westinghouse problem. What problem? See, the day before they had a problem that a tube sheet was cracked. Then all at once they don't have no more problem because they called their home office and they probably said you idiots, don't tell them. So they said the only problem we have is the tubes are not rolled up tight enough. I said, we are cracking the tube sheets already and they are rolled at a minimum and not a maximum. I said we would be in trouble if we had to roll them to the max, or if we had to roll them over the max, superroll them.

. !

(At this point in the proceedings is referring to Exhibit 1.)

Here is your water boxes right here and your condensers. All right, in condenser A on the inlet end on the west box and it is in three sections. You have got some cracked tube sheets in here. Back there you have got some cracked tube sheets. You have got overrolled tubes or barely overrolled. They are supposed to be rolled 069 thousand is a perfect roll inside reading. They allow us to go to 071 thousand. We went up 90-some thousands.

expander run out. Manually ne rolled it so tight the expander and motor jumped off. They just pop them just

TAYLOE ASSOCIATES
1625 | STREET, N.W. - SUITE 1004
WASHINGTON. D.C. 20066
(202, 293-3950

It is the wrong type of condenser for the wrong type steam generator to start off with. It was a \$10 million good-up. Westinghouse said wait a minute, I think we can straight this problem out since it is air condensers, which they went bankrupt and are no more in the condenser business. They decided they had to intergroove a tube sheet. They took an inch and a quarter tube sheet and they cut it in half. They should have used two tube sheets if they were going to do that and made it twice as strong and not half.

MR. GRIFFIN: Are these things still there?

: They are still there, yes. All
you got to do is go in there. It is really terrible. What
I would suggest doing is on the big ones like 90-some
thousand is cutting the tube out and look at your sheet.
There is a spider wed crack. I showed the people the
crack, and that is when I first starting getting the
pressure, this is about three years ago, after I reported
this stuff. I kept on insisting on this crack, and then
everybody would go oop, and the people in the pressure, it is a pour three years ago, after I reported
this stuff. I kept on insisting on this crack, and then
everybody would go oop, and the people it would
go I am not. You know, you can throw a cat through it, and
the goes no, no, no.

Well, undoubted TUGCO told nim to back off.

TAYLOE ASSOCIATES
1625 I STREET, N.W. - SUITE 1004
WASHINGTON D.C. 20001

. 4

..

11.

4 5

millions of collars. So they are talking about time and they won't want nothing to stop this plant.

should be twice as many support sheets in there and all that stuff. So they intergrooved the tube sheet and they still have got leaks over there on this section here and we are not supposed to have no leaks at all.

MR. HERR: She can't see "right there" -(Indicating the reporter). So when you say section one,
identify what you are pointing to.

okay. Condenser B, Unit 1, west discharge water box and you have got a cracked tube sneet. Also, the tubes are overrolled severely.

on the east water box, condenser B, discharge end, you are heavily overrolled and you undoubtedly have got quite a few cracks in it. I can swear to that. I know you do because it swelled up so big.

Overroll on the west box, condenser A, Unit 1, discharge end.

East water box, discharge end, condenser A, you are still leaking, and overrolled.

The more you roll, the more they leak. They more they leak, the more you roll, and the more your roll, the more damage you are doing. They just went nuts with

TAYLOE ASSOCIATES
1625 | STREET N.W. - SUITE 1004
WASHINGTON, D.C. 20006
(202, 293-3950

12.

You have got cracked tube sneets.


It is very simple to check because I put little plugs in there. You can just take a wrench and just screw your two nuts loose and pull the plug out and look at it and put it right back in. It wouldn't take five minutes to look.

follows.)

2 . .

22 23

TAYLOE ASSOCIATES
1625 | STREET N.W. - SUITE 1004
WASHINGTON D.C. 20006
(202, 293-3950



MR. GRIFFIN: .. did anymody intimidate you into overrolling those things?

-

TUGCO saying get it a little more, get it a little more to my people. I went and told . I said they are killing that water box. Nobody had ever did the tube work before and nobody knew. They are experimenting with an item.

In the first place, the condenser wasn't a very good designed condenser, in my opinion. I have worked on them since I was 15 years old. These was I would say between 1 and 10 about a 6, you know, a so-so condenser. When they intergrooved their sheet, they made the sheet real, real thin.

MR. GRIFFIN: But did anybody tell you or instruct you to do that?

leaks, for instance. I was rolling tubes and I was stopping the water box from leaking. I have got a water box over here leaking and it is still leaking. I go tell says how does that box look, and I said it looks good but the other one started leaking again, and I have got to get it. He goes goddamn, I can go there any day and make things better than they are. I don't want you to do that. I go I am just trying to stop the leaks, you know. You ain't supposed to have leaks.

TAYLOE ASSOCIATES

- 1625 I STREET, N.W. - SUITE 1004
WASHINGTON, D.C. 20006
,202, 293-3950

Your river water leaks into, you know, that type steam generator and you can't allow no river water inside, lake wat . So it is still leaking. My problem was I of course coulan't do a good job. MR. GRIFFIN: You are saying it is still 5 leaking today or it was still leaking when you left? 6 : It was still leaking when I left and it is still leaking today because they didn't 8 9 rework it. MR. HERR: Who was the engineer? 10 11 MR. HERR: Let me get one thing straight. 12 Excuse me for a second. 13 they your supervisors? 14 15 16 supervisor. MR. HERR: What was his title? 17 : He was the 18 19 MR. HERR: Who was the other guy, what 20 was his job title? 21 : He was a three striper. I 23

1

3

4

24

25

don't know where he come from. He don't know anything. He three striper. is supposd to be a

MR. HERR: What is a three striper?

TAYLOE ASSOCIATES 1625 | STREET, N.W. - SUITE 1004 WASHINGTON, D.C. 20006 (201, 293-3950

:. \$ w ?

nn

setting the condensers. The ECP inspector come down and checked the welds on it, he rejected all the welds. We had a rig hooked up. He even rejected the factor welds.

The said have you got a condenser in that hole yet? I go no, I said it don't look like we are going to do it either because a BOP inspector just turned down all the welds. Boy he started cussing, he said I want that son of a bitch's name and badge number.

So he started making calls. So I dropped back to the guy and ne just bought it off sitting in his office. Well, as a matter of fact, it got to a point where they wouldn't even come and look at none of the welds. They would just buy them off.

MR. GRIPFIN: Who is this guy again that bought toff?

still out there. I think it the last name.

MR. GRIFFIN:

I think he ended up in QC. I think he name was

MR. HERR: What year was that?

This was probably '79 or '80

when we was setting Unit 2 condensers. Condenser A was

TAYLOE ASSOCIATES
1825 | STREET, NW. - SUITE 1004
WASHINGTON, D.C. 20006

going and the house, the autier part.

MF. GRIFFINE This is more mon-1 work?

: hon-Q, yes.

MR. GRIFFIN: this is before he was a OC inspector?

Yes. He was a BOP inspector.

MR. HERR: BOP?

Right.

MR. GRIFFIN: What is BOP? I don't know what

that is.

3

4

3

6

10

11

12

13

14

15

16

17

19

20

21

20

23

24

: I con't know either.

condensers here are non-Q; but they are Q at other plants?

They are Q in South Texas. It is according if they want to make them Q or not. They are safety related because you can't operate the plant without the condenser. It is just that simple. For instance, that is the reason you have got the intergroove in the tube sheet because you cannot allow the water in the steam generator because they got problems, you know. I don't know now fast they can cool a reactor down if something did happen to the condensers, like if tube sheets bust out with water pressure or something.

I was going to show you how they weaken a tube sneet, but I don't guess that is necessary.

TAYLOE ASSOCIATES
1625 | STREET, N.W. - SUITE 1004
WASHINGTON D.C. 20006
(202 292-2950

Mr. Chiffing 1 trans car people will

understand it.

1-

nice thick tupe sheet to start off.

notebook.)

This is a real good example. These tube support sheets came in. We laid them on top of each other and we put dowel pins in them. Some of the noies was three-eighths of an inch off from the others, you know.

are going to have a problem here. These holes are way off. well, he calls Westinghouse, and Westinghouse says oh, there is nothing to it. Says, they are just three-eighths of an inch off. I said well, you have got three foot from the center of one sheet to the other, and when you start off with three-eighths of an inch off you are off quite a ways when you get to the other end, you know, the three foot.

If you go three-eighths of an inch off, over here you might be an inch and a half off, and by the time you turn it back in then automatically you are going to head the other way. So you are binding every sheet. You are cutting into the tubes.

These tube support sheets are made with a

TAYLOE ASSOCIATES
1625 I STREET, N.W. - SUITE 1034
WASHINGTON D.C. 20006
1202, 293-3950

oficature endant of creatence so that they con with the side without cincing. They are out in two ners. MR. GRIFFIN: Now what system is this? R: This is Unit 1 and Unit 2 A and b condensers, the main condensers. This is what I am talking about. I am not talking nothing about the 5 Auxiliary condenser. Everything is the main condensers. 6 There is supposed to be something like 39 thousand 7 clearance in the tube support sheets so that your tubes 8 can expand in its track without binding. Now your main 9 tube sneet is lù thousand before they roll these. 10 Exhibit 2, the document just 11 12 referred to, follows:) 13 14 15 16 1: 18 19 20 21

2

3


4

23

24

25

TAYLOE ASSOCIATES 1625 | STREET NW. - SLITE 1004 WASHINGTON D.C. 20006 (202: 293-3950



particular problem in your previous afficients?

-

anybody because it seemed like when you bring up a problem it is covered up. In my opinion, it is not corrected at all. That is the reason I wanted to bring it out and I would like to snow people. They stuff here coulon't have been covered up except by paperwork because you can go down there any day of the week and read the inside diameter of your tube and you know you are overrolled.

Everything that I could actually put my finger on, like the letter, they automatically agree, just like the light poles, you know. That is a 15 cent item I the light poles, you know. That is a 15 cent item I brought up. Well, they jumped on that with both hands and brought up. Well, they jumped on that with both hands and both feet and made a big deal out of it. They really cleaned that up.

well, you have got some spray pipes also down in there. Well, it is going to be a bigger job to cut them loose to do it. They haven't even mentioned that, see. I think I mentioned that one in my affidavit. That goes in the fuel pools. You have got four spray pipes that go down in there. The holes of it was undersized and the pipe in there. The holes of it was undersized and they used department went in there and redrilled them and they used cutting material, lube oil or some type of cutting oil and they just pulled it off and there it was.

TAYLOE ASSOCIATES
1625 | STREET, N.W. - SUITE 1004
WASHINGTON D.C 20006
[202: 293-3950

: No, they haven't, and they propebly won't until you tell them about it.

MR. GRIFFIN: But you have already provided that in your afficavit?

I think so.

: About the light poles?

: No, this is some more. The light poles, they could take those out like so.

: I think the light poles are all that you talked about I believe. I don't recall the other.

: See, one day I want to set down and just make a whole book of it, you know. But I have always been so busy and I don't have the education and I can't do it, you know.

: There was an investigation done by the NRC Region IV Office about the things that were in a newspaper article that were done.

MR. HERR: Excuse me, was that an investigation or an inspection?

It was an inspection I pelieve. I don't think it was done by the investigators.

MR. HERR: Thank you.

: This is one of the things that

TAYLOE ASSOCIATES 1625 1 STREET, N.W. - SUITE 1004 WASHINGTON, D.C. 20006 (202: 293-3950

3

4 5

6

*

8

9

10

11

12

13

14

15

16 17

18

19

20 21

20

23

24

-

They are 1/32nd flush, the tubes, and they are flared. If they are sticking out, you get a build-up between your tubes. So when we flared these we busted a lit of tubes, or quite a few of them as a matter of fact.

Now this chart, and it sticks out, but we cut them down like a half inch so it would look half way decent. But when we was flaring these tubes they was busting pretty bad, and the reason they was busted so bad in this one area is because the counterbore in your tube sheet where it allows the flare to flare out was way overboard. So in order for us to flare it tight enough we busted a tube, and the ones that didn't bust we hadn't flared it tight enough. When you don't flare them tight enough you get a build-up between your sheet and your tubes and it eats the tube off.

Just like the job in North Carolina, we had holes in all the tubes before we ever got the fuel in there. The first two weeks it was eat up. So instead of us repairing it, we had several months before the fuel came in, they went areas and poxied it in and used it as is and

TAYLOE ASSOCIATES
1625 | STREET, N.W. - SUITE 1004
WASHINGTON D.C. 20006
(202 293-3950

dumped truckloads of sawdust in the intakes in trying to stop the tubes from leaking. Now the radiation level is so high on the turbine deck that you have to be dressed out just like you are going in the reactor. They should shut it down an retube it.

referred to, follows:)

*

1:

TAYLOE ASSOCIATES
1625 | STREET, NW. - SUITI 1004
WASHINGTON, D.C. 20006
(202) 293-3950

The state of the s WIND WIND Dshchonge

p.s. mible where is there

: We have got cracks here on

these flares.

MR. HERR: What is the location of the plant?

: The flare is the intake end of

all condensers and your water boxes.

MR. HERR: Is this in Glen Rose?

Yes, Glen Rose, Texas at

Comanche Peak. Most of them is in condenser A on the inlet end east water box midale way of the sheet.

Exhibit 4 follows:)

TAYLO

TAYLOE ASSOCIATES 1625 1 STREET, N.W. - SUITE 1004 WASHINGTON, D.C. 20006 (202: 293-3990

3

4

5

6

:

8

9

,

10

11

12

13

14

15

16

17

18


19


20

21

22

24





coupensor

MA. GRIFFI': . I think we have get endage on that where our people can probably go out and look at these.

consenser to the turbine. Again, I nate to bring up experience, but when you are bringing this condenser up, you set the condenser low, but when you set the turbine in they can set it on the right elevation and not be in the way of the condenser.

when you get your turbine perfect within so many thousandths, you bring your condenser up to meet. You don't make a contact with your turbine. You come up like a quarter of an inch or an eighth of an inch with your expansion joints. You have an expansion joint in between it. Then you tie them together.

Well, the condenser was so neavy when you load it with tubes and everything. It propably weighs 600 tons. Well, we took all our jacks and put them on one end so we had to rack it up. Of course, when you jack at one end it throws it way in and then you pick the other side up and it throws it way in.

So I told this general foreman, and I was just foreman then, but I told the other foreman don't tie anything to the turbine to the condenser. I said we are going to go up and it is going to fall down, but when we

TAYLOE ASSOCIATES
1625 | STREET, N.W. - SUITE 1004
WASHINGTON D.C. 20006
(202, 293-3950

\$

8 9

will keep working it until we bring it up.


well, this general foreman, he gets there and he starts welding all kind of stuff to hold it to keep from coming past it. Well, what we did was we jacked the turbine over. We went ahead and got it up. Well, instead of them making a final check to see whether they was in line or not, they just assumed they were and they was three-eighths of an inch off. So we welced it all together.

They took a reading and they was three-eighths of an inch off alignment. So they went up here and they took jacks and they started jacking and, boy, jacked it all the way over to where they want it and they release it, that little old expansion joint, and pulled it back. The little expansion joint was a one loop and it was an eighth of an inch thick and it had one little fillet weld on each side of it, real weak. They put several, several tons on it. I will show you what it looked like.

Exhibit 5A and 5B follows:)

1"

TAYLOE ASSOCIATES
1625 | STREET NW - SUITE 1004
WASHINGTON D.C. 20006
(202 293-3950



no.

MR. GRIFFIN: Your crew was down there putting this turbine on top of this condenser?

: Right.

that little expansion joint out.

Right, it is non-Q. We are down here throwing that turbine back. They started having us jack it. We jacked it up and down putting all kind of stress on it, and well sideways. You know, you can tear

MR. GRIFFIN: Is this a non-O area also?

foreman over the turbine that I weren't going to jack it no more without them giving me written permission to do it or telling me to do it in writing because I says I might want to work another job somewheres, and I said I will never work for Brown and Root again if we rip it out, but I might want to work another construction job, you know. So finally they quit jacking it then.

Also, as we jacked the condenser up, the pipe department was tied in with our pipe. They was also supposed to take a pipe up with us, which they didn't do, and we put a lot of stress on the pipe.

TAYLOE ASSOCIATES
1828 | STREET, N.W. - SUITE 1004
WASHINGTON, D.C. 20006
:202: 293-3950

4 5

Inis right here is just showing ib of the noie, the OD of the tute and OD of the tube and what it is supposed to be like after we get through rolling it to be 3 4 a periect roll. 5 MR. GRIFFIN: The condenser tubes? 6 : Right, on the condenser. This is the minimum we are supposed to roll them, the ID ô reading. . 9 MR. GRIFFIN: Can we have this also so we can 10 give it to the inspectors? 11 : Yes. 12 MR. GRIFFIN: we would appreciate that because if these guys can go right to the stuff and look at it, it 13 14 will sure be nelpful. 15 16 17 18

Exhibit 6 follows:)

21 22

19

20

23

24

25

TAYLOF ASSOCIATES 1615 | STAFET NW. - SUITE 1004 WASHINGTON, D.S. 20006 (202. 293-3950

The Kolled we were soing for the Stars that the Stars that the soil was soil that the soil that the soil IO AFTER ROLLES Tube 1.125 1.033 Tabe de Di Di

We were Aloud 3 to 7 World Reduction

War Man MAX

1068 TO 1.071

A ANO B

ANO B

Whit # 7

LANIELL NO.

(The reporter noticed a drawing on the back sice of Exhibit 5 and propent it to ! attention.) : (Referring to Exhibit 52)Oh, this is the expansion joint I was talking about with the figlet welds. It is a real small stainless steel 1/bth expansion joint and it has got two small, little fillet welds there. MR. GRIFFIN: Okay. I think we have got that down in the testimony. : We put several, several, I think two or three hundred tons against it. Okay, stainless steel liners. This is like the reactor building and the fuel building. We are supposed to have a gap in here on our fit-ups. This is not in there. MR. GRIFFIN: This is something new? 16 : Yes. 18 MR. GRIFFIN: Okay. We are supposed to have a cap 19 in here no less than 3/16ths and no more than 3/8ths. 20 MR. HERR: Where is it? For the record, 21 20 describe what it is. : This is a stainless steel 23

1

3

4

5

6

7

Ö

9

10

11

12

13

14

15

17

24

25

TAYLOE ASSOCIATES 1625 | STREET, N.W. - SUITE 1004 WASHINGTON, D.C. 20006 (202 293-3950

liner. This is an embed floor plate to angle on the pottom

and side plate to angle. I don't know exactly where, but