	EXHIBIT A
	CONTROL BLOCK: _ _ _ _ _ _ _ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
7 1 1 8	1 A R A N O 2 12 1 O O - O O O O O O O
1 1 0 1 1 1 8	SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
10121	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During Hode 1 operation, the control room emergency air conditioner compressor, 2VE-1A, tripped while being
1 6 1 3 1	Jused to provide cooling to the Core Protection Calculator (CPC) room. Cooling was being temporarily provided
10141	Idue to CPC room cooler being out of service. The redundant Emergency Air Conditioning system was verified
10151	loperable. There had been no similar occurrences. Reportable per Technical Specification 6.1.9.1.b.
10161	
10171	
10181	
10191	SYSTEM
, ,	SEQUENTIAL OCCURRENCE PEDDAT DEVICION
17	REPORT 1 8 0 11 1 0 2 6 1 / 1 1 0 3 1 x 1 11 1 1 1
	NUMBER 1 21 22 23 24 20 27 28 29 30 31 32
T/	TION FUTURE EFFECT SHUTDOWN ACTION ON PLANT METHOD HOURS SUBMITTED FORM SUB SUPPLIER MANUFACTURER E 18 Z 19 Z 20 Z 21 0 0 0 0 22 Y 23 Y 24 A 25 C 7 8 0 126 37 40 41 42 43 43 44 43 44 45 44 44
1101	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 The unit was found to have tripped on freeze protection due to insufficient load for this chiller when
1111	Iproviding cooling for the CPC room. Unit was reset and declared operable per Technical Specification 3.7.6.1.
1121	Ito prevent the compressor from freezing, the operating procedure for control room air conditioning and
1131	Iventilation was revised to require an adjustment of the control room thermostat upward to energize the
7 1 4 1	lelectric unit duct heaters to apply additional heat load, if necessary, when the emergency chillers (cont d)
	FACILITY METHOD OF 80
7 1 5 1	STATUS % POWER OTHER STATUS DISCOVERY DISCOVERY DESCRIPTION E 128 0 8 0 129 N/A 130 A 131 N/A
	ACTIVITY CONTENT
7 8	RELEASED OF RELEASE AMOUNT OF ACTIVITY Z 133
17171	NUMBER TYPE DESCRIPTION
	1 0 1 0 1 0 137 1 Z 138 1 NA 139 139 ERSONNEL INJURIES 80
11101	NUMBER DESCRIPTION
7 8	1 0 1 0 1 0 140 1 NA 141 12 141 15 15 15 15 15 15 15 15 15 15 15 15 15
1191	LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 1 Z 142 1 NA
	PUBLICITY ISSUED DESCRIPTION
7 1 0 1	1 N 144 1 NA 145 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	NAME OF DESPASED.
	NAME OF PREPARER: Patrick Rogers PHONE: (501) 964-3100



EXHIBIT A

LER No. 50-368/80-026/03X-1

Occurrence Date: __05/14/80

Cause Description and Corrective Actions (Continued)

are being used as supplemental CPC room chillers.



ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000 July 24, 1984

2CANØ784Ø9

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject: Arkansas Nuclear One - Unit 2

Docket No. 50-368 License No. NPF-6 Licensee Event Report No. 80-026/03X-1

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.1.9.1.b, attached is the subject report concerning the control room air conditioner compressor 2VE-1A. This is an update to a previous submittal dated June 11, 1980.

Very truly yours,

bohn R. Marshall Manager, Licensing

JRM: KJS: ac

Attachment

cc: Mr. Richard C. DeYoung
 Office of Inspection and Enforcement
 U. S. Nuclear Regulatory Commission
 Washington, DC 20555

Mr. Norman M. Haller, Director Office of Management & Program Analysis U. S. Nuclear Regulatory Commission Washington, DC 20555

IEZZ