1 3 U S NUCLEAR REGULATORY COMMISSION APPROVED OME NO 3150-0104 EXPIRES 8/31/85 LICENSEE EVENT REPORT (LER) DOCKET NUMBER (2) FACILITY NAME (1) 1 OF 0 0 15 10 10 10 13 10 15 Kewaunee Nuclear Power Plant TITLE (4) Unplanned Start of "B" Train Auxiliary Building Special Ventilation System OTHER FACILITIES INVOLVED (8) LER NUMBER (6) REPORT DATE (7) EVENT DATE (6) DOCKET NUMBERIS FACILITY NAMES SEQUENTIAL MONTH MONTH DAY YEAR YEAH 0 |5 | 0 | 0 | 0 | NA 0 | 5 | 0 | 0 | 0 | 0 8 0 8 4 8 4 8 4 0 1 3 0 0 d 7 0 2 THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR & (Check one or more of the following) (11) MODE (8) 80 73(a)(2)(iv) 73.71(b) 20 406(2) 73.71(c) 50 36(e)(1) 60 73(a)(2)(v) 20 405(6)(1)(1) OTHER (Specify in Abstract below and in Tast, NRC Form 366A) 60 73(a)(2)(vii) 80 36(c)(2) 11000 30 408 (a)(1)(H) 60 73(a)(2)(vili)(A) 20 408(4)(1)((()) 80 73(a)(2)(i) 50 73(a)(2)(vill)(B) 80.73(a)(2)(ii) 20 406(a)(1)(iv) 50 73(a)(2)(x) 20.406(a)(1)(v) 50 73(a)(2)(iii) LICENSEE CONTACT FOR THIS LER (12) PERMUN SHOHELS NAME AREA CODE Sherry Bernhoft - Plant Technical Support Engineer 3 | 8 | 8 | - | 2 | 5 | 6 | 0 41114 COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13) EPORTABLE MANUFAC TURER TO NPROS MANUFAC CAUSE SYSTEM COMPONENT CAUSE SYSTEM COMPONENT VIJ PISIV J1017 5 YES X YEAR MONTH DAY SUPPLEMENTAL REPORT EXPECTED (14) EXPECTED DATE (15) NA YES IT yes, complete EXPECTED SUBMISSION DATE! ABSTRACT (Limit to 1400 spaces . e. approximately fifteen single space typewritten lines) (16) On July 2, 1984, with the plant at full power operation, the auxiliary operator discovered that Train "B" of the Auxiliary Building Special Ventilation System (ABSV)

On July 2, 1984, with the plant at full power operation, the auxiliary operator discovered that Train "B" of the Auxiliary Building Special Ventilation System (ABSV) was running for no apparent reason. When the control room operator attempted to secure the system he discovered a blown fuse for the solenoid valve on the Zone SV Exhaust Filter 1B Inlet Damper. Investigation revealed that the coil on the solenoid valve had burnt out failing it in the closed position which automatically opened the damper and started the 1B Zone SV Exhaust Fan.

Due to similar failures of this model of Johnson Solenoid valves, a design change had been in place to replace these valves as they fail with ASCOs. Once completed, this design change should prevent a recurrence of this event.

Since the system failed in the safe position there was no effect on the public health and safety.

J972

8408080510 840801 PDR ADDCK 05000305 S PDR NRC Form 366A

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

US NUCLEAR REGULATORY COMMISSION
APPROVED OMB NO 3:50-0104

FACILITY NAME (1)	EXPIRES 8/31/85				
PACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6) PAGE		
Kewaunee Nuclear Power Plant		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
	0 5 0 0 0 3 0 5	814-	- 01113	- 010	012 05 0 12
TEXT III more space is required, use additional NAC Form 308A's) [17]		1			0 2 0 10 12

At 0105 on July 2, 1984, with the plant at 100% full power operation, the auxiliary operator discovered that Train "3" of the Auxiliary Building Special Ventilation System (VJ) was running. The Control Room operators could find no apparent reason for the system to be running and unsuccessfully attempted to secure it. Following this attempt, a blown fuse (FU) was discovered in the relay rack (RK) for the Solenoid valve (PSV) which controls the Zone SV Exhaust Filter 1B Inlet Dampet (DMP). Based on the past history of this system the operators suspected that the coil (CL) was burned out on the normally energized solenoid valve.

Due to the hour of the day when the discovery was made, the Shift Supervisor decided to leave the system running which is its safe mode of operation. Maintenance removed the system from service at 0815 on 7/3/84 and confirmed the operators suspicion of a burnt out coil. The burnt out coil resulted in the solenoid valve failing closed and opening the damper. The damper opening actuated a signal to open the Zone SV Exhaust Fan 1B Discharge Damper which in turn actuated a signal to start the Zone SV Exhaust Fan 1B (FAN). The valve was replaced and the system placed back in service on 7/10/84.

Due to a history of similar failures of this model of Johnson Controls V-24 solenoid valves, a design change was initiated approximately three years ago to replace all of these valves on an as fail basis with ASCO NP8320A176E solenoid valves.

During a discussion of this incident the Plant Operations Review Committee recommended that a review be done to identify the number of remaining Johnson V-24 solenoid valves and in particular those whose failure will result in the unplanned actuation of safeguards systems. This review identified fifty-nine remaining Johnson V-24 valves, two of which fall into the category of initiating safeguards equipment.

These two valves will be replaced by 1/1/85 in order to prevent any further unnecessary challenges to safeguards equipment.

See also LER 82-03, LER 32-28 and 81-34.

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

August 1, 1984

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Gentlemen:

Docket 50-305 Operating License DPR-43 Kewaunee Nuclear Power Plant Reportable Occurrence 84-013-00

In accordance with the requirements of 10 CFR 50.73 "Licensee Event Report System", the attached Licensee Event Report for reportable occurrence 84-013-00 is being submitted.

Carlen Giesle for

D. C. Hintz

Manager - Nuclear Power

JGT'js

Attach.

cc - INPO Records Center
Suite 1500, 1100 Circle 75 Parkway
Atlanta, GA 30339
Mr. Robert Nelson, NRC Resident Inspector
RR #1, Box 999, Kewaunee, WI 54216
Mr. S. A. Varga, Chief
US NRC, Washington, DC 20555
Mr. J. G. Keppler, Regional Administrator
Region III, US NRC, 799 Roosevelt Road
Glen Ellyn, IL 60137

IE22