



GULF STATES UTILITIES COMPANY

RIVER BEND STATION POST OFFICE BOX 220 ST. FRANCISVILLE, LOUISIANA 70775
AREA CODE 504 231-6094 346-8001

January 10, 1992
RBG-36,235
File Nos. G9.5, G9.25.1.3

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Gentlemen:

River Bend Station - Unit 1
Docket No. 50-458

Please find enclosed Licensee Event Report No. 91-021 for River Bend Station - Unit 1. This report is submitted pursuant to 10CFR50.73. Based on a discussion with Mr. Elmo Collins of the NRC, the submittal date of this report has been extended.

Sincerely,

W.H. Cdell
Manager - Oversight
River Bend Nuclear Group

WAE PDG GAB DCH JPS
WAE/PDG/GAB/DCH/JPS/kvm

cc: U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

NRC Resident Inspector
P.O. Box 1051
St. Francisville, LA 70775

INPO Records Center
1100 Circle Parkway
Atlanta, GA 30339-3064

Mr. C.R. Oberg
Public Utility Commission of Texas
7800 Shoal Creek Blvd., Suite 400 North
Austin, TX 78757

9201210111 920110
PDR ADDCK 05000458
S PDR

JE22
11

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 500 HRS FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-630) U.S. NUCLEAR REGULATORY COMMISSION WASHINGTON, DC 20555 AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104) OFFICE OF MANAGEMENT AND BUDGET WASHINGTON DC 20503.

FACILITY NAME (1) RIVER BEND STATION DOCKET NUMBER (2) 050004581 OF 04

TITLE (4) REACTOR PROTECTION SYSTEM ACTUATION DUE TO OPERATOR FAILURE TO VERIFY THE SCRAM DISCHARGE VOLUME LEVEL

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)
12	08	91	19	02	1	0	11	09		050000
										050000

OPERATING MODE (9) 3

POWER LEVEL (10) 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 50. (Check one or more of the following: (11))

<input type="checkbox"/> 50.402(b)	<input type="checkbox"/> 50.405(a)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input type="checkbox"/> 50.405(a)(1)(ii)	<input type="checkbox"/> 50.56(a)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)
<input type="checkbox"/> 50.405(a)(1)(iii)	<input type="checkbox"/> 50.56(a)(2)	<input type="checkbox"/> 50.73(a)(2)(vi)	<input type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 366A)
<input type="checkbox"/> 50.405(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(vii)(A)	
<input type="checkbox"/> 50.405(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(vii)(B)	
<input type="checkbox"/> 50.405(a)(1)(vi)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(viii)	
<input type="checkbox"/> 50.405(a)(1)(vii)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME L.A. ENGLAND, DIRECTOR-NUCLEAR LICENSING TELEPHONE NUMBER 504 381-4145

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFAC TUNER	REPORTABLE TO NRCDS	CAUSE	SYSTEM	COMPONENT	MANUFAC TUNER	REPORTABLE TO NRCDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If you complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15)

ABSTRACT (Limit of 7,400 characters - approximately fifteen single space typewritten lines) (16)

At approximately 1524 on 12/08/91, with the reactor in Operational Condition 3, an unplanned reactor protection system (RPS) actuation occurred when the at-the-controls (ATC) operator placed the control rod drive (CRD) scram discharge volume high water level bypass switches from "bypass" to "normal" without assuring that the scram discharge volume (SDV) water level was less than 49". All control rods were inserted previously and no additional rod motion occurred due to the RPS actuation. This event is reportable pursuant to 10CFR50.73(a)(2)(iv), as an engineered safety feature (ESF) actuation.

Abnormal Operating Procedure (AOP)-0001 ("Reactor Scram") is being revised to include a dedicated section to provide specific instructions for resetting a reactor scram or RPS (*JE*) actuation. This section will require the ATC operator to place the SDV high water level bypass switches to "bypass" as the first step and verify the SDV high level alarm is clear prior to placing the switches in the "normal" position.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRC. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (F-530), U.S. NUCLEAR REGULATORY COMMISSION, 1200 MCLEAN BLVD., WASHINGTON, DC 20545. AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (8)

PAGE (3)

RIVER BEND STATION

0 | 5 | 0 | 0 | 0 | 4 | 5 | 8 | 9 | 1 | - | 0 | 2 | 1 | - | 0 | 0 | 0 | 2 | OF | 0 | 4

TEXT IF MORE SPACE IS REQUIRED, USE ADDITIONAL NRC Form 386A's (17)

REPORTED CONDITION

At approximately 1524 on 12/08/91, with the reactor in Operational Condition 3, an unplanned reactor protection system (RPS) (*JE*) actuation occurred when the at-the-controls (ATC) operator placed the control rod drive (CRD) scram discharge volume high water level bypass switches from "bypass" to "normal" without assuring that the scram discharge volume (SDV) water level was less than 49". All control rods were inserted previously and no additional rod motion occurred due to the RPS actuation. This event is reportable pursuant to 10CFR50.73(a)(2)(iv), as an engineered safety feature (ESF) actuation.

INVESTIGATION

Prior to the event, reactor power had been reduced to 11 percent as part of a normal plant shutdown for generator repairs. At 1510, the ATC operator inserted a manual reactor scram, which resulted in successful insertion of all control rods. In the attempt to place the mode switch in the "shutdown" position, the mode switch key broke off between the "startup" and "refuel" positions. The mode switch was successfully placed in the "shutdown" position with needle-nosed pliers. This resulted in an additional RPS (*JE*) actuation following the reactor scram which occurred at 1510. Note that this actuation is not considered reportable. Per procedure the ATC attempted to take the mode switch key to the shutdown position. When this happens an RPS actuation is an expected part of the system response. The ATC operator had taken the SDV high water level bypass switches to "bypass" per Abnormal Operating Procedure (AOP)-0001, "Reactor Scram." Following this, he reset the RPS (*JE*) actuation, to prevent excessive temperature changes in the reactor vessel bottom head. The subsequent actions of AOP-0001 had been initiated following the RPS actuation. When the hydraulic control unit (HCU) accumulator faults cleared, the ATC operator returned the SDV high level bypass switches to "normal", but failed to verify the SDV level was less than 49" or that the SDV high level annunciator (*LA*) was clear. At this point, the RPS actuation occurred per plant design. This actuation was not a part of a preplanned activity and thus is reportable under 10CFR50.73 as an ESF actuation.

ROOT CAUSE

The root cause of this event was a lack of attention to detail by the ATC operator in verifying that the scram discharge volume level was less than 49" prior to returning the SDV high level bypass switches to "normal". The event was complicated by the breaking of the mode switch key and the subsequent RPS (*JE*) actuation that occurred. After resetting the RPS actuation, the ATC operator was focused on the

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 500 HRS FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-630), U.S. NUCLEAR REGULATORY COMMISSION WASHINGTON, DC 20555 AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET WASHINGTON, DC 20503

FACILITY NAME (1) RIVER BEND STATION	DOCKET NUMBER (2) 0 5 0 0 0 4 5 8	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		9 1	0 2 1	0 0	0 3	OF 0 4

TEXT (if more space is required, use additional NRC Form 308A (1/77))

procedural note in AOP-0001 that informs the operator that an RPS (*JE*) actuation with no rod movement will take the SDV longer to fill (greater than one minute). This note was added as a corrective action of LER 90-028, to address the specific case in which the plant is at reduced reactor pressure and/or there is no control rod motion. While the note is considered to be a contributing factor, the ATC operator's lack of attention to detail is the root cause of this event. When the ATC operator placed the bypass switches in the "normal" position it had been several minutes since he had reset the last RPS actuation, and he believed that the SDV was drained. Had he responded properly, he would have verified the SDV level or that the SDV high level annunciator was clear prior to placing the bypass switches in the "normal" position.

A similar event described in LER 90-028 reported an unplanned RPS actuation that occurred while the plant was shutdown. In this case, the ATC operator failed to place the high water level bypass switches in the "bypass" position before resetting a previous (planned) RPS (*JE*) actuation. The unplanned RPS (*JE*) actuation resulted from this action. As a result of this event, a caution was added to AOP-001 to remind operators that at reduced reactor pressure and/or with no control rod motion, the SDV takes longer to fill and reach the high level trip. While RPS actuations during shutdown resulted in both events (LER 90-028 and 91-021), the conditions leading to each event, and the root causes are different.

CORRECTIVE ACTION

Abnormal Operating Procedure (AOP)-0001 ("Reactor Scram") is being revised to include a dedicated section to provide specific instructions for resetting a reactor scram or RPS (*JE*) actuation. This section will require the ATC operator to place the SDV high water level bypass switches to "bypass" as the first step and verify the SDV high level alarm is clear prior to placing the switches in the "normal" position. This revised section is designed to address any circumstances in which a reactor scram or RPS actuation may need to be reset. Note that this revised section supersedes the note provided as corrective action in LER 90-028.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) RIVER BEND STATION	DOCKET NUMBER (2) 0 5 0 0 0 4 5 8 9 1	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
			0 2 1	0 0	0 4	OF 0 4

TEXT (if more space is required, use additional NRC Form 3054's) (17)

Simulator training will be enhanced to include human factors by training the operators to place the bypass switches in the "normal" position one Division at a time, instead of simultaneously. In the event that the SDV level is not drained below 49", taking only one Division to the "normal" position will result in a half-scam, rather than a full RPS actuation.

SAFETY ASSESSMENT

The control rods were fully inserted prior to this event. No additional rod motion occurred as a result of the unplanned RPS actuation, and the RPS system (*JE*) responded as designed.