HUNTON & WILLIAMS P. O. Box 109

B B & T BUILDING

RALEIGH, NORTH CAROLINA 27802

TELEPHONE 919 - 828 - 9371

2000 PENNSYLVANIA AVENUE, N W COCKETET WASHINGTON D. C. 20036 TELEPHONE 202 985-1500

333 SOUTH GRAND AVENUE LOS ANGELES. CALIFORNIA 9007 TELEPHONE 213-617-3052

DOCKETING & SERVICE NO. 24566.3 KNOXVILLE. TENNESSEE 37901

August 1, 1984

In the Matter of LONG ISLAND LIGHTING COMPANY

(Shoreham Nuclear Power Station, Unit 1) Docket No. 50-322-1 (OL)

Hon. Lawrence Brenner, Esq. Administrative Judge Atomic Safety and Licensing Board U.S. Nuclear Regulatory Commission Washington, D.C. 20555

707 EAST MAIN STREET P. O. BOX 1835

RICHMOND. VINGINIA 23212 TELEPHONE BOA-788-8200 TWX 710 956-0061

200 PARK AVENUE

EW YORK. NEW YORK (017)

TELEPHONE 212-980-8200

TELEX 754708 FIRST VIRGINIA BANK TOWER

P. O BOX 3889

NORFOLK, VIRGINIA 235 TELEPHONE 804-629-8501 TELEX 755628

> Hon. Dr. George A. Ferguson Administrative Judge School of Engineering Howard University 2300 - 56 Street, N.W. Washington, D.C. 20059

Hon. Dr. Peter A. Morris Administrative Judge Atomic Safety and Licensing Board U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Dear Administrative Judges:

In accordance with the Board's Order of July 25, 1984 dismissing the crankshaft oil passage plug issue, enclosed for filing is the Affidavit of Clinton Mathews attesting to the accuracy of the information contained in his letter of July 12, 1984 to Craig Seaman of LILCO. I am sending the original Affidavit to Judge Brenner with copies to all other parties.

Very truly yours,

David Dreifus

300/918 Enclosure

Alan Roy Dynner, Esq. (w/encl) (By Federal Express) Richard J. Goddard, Esq. (w/encl) (By Federal Express) Fabian G. Palamino, Esq. (w/encl) (By Federal Express) Entire Service List (w/o encl)

8408090223 840806 PDR ADOCK 05000322 PDR

#### UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION

## Before the Atomic Safety and Licensing Board

In the Matter of

LONG ISLAND LIGHTING COMPANY

Docket No. 50-322-01

\*84 AGD -0

(Shoreham Nuclear Power Station, Unit 1)

COFFICE OF SECULOR OF

## AFFIDAVIT OF CLINTON S. MATHEWS

STATE OF CALIFORNIA)
) ss.:
COUNTY OF ALAMEDA )

CLINTON S. MATHEWS, being duly sworn, deposes and says:


- I am Vice President and General Manager of the Engine and Compressor Division of Transamerica Delaval Inc. ("TDI").
- 2. On July 12, 1984, I wrote to Craig Seaman of The Long Island Lighting Company comparing the design of the crank-shaft oil hole plugs used in the TDI engines at Rafha, Saudi Arabia and those used at Shoreham. The information contained in that letter and its attachments (copies of which are annexed as Exhibit A) is accurate.

Clinton S. Mathews

Sworn to before me this

301H day of July, 1984

Ballaure Notary Public



Engine and Compresso \$550 85th Avenue P.O. Box 2161 Oakland, California 94621 (415) 577-7400

July 12, 1984

Mr. Craig Seaman Long Island Lighting Company Shoreham Nuclear Power Station P.O. Box 618 North Country Road Wading River, New York 11792

Subject: Crankshaft Oil Hole Plug

P/N R-3149

Dear Craig:

In response to your inquiry regarding the design of the oil hole plugs used in the crankshaft at Rafha Electricity Corp., enclosed are drawing R-3149, the drawing release and change notice form showing the original release, and the change notices for change A (3/10/80) and change B (6/23/82) which describe the oil hole plug and its changes over the years. As set forth below, the oil hole plugs in place at Shoreham use significantly thicker steel than used at Rafha and TDI has no knowledge of any failures of the Shoreham design plug which is in use in more than 300 "R" series engine crankshafts.

The original design of the crankshaft oil hole plug was released in December, 1965 and called for the plug to be stamped from 16 gauge sheet steel which is approximately 1/16" in thickness. Over the years this plug was completely successful. However, our manufacturing people suggested changing to a lighter gauge material which would reduce the time required for installation. Please note that the plug installation consists of inserting the plug into its location and then mechanically deforming the plug by rolling it into a premachined groove in the crankshaft, thereby locking the plug in place. In March of 1980, the plug material was changed from 16 gauge sheet steel to 22 gauge sheet steel, for "ease of assembly" (change symbol A). Twenty-two (22) gauge sheet metal is approximately 1/32" in thickness, or approximately one-half the thickness of the previously-used 16 gauge material.

# iransamerica Delaval



Mr. Craig Seamn Long Island Lighting Company July 12, 1984

Page 2

While almost all of the 22 gauge plugs worked perfectly, field experience and shop experience showed us that the crankshaft oil hole plugs made from the thinner 22 gauge material were more likely to be damaged during the installation process where they were set into the crankshaft hole with a plug punch. Such installation damage is believed to have resulted in failures at Rafha in Saudi Arabia. As a result of these failures, where the center of the 22 gauge plug partially sheared out, we returned to the original 16 gauge material design in June of 1982 (change symbol B), which design remains unchanged from that time to the present. In the 300 R4 and RV-4 series engines shipped in the last 20 years, this 16 gauge plug has been used approxiamtely 6000 times with no reported failures. Both the original Shoreham crankshafts and the replacement crankshafts use the heavier 16 gauge plugs.

We trust the foregoing satisfies your needs. If not, please let me hear from you.

Best regards,

C. S. Mathews

Vice President and General Manager


CSM/pn

cc: Mr. Clarence Ray, TDI Owners Group w/att.

טבפוצה פי	ENG.		MOCEL	7				CHANGE BYMBO RE
70								
M	DRAWING	DETEA	SED BO	PRODI	CTION			
NEW	DKYMTAG	RELEA	SED FC	K PRODU	or ron.			RECEIVED
								PRODUCTION
								JEDVOLNEN.
1014								MAR 03 1966
~ .								
Code	2910	1012					- AM	
		124	-70 .				7.5	2.9.11.12,1,2,3,4
LEASED FOR				FILE D	,	BECO	RD K	EXPERIMENT
LEASED FOR	PRODUCTION	UNIL		! REMARK		RECO	NO A	EXTENSES FOR
TS								
ECTES								NEW PATER
DISPOSITION	FINISHED	ROUGH	PROGRESS	ORDER	AGSEMBLED!	PARTS	PER CHANGE	OF NOTICE TO
SCRAP	BIGCK	a loca	PROGRESS	ONDER	NOT SHIPE	REPAIR		- FATTERN C
REW'ORK		No.	STOC	4		SERVICE	PER PARTS LIS	- I
SE W/C CHANGE			T	1			SEE REMARKS	
N' 6-4024 ( LAVAL TURBINE INC			TICE	FERST	NE IOR		R-31	49
WING	CHANGE CRANKSI	NO	TICE		VE JOB		PART NO. R-31 CHANGE SY	uno. A
NING PLUG	CHANGE -CRANKSI	NO	IL HOL		VE JOB		R-31	
WING PLUG	CHANGE	NO	IL HOL		VE JOB		R-31	uno. A
NING PLUG	CHANGE -CRANKSE D. PRAT	NO HAFT O MODE	IL HOL	E		FT STA	R-31 CHANGE SY	uno. A
WING PLUG	CHANGE -CRANKSE D. PRAT	NO HAFT O MODE	IL HOL	E	VE JOB	ET STA	R-31 CHANGE SY	uno. A
NING PLUG	CHANGE -CRANKSE D. PRAT	NO HAFT O MODE	IL HOL	E		ET STA	R-31 CHANGE SY	uno. A
NING PLUG	CHANGE -CRANKSH D. PRAT	NO PAFT O MODE TT	IL HOL	0595) \$		CET STA	R-31 CHANGE SY	uno. A
WING PLUG	CHANGE -CRANKSH D. PRAT	NO PAFT O MODE TT	IL HOLL	0595) \$		CET STA	R-31 CHANGE SY	uno. A
PLUG  PLUG  MATER  REASO	CHANGE CRANKSE D. PRATI IAL WAS	NO PAFT OF MODE TT MODE TT MODE	JAGE (.	0595) S		CET STA	R-31 CHANGE SY	uno. A
NING PLUG	CHANGE CRANKSE D. PRATI IAL WAS	NO PAFT OF MODE TT MODE TT MODE	IL HOLL	0595) S	STEEL SHE		R-31 CHANGE SY	uno. A
PLUG  PLUG  MATER  REASO	CHANGE CRANKSE D. PRATI IAL WAS	NO PAFT OF MODE TT MODE TT MODE	JAGE (.	0595) S	STEEL SHE		R-31 CHANGE SY	uno. A
PLUG PESTED BY  MATER  REASO	CHANGE CRANKSE D. PRATI IAL WAS	NO PAFT OF MODE TT MODE 16 GU	JAGE (.	0595) S			R-31 CHANGE SY	uno. A
WING PLUG PESTED BY MATER REASO NOTE:	CHANGE -CRANKSH D. PRATI IAL WAS N: EAS EFFEC	NO PAFT OF MODE TT MODE 16 GU	JAGE (.	0595) S	STEEL SHE	to	R-31 CHANGESY DATE MPING.	MBOL A 3/10/80
PLUG PLUG PESTED BY MATER REASO NOTE:	CHANGE -CRANKSH D. PRATILITIES IAL WAS N: EAS EFFEC	NO PAFT O MODE TT 16 GU E OF A	JAGE (.	0595) S	STEEL SHE	to	R-31 CHANGE SY	MBOL A 3/10/80
WING PLUG PESTED BY MATER REASO NOTE:	CHANGE CRANKS!  D. PRATICAL WAS  N: EAS  EFFEC	NO PAFT O MODE TT 16 GU E OF A	ASSEMBI	0595) S	STEEL SHE	to	R-31 CHANGESY DATE MPING.	MBOL A 3/10780
WING PLUG  MATER  REASO  NOTE:	CHANGE -CRANKSH D. PRATILITIES IAL WAS N: EAS EFFEC	NO PAFT O MODE TT 16 GU E OF A TIVE O	JACE (.	O595) S	STEEL SHE	OTHER	R-31 CHANGESY DATE MPING.	PATTERN CHANGE NO NEW PATTERN
WING PLUG  MATER  REASO  NOTE:	CHANGE -CRANKSH D. PRATI IAL WAS N: EAS EFFEC	NO PAFT OF MODE TT MODE TO GU	JACE (.	0595) S	STEEL SHE	OTHER	R-31 CHANGESY DATE MPING.	PATTERN CHANGE NO NEW PATTERN NO
WING PLUG  MATER  REASO  NOTE:	CHANGE CRANKSH D. PRATITION IAL WAS  N: EAS  EFFEC  ODUCTION DISPOSITE OF STOC  SCRAP  FEWORK	NOTAFT OF A	JACE (.	O595) S	STEEL SHE	OTHER I	CHANGE SY DATE	PATTERN CHANGE NO NEW PATTERN
WING PLUG  MATER  REASO  NOTE:	CHANGE CRANKSH  D. PRATI  IAL WAS  N: EAS  EFFEC  CODUCTION  DISPOSITION OF STOCE  SCRAP  REWORK  NEW REL	NOTAFT OF A TIVE OF A	JACE (.	O595) S	ISSUE TO ASSEMBLY  USE AS	OTHER I	CHANGE SY DATE	PATTERN CHANGE NO NEW PATTERN NO

HAWING URCH SPEC AME PLUG, CR		HOLE	EFFECTI	IVE JOB	CHANGESY	
EQUESTED BY	D. RII	PPFF CHG.	REQUEST	OF 6-14-82	DATE	6/23/82
REASON:	. WAS 22 GA. TO LESSEN C	HANCE OF I	DAMAGE TO	PLUG AT II		
	ENEXT PART	MADE MUST	BE PEK IF	112 KEV121	UN	
	82-135	MADE MUST	FILE []	412 KEV1210	UN	
MISC.	82-135	WORK IN PROGRESS		ISSUE TO ASSEMBLY	OTHER PARTS AFFECTED	PATTERN CHANGE
MISC.	82-135	WORK IN	FILE []	ISSUE TO		The second secon
MISC.	DISPOSITION OF STOCK	WORK IN PROGRESS	FILE ON HAND	ISSUE TO ASSEMBLY		NO
MISC.	DISPOSITION OF STOCK	WORK IN PROGRESS	FILE ON HAND	ISSUE TO ASSEMBLY	OTHER PARTS AFFECTED	NO NEW PATTERN NO CHANGE CODE
MISC.	DISPOSITION OF STOCK SCRAP	WORK IN PROGRESS	FILE ON HAND	ISSUE TO ASSEMBLY	OTHER PARTS AFFECTED	NO NEW PATTERN NO

Form E 241 1/77



### UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION

## Before the Atomic Safety and Licensing Board

In the Matter of )
LONG ISLAND LIGHTING COMPANY )
(Shoreham Nuclear Power )

Docket No. 50-322-OL

\*84 AGD -8 A10:30

#### AFFIDAVIT OF CLINTON S. MATHEWS

STATE OF CALIFORNIA)
) ss.:
COUNTY OF ALAMEDA

Station, Unit 1)

CLINTON S. MATHEWS, being duly sworn, deposes and says:

- 1. I am Vice President and General Manager of the Engine and Compressor Division of Transamerica Delaval Inc. ("TDI").
- 2. On July 12, 1984, I wrote to Craig Seaman of The Long Island Lighting Company comparing the design of the crankshaft oil hole plugs used in the TDI engines at Rafha, Saudi Arabia and those used at Shoreham. The information contained in that letter and its attachments (copies of which are annexed as Exhibit A) is accurate.

Clinton S. Mathews

Sworn to before me this 301H day of July, 1984

Ballowy Public

OFFICIAL SEAL

8 J DOWD

NOTARY PUBLIC - CALIFORNIA

ALAMEDA COUNTY

My comm. expires JUL 5, 1985

Transamerica Delaval Inc. Engine and Compresso 550 85th Avenue P.O. Box 2161 Oakland, California 94621 (415) 577-7400

EXHIBIT A

July 12, 1984

Mr. Craig Seaman Long Island Lighting Company Shoreham Nuclear Power Station P.O. Box 618 North Country Road Wading River, New York 11792

Subject: Crankshaft Oil Hole Plug

P/N R-3149

Dear Craig:

In response to your inquiry regarding the design of the oil hole plugs used in the crankshaft at Rafha Electricity Corp., enclosed are drawing R-3149, the drawing release and change notice form showing the original release, and the change notices for change A (3/10/80) and change B (6/23/82) which describe the oil hole plug and its changes over the years. As set forth below, the oil hole plugs in place at Shoreham use significantly thicker steel than used at Rafha, and TDI has no knowledge of any failures of the Shoreham design plug which is in use in more than 300 "R" series engine crankshafts.

The original design of the crankshaft oil hole plug was released in December, 1965 and called for the plug to be stamped from 16 gauge sheet steel which is approximately 1/16" in thickness. Over the years this pluc was completely successful. However, our manufacturing people suggested changing to a lighter gauge material which would reduce the time required for installation. Please note that the plug installation consists of inserting the plug into its location and then mechanically deforming the plug by rolling it into a premachined groove in the crankshaft, thereby locking the plug in place. In March of 1980, the plug material was changed from 16 gauge sheet steel to 22 gauge sheet steel, for "ease of assembly" (change symbol A). Twenty-two (22) gauge sheet metal is approximately 1/32" in thickness, or approximately one-half the thickness of the previously-used 16 gauge material.

# Transamerica Delaval



Mr. Craig Seamn Long Island Lighting Company July 12, 1984

Page 2

While almost all of the 22 gauge plugs worked perfectly, field experience and shop experience showed us that the crankshaft oil hole plugs made from the thinner 22 gauge material were more likely to be damaged during the installation process where they were set into the crankshaft hole with a plug punch. Such installation damage is believed to have resulted in failures at Rafha in Saudi Arabia. As a result of these failures, where the center of the 22 gauge plug partially sheared out, we returned to the original 16 gauge material design in June of 1982 (change symbol B), which design remains unchanged from that time to the present. In the 300 R4 and RV-4 series engines shipped in the last 20 years, this 16 gauge plug has been used approxiamtely 6000 times with no reported failures. Both the original Shoreham crankshafts and the replacement crankshafts use the heavier 16 gauge plugs.

We trust the foregoing satisfies your needs. If not, please let me hear from you.

Best regards,

C. S. Mathews

Vice President and General Manager


CSM/pn

cc: Mr. Clarence Ray, TDI Owners Group w/att.

ARTS LIST	CHANGE		NOIL		EFFECTIV	E JOB_			o R-3149
F PINC	- CRANI	CH _	DIL H	R					NO
	ENG.		MODE	K					2-28-66
VESTER BY	210;							Lorie	
NEW	DRAWING	RELEA	ASED PO	R PRODU	CTION.				
112"	D.C. 2.0								ECEIVED
									PASSUEN
	,								AR 03 1966
Code	2910	1012						AM	100100 a
		12-1	- 20					7.8.9.1	0.11.12,1,2,3,4
EASED FOR	PRODUCTIO	OK NO		FILE D		RECO	RD K		EXPERIMENT
£				REMARK	S.				EXTEL COT T
ECTED									NEW PATITION
DISPOSITION	FINISHED	ROUGH	i in	1 ON	ASSEMBLEDÍ		I PER CHA	NGE	OF NOTICE T
OF STOCK	STOCK	STOCK	PROGRESS	GROER	NOT SHPPD.	PARTS	-		PATTERN C.
REWORK.		No	STOC	4		SERVICE	PER PAR	TS LIST	
REWORF.			-	_			SEE REM	ARMS	
MIGEO BY NE	S CHECKE			DCR	PARTS LIST.		TPAST	<b>v</b> O.	
NING	S CHECKE	NO	TICE	EFFECTI	VE JOB			-3149	
MING	S CHECKE	NO IAFT C	TICE	EFFECT!			- R	-3149	07E0
VING	CHANGE	NO	TICE	EFFECT!			- R	-3149 SE SYMOOL	0780
VING  PLUG	CHANGE CRANKSH	NO IAFT C MODE	TICE	EFFECT!	VE JOB		CHANG	-3149 SE SYMOOL	0/80
VING PLUG	CHANGE CRANKSH	NO IAFT C MODE	TICE	EFFECT!	VE JOB	EET STA	CHANG	-3149 SE SYMOOL	0/80
VING  PLUG	CHANGE	NO IAFT C MODE	TICE	EFFECT!	VE JOB	EET STA	CHANG	-3149 SE SYMOOL	0780
VING  PIUG  MATER	CHANGE CRANKSH	NO MAFT C MODE	TICE DIL HOLL ALL JAGE (.	EFFECTI E 0595) S	VE JOB	EET STA	CHANG	-3149 SE SYMOOL	0780
VING  PIUG  MATER	CHANGE CRANKSH	NO MAFT C MODE	TICE DIL HOLL ALL JAGE (.	EFFECTI E 0595) S	VE JOB	EET STA	CHANG	-3149 SE SYMOOL	0780
VING  PLUG  ESTED BY  MATER	CHANGE -CRANKSH D. PRAT	NO MAFT C MODE 16 GU	TICE DIL HOLL JAGE (.	EFFECTI E 0595) S	VE JOB	EET STA	CHANG	-3149 SE SYMOOL	0780
VING  PLUG  MATER	CHANGE -CRANKSH D. PRAT	NO MAFT C MODE 16 GU	TICE DIL HOLL ALL JAGE (.	EFFECTI E 0595) S	VE JOB		CHANG	-3149 SE SYMOOL	0780
VING  PLUG  ESTED BY  MATER	CHANGE -CRANKSH D. PRAT	NO MAFT C MODE 16 GU	TICE DIL HOLL JAGE (.	EFFECTI E 0595) S	VE JOB		CHANG	-3149 SE SYMOOL	0780
VING  PIUG  ESTED BY  MATER  REASO  NOTE:	CHANGE -CRANKSH D. PRAT	NO MAFT C MODE 16 GU	TICE DIL HOLL JAGE (.	EFFECTI E 0595) S	VE JOB	er ko	CHANG DATE	-3149 SE SYMBOL 3/1	0780
VING  PLUG  ESTED BY  MATER  REASO  NOTE:	CHANGE CRANKSH D. PRATI	NO IAFT COMMODE 16 GU	JAGE (.	EFFECTI E 0595) S	VE JOB	OTHER	CHANG	-3149 SE SYMBOL 3/1	O780
VING  PIUG  ESTED BY  MATER  REASO  NOTE:	CHANGE -CRANKSH D. PRAT	NO IAFT COMMODE 16 GU	JAGE (.	EFFECTI E 0595) S	VE JOB	OTHER	CHANG DATE	-3149 SE SYMBOL 3/1	TTERN CHANGE
MATER  REASO  NOTE:	CHANGE CRANKSH D. PRATI	NO IAFT COMMODE 16 GU	JAGE (. ASSEMBL	EFFECTI E 0595) S	OF 2/	OTHER	CHANG DATE	-3149 SE SYMBOL 3/1	TTERN CHANGE NO
WING PLUG  MATER  REASO  NOTE:	CHANGE CRANKSH  D. PRAT  IAL WAS  N: # EASI  OUCTION  DISPOSITION OF STOCK	NO IAFT COMMODE 16 GU	JAGE (. ASSEMBL	EFFECTI E 0595) S	O/U 2/	OTHER	CHANG DATE	-3149 SE SYMBOL 3/1	O780  TTERN CHANGE NO EW PATTERN NO
MING PLUG  MATER  REASO  NOTE:	CHANGE CRANKSH D. PRATI  IAL WAS  EFFECT  ODUCTION  DISPOSITION  DISPOSITION  SCRAP  REWORK	NO AFT COMMODE  16 GU  TIVE	JAGE (. ASSEMBL	EFFECTI E 0595) S Y MADE	OF 2/	OTHER I	MPING.	-3149 SE SYMBOL 3/1	TTERN CHANGE NO EW PATTERN NO HANGE CODE
MING PLUG  MATER  REASO  NOTE:	CHANGE CRANKSH  D. PRAT  IAL WAS  N: # EASI  EFFECT  ODUCTION  DISPOSITION  OF STOCK  SCRAP  REWORK  NEW RELE	NO IAFT C MODE 16 GU TIVE	JAGE (. ASSEMBL	EFFECTI E 0595) S Y MADE	OF 2/	OTHER I	MPING.	-3149 SE SYMBOL 3/1	O780  TTERN CHANGE NO EW PATTERN NO

HAWING	CHANGE	HOLE	EFFECT	VE JOB	PART NO.	R-3149
AME FLOOR C		IODEL			CHANGE S	
EQUESTED BY	D. RI	PPEF CHG.	REQUEST	OF 6-14-82	DATE	6/23/82
REASON:		(.0229) CC	DAMAGE TO	PLUG AT I		
REMARKS MISC.	: NEXT PART 82-135	MADE MUST	BE PER TH	IIS REVISIO	JN	
MISC.	82-135	MADE MUST		HIS REVISIO	JN	
MISC.	82-135	MADE MUST	FILE O	ISSUE TO ASSEMBLY	OTHER PARTS AFFECTED	PATTERN CHANGE
MISC.	82-135	WCRK IN	FILE []	ISSUE TO		The state of the s
MISC.	82-135  RODUCTION S  DISPOSITION OF STOCK	WCRK IN PROGRESS	FILE O	ISSUE TO ASSEMBLY		CP
MISC.  RELEASED FOR PI  TYPE  MAJOR	82-135  RODUCTION S  DISPOSITION OF STOCK  SCRAP	WCRK IN PROGRESS	FILE O	ISSUE TO ASSEMBLY	OTHER PARTS AFFECTED	NEW PATTERN NO CHANGE CODE
MISC.  RELEASED FOR PI  TYPE  MAJOR	B2-135  RODUCTION S  DISPOSITION OF STOCK  SCRAP  REWORK	WCRK IN PROGRESS	FILE O	ISSUE TO ASSEMBLY	OTHER PARTS AFFECTED	NO NEW PATTERN

Feem & 241 1/77



6. PACE WITHIN TO BE PARALLEL TO FACE WITHIN T.I.E.

1.1E. AND AT BIGHT ANGLES TO FACE WITHIN T.I.E.

1.N. INCH IENGTH.

3. DIAMETERS MARPEO & ARE TO BE CONCENIRIC TO EACH OIMER.

WITHIN DIAMETERS MARKED A ARE TO BE CONCENISE TO EACH WITHIN

WITHIN WITH THE STATE WITH NUMBER INDICATING MU IN BMS.

3. ALL MACHINING THATMSIONS . . . OIG UNITES OTHERW SE SPECIFIED 3. REMO-1 ALL BURSS AND CHARF COANERS

1 DO NOT SCALL GRAWING

MINE PROPERTY OF THE STANDARD STANDARD STANDARD STANDARD TO STANDARD STANDA

THE CHAIN IN THE LET IN INTINIANT OF THE HITTER OF THE

. ON THE POPKETS CONF. LOW

irl, fir ball

C11 - P. T. A. T.1

THE WEDGER! TO LIMIT THE THE THE THE

NOTES

# DE LAVAL TURBINE INC.

OAKLAND, CALIFORNIA.

FL FFALLING

...

· .

31.75

9

-11-

P' L AND HARDNESS

(m)

6..5.32 PATI WAS 22 CA

CRANKSHAFT OIL HOL

SCALE CULL CHECKED HUNG

日本のでは、日本のでは

The second section in the second

THE PARTY OF THE PROPERTY OF

NO.

PARTA DOCE NO

R-3140

### UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION

## Before the Atomic Safety and Licensing Board

In the Matter of

LONG ISLAND LIGHTING COMPANY

(Shoreham Nuclear Power
Station, Unit 1)

Docket No. 50-322-OL

## AFFIDAVIT OF CLINTON S. MATHEWS

STATE OF CALIFORNIA)
) ss.:
COUNTY OF ALAMEDA )


CLINTON S. MATHEWS, being duly sworn, deposes and says:

- 1. I am Vice President and General Manager of the Engine and Compressor Division of Transamerica Delaval Inc. ("TDI").
- 2. On July 12, 1984, I wrote to Craig Seaman of The Long Island Lighting Company comparing the design of the crank-shaft oil hole plugs used in the TDI engines at Rafha, Saudi Arabia and those used at Shoreham. The information contained in that letter and its attachments (copies of which are annexed as Exhibit A) is accurate.

Clinton S. Mathews

Sworn to before me this 30TH day of July, 1984

BACourd Notary Public



Transamerica Delaval Inc.

(415) 577-7400

Engine and Compresso 550 85th Avenue P.O. Box 2161 EXHIBIT A Oakland, California 94621



July 12, 1984

Mr. Craig Seaman Long Island Lighting Company Shoreham Nuclear Power Station P.O. Box 618 North Country Road Wading River, New York 11792

Subject: Crankshaft Oil Hole Plug

P/N R-3149

Dear Craig:

In response to your inquiry regarding the design of the oil hole plugs used in the crankshaft at Rafha Electricity Corp., enclosed are drawing R-3149, the drawing release and change notice form showing the original release, and the change notices for change A (3/10/80) and change B (6/23/82) which describe the oil hole plug and its changes over the years. As set forth below, the oil hole plugs in place at Shoreham use significantly thicker steel than used at Rafha, and TDI has no knowledge of any failures of the Shoreham design plug which is in use in more than 300 "R" series engine crankshafts.

The original design of the crankshaft oil hole plug was released in December, 1965 and called for the plug to be stamped from 16 gauge sheet steel which is approximately 1/16" in thickness. Over the years this plug was completely successful. However, our manufacturing people suggested changing to a lighter gauge material which would reduce the time required for installation. Please note that the plug installation consists of inserting the plug into its location and then mechanically deforming the plug by rolling it into a premachined groove in the crankshaft, thereby locking the plug in place. In March of 1980, the plug material was changed from 16 gauge sheet steel to 22 gauge sheet steel, for "ease of assembly" (change symbol A). Twenty-two (22) gauge sheet metal is approximately 1/32" in thickness, or approximately one-half the thickness of the previously-used 16 gauge material.

# Transamerica Delaval



Mr. Craig Seamn Long Island Lighting Company July 12, 1984

Page 2

While almost all of the 22 gauge plugs worked perfectly, field experience and shop experience showed us that the crankshaft oil hole plugs made from the thinner 22 gauge material were more likely to be damaged during the installation process where they were set into the crankshaft hole with a plug punch. Such installation damage is believed to have resulted in failures at Rafha in Saudi Arabia. As a result of these failures, where the center of the 22 gauge plug partially sheared out, we returned to the original 16 gauge material design in June of 1982 (change symbol B), which design remains unchanged from that time to the present. In the 300 R4 and RV-4 series engines shipped in the last 20 years, this 16 gauge plug has been used approxiamtely 6000 times with no reported failures. Both the original Shoreham crankshafts and the replacement crankshafts use the heavier 16 gauge plugs.

We trust the foregoing satisfies your needs. If not, please let me hear from you.

Best regards,

C. S. Mathews

Vice President and General Manager

CSM/pn

cc: Mr. Clarence Ray, TDI Owners Group w/att.

TS LIST	CHANGE		NUIN	101.5	EFFECTIV		L	
PIUG	- CRAN		DIL E	R				D.M.G NO
	ENG.		MODE					DATE 2-28-66
ESTED OF								
NEW	DRAW ING	RELEA	SED FO	OR PRODU	OCTION.			PRODUCTION
								MAR 03 196
Code	2940	1012					1	AM .
Coom								, R. Q. W. 11.12, 1, 2, 3
		12-1	- 20	Fu e el	,	PECO	RD K	EXPERIME
EASED FOR	PRODUCTI	ONZ		FILE C		AECO	THE R	EXTRA COT
s Creb								NEW PATE
	(	PC11511	1	1 ~	ASSEMBLEDI			_
OF STOCK	FINISHED	FOUGH	PROGRESA	ORDER	NOT SHPPD.	PARTS REPAIR	PER CHANG	PATTERN S
REWORK.		No.	5700	-		SERVICE	PER PARTS	
THE RESIDENCE OF THE PARTY OF T	The state of the s		which have been dearly	-			SEE REMAP	exs II
GED BY NH	S CHECKE			ED DCR	PARTS LIST		[DART NO	
ING	CHANGE	NO HAFT O	TICE	EFFECT!				3149
ING	S CHECKE	NO HAFT O	TICE	EFFECT!			R-3	3149 A
ING PLUG- STED BY MATER	CHANGE -CRANKS	NO HAFT O MODE	TICE	EFFECT!		EET STA	CHANGE	3149 A
ING PLUG- STED BY MATER	CHANGE-CRANKS	NO HAFT OF	TICE	EFFECT!	IVE JOB	EET STA	CHANGE	3149 A
PLUG- MATER  REASO	CHANGE-CRANKS	NO HAFT OF	TICE L HOL JAGE (.	EFFECTIVE .0595) S	STEEL SH		CHANGE	3149 A
PLUG- MATER  REASO  NOTE:	CHANGE-CRANKS	NO HAFT OF	TICE L HOL JAGE (.	EFFECTIVE .0595) S	STEEL SH	ez to	CHANGE DATE	3149 SYMBOL A 3/10/80
PLUG- MATER  REASO  NOTE:	CHANGE-CRANKS	NO HAFT OF MODE 16 GU	TICE L HOL JAGE (.	EFFECTIVE .0595) S LY T MADE	STEEL SH	OTHER	CHANGE	SYMBOL A 3/10/80  TED PATTERN CHANGE NO
PLUG- MATER  REASO  NOTE:	CHANGE-CRANKS	NO HAFT OF MODE  16 GU  TTVE	JAGE (	EFFECTIVE	STEEL SHI	OTHER !	CHANGE DATE	SYMBOL A 3/10/80  TED PATTERN CHANGE NO NEW PATTERN
MATER  REASO  NOTE:	CHANGE-CRANKS	NO HAFT OF MODE  16 GU E OF MODE	JAGE (	EFFECTIVE	STEEL SHI	OTHER !	CHANGE DATE	SYMBOL A 3/10/80  TED PATTERN CHANGE NO NEW PATTERN NO
MATER  REASO  NOTE:	CHANGE-CRANKS	NO HAFT OF MODE  16 GU E OF MODE	JAGE (	EFFECTIVE	STEEL SHI	OTHER !	CHANGE DATE	SYMBOL A 3/10/80  TED PATTERN CHANGE NO NEW PATTERN

RAWING	CHANGE RANKSHAFT OIL		EFFECT	IVE JOB	PART NO.	R-3149
AME TEVOL	M	ODEL		25 6 14 00	CHANGE SY	
QUESTED BY	D. RI	PPEF CHG.	REQUEST	OF 6-14-82	DATE	6/23/82
REASON:	WAS 22 GA. TO LESSEN C	HANCE OF	DAMAGE TO	PLUG AT I		
MISC.	: NEXT PART 82-135	MADE MUST	BE PER IF	HIS KEVISI		
	82-135	MADE MUST	FILE []	412 KEA121		
MISC.	82-135	WORK IN		ISSUE TO ASSEMBLY	OTHER PARTS AFFECTED	PATTERN CHANGE
MISC.	82-135	WORK IN	FILE []	ISSUE TO		states were allowed as could referred to
MISC.	82-135	WORK IN	FILE []	ISSUE TO ASSEMBLY		40
MISC.	82-135  RODUCTION S  DISPOSITION OF STOCK  SCRAP	WORK IN	FILE []	ISSUE TO ASSEMBLY	OTHER PARTS AFFECTED	NEW PATTERN NO CHANGE CODE
MISC.	82-135  RODUCTION S  DISPOSITION OF STOCK  SCRAP  REWORK	WORK IN	FILE []	ISSUE TO ASSEMBLY	OTHER PARTS AFFECTED	NEW PATTERN NO

CHANGED 8Y \_\_

