UPDATE REPORT	PREVIOUS REPOR	RT ISSUED - 6/02/77
NRC FORM 366 (12-81) 10 CFR 50	U.S. NUCLEAR REGULATORY COMMISSION	APPROVED BY OMB 3150-0011
CONTROL BLOCK	PLEASE PRINT OR TYPE ALL REQUI	RED INFORMATION)
OII MAPPSIO	0 - 0 0 0 0 0 - 0 0 0 4 1 1 1 LICENSE NUMBER 25 26 LICENSE TO	1 1 4 57 CAT 58 5
CON'T	- 0 2 9 3 7 0 5 0 2 7 7 8 0 KET NUMBER 68 69 EVENT DATE 74 75	7 2 0 8 4 9
EVENT DESCRIPTION AND PROBABL	e consequences) g plant heatup to operating temperature a	and pressure,
03 Control Rod Drive 46-	39 was withdrawn beyond the full-out pos	ition. "Rod
0 4 Over-travel" and "Rod	Drift" alarms were received indicating	that the CRD was
05 Luncoupled from the con	ntrol rod. (Refer to attachment for add	itional details.)
0 6 LER 77-018/03L ("CRD 4	46-39")	
07		
08		80
SYSTEM CAUS		SUBCODE
	12 13 C R D R V E 14 Z 15 sequential occurrence Report	Z (16) REVISION
1) LER/RO REFORT NUMBER	REPORT NO. 24 26 27 28 29 30	NO.
ACTION FUTURE EFFECT SH	HOURS (22) SUBMITTED FORM SUB. SUP	e comp. component 20 pplier manufacturer 20 N 23 G 0 8 0 44 47
CAUSE DESCRIPTION AND CORRECT	and replaced 9/1/77, during Refueling O	utage Number 3.
Linearithmental Annual Annual and a second s	a badly bent uncoupling rod.	
12		
13		
	and the second	
7 8 9 FACILITY	NA (31) Operational	
7 8 8 10 12 13 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF 1 6 2 33 2 34	ACTIVITY 33 LOCATION OF NE	BO
	44 45	80
	NA	
PERSONNEL INJURIES NUMBER DESCRIPTION (4)	NA	
1 8 0 0 0 00 7 8 9 11 12 LOSS OF OR DAMAGE TO PACILITY TYPE DESCRIPTION (43)		62 × **
	NA	T 1 40
ISSUED DESCRIPTION 45 201 44 No press r	elease by Boston Edison Co.	
7 8 9 10 NAME OF PREPARER _	68	** ***********************************
	S PDR	

PREVIOUS REPORT DATE - 6/02/77

UPDATE REPORT

. . .

BOSTON EDISON COMPANY PILGRIM NUCLEAR POWER STATION DOCKET NO. 50-293

Attachment to LER 77-018/03X-1

On May 2, 1977, during plant heatup to operating temperature and pressure, Control Rod Drive 46-39 was withdrawn beyond the full-out position. "Rod Overtravel" and "Rod Drift" alarms were received indicating that the CRD was uncoupled from the control rod.

After several unsuccessful attempts to couple the drive, CRD 46-39 was inserted to the full in position and electrically disarmed.

Kall The State of State

On 9/1/77, during Refueling Outage #3, CRD 46-39, Serial Number 1790 was removed and replaced with Serial Number 1222. Disassembly revealed a badly bent uncoupling rod. Functional scram and friction testing of the new drive (#1222) was accomplished. BOSTON EDISON COMPANY 800 BOYLSTON STREET BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON BENIDA VICE PRESIDENT NUCLEAR

-1-

July 20, 1984

BECo Ltr. #84-111

Dr. Thomas E. Murley Regional Administrator, Region I U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

> Docket Number 50-293 License DPR-35

> > 2.2

Dear Sir:

Ine attached update Licensee Event Report 77-018/03X-1, "CRD 46-39," is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.8.2.b.

If there are any questions on this subject, please do not hesitate to contact me.

Respectfully submi ed,

WD Harrington

W. D. Harrington

PH:caw

Enclosure: LER 77-018/03X-1

cc: Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Standard BECo LER Distribution