



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

SAFETY EVALUATION BY THE OFFICE OF NUCLEAR REACTOR REGULATION

SUPPORTING RELIEF TO USE HELICAL COIL THREADED INSERTS

ENERGY OPERATIONS, INC.

WATERFORD STEAM ELECTRIC STATION, UNIT 3

DOCKET NO. 50-382

1.0 INTRODUCTION

Steam generators are provided with access for periodic inspection and maintenance. Access is gained through manways located in areas of interest. The manway cover plates are secured to a number of threaded studs (typically 20) by hexagonal nuts. The base of each stud is tightened into a matching threaded hole in the base of the manway. After the manway cover is removed, the studs are removed to provide free access to the generator and protect the studs from possible damage.

During the repair of a leak in the cold leg steam generator manway the licensee determined that helical coil inserts were installed during refueling outage four without the required approval from the NRC. These inserts were used as a result of stuck manway studs. The removal and repair of these studs not only results in confusion and delay during an outage, it also results in additional radiological exposure to maintenance workers.

The licensee at Waterford 3 removed the stuck studs by drilling and machining, enlarged the resulting stud hole slightly, then restored the stud hole to its original size, configuration and load carrying capacity through the use of a threaded helical coil insert.

The use of oversized studs in place of those removed has been considered. Although the next larger size stud also would satisfy stress requirements, multiple sized studs, nuts and tools would increase the possibility of installation error, equipment damage and unnecessary radiological exposure to workers. The use of weld build-up and redrilling the stud hole to its original size was also considered. This technique would result in field welding under difficult conditions in an adverse radiological environment.

2.0 DISCUSSION

The studs for the primary side manway covers are designed and inspected according to the requirements of the American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code. The ASME code covers the situation

where a stud cannot be removed and must be replaced under IWA-7000, IWB-7000, IWC-7000 or IWD-7000. The replacement stud "shall meet the edition of the Construction Code to which the original component or part was constructed" as stated in IWA-7210 of the ASME code. Normal practice has been to drill or machine the stud out and to tap the new stud hole for the next larger sized stud. Using the next larger size stud provides a larger stud cross-sectional area and the stress requirements of NB 3230 of the code are satisfied. The use of a helical coil insert would permit the use of a stud identical to the one that was drilled out and the stress requirements of NB 3230 would be satisfied. The licensee at Waterford 3 has included the stress analysis results and has shown that the maximum stud service stress intensity meets the requirements of the ASME code. The helical coil is designed so that the stress on the helical coil is lower than the stress on the stud and; hence, also meets the requirements of NB 3230.

ASME Code Case N-496 has been approved by the ASME but has not been endorsed by the NRC. The use of this code case would reduce confusion on the part of maintenance personnel who would have to carry a range of sizes of wrenches to accommodate the range of sizes of studs. Also, the clearance between studs is not great and the studs may become more difficult to remove as the number of oversized studs increases. The maintenance personnel would be exposed to an increased manrem exposure as a result of the mixture of stud sizes and the decreased spacing between studs as the number of oversized studs increases.

### 3.0 CONCLUSION

Based on a review of the information provided, the staff has concluded that this use of helical coils according to ASME Code Case N-496 for the Waterford 3 steam generator primary side plenums provides an adequate level of quality and safety and, thus, is an acceptable alternative repair in accordance with 10 CFR 50.55a(a)(3)(i).

Principal Contributors: J. A. Davis, NRR/DET  
D. L. Wigginton, NRR/PDIV-1

Date: February 21, 1992

Mr. Ross P. Barkhurst  
Entergy Operations, Inc.

Waterford 3

cc:

Mr. Glenn Miller, Administrator  
Radiation Protection Division  
Office of Air Quality and Nuclear Energy  
Post Office Box 82135  
Baton Rouge, Louisiana 70884-2135

Regional Administrator, Region IV  
U.S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Mr. John R. McGaha  
Vice President, Operations  
Support  
Entergy Operations, Inc.  
P. O. Box 31995  
Jackson, Mississippi 39286

Resident Inspector/Waterford NPS  
Post Office Box 822  
Killona, Louisiana 70066

President, Parish Council  
St. Charles Parish  
Hahnville, Louisiana 70057

William A. Cross  
Bethesda Licensing Office  
3 Metro Center  
Suite 610  
Bethesda, Maryland 20814

Mr. Donald C. Hintz  
Executive Vice President and  
Chief Operating Officer  
Entergy Operations, Inc.  
P. O. Box 31995  
Jackson, Mississippi 39286

Mr. Robert B. McGehee  
Wise, Carter, Child & Caraway  
P.O. Box 651  
Jackson, Mississippi 39205

Chairman  
Louisiana Public Service Commission  
One American Place, Suite 1630  
Baton Rouge, Louisiana 70825-1697

Mr. D. F. Packer  
General Manager Plant Operations  
Entergy Operations, Inc.  
P. O. Box B  
Killona, Louisiana 70066

Mr. R. F. Burski, Director  
Nuclear Safety  
Entergy Operations, Inc.  
P. O. Box B  
Killona, Louisiana 70066

Mr. L. W. Laughlin, Licensing Manager  
Entergy Operations, Inc.  
P. O. Box B  
Killona, Louisiana 70066

Winston & Strawn  
Attn: N.S. Reynolds  
1400 L Street, N.W.  
Washington, DC 20005-3502