NRC For (9-83)	m 366				LIC	ENSE	E EVE	NT RE	PORT	(LER)		UCLEAR REGULATO APPROVED OMB NO EXPIRES: 8/31/85	
FACILIT	Y NAME (	1)								10	OCKET NUMBER	(2)	PAGE (3)
	D	resde	en Nu	clear Pov	ver Stat	ion U	nit 3				0  5   0   0	10121419	1 OF Q
TITLE (4										SE FEE			
ev.	ENT DATE		or No	t Vented		-		the second second	e Les		The second secon	tion Tempe	rature
MONTH	1	YEAR	YEAR	SEQUENTIA	197	MONTH	DAY DAT	YEAR		FACILITY NAM	FACILITIES INVO	DOCKET NUMBER	(4)
MUNTH	UAT	TEAR	TEAN	NUMBER	NUMBER	MONTH	UAT	TEAR					
017	1 h	8 4		O O O O	0 8		8 4	INTS OF 10	CER 8: 10	Check one or more o	f the followings (1	0   5   0   0	
	ODE (9)	N		402(b)		20,406	-		3	50.73(a)(2)(iv)	· · · · · · · · · · · · · · · · · · ·	73.71(b)	
POWE			20.	406(+)(1)(i)		60.36(c)	(1)			50.73(a)(2)(v)		73.71(e)	
(10)		1010	20.	405(a)(1)(ii)		50.36(c)	(2)			50.73(a)(2)(vii)			cify in Abstract
			20.	406(a)(1)(iii)	X	50.73(a)	(2)(1)			50.73(a)(2)(viii)(A	0	366A)	Text, NHC Form
			20.	405(a)(1)(IV)		50.73(a)	(2)(8)			50.73(e)(2)(viii)(8	)		
			20.	405(a)(1)(v)		50.73(a)				50.73(a)(2)(x)			
NAME					- 1	ICENSEE	CONTACT	FOR THIS	LER (12)				
The same											AREA CODE	TELEPHONE NUMB	ER
	T	im Wo	jtul	ewicz				(X-	523)			0 ./ . 2	2 . 0 . 2 . 0
				COMPLETE	ONE LINE FOR	EACH CO	MPONENT	FAILURE	DESCRIBE	D IN THIS REPORT	8 1 5	19 4 2 -	2   9   2   0
CAUSE	SYSTEM	сомро	DNENT	MANUFAC- TURER	REPORTABLE TO NPROS				SYSTEM	COMPONENT	MANUFAC TURER	REPORTABLE TO NPROS	

ABSTRACT (Limit to 1400 speces i.e., approximately fifteen single-space typewritten lines) (16)

YES III yes, complete EXPECTED SUBMISSION DATE!

SUPPLEMENTAL REPORT EXPECTED (14)

With the reactor locked in shutdown since early April, 1984, for turbine work, the shift Control Room Engineer observed that the reactor vessel was not vented at less than 149°F. Reactor pressure was 0 psig, and reactor vessel level was +308 inches at the time of this observation.

YEAR

EXPECTED SUBMISSION DATE (15)

TE22

This event was the first violation of the Tech Spec (3.5.B.1) venting requirement at Dresden.

Upon discovery of the violation, reactor metal temperature was increased.

This event was of minimal safety significance, since no control rod drive pump was running, and one condensate pump was running. Both recirculation pumps were running to maintain reactor water temperature between 130° to 149°F. If the reactor vessel was inadvertantly pressurized, reactor temperature was above the 100°F minimum temperature required for an inservice pressure test. Operating personnel will be reminded of procedure requirement during the Operator training week. Possibility of Tech Spec change is being investigated to prevent recurrence.

8408130146 840803 PDR ADOCK 05000249 S PDR

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-0104

Dresden Nuclear Power Station Unit 3 0 15 10 10 10 1 2 14 19 8 14 0 0 6 0 1 0 1 2 2	AGE (3)	(3)	(3)	1)	-	-	-	-	-	-	-	-	-	-	-	-	31	3	0	E	GF	40	A	P /	p		_	-	-	-	_	T	-	-	-	-	-	-	_	-	-	)	(6)	A I	EF	ABI	JM	NU	ER	LI	-	_	_	-	T		_	_	-	-	(2)	9 (2	EA	48	UA	N	ET	KE	oc	00	1	_	-	_	_	_	-	_	_			-	_		_	_	-					-	_		_	_											Ī					-					Ī											_				7			7	100					18
Dresden Nuclear Power Station Unit 3 0  5  0  0  0  2  4  9 8  4 _ 0 0 6 _ 0 1 0   2		T	Γ																I		-		T	7	-	_	-		-			+	2 0	ON	38	510	Ma Ma	EVE	RE			I	L	A	SE.	E N	UN	EQU	5		T	R	AP	YE	L																																																																																						
	OF O	F (	C	0	)	6					1	1			)	)	0	1		F	0	C		2	2	-		1	1	0	0		1	1	1	1	)1	0		-	_	1.	6		q	.(	)	0		_		4	4	8		9	4	14	2	i	0	1	0	1	0	1	5	5	1	0		3		t	ii	Ur	ι	1	n	or	ic	at	ta	St	5		r	er	re:	we	OW	0	P	P	I		r	r	ar	a	2 8	e	e	le	16	1	: 1	: ]	c ]	c	c	c	c	c	2	: ]	1	1	1	Le	e	e	e	e	e	e	26	0	a	a	a	a	aı	a 1	11	ır	ır	ır	ır	ır	ır

With the reactor vessel locked in shutdown the shift Control Room Engineer observed that the reactor vessel was not vented at less than 149°F. This event was a violation of the venting requirement in Technical Specification 3.6.B.1. The reactor metal temperature was increased by increasing reactor water temperature.

The cause of this event was an inadvertant procedure violation. During shutdowns of long duration it is desirable to leave the head vent closed to prevent the introduction of additional contamination into the drywell.

All licensed operators will be reminded of the venting requirement when less than 149°F during the Operating training week.

This event was of mirimal safety significance since no control rod drive pump was running, and one condensate pump was running. Both recirculation pumps were running to maintain reactor water temperature between 130° to 140°F. If the reactor vessel was inadvertantly pressurized, reactor temperature was above the 100°F minimum temperature required for an inservice pressure test. Investigation into the basis for the Tech Spec requirement indicates that at conditions which existed, the 149°F is conservative. CECo Technical Services personnel indicated that no adverse effect occurred as a result of this event. Therefore, Dresden Station is investigating the feasability of changing the venting requirement in Technical Specification 3.6.B.1 which would prevent recurrence.

This event is the first violation of the Technical Specification (3.6.B.1) venting requirement at Dresden.

August 7, 1984

DJS Ltr #84-780

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Licensee Event Report #84-006-0, Docket #050249 is being submitted as required by Technical Specification 6.6, NUREG 1022 and 10 CFR 50.73 (a)(2)(i)(B).

D/J. Scott

Station Superintendent

Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: J.G. Keppler, Regional Administrator, Region III
File/NRC
File/Numerical

IEZZ