

LICENSEE EVENT REPORT

EXHIBIT A

LER No. 50-313/80-040/99X-1

Occurrence Date: 10/01/80

Cause Description and Corrective Actions (Continued)

(2) plant preheatup containment integrity checklists were revised to include local leak rate connections on hatches.

Final corrective action included implementation of a design change which added isolation valves replacing test connection nipples and caps for the emergency hatch. This design change was completed on 6/23/81.



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

August 3, 1984

1CAN088403

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Arkansas Nuclear One - Unit 1
Docket No. 50-313
License No. DPR-51
Licensee Event Report
No. 80-040/99X-1

Gentlemen:

Attached is an informational report concerning the local leak rate test connections to the reactor building emergency hatch, which had been found uncapped during plant operation. This is an update to a previous submittal dated November 19, 1980.

Very truly yours,

A handwritten signature in cursive script that reads "John R. Marshall".

John R. Marshall
Manager, Licensing

JRM:RJS:ac

Attachment

cc: Mr. Richard C. DeYoung
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Norman M. Haller, Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, DC 20555