

PRELIMINARY NOTIFICATION

March 1, 1977

S. L. [Signature]

PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE--PNO-77-35

This preliminary notification constitutes EARLY notice of an event of Possible safety or public interest significance. The information presented is as initially received without verification or evaluation and is basically all that is known by IE staff on this date.

Facility: Consumers Power Company (Midland Unit 2)
(Docket No. 50-330) Midland, Michigan

Subject: BULGE IN CONTAINMENT LINER PLATE

A bulge was discovered in the containment liner plate at approximately 11:00 p.m., February 26, 1977, during a routine weekend walk through of the construction area. The containment liner was separated from the concrete by a maximum of three feet in an area approximately 20 feet wide and 107 feet high. The liner plate had pulled away from penetration areas and water was observed coming through tears in the liner plate.

Additional holes were cut in the liner plate to facilitate draining; however, water continued to flow. The construction water supply was then valved off and the drainage stopped.

The source of the water is reported to have been the 2-inch construction water line imbedded in the concrete. This water supply is used primarily to wet down the concrete during the curing process.

Three holes, 12 inches wide and 24 inches high, were cut in the bulge to inspect for damage. Concrete was observed to have been pulled out by the angle iron imbedments that are welded to the liner plate. The extent of the damage and the impact on the construction schedule is not known at this time. Region III dispatched an inspector to the site on Monday, February 28, and will follow this event closely.

Local press interest is anticipated due to the current public hearing regarding continuation of the Construction Permit. The licensee has issued a press release.

Region III received notification of this occurrence from the Project QA Administrator of Consumers Power Company at 1:15 p.m., February 28, 1977. This information is current as of 10:00 a.m., March 1, 1977.

Contact: RFWarnick, IE x27261 GWRoy, IE x27261 DThompson, IE x27541

Distribution:

Chairman Rowden	Commissioner Kennedy	S. J. Chilk, SECTY
Commissioner Gilinsky	C. C. Kammerer, CA	G. F. Murphy, JCAE
L. V. Gossick, EDO	K. R. Chapman, NMES	R. G. Ryan, OGP
S. H. Henauer, EDO	E. Volgenau, OIE	J. A. Harris, PA
B. C. Rusche, NRR	H. K. Sharpe, ELD	T. J. McTiernan, OA

Transmitted: PBldg 1:05P; H St. 1:06PM; ss 1:08P; Land 1:08P

Reg. III / 1:10

PRELIMINARY NOTIFICATION

8408150694 840718
PDR FOIA
RICE84-96


PDR

rec'd 12:20 3/1/77 b/c

NONCONFORMANCE REPORT

1. Date:	1-1-64	2. Job No.:	7020	3. Drawing Part No.:	R-1	4. Nonconformity:	Welded Joint	5. Nonconformity:	Welded Joint
6. Serial No.:	7520-111	7. Serial No.:	7520-111	8. Replaces Part No.:	R-1	9. Replaces Part No.:	R-1	10. Contact/Author:	
11. Part Description:	Reinforcing Bar	12. Part Description:	Reinforcing Bar	13. Search:	SEARCHED	14. Reviewed By:			
15. Spec. Source:	Other	16. Spec. No.:	Other	17. Date:	10-10-63	18. Date:	10-10-63		
19. Description of Nonconformance: The liner plate in Container No. 7020-60 separated away from the exterior wall concrete (at above boundaries). The separation ranged up to one inch by 6.0 feet.									
20. Analysis of the concrete occurred during the inspection, no plastic #4, 109.									
21. Cause Applied, Held for Engineer's Inspection.									
22. Corrective Action Taken:									
23. Disposition:									
24. Remarks:									
25. Signature:									

Unit 2



~ 108' high
~ 20' wide

1/4 liner plate

3/16" weld

channel
5 [6.7

L $3 \times 2 \times \frac{1}{4}$

Spaced ~ 14"


13^A x 2000


96,000

Liner plate + L iron spliced from the channel

@ 11:00 pm

Problem identified: 2/26/77 Sat. by Reactor
 Reported to CP on 2/27/77 @ 11:00 am
 - Cf 58 55(e) report to NRC III 2/28/77 @ 1:15 pm





Proj. Eng.-A²


AAC

R. Castleberry - P.E. ↗
J. Hink A.P.E.
B. Dhar ↗
T. Thirugavaram ↗

K. Wiedner ENG. MGR.
Fred Meyer - CHIEF CIV. ENGR.
M. Elgaly - CIVIL STAFF ENGR
Civil Des Engrs

S. F. OFFICE



Howard Wahl - MGR. OF ENGINEERING
Ted Johnson - SUPV. - ~~CONTAINMENT DESIGN GROUP~~
~~SPEC. STRUCTURES GROUP~~




SUNDAY FEB 27, 1977

9

1145 REC'D CALL @ HOME FROM JFH @ SITE
LINER PLATE, RBII HAS LARGE BUCKLE
OR BUBBLE NEAR 260° AZIMUTH
IMMEDIATELY WENT TO SITE & OBSERVED:



BUBBLE DAMAGE
CROSS SECTION AND
SECTION OF LINER
GIRT TOOK LOOSE @ 670°
ABOUT 12' HORIZONTAL



PROFILE OF DAMAGE
BUBBLE STARTS ABOUT 15' ABOVE
WIND GIRT
Some CONCRETE SPALLING (O.Holman-Bechtel)
Some HOLES IN PLATE WHERE L
STIFFENER TOOK LOOSE
WATER STREAMING OUT SOME HOLES
PENETRATION HOLE PLATE BACK SOME
NEAR BOTTOM

1207 INFORMED Project Manager and QA (J.L.Conley)
1225 Conley @ SITE

Bechler pipe watch who detected this about
2300 hrs on 2-26-77 (LAST NIGHT)
Newgen notified Weidner, PASTLICERITY, Bechler,
Conley and Hermiston

Joint telecon - Conley & Conley to HHI SASCAL
1320 Depart Site

CC Cole