

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Browns Ferry - Units 1, 2, and 3 DOCKET NUMBER (2) 0 5 0 0 0 2 5 9 1 OF 0 2 PAGE (3)

TITLE (4) Design Oversight on Load Shed Logic and Single Failure Criteria

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
05	12	84	84	022	02	08	08	84	Browns Ferry - Unit 2		05000260
									Browns Ferry - Unit 3		05000296

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 8. (Check one or more of the following) (11)

OPERATING MODE (9) N	20.402(b)	20.408(c)	80.73(a)(2)(iv)	73.71(b)
POWER LEVEL (10) 0916	20.408(a)(1)(i)	80.36(a)(1)	80.73(a)(2)(v)	73.71(a)
	20.408(a)(1)(ii)	80.36(a)(2)	80.73(a)(2)(vii)	<input checked="" type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 305A)
	20.408(a)(1)(iii)	80.73(a)(2)(i)	80.73(a)(2)(viii)(A)	Part 21
	20.408(a)(1)(iv)	<input checked="" type="checkbox"/> 80.73(a)(2)(ii)	80.73(a)(2)(viii)(B)	
	20.408(a)(1)(v)	80.73(a)(2)(iii)	80.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12) NAME: Jimmy B. Walker TELEPHONE NUMBER: 21057291-10865

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUF. TURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUF. TURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14) YES (If yes, complete EXPECTED SUBMISSION DATE: 01 01 85) NO

ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single space typewritten lines) (15)

An IE Bulletin 79-01B investigation determined that a single failure or a loss of coolant accident and a loss of offsite power, could cause equipment necessary for electrical board room cooling to be lost. The cause of this condition is a design oversight.

Single failure of a distribution board could cause the loss of redundant cooling equipment in some electrical board rooms. During a loss of coolant accident in conjunction with loss of offsite power, normal ventilation for electrical board rooms is load shed with no provisions for manual restart.

As interim corrective measures, operating instructions have been revised to allow for restarting the necessary equipment within one hour by using electrical jumpers and/or mechanically providing an exhaust air duct opening. Long-term corrective action is under evaluation and proposed changes will be addressed in a followup report by January 1, 1985.

8408160508 840808
PDR ADOCK 05000259
S PDR

IE22
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Browns Ferry - Units 1, 2, and 3	0 5 0 0 0 2 5 9 8 4	-	0 2 2	-	0 2	0 2 OF 0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Unit 1 was operating at 96 percent power, unit 2 was operating at 59 percent power, and unit 3 was in a refueling outage. All three units were affected by this event.

On May 12, 1984, during IE Bulletin 79-01B evaluations, it was determined that during a loss of coolant accident in conjunction with loss of offsite power (EK), necessary cooling equipment for some electrical board (BD) rooms for units 1 and 2 could be lost. Because of a design error, the normal exhaust fans (FAN) (common to board rooms "A" and "B" on unit 1, and board rooms "C" and "D" on unit 2) are automatically and permanently load shed (ED) from their power supply upon receipt of an accident signal (LOCA) and concurrent loss of offsite power. This condition would not affect unit 3 electrical board room cooling, because unit 3 has no comparable load shed logic contacts.

A single failure of a 480V reactor motor operated valve board (RMOV) (ECBD) (1A, 2A, or 3A) causes the loss of redundant cooling equipment for some electrical board rooms. The equipment affected is the normal exhaust fan (1A board affects electrical board rooms A and B; 2A board affects electrical board rooms C and D; 3A board affects electrical board rooms 3A and 3B) and the emergency air-conditioners (ACU) for electrical board rooms A, C, and 3A. This is contrary to Final Safety Analysis Report, Section 10.12.5. (Note: Room cooling is dependent upon either the exhaust fan or the emergency air-conditioner.)

The Plant Operating Instruction - 57, and Emergency Operating Instruction - 36 were revised May 12, 1984 for operating units 1 and 2, and June 15, 1984 for outage unit 3 (cycle 5 refueling outage) to include appropriate action to be taken upon loss of the cooling units listed above. The instruction options include jumpering the 480V load shed logic contacts on the units 1 and 2 fans affected within the first hour of losing ventilation, and/or providing an exhaust path in the exhaust fan ductwork following the loss of a 480V RMOV BD (1A, 2A, or 3A) (DUCT).

Analysis shows that all essential equipment in the electrical board rooms would function for one hour during which time the above operator action would be necessary.

It is anticipated that long-term corrective action will consist of correcting the load shedding logic, separating the power sources for electrical board room cooling equipment, and making various changes to provide environmental qualification of the ventilation equipment. The proposed changes will be addressed in a followup report by January 1, 1985.

This event is deemed Part 21 reportable. TVA, Office of Engineering, is the designer of the electrical board room cooling system.

Responsible Section - ED

Previous Similar Events - None

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

Browns Ferry Nuclear Plant

P. O. Box 2000

Decatur, Alabama 35602

August 8, 1984

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555


Dear Sir:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT BFRO-50-259/84022 R2

The enclosed updated report provides information concerning Part 21
reportability. Subsequent review of this event reveals that it should be
noted as Part 21 reportable. This report was initially submitted in
accordance with 10 CFR 50.73 (a)(2)(ii).

Very truly yours,

TENNESSEE VALLEY AUTHORITY



G. T. Jones
Plant Manager
Browns Ferry Nuclear Plant

Enclosure

cc (Enclosure):
Regional Administrator
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 2900
Atlanta, GA 30303

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

NRC Resident Inspector, BFN

IG22
11