#### CRACK MAPPING MONITORING STATUS

DATE	ITEM	CORRECTIVE ACTION	SCHEDULED RESOLUTION DATE
10-31-83	Delay in WJE identifying alert level to RSE	QAR RS-00051 issued 10-31-83. Procedure revised, information put on printed form, and training of WJE personnel	11-29-83 closed
	5dw		
11-4-83	NIR #16 issued- WJE procedure not conforming to specification	QAR RS-00061 issued 11-9-83. WJE procedure not conforming to specification while work activities performed	11-23-63
		Procedures revised to bring procedure in compliance with specification	
11-7-83	MORAN OF CTACK Mepping process indicated that QC/QA	Complete QC Inspections	? 11-29-83
	inspections and overview were incomplete for crack mapping	Initiate QA over inspections	
		Review procedure and PQCI to determine corrective action required such as: a. time restraint	
		b. receipt of documents c. formal notification when mapping is requested	
		Review all other PQCIs for similar problems with SCM-1.0	11-21-83

DATE	ITEM	CORRECTIVE ACTION	RESOLUTION DATE
11-09-83	Initiate inspection process of crack mapping to bring up to date.  Ross & public Meeting Meeting Meeting with QA, QC, Resident Engineering, SMO to resolve crack mapping issues - discuss steps to be taken to resolve immediate issue and preclude recurrence.	Crack Mapping Action Item List issued to easign responsibilities.	
11-14-83	Reorganize QC Yard Group	Instructed QC inspection staff on the importance of crack mapping monitoring and the need to maintain inspection close to mapping time	11-14-83
		pod Bennett  replaced  replaced with  replaced with	P 11-23-83

Page 2 of 4

SCHEDIR PD

ITEM	CORRECTIVE ACTION	SCHEDULED RESOLUTION DATE
MIR #18 immued-Wall not properly marked	QAR RS-00069 issued for for walls not marked properly	
	(Removal of "grafitti" removed crack mapping marks)	
WJE procedures for crack mapping and SCN 13007 issued for review		
PQCI revision initiated for process controls and procedure revisions		12-1-83
Meeting CPCo, Soils Management, Resident Engineering, SMO, MPQAD Soils and Stone and Webster	Provide updated status of corrective action	
Coordinated logging system for checking MJE mapping submittals to RSE and MPQAD Soils and establish completion dates	Complete MPQAD log and check status with RSE, log of crackmapping	11-29-83
NIR #19 issued- Lack of QA/QC inspection	QAR RS-00077 issued 11-29-83 lack of QA overinspection	
	All other previous corrective action noted for QC corrective action.	\$
	WJE procedures for crack uspping and SCN 13007 issued for review  PQCI revision initiated for process controls and procedure revisions  Meeting CPCo, Soils Management, Resident Engineering, SMO, MPQAD Soils and Stone and Webster  Coordinated logging system for checking WJE mapping submittals to RSE and MPQAD Soils and establish completion detes	WIR #18 insued-Wall not properly marked  QAR RS-00069 issued for for walls not marked properly  (Removal of "grafitti" removed crack mapping marks)  WJE procedures for crack mapping and SCN 13007 issued for review  PQCI revision initiated for process controls and procedure revisions  Heeting CPCo, Soils management, Resident Engineering, SMO, MPQAD Soils and Stone and Webster  Coordinated logging system for checking WJE mapping submittals to RSE and MPQAD soils and establish completion detes  NIR #19 issued-Lack of QA/QC inspection  All other previous corrective action noted for QC corrective

Page 3 of 4

DATE	wew ITEM	CORRECTIVE ACTION	RESOLUTION DATE
11-28-82	W.JE Site Engineering Lead brought on site full time	Site Engineering Lead assigned full time to review monitoring activities and all data.	
11-29-83	QC completed all inspections for WJB mapping through October 1983	57 NCRs and 3 QARs issued 57 QC. Evaluate and resolve the nonconforming conditions.	
11-30-83	Prepare draft revision WJE crack mapping procedures and specification change notice	Revision of WJE crack mapping procedures to correct other deficiencies and NCR trend problems identified by MPQAD Soils.	1012

Page 4 of 4



# Work parize 59 respond after I reviewed it

Grillage acceptance criteria

- 1. 20% strain
- 2. settlement of building Twitine settlement of building Twitine settlement of building settlements/48hr
- 3. act of Window





## Dec. 8 Solw Public Meeting

CIO

#23, p.4, what are monitors? No Answr From anyone

SOILS

SHW (STAN)

1ST SHW (STAN)

Of report

Of report

1. 59-17 Carlsons (Form reproval)

2. FER/FON Roview 208/856 problems

200 STATUS OF WHAT HAPPENED (NAYNE)

· evalt mapping

· work ativity pakages

- review old reports 1.29



### · FER/FON STOP WORK



300 SOW REPORT (BILL CRAIG) 384 ACTION ITEMS
INFEPORT MAKES

viatabout BOP For 142 jecommondations

Twhere was MPRAP
Rebutted on Stan

47H Action Itans from lat month, CRG's

1. U.S. Facting is improving

Time to do my own audit.

2. Truck Prun Rotation

3. lessons learned from aux to swps
by Janzoth 84 will be
completed

4. ac inspection of non-Athelding



# only for Jack stands tact welds to hold than in place

5. CRACK MAPPING

Delays, Speculfroredure discrepancies

Lack 3

allon lovel 1 now CHECK on site

where was fraudit function [24RS]

Reports

59-17 open NCR'S ON W8 11-3-83 opened

They only have concepts in them, who caves.



## Work partage 59 respond after I reviewed it

[grillage acceptance criteria]

- 1. 20% strain
- 2. settlement of building Tax bue somits/48hr
- 3. act of Window



. 1	1-30-83 phone call money, Whieler, Pon, Bruce
(Nac	h issue
	to of worms, coult get a back into ean (Jim 808)
(1) b	iscussed fax.
MY	Bottom lime  a) aver all buildings mapped up to date - will be it  b) has there been an engineering analysis - will be if
(3) 7	heir bottom line vs procedures revised dissued
	Spec "  PACI  "
	closed Nek
	evaluate QAR
1000	will not start work intil all completed.



General Offices: 1945 West Pernall Road, Jackson, MI 49201 \* (517) 788-0774

December 2, 1983

Mr J J Harrison Midland Project Section U S Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDLAND ENERGY CENTER GWO 7020 CRACK MAPPING MONITORING STATUS File: 0485.16 UFI: 42\*05\*22\*04 Serial: CSC-7057

On November 30, 1983, CPCo provided Region III with an update relative to crack mapping monitoring status. The attached chronology entitled <u>Crack Mapping Status</u> was used to explain the various significant actions/events associated with crack monitoring.

Prior to resuming soils work the following actions will be completed:

- 1. WJE procedures will be revised and reissued.
- 2. The specification will be revised and issued.
- 3. The PQCI's will be revised and issued.
- 4. The 57 NCR's will be closed.
- 5. The 3 QAR's will be resolved.

If you require any further information please advise our Mr. R. M. Wheeler.

Somowney

JAM/RMW/klw

Attachment

Midland Project Office

J A Mooney Executive Manager

PRINCIPAL STAFF

RA\* DPRP

D/RA DE

A/RA DPMSP

RC DRMA

PAO SCS / Light

ENF File


8312120346

DEC 7 1983

#### CRACK MAPPING MONITORING STATUS

DATE	ITEM	CORRECTIVE ACTION	RESOLUTION DATE
10-31-83	Delay in WJE identifying alert level to RSE	QAR RS-00051 issued 10-31-83. Procedure revised, information put on printed form, and training of WJE personnel	11-29-83 closed
11-4-83	NIR #16 issued- WJE procedure not conforming to specification	QAR RS-00061 issued 11-9-83. WJE procedure not conforming to specification while work activities performed	11-23-83
		Procedures revised to bring procedure in compliance with specification	
11-7-83	Review of crack mapping process indicated that QC/QA inspections and overview were incomplete for crack mapping	Complete QC Inspections  Initiate QA over inspections  Review procedure and PQCI	11-29-83
+		to determine corrective action required such as: a. time restraint b. receipt of documents c. formal notification when mapping is requested	
		Review all other PQCIs for similar problems with SCM-1.0	11-21-83

DATE	ITEM	CORRECTIVE ACTION	SCHEDULED RESOLUTION DATE
11-09-83	Initiate inspection process of crack mapping to bring up to date.		
11-11-83	Meeting with QA, QC, Resident Engineering, SMO to resolve crack mapping issues - discuss steps to be taken to resolve immediate issue and preclude recurrence.	Crack Mapping Action Item List issued to assign responsibilities.	
11-14-83	Reorganize QC Yard Group	Instructed QC inspection staff on the importance of crack mapping menitoring and the need to maintain inspection close to mapping time	11-14-83
		QC Yard Group Supevisor to be replaced	11-23-83



DATE	ITEM	CORRECTIVE ACTION	SCHEDULED RESOLUTION DATE
11-17-83	NIR #18 issued-Wall not properly marked	QAR RS-00069 issued for for walls not marked properly	
		(Removal of "grafitti" removed crack mapping marks)	
	WJE procedures for crack mapping and SCN 13007 issued for review		
11-21-83	PQCI revision initiated for process controls and procedure revisions		12-1-83
11-22-83	Meeting CPCo, Soils Management, Resident Engineering, SMO, MPQAD Soils and Stone and Webster	Provide updated status of corrective action	
	Coordinated logging system for checking WJE mapping submittals to RSE and MPQAD Soils and establish completion dates	Complete MPQAD log and check status with RSE, log of crackmapping	11-29-83
11-23-83	NIR #19 issued- Lack of QA/QC inspection	QAR RS-00077 issued 11-29-83 lack of QA overinspection	
		All other previous corrective action noted for QC corrective action.	

S	CH	IED	UL	ED	
RES	OL	UT	10	N	DATE

DATE	ITEM	CORRECTIVE ACTION
11-28-83	WJE Site Engineering Lead brought on site full time	Site Engineering Lead assigned full time to review monitoring activities and all data.
11-29-83	QC completed all inspections for WJE mapping through October 1983	57 NCRs and 3 QARs issued by QC. Evaluate and resolve the nonconforming conditions.
11-30-83	Prepare draft revision WJE crack mapping procedures and specification change notice	Revision of WJE crack mapping procedures to correct other deficiencies and NCR trend problems identified by MPQAD Soils.



General Offices: 1945 West Pernall Road, Jackson, MI 49201 \* (517) 788-0774

November 22, 1983

Mr J J Harrison Midland Project Section U S Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDLAND ENERGY CENTER GWO 7020 WORK AUTHORIZATION PROCEDURE FILE: 048516 UEL: 42\*

FILE: 048516 UFI: 42\*05\*22\*04,12\*32

SERIAL: CSC-7027

PRINCIPAL STAFF

RA DPRP

D/RA DE

A/RA DRMSP

RC DRMA

PAO SCSV orig † 3

Eirr File

J A Mooney

Executive Manager

Midland Project Office

This letter documents the November 16, 1983 phone conversation between R. Wheeler of CPCo and Dr. R. Landsman of NRC Region III. As part of the work package for Activities 165054045 and 155054045 (Piers CT1 & CT12), Dr. Landsman reviewed the soil stabilization grouting plan for the control tower area. Therefore, CPCo may proceed with the soil stabilization as required for both piers CT1/12 and the remainder of the control tower. The sequencing of this grouting will be done for the convenience of construction, but at no time will drifts in this area proceed in unstabilized soil that has not been approved by the RGE. Actual pier and drift excavations for piers beyond CT1/12 will be authorized by Region III in accordance with the Work Authorization Procedure. Dr. Landsman concurred with the authorization of the soil stabilization under the previously authorized activities.

JAM/RHW/p1



#### UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

November 21, 1983

Docket Nos: 50-329 OM, OL and 50-330 OM, OL

MEMORANDUM FOR: The Atomic Safety and Licensing Board for

the Midland Plant, Units 1 and 2

FROM:

Thomas M. Novak, Assistant Director

for Licensing

Division of Licensing

SUBJECT:

BOARD NOTIFICATION REGARDING MIDLAND AUXILIARY

BUILDING UNDERPINNING (BN 83-174)

This Notification is provided in accordance with NRC procedures regarding Board Notifications and is deemed to provide new information material and relevant to safety issues in the OM-OL proceeding. On September 14 and 15, 1983, the NRC and its consultants audited revised calculations for the design adequacy of the Midland Auxiliary Building reflecting the results of an underpinning pier load test. The test results had indicated that the soil modulus for the base of the underpinning should be 1500 KSF rather than the 3000 KSF used in the original analysis; thus, Bechtel revised its structural analysis using \( \frac{1}{2} \)" of settlement rather than \( \frac{1}{2} \)". The audit meeting was summarized by R. Warnick's letter of October 5, 1983, and copies were provided to the ASLB and hearing parties. During the course of this audit, the NRC received additional information which calls into question the validity of the assumptions upon which the staff's acceptance of the underpinning design was based. The additional information is reflected in paragraphs d, e and g of R. W. Warnick's memorandum of October 11, 1983 (Enclosure 1). The information concerns (1) the manner in which differential settlement has been applied in the applicant's structural stress calculations, (2) the absence of limits for upward movement of the structure during jacking operations, (3) the acceptability of the actual measured upward movement due to jacking, and (4) the extent to which settlement stresses can be jacked out of the completed structure.

Paragraph d of Enclosure 1 notes that the stress calculations for 1" of differential settlement at the southern edge of the Control Tower results from a settlement gradient that begins at the center of the main Auxiliary Building, rather than a point at the northern edge of the Control Tower. Application of the i" gradient over this longer distance is inconsistent and non conservative with respect to the prior review performed by the staff which led to acceptance of the 1" differential settlement in Supplement 2 to the SER, page 2-40. The staff is presently evaluating the effects of this recent information and believes a solution can be reached by establishing a future differential settlement limit in the Technical Specifications that will be based on field monitoring records. The limit to be established will assure the integrity of the involved structures.

334010021

Paragraphs e and g of Enclosure 1 call into question 1) what should be the upward movements of the structures during jacking operations and 2) whether or not the stresses due to settlements prior to and during underpinning construction can be completely jacked out of the completed structure. With respect to the upward movements, the staff understands that the east EPA has been jacked to 91 mils of upward movement and the west EPA has been jacked to 70 mils. Upward movement in excess of 30 mils has not been reviewed by the staff. On the issue of stresses due to settlement, and underpinning operations, the allowable jacking loads are limited by a concern for redistribution of stresses following upward movement of the structures. The applicant's analysis, relied upon by the staff, assumed no significant residual stress due to earlier settlements for the completed underpinned structure and, therefore, may not be sufficiently conservative. We understand that Region III has verbally imposed a hold on further jacking in excess of that previously reviewed by the NRC staff pending establishment of allowable jacking limits.

The issues associated with this and other information from the September design audit are presently being reviewed by NRR in accordance with R. Warnick's request by Enclosure 1. The staff's response to Enclosure 1, once available, will be provided to the Board.

Thomas M. Novak, Assistant Director for Licensing

Division of Licensing

Attachment:

R. Warnick memo dated October 11, 1983.

cc: See next page

#### DISTRIBUTION LIST FOR BOARD NOTIFICATION

#### Midland Units 182, Docket Nos. 50-329/330

Charles Bechhoefer, Esq. Ms. Lynne Bernabei Lee L. Bishop, Esq. James E. Brunner, Esq. Dr. John H. Buck Myron M. Cherry, P.C. Dr. Frederick P. Cowan T. J. Creswell Steve J. Galder, P.E. Dr. Jerry Harbour Mr. Wayne Hearn Mr. James R. Kates Frank J. Kelley, Esq. Christine N. Kohl, Esq. Mr. Howard A. Levin Mr. Wendell H. Marshall Michael I. Miller, Esq. Thomas S. Moore, Esq. Mr. Paul Rau Ms. Mary Sinclair Ms. Barbara Stamiris Frederick C. Williams, Esq.

Atomic Safety and Licensing Board Panel Atomic Safety and Licensing Appeal Panel Docketing and Service Section Document Management Branch

#### ACRS Members

Dr. Robert C. Axtmann Mr. Myer Bender Dr. Max W. Carbon Mr. Jesse C. Ebersole Mr. Harold Etherington Dr. William Kerr Dr. Harold W. Lewis Dr. J. Carson Mark Mr. William M. Mathis Dr. Dade W. Moeller Dr. Milton S. Plesset Mr. Jeremiah J. Ray Dr. David Okrent Dr. Paul C. Shewmon Dr. Chester P. Siess Mr. David A. Ward

MIDLAND (For BNs)

Mr. J. W. Cook Vice President Consumers Power Company 1945 West Parnall Road Jackson, Michigan 49201

cc: Stewart H. Freeman
Assistant Attorney General
State of Michigan Enviornmental
Protection Division
720 Law Building
Lansing, Michigan 48913

Mr. Paul Rau Midland Daily News 124 McDonald Street Midland, Michigan 48640

Mr. R. B. Borsum Nuclear Power Generation Division Babcock & Wilcox 7910 Woodmont Avenue, Suite 220 Bethesda, Maryland 20814

Mr. Don van Farrowe, Chief Division of Radiological Health Department of Public Health P.O. Box 33035 Lansing, Michigan 48909

U.S. Nuclear Regulatory Commission Resident Inspectors Office Route 7 Midland, Michigan 48640

Mr. Paul A. Perry, Secretary Consumers Power Company 212 W. Michigan Avenue Jackson, Michigan 49201

Mr. Walt Apley
c/o Mr. Max Clausen
Battelle Pacific North West Labs (PNWL)
Battelle Blvd.
SIGMA IV Building
Richland, Washington 99352

Mr. I. Charak, Manager NRC Assistance Project Argonne National Laboratory 9700 South Cass Avenue Argonne, Illinois 60439 James G. Keppler, Regional Administrator
U.S. Nuclear Regulatory Commission,
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Mr. Ron Callen
Michigan Public Service Commission
6545 Mercantile Way
P.O. Box 30221
Lansing, Michigan 48909

Geotechnical Engineers, Inc. ATTN: Dr. Steven J. Poulos 1017 Main Street Winchester, Massachusetts 01890

Billie Pirner Garde
Director, Citizens Clinic
for Accountable Government
Government Accountability Project
Institute for Policy Studies
1901 Que Street, N.W.
Washington, D. C. 20009

Commander, Naval Surface Weapons Center ATTN: P. C. Huang White Oak Silver Spring, Maryland 20910

Mr. L. J. Auge, Manager Facility Design Engineering Energy Technology Engineering Center P.O. Box 1449 Canoga Park, California 91304

Mr. Neil Gehring
U.S. Corps of Engineers
NCEED - T
7th Floor
477 Michigan Avenue
Detroit, Michigan 48226

ATTN: Clyde Herrick Frenklin Research Center 20th & Race Streets Philidelphia, Pennsylvania 19103

Mr. Patrick Bassett
Energy Division
Norwest Bank Minneapolis, N.A.
8th and Marquetts
Minneapolis, MN 55479



### UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

OCT 1 1 1989

MEMORANDUM FOR:

D. G. Eisenhut, Director, Division of Licensing, NRR

FROM:

R. F. Warnick, Director, Office of Special Cases

SUBJECT:

NRC AUXILIARY BUILDING AUDIT

On September 14 and 15, 1983, an NRC team comprised of Messrs. J. Kane and F. Rinaldi of NRR; Mr. R. Landsman of RIII and Consultants S. Poulous and G. Harstead, audited the licensee reanalysis of the Midland Auxiliary Building. This audit was performed at the Bechtel Office in Ann Arbor, Michigan. As a result of the audit, the team identified several design concerns and issues requiring resolution. These are referred to the Office of Nuclear Reactor Regulation for action as appropriate.

- a. The design of the remedial soils slab fix at Elev. 659 (i.e. the eye bars) was performed to ACI 318 and not to ACI 349. The acceptability of the licensee's decision to use ACI 318 in lieu of ACI 349 needs to be evaluated.
- b. In view of the critical nature of the eye bars, the question arose as to the need for some type of monitoring on this fix (i.e. strain gages) due to the anticipated settlement over the life of the plant. Do monitoring requirements need to be imposed?
- c. Because of the anticipated differential settlement expected to occur during the life of the plant, the control tower will be pulling away from the main auxiliary building. Has the mechanical branch determined that equipment between the two buildings can withstand this elongation?
- d. The licensee performed an analysis on differential settlement of the buildings that was different from that which the NRC anticipated. The staff expected the differential settlement to be measured between the edge of the main auxiliary building and the edge of the control tower. In reality, the licensee performed an analysis using the center of the main auxiliary building as one point instead of the edge. Thus, for the requested 0.25" differential settlement analysis, the actual value was 0.17", and for the requested 0.50" differential, the actual value was 0.24". Is the licensee's analysis acceptable to NRR?
- e. There appears to be a lot of confusion as to what upward building movements the licensee and NRC staff should allow during underpinning. What are the allowable upward movements during jacking operations?
- f. The licensee stated that existing structures were analyzed according to ACI 318 as agreed to with NRR. The SSER #2 states that the buildings have been checked against ACI 349. Is this acceptable to NRR?

844140455

OCT 1 1 1983

D. G. Eisenhut

g. The analysis of the existing structures has been performed by assuming that the existing settlement stresses will be removed during the permanent underpinning jacking. The audit team feels that the existing stresses cannot be jacked out in their entirety and must be included in the final analysis of the building. What is the NRC position in regards to including existing settlement stresses in the analysis?

2

Should you or members of your staff need additional information, please feel free to contact R. Landsman (388-5587).

RFWinnick

R. F. Warnick, Director Office of Special Cases

cc: J. C. Stone, IE

E. G. Adensam, NRR

J. D. Kane, NRR

F. Rinaldi, NRR