	365			-	LIC	ENSEE EVEN	TRE	PORT	(LER)	U.S. NU A E	CLEAR REGUL	ATORY COMMISSION NO. 3150-0104 5
ACILITY	NAME (1	1						-	1	DOCKET NUMBER	(2)	PAGE (3)
	Sus	queha	inna	Steam Elec	ctric St	tation - Un	it 1			0   5   0   0	01318	7 1 OF 0 1
	Uni	t 1	Scra	n on Phase	a-to-Pha	se Fault:	Unit	2 Sc	ram on Lo	oss of Cor	ndenser	Vacuum.
EVE	INT DATE	(5)		LER NUMBER (	6)	REPORT DATE	(7)		OTHER	FACILITIES INVO	LVED (8)	
MONTH	DAY YEAR		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH DAY	YEAR		FACILITY NA	MES	DOCKET NUM	BER(S)
				_	_			SSES - Unit		2	0   5   0	0 0 3 8
0 7	15	8 4	8 4	0 3 4	00	0 8 1 4 8	4				0 5 0	0 0 1 1
OPE	RATING DE (9)	1	20.	402(b)	O PURSUANT	20 406(c)	TS OF 10	CFR 9: /	No 73(a)(2)(iv)	of the following) (1	73.71(b)	
POWE	R		20	406(a)(1)(i)		50.38(e)(1)		Ê	50.73(a)(2)(v)		73.71(e)	
(10)	11010		20	405(a)(1)(ii)		50.36(e)(2)		50.73(s)(2)(vii)				(Specify in Abstract nd in Text, NRC Form
			20	405(a)(1)(iii)	-	50.73(a)(2)(i)		-	60.73(a)(2)(viii)	(A)	366A)	
			20	406(a)(1)(v)		50.73(a)(2)(iii)			60.73(a)(2)(vin)		· · · · · · · · · · · · · · · · · · ·	
						LICENSEE CONTACT P	OR THIS	LER (12)			1	
NAME										AREA CODE	TELEPHONE N	UMBER
	L.A	. Ku:	zcyns	ki - Nucl	ear Plan	nt Speciali	st I	11		7 1 11 7	51412	- 1 31715 10
				COMPLETE	ONE LINE FOR	EACH COMPONENT	AILURE	DESCRIBE	D IN THIS REPO	AT (13)	121412	1 21/12
CAUSE	SYSTEM	COMP	ONENT	MANUFAC- TURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABI	LE .
С	EJL	CIB	IL I	*	N				111			
x	WIF	JIC	í í	**	N							
	1 1.		1t	SUPPLEM	ENTAL REPORT	EXPECTED (14)				+ + + + + + + + + + + + + + + + + + + +	MO	NTH DAY YEA
										SUBMISS DATE (1	ION (5)	
YE	S (IT YES, C	to 1400 st	wees i.e.	SUBMISSION DATE	sinala space tuo	XINO				1		
ABSTRAC	On	July	15,	1984, at	0914 wh	ile operati	ng a	t 100	% power,	the 230K	V transm	mission
ABSTRAC	On lin res cau at its	July e ex ulti sed 1007 ass	15, perie ng in a Uni from ociat	1984, at nced a ph a genera t 1 scram 25% powe ed off ga	0914 wh ase-to- tor loa . Subs r due t s recom	ewritten lined (10) ile operati phase fault d rejection equently, t o low conde biner tripp	ng a . T and Init enser bed a	t 100 his o turb 2 exp vacu nd co	% power, pened the ine trip erienced um which uld not	the 230K e Unit 1 . This, a reacto develope be return	V transm sync bre in turn r scram d after ed to se	nission eaker, , ervice.
ABSTRAC	On lin res cau at its	July e ex ulti sed 1007 ass PI S Sou	15, perie ng in a Uni from ociat	1984, at nced a ph a genera t 1 scram 25% powe ed off ga	0914 wh ase-to- tor loa . Subs r due t s recom	evention (new) (10) ile operati phase fault d rejection equently, U o low conde biner tripp	ng a . T and Init enser a	t 100 his o turb 2 exp vacu nd co	<pre>% power, pened the ine trip erienced um which uld not</pre>	the 230K e Unit 1 . This, a reacto develope be return	V transm sync bre in turn r scram d after ed to se	nission eaker, , ervice.
ABSTRAC	CT (Limit On lin res cau at its	July e ex ulti sed 1007 ass Sou Sou	15, perie ng in a Uni from ociat	1984, at nced a ph a genera t 1 scram 25% powe ed off ga 00283 84 00CK 050 re Co.	0914 wh ase-to- tor loa . Subs r due t s recom 00387 PDR	providen Wined (18) ile operati phase fault d rejection equently, to o low conder biner tripp	ng a . T and Init enser bed a	t 100 his o turb 2 exp vacu nd co	<pre>% power, pened the ine trip erienced um which uld not</pre>	the 230K e Unit 1 . This, a reacto develope be return	V transm sync bre in turn r scram d after ed to se	rvice.

4.

UCENSEE EVENT REPO	U.S.	U.S. NUCLEAR PEGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES. 8/31/85						
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)		
Susquehanna Steam Electric Station		YEAR		NUMBER	REVISION NUMBER		Π	
Unit 1	0 15 10 10 10 13 1 817	814	_	01314	- 0:0	012	OF	012

## TEXT /// more space is required, use additional NRC Form 366A's/ (17)

On July 15, 1984, at 0914 Unit 1 experienced a B-to-C phase fault on the transmission lines to its 230KV Susquehanna switching station. Within the following second, the generator span protection tripped, the main turbine master trip actuated and a reactor scram occurred. Three safety relief valves actuated to bring reactor pressure from 1081 ps g to approximately 975 psig. There were no ECCS initiations associated with this scram and none were required. Approximately fifteen minutes after the Unit 1 scram, the common off-gas recombiner which had been in operation and aligned to support Unit 2 tripped. Operations personnel tried three times to return it to service, but received an isolation each time due to low inlet temperature. The on-call Reactor Engineer was contacted at the time of the initial recombiner trip and provided direction regarding the insertion of control rods to reduce power to prevent condenser vacuum from reaching the turbine trip setpoint. Although several rod adjustments were accomplished (bringing reactor power from 37% to 25%). by 1007 sufficient vacuum was lost to trip the turbine. A reactor scram followed on turbine control valve fast closure. There were no safety relief valve or ECCS initiations; none were required.

The Unit 1 scram was caused by transmission line sag into a tree. This event occurred after several days of high heat and humidity with the unit operating near rated capacity. The tree has been cut down. At the time of the Unit 1 generator trip, the Unit 2 off-gas recombiner was out of service. Unit 2 was operating on the common off-gas recombiner. A review of Unit 2 computer data indicates that the common recombiner began to malfunction at the time of the Unit 1 generator trip. The malfunction of the common recombiner is postulated as being due to a momentary loss of power to the recombiner's control panels. The problems encountered while operations personnel tried to restart the recombiner should be alleviated by revisions which will be implemented to recombiner operation procedures to change the rate at which a recombiner is placed in service.



Pennsylvania Power & Light Company

August 14, 1984

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION LICENSEE EVENT REPORT 84-034-00 ER 100450 FILE 841-23 PLA-2282

Docket No. 50-387 License No. NPF-14

IE22

Attached is Licensee Event Report 84-034-00. This event was determined reportable per 10CFR50.73(a)(2)(iv), in that Unit 1 scrammed due to a phase-to-phase fault on its main transmission lines and Unit 2 scrammed shortly thereafter on loss of condenser vacuum.

mappu

Superintendent of Plant-Susquehanna

LAK/pjg

cc: Dr. Thomas E. Murley Regional Administrator-Region I U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

> Mr. R.H. Jacobs Senior Resident Inspector U.S. Nuclear Regulatory Commission P.O. Box 52 Shickshinny, PA 18655