

CONTROL BLOCK: [] [] [] [] [] (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[01] [M][D][C][C][N] [2] [2] [0][0]-[0][0][0][d][d]-[0][0] [3] [4][1][1][1][1] [4] [] [] [5]

CON'T

[01] REPORT SOURCE [L][L] [6] [0][5][0][0][0][3][1][8] [7] [1][2][0][2][8][3] [8] [0][8][1][3][8][4] [9]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[02] During normal operations on 12/02/83 and 12/10/83, erratic metrascope indication for CEAs 57 and 4 and metrascope associated alarms identified failed reed switch position transmitter (RSPT) stacks. The affected stacks were declared inoperable (T.S. 3.1.3.3) and both CEAs were verified in the full out position. The pulse counting position indication and the upper electrical limit "full out" indication systems for the affected CEAs remained operable. Similar events: 50-317/83-36.

[09] [R][B] [11] [E] [12] [B] [13] [I][N][S][T][R][U] [14] [S] [15] [Z] [16]

[17] LER/RO REPORT NUMBER [8][3]

EVENT YEAR [8][3]

SEQUENTIAL REPORT NO. [0][6][5]

OCCURRENCE CODE [0][3]

REPORT TYPE [X]

REVISION NO. [1]

ACTION TAKEN [B] [18] FUTURE ACTION [Z] [19] EFFECT ON PLANT [Z] [20] SHUTDOWN METHOD [Z] [21] HOURS [0][0][0][0] [22] ATTACHMENT SUBMITTED [N] [23] NPRO-4 FORM SUB. [Y] [24] PRIME COMP. SUPPLIER [N] [25] COMPONENT MANUFACTURER [E][1][4][6] [26]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[10] The cause of this event was the failure of reed stack position transmitters (RSPT) (Electro-Mechanics, Part #N9027, Rev. 1) for CEAs 57 and 4. The RSPTs were replaced. Repairs were made to the failed RSPTs by the vendor following their root cause inspection.

[15] FACILITY STATUS [E] [28] % POWER [1][0][0] [29] OTHER STATUS [N/A] [30] METHOD OF DISCOVERY [A] [31] DISCOVERY DESCRIPTION [Metrascope alarms & indications] [32]

[16] ACTIVITY CONTENT RELEASED OF RELEASE [Z] [33] [Z] [34] AMOUNT OF ACTIVITY [N/A] [35] LOCATION OF RELEASE [N/A] [36]

[17] PERSONNEL EXPOSURES NUMBER [0][0][0] [37] [Z] [38] DESCRIPTION [N/A] [39]

[18] PERSONNEL INJURIES NUMBER [0][0][0] [40] DESCRIPTION [N/A] [41]

[19] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] [42] DESCRIPTION [N/A] [43]

[20] PUBLICITY ISSUED DESCRIPTION [N] [44] DESCRIPTION [N/A] [45]

8408200492 840813 PDR ADOCK 05000318 S PDR

NRC USE ONLY

NAME OF PREPARE: J. W. Raynor

PHONE: (301) 260-4313

HERZ/11

BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT
CALVERT CLIFFS NUCLEAR POWER PLANT
LUSBY, MARYLAND 20657

August 13, 1984

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Docket No. 50-318
License No. DPR 69

Dear Sirs:

The attached revision to LER 83-65, Rev. 1 is being forwarded to you for your information.

Should you have any questions regarding this report, we would be pleased to discuss them with you.

Very truly yours,

LBR Russell
L. B. Russell
Plant Superintendent

for
LBR:JWR:srm

Attachment

cc: Dr. Thomas E. Murley
Director, Office of Management Information
and Program Control
Messrs: A. E. Lundvall, Jr.
J. A. Tiernan

IE22
11