

1650 CALVERT CLIFFS PARKWAY • LUSBY, MARYLAND 20657-4702

GEORGE C. CREEL VICE PRESIDENT NUCLEAR ENERGY (410) 280-4455

April 10, 1992

U. S. Nuclear Regulatory Commission Washington, DC 20555

ATTENTION:

Document Control Desk

SUBJECT:

Calvert Cliffs Nuclear Power Plant

Unit Nos. 1 & 2; Docket Nos. 50-317 & 50-318

Response to Improper Operation of Emergency Air Lock Notice of

Violation

REFERENCE:

(a) Letter from Mr. C. J. Cowgill (NRC) to Mr. G. C. Creel (BG&E), Combined Inspection Nos. 50-317/92-02; 50-318/92-02, dated

March 12, 1992

Gentlemen:

In response to Reference (a), Attachment (1) is provided.

Should you have any further questions regarding this matter, we will be pleased to discuss them with you.

Very truly yours,

GCC/DWM/dwm/dlm/bjd

Attachment

cc:

D. A. Brune, Esquire

J. E. Silberg, Esquire R. A. Capra, NRC

D. G. McDonald, Jr., NRC

T. T. Martin, NRC

P. R. Wilson, NRC

R. I. McLean, DNR

J. H. Walter, PSC

PROT 376 335

9204140339 920410 PDR ADDCK 05000317 JE01 .

ATTACHMENT (1)

IMPROPER OPERATION OF EMERGENCY AIR LOCK NOTICE OF VIOLATION

I. DESCRIPTION AND CAUSE OF EVENT

We have reviewed this event and concur that it constituted a valid quality problem. As described in LER 91-007, the failure of the personnel involved in this event to verify that pressure had equalized before opening the door was a contributing cause of this event. Our conclusion is that, although operation of the door is within the bounds of our expectations for skill of the craft, the personnel involved in this event had not been made sufficiently aware of the need to allow pressure to equalize across the Emergency Air Lock (EAL) door prior to opening it. Instructions posted at the air lock door and adequate awareness training would have provided an extra measure of defense to prevent this event.

Our design barrier to breaches of containment integrity via the EAL is its interlock mechanism, which provides door position indication and prevents operation of one door while the other is unlatched. The primary cause of this event was failure of the interlock. This problem is being investigated and the mechanism will be repaired.

An additional item discussed in Reference (a) concerned our not having initiated an investigation into the human factors implications of this event in a timely manner. An Issue Report (IR) was initiated the day of this event and later reviewed by the Issues Assessment Unit. On January 9, 1992, as part of its normal reportability review, Compliance determined the event to be reportable as an LER in accordance with the requirements of 10 CFR 50.73. Human factors considerations are routinely addressed during LER investigations. The failure to direct a human factors investigation had this event not been reportable was documented as a problem in an IR on January 10, 1992.

II. CORRECTIVE STEPS TAKEN AND RESULTS ACHIEVED

We have posted signs at the interior and exterior doors and inside the air lock for the Unit I and 2 EAL and Personnel Air Lock. These signs caution against opening air lock doors rapidly or before pressure across them is equalized ar in quire contacting the Control Room if pressure does not equalize within 60 seconds (in we indication that the interlock is a controlled by Calvert Cliffs Instruction CCI-308. Additionally, the signs in these signs is controlled by Calvert contacting the Control Room in the control Room is controlled by Calvert cliffs Instruction CCI-308. Additionally, the signs in the control Room is controlled by Calvert cliffs Instruction CCI-308. Additionally, the signs is controlled by Calvert cliffs Instruction CCI-308. Additionally, the signs is controlled by Calvert contacting the Control Room in the control Room is controlled by Calvert cliffs Instruction CCI-308. Additionally, the signs is controlled by Calvert contacting the Control Room in the control Room is contacting the Control Room in the control Room in the control Room is contacting the Control Room in the control Room in the control Room in the control Room in the control Room is contacting the Control Room in the control

To ensure personnel are aware of the need to exercise caution when operating air locks, we have added a discussion of the details of this and similar industry events to annual General Orientation Training. The training also includes cautions against opening the doors too quickly or with at pressure equalizing across them.

III. CORRECTIVE STEPS WHICH WILL BE TAKEN TO AVOID FURTHER VIOLATIONS

The above actions are sufficient to prevent future incidents of this type.

IV. DATE WHEN FULL COMPLIANCE WILL BE ACHIEVED

Full compliance was achieved when the permanent signs were posted at the air locks.