

## NUCLEAR REGULATORY COMMISSION

REGIONIV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

DEC | 1995

Wolf Creek Nuclear Operating Corporation ATTN: Neil S. Carns. President and Chief Executive Officer P.O. Box 411 Burlington. Kansas 66839

SUBJECT: NRC INSPECTION REPORT 50-482/95-98

This refers to the inspection conducted by Mr. C. J. Paulk and Ms. L. J. Smith of this office on August 15-17, 1995, at the Wolf Creek Generating Station facility. This initiative was prompted by recurring failures of safety-related steam turbine-driven standby pumps at several facilities in Region IV. We concurrently performed this inspection at most Region IV facilities to better understand the scope of design, maintenance, and testing practices related to safety-related steam turbines, which were supplied by the Terry Corporation. We also examined several aspects of various experience review processes to determine why similar failures continued to occur. On November 9, 1995, at the conclusion of the in-office review, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures, representative records, and interviews with personnel. The combined results of this inspection for each of the Region IV facilities are documented in the enclosed report and executive summary.

With respect to your facility, the inspection identified several conditions that have resulted in mechanical overspeed trips of safety-related steam turbine-driven standby pumps at other facilities. Specifically, your staff had not established a program for routine refurbishment of the auxiliary feedwater turbine governor. They also had not established an acceptable range for the turbine oil level, which could result in aeration of the oil or a loss of lubrication. The inspection also noted that the governor valve stem material in use at your plant may be susceptible to sticking because the assumptions made regarding the stem material were inaccurate. We encourage you to review these conditions to ensure continued reliable operation of the auxiliary feedwater pump turbine.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice." a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

1501

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely.

Thomas P. Gwynn, Dire Division of Reactor Safety

Docket: 50-482 License: NPF-42

Enclosure:

NRC Inspection Report

50-482/95-98 w/attachment

cc w/enclosure:

Wolf Creek Nuclear Operating Corp. ATTN: Vice President Plant Operations P.O. Box 411

Burlington, Kansas 66839

Shaw, Pittman, Potts & Trowbridge ATTN: Jay Silberg, Esq. 2300 N Street, NW Washington, D.C. 20037

U.S. Nuclear Regulatory Commission ATTN: Regional Administrator, Region III 801 Warrenville Road Lisle, Illinois 60532-4351

Wolf Creek Nuclear Operating Corp. ATTN: Supervisor Licensing P.O. Box 411 Burlington, Kansas 66839

Wolf Creek Nuclear Operating Corp. ATTN: Supervisor Regulatory Compliance P.O. Box 411 Burlington, Kansas 66839

Wolf Creek Nuclear Operating Corporation

Missouri Public Service Commission ATTN: Assistant Manager Energy Department P O Box 360 Jefferson City. Missouri 65102

Kansas Corporation Commission ATTN: Chief Engineer Utilities Division 1500 SW Arrowhead Rd. Topeka, Kansas 66604-4027

Office of the Governor State of Kansas Topeka, Kansas 66612

Attorney General Judicial Center 301 S.W. 10th 2nd Floor Topeka. Kansas 66612-1597

County Clerk Coffey County Courthouse Burlington, Kansas 66839-1798

Kansas Department of Health and Environment Bureau of Air & Radiation ATTN: Public Health Physicist Division of Environment Forbes Field Building 283 Topeka. Kansas 66620 -4

E-Mail report to D. Nelson (DJN) E-Mail report to NRR Event Tracking System (IPAS)

## bcc to DMB (IEO1)

bcc distrib. by RIV:

L. J. Callan
Branch Chief (DRP/B)
Section Chief (RIII, DRP/3C)
SRI (Callaway, RIII)
Project Engineer (DRP/B)
Branch Chief (DRP/TSS)

Resident Inspector
DRSS-FIPB
RIV File
MIS System
Leah Tremper (OC/LFDCB, MS: TWFN 9E10)

DOCUMENT NAME: R:\ WC\WC598RP.CJP

To receive copy of document, indicate in box: "C" = Copy without enclosures, "E" = Copy with enclosures "N" = No copy

RIV:RI:EB	The state of the s	C:EB	E	D: DR	39 N	D:DRP		D: DR	SI	J
LJSmith ws	CJPaulk*	CAVanDenb	urgh*	TPGW	ynn (*	<b>Y</b> JEDyer	popu	TPGW	ynn	11
11/29/95	11/22/95	C:EB CAVanDenb 11/22/95		12/1	/95	11/30	95	12/	/95	-

\*previously concurred

OFFICIAL RECORD COPY

E-Mail report to D. Nelson (DJN) E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IE01)

bcc distrib. by RIV:

L. J. Callan Branch Chief (DRP/B; Section Chief (RIII. DRP/3C) SRI (Callaway, RIII) Project Engineer (DRP/B) Branch Chief (DRP/TSS) Resident Inspector
DRSS-FIPB
RIV File
MIS System
Leah Tremper (OC/LFDCB, MS: TWFN 9E10)

DOCUMENT NAME: R:\ WC\WC598RP.CJP

To receive copy of document, indicate in box: "C" = Copy without enclosures, "E" = Copy with enclosures "N" = No copy

RIV:RI:EB	RI:MB	C:EB E	D: DRS9 N	D:DRP   JEDyer 106- 11/3 = 195	D: DRS N
LJSmith ws	CJPaulk*	CAVanDenburgh*	TPGwynn (**	Y JEDyer Mate	TPGwynn 77
11/29/95	11/22/95	11/22/95	12/1/95	11/3 2/95	12///95

\*previously concurred

OFFICIAL RECORD COPY