

# The Light company

Houston Lighting & Power

South Texas Project Electric Generating Station P. O. Box 289 Wadsworth, Texas 77483

April 13, 1992  
ST-HL-AE-4068  
File No.: G26  
10CFR50.73

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, DC 20555

South Texas Project  
Unit 1  
Docket No. STN 50-498  
Licensee Event Report 92-003  
Reactor Trip Due to Failure to Follow  
Procedures During RCS Flow Transmitter Restoration

Pursuant to 10CFR50.73, Houston Lighting & Power (HL&P) submits the attached Licensee Event Report 92-003 regarding a reactor trip due to failure to follow procedures during RCS flow transmitter restoration. This event did not have adverse impact on the health and safety of the public.

If you should have any questions on this matter, please contact Mr. C. A. Ayala at (512) 972-8628 or me at (512) 972-7205.

*Warren H. Kusey*  
for William J. Jump  
Manager,  
Nuclear Licensing

MAC/nl

Attachment: LER 92-003 (South Texas, Unit 1)

010007

LER\92091001.U1

A Subsidiary of Houston Industries Incorporated

9204210378 920413  
PDR ADOCK 0500049E  
S PDR

*TE22*

Houston Lighting & Power Company  
South Texas Project Electric Generating Station

ST-HL-AE-4068  
File No.: G26  
Page 2

cc:

Regional Administrator, Region IV  
Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011

George Dick, Project Manager  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

J. I. Tapia  
Senior Resident Inspector  
c/o U. S. Nuclear Regulatory  
Commission  
P. O. Box 910  
Bay City, TX 77414

J. R. Newman, Esquire  
Newman & Holtzinger, P.C.  
1615 L Street, N.W.  
Washington, DC 20036

D. E. Ward/T. M. Puckett  
Central Power and Light Company  
P. O. Box 2121  
Corpus Christi, TX 78403

J. C. Lanier/M. B. Lee  
City of Austin  
Electric Utility Department  
P.O. Box 1088  
Austin, TX 78767

K. J. Fiedler/M. T. Hardt  
City Public Service Board  
P. O. Box 171  
San Antonio, TX 78296

Rufus S. Scott  
Associate General Counsel  
Houston Lighting & Power Company  
P. O. Box 61867  
Houston, TX 77208

INPO  
Records Center  
1100 Circle 75 Parkway  
Atlanta, GA 30339-3064

Dr. Joseph M. Hendrie  
50 Bellport Lane  
Bellport, NY 11713

D. K. Lacker  
Bureau of Radiation Control  
Texas Department of Health  
1100 West 49th Street  
Austin, TX 78756-3189

Revised 10/11/91

L4/NRC/

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-30), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20545 AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)						DOCKET NUMBER (2)				PAGE (3)	
South Texas, Unit 1						0 5 0 0 0 4 9 8 1				OF 0 4	

TITLE (4) Reactor Trip Due to Failure to Follow Procedures During RCS Flow Transmitter Restoration

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
03	14	92	92	003		00	04	13	92		0 5 0 0 0
											0 5 0 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 50. (Check one or more of the following) (11)

OPERATING MODE (9)	1	20.402(b)	20.405(c)	X	50.73(a)(2)(vi)	73.71(b)
POWER LEVEL (10)	100	20.405(a)(1)(i)	50.36(c)(1)		50.73(a)(2)(v)	73.71(c)
		20.405(a)(1)(ii)	50.36(c)(2)		50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text NRC Form 305A)
		20.405(a)(1)(iii)	50.73(a)(2)(iii)		50.73(a)(2)(viii)(A)	
		20.405(a)(1)(iv)	50.73(a)(2)(iv)		50.73(a)(2)(viii)(B)	
		20.405(a)(1)(v)	50.73(a)(2)(v)		50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER
Charles Ayala - Supervising Licensing Engineer	5 1 2 9 7 2 - 8 6 2 8

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
X					

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

On March 14, 1992, Unit 1 was in Mode 1 at 100% power. A reactor trip occurred at approximately 1108 hours from a momentary false reactor coolant low flow trip signal. Instrumentation & Control Technicians calibrating the Reactor Coolant flow transmitter reversed the procedural sequence of restoring the transmitter causing a momentary low (below setpoint) differential pressure to be detected by the two adjacent flow transmitters. This event completed the logic in the Solid State Protection System to trip the reactor. The cause of this event was failure to follow procedures which resulted from insufficient supervisory and management emphasis on the risk associated with the task, and a limited sense of responsibility by the technicians to ensure proper task completion. The actions being taken to correct this event are: supervision is required to be present to ensure emphasis is placed on completing the activity correctly when a potential reactor trip could occur; clear direction for use and physical presence of procedures has been provided to maintenance craftsmen; and a memo-andum from management was issued emphasizing the self-checking principle.

LER\92091001.U1

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST, 900 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  South Texas, Unit 1	DOCKET NUMBER (2)  0 5 0 0 0 4 9 8 9 2	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
			— 0 0 3	— 0 0	0 2	OF 0 4

TEXT (if more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION OF EVENT:

On March 14, 1992, Unit 1 was in Mode 1 at 100 percent power. A reactor trip occurred at approximately 1108 hours from a momentary false reactor coolant low flow trip signal. At that time, Instrumentation and Control Technicians were calibrating a flow transmitter for Reactor Coolant Flow Loop 2 Protection Set 2. The work document to perform the calibration was initiated on March 13, 1992, due to an evaluation of the previous two transmitter data and channel comparisons rendering the transmitter calibration suspect. The work document instructions directed the technicians to use a surveillance procedure. The transmitter was removed from service and as found data was recorded. An adjustment was made to the transmitter to bring it within tolerance. While returning the transmitter to service, the transmitters high pressure side valve was opened first instead of the low pressure side valve to pressurize the transmitter which was contrary to the procedure. A momentary low (below setpoint) differential pressure was detected by two adjacent flow transmitters. This completed the two-out-of-three coincidence logic in the Solid State Protection System and with the Nuclear Instrumentation System permissive P-8 being satisfied (Reactor Power above 40% Power), the reactor tripped on reactor coolant low flow. The plant was stabilized in Mode 3. The main steam isolation valves were closed to limit Reactor Coolant System cooldown. The NRC was notified on March 14, 1992 at 1327 hours.

The three transmitters, that measure reactor coolant flow, are connected to the process line by a common tap on the high pressure side. This is a unique piping arrangement. The opening of the high pressure valve first results in the two adjacent flow transmitters momentarily supplying the pressure needed to pressurize the transmitter being returned to service. A momentary pressure drop of approximately three pounds per square inch is all that is required to exceed the differential pressure setpoint.

CAUSE OF EVENT:

The cause of this event was failure to follow procedures which resulted from insufficient supervisory and management emphasis on the risk associated with the task, and a limited sense of responsibility by the technicians to ensure proper task completion. In addition, management controls over procedure usage were not clearly stated resulting in confusion over requirements for having procedures present during task performance.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 600 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20545, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  South Texas, Unit 1	DOCKET NUMBER (2)  0 5 0 0 0 4 9 8 9 2	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
			0 0 3	0 0 0	3	OF	0 4

TEXT (if more space is required, use additional NRC Form 366A's) (17)

CAUSE OF EVENT: (Continued)

The technician in the Reactor Containment Building (RCB) performing the work to return the transmitter to service did not have a copy of the procedure in his possession, but rather was following verbal instructions from a technician in the relay rack area of the Electrical Auxiliary Building who did possess the procedure. The technician providing verbal direction failed to read and communicate specific steps for return to service. The technician in the RCB valved in the flow transmitter in the reverse order.

ANALYSIS OF EVENT:

The event is reportable pursuant to 10CFR50.73(a)(2)(iv). There were no adverse radiological or safety consequences as a result of this event. Engineered Safety Systems functioned as designed and no unexpected post-trip transients occurred.

CORRECTIVE ACTIONS:

1. Shift and Unit supervisors are being briefed and it is being emphasized that they will be held accountable for taking conservative action, including power reduction or other actions that will increase the safety margin and/or reduce the risk of a plant transient or trip when evaluating the safety impact of work or testing and to monitor these activities to ensure that they are controlled. This activity will be completed by May 1, 1992.
2. Plant Management has established a reactor trip prevention policy which adds administrative controls to work activities that have a potential to cause a reactor trip. These activities are required to be under direct control of an on-the-scene supervisory individual to ensure the job is completed correctly and within safety margins.
3. A Maintenance Department Standing Order was issued requiring that performers of a procedure will have a copy of the procedure or, at the minimum, a copy of the portion of the procedure that is to be performed by those personnel who are working at locations other than where the controlling procedure is maintained.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST, 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  South Texas, Unit 1	DOCKET NUMBER (2)  0500049892	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		0	0	3	0	4 OF 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

CORRECTIVE ACTIONS: (Continued)

4. Department training sessions will be conducted for appropriate maintenance personnel. The session will discuss the lessons learned from this event and the training will be completed by May 28, 1992.
5. Management has issued a memorandum to emphasize the importance of the self-checking principle and to request line management to reinforce these principles with their personnel.

ADDITIONAL INFORMATION:

Similar events have been reported regarding reactor trips due to failure to follow procedure which are LER 89-011 (Unit 2) "Inadvertent Safety Injection and Reactor Trip System Actuations Due to Personnel Error", LER 90-013 (Unit 2) "Reactor Trip Caused by Manipulation of the Incorrect Reactor Trip Breaker Test Pushbutton" and LER 91-022 (Unit 1) "Reactor Trip During Performance of SSPS Logic Functional Test".