NRC Form 364 U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO 3150-0104 EXPIRES 8/31/85 LICENSEE EVENT REPORT (LER) FACILITY NAME (1) DOCKET NUMBER (2) D. C. COOK NUCLEAR PLANT UNIT ONE 0 15 10 10 10 1 3 1 1 5 1 OF 0 12 TITLE (A) BOTH SAFETY INJECTION PUMPS INOPERABLE EVENT DATE (6) REPORT DATE (7) OTHER FACILITIES INVOLVED (8 LER NUMBER (6) SEQUENTIAL NUMBER DOCKET NUMBER(S) FACILITY NAMES DAY YEAR YEAR MONTH DAY 0 | 5 | 0 | 0 | 0 0 0 8 1 5 4 0 7 1 6 8 4 8 4 0 1 4 0 | 5 | 0 | 0 | 0 | THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR & 'Check one or more of the following) (11) OPERATING MODE (9) 20.405(c) 50 73(e)(2)(iv) 73.71(b) X 20.405(a)(1)(i) 50 36(c)(1) 50.73(a)(2)(v) 73.71(c) 0,0 OTHER (Specify in Abstract below and in Text NRC Form 366A) 20.405(a)(1)(ii) 50.36(c)(2) 50.73(a)(2)(vii) X 20.406(a)(1)(iii) X 50.73(a)(2)(i) 50.73(a)(2)(viii)(A) 20.405(a)(1)(iv) X 50.73(a)(2)(ii) 50.73(a)(2)(viii)(B) 50.73(a)(2)(x) 20,406(a)(1)(v) 50.73(a)(2)(iii) LICENSEE CONTACT FOR THIS LER (12) TELEPHONE NUMBER NAME AREA CODE K. R. BAKER, OPERATIONS SUPERINTENDENT 6, 1,6 4,6,5,-,5,9,0,1 COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13) TO NPROS MANUFAC TURER TO NPRDS SYSTEM CAUSE COMPONENT CAUSE SYSTEM COMPONENT MONTH DAY YEAR SUPPLEMENTAL REPORT EXPECTED (14) EXPECTED SUBMISSION DATE (15) YES (If yes, complete EXPECTED SUBMISSION DATE) ABSTRACT (Limit to 1400 speces i.e. approximately fifteen single-space typewritten li ON 7-16-84 at 0445 HOURS WITH THE REACTOR COOLANT SYSTEM IN MODE 1 AT 100% REACTOR POWER A VALVING ERROR WAS COMMITTED WHILE IN THE PROCESS OF PERFORMING A SCHEDULED SURVEILLANCE TEST ON THE ECCS. A NON-LICENSED OPERATOR INADVERTENTLY ISOLATED THE NORTH LOW HEAD SAFETY INJECTION PUMP. THE LICENSED CONTROL ROOM OPERATOR HAD PREVIOUSLY LOCKED OUT THE SOUTH PUMP IN PREPARATION FOR THE QUARTERLY VALVE TESTS. WHEN NOTIFIED THAT THE NORTH PUMP HAD BEEN ISOLATED THE CONTROL ROOM OPERATOR REQUESTED VERIFICATION OF WHICH PUMP WAS ISOLATED. WHEN IT WAS VERIFIED TO BE THE WRONG PUMP, THE VALVES WERE IMMEDIATELY REOPENED. THE TOTAL TIME BOTH PUMPS WERE INOPERABLE WAS THREE TO FIVE MINUTES. THE EVENT WAS CAUSED BY PERSONNEL ERROR. PROCEDURE ENHANCEMENTS ARE BEING MADE TO PREVENT RECURRENCE. 8408220486 840815 PDR ADOCK 05000315 PDR

| VRC Form 366A 9-83) | LICENSEE EVENT REPORT (LER) TEXT CONTINUATION | | | | | | | U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 31500104 EXPIRES. 8/31/85 | | | | |
|------------------------|---|-------|------|-------------------|-----------------------|----------------|--|---|----------|-----|----|------|
| FACILITY NAME (1) | | | | DOCKET NUMBER (2) | 1 | LER NUMBER (6) | | | PAGE (3) | | | |
| | | | | | | YEAR | | SEQUENTIAL | REVISION | | | |
| D. C. COOK | NUCLEAR | PLANT | UNIT | ONE | 0 15 10 10 10 13 11 1 | 5 814 | | 01114 | -010 | 012 | OF | 0 12 |

FEXT I'll more space is required, use additional NRC Form 3684's) (17)

ON 7-16-84 AT 0445 HOURS WITH THE REACTOR COOLANT SYSTEM IN MODE 1 AT 100% REACTOR POWER A VALVING ERROR WAS COMMITTED WHILE IN THE PROCESS OF PERFORMING A SCHEDULED SURVEILLANCE TEST ON THE ECCS. A NON-LICENSED OPERATOR INADVERTENTLY ISOLATED THE NORTH LOW HEAD SAFETY INJECTION PUMP. THE LICENSED CONTROL ROOM OPERATOR HAD PREVIOUSLY LOCKED OUT THE SOUTH PUMP IN PREPARATION FOR THE QUARTERLY VALVE TESTS. WHEN NOTIFIED THAT THE NORTH PUMP HAD BEEN ISOLATED THE CONTROL ROOM OPERATOR REQUESTED VERIFICATION OF WHICH PUMP WAS ISOLATED. WHEN IT WAS VERIFIED TO BE THE WRONG PUMP, THE VALVES WERE IMMEDIATELY REOPENED. THE TOTAL TIME BOTH PUMPS WERE INOPERABLE WAS THREE TO FIVE MINUTES.

THE EVENT WAS CAUSED BY PERSONNEL ERROR PRIMARILY DUE TO BREAKDOWN IN COMMUNICATIONS AND JOB BRIEFING AS TO WHICH TRAIN WAS UNDERGOING TESTING. THE SIGNOFF SHEET IN POSSESSION OF THE NON-LICENSED OPERATOR DID NOT IDENTIFY WHICH TRAIN WAS TO BE TESTED.

A REVIEW OF THIS EVENT INDICATED THAT PROCEDURE ENHANCEMENT COULD PREVENT THIS FROM RECURRING. THE PROCEDURE FOR PERFORMING THIS TEST IS VERY COMPLICATED AND WILL BE SIMPLIFIED BY TESTING EACH TRAIN UNDER DIFFERENT PROCEDURES.

THE CONSEQUENCES OF THIS EVENT WERE MINIMUZED DUE TO THE RAPID IDENTIFICATION AND CORRECTION OF THE PROBLEM. IN THE ECCS TRAIN NOT UNDERGOING TESTING THE HIGH HEAD SAFETY INJECTION PUMP AND THE RESIDUAL HEAT REMOVAL PUMP WERE OPERABLE.



DONALD C. COOK NUCLEAR PLANT P.O. Box 458, Bridgman, Michigan 49106 (616) 465-5901

August 15, 1984

United States Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Operating License DPR-58 Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10CFR50.73 entitled Licensee Event Reporting System, the following report/s are being submitted:

RO 84-014-0

Sincerely,

for W.G. Smith, Jr.
Plant Manager

/cbm

Attachment

CC: John E. Dolan
J.G. Keppler, RO:III
M.P. Alexich
R.F. Kroeger
H. Brugger
E.R. Swanson, RO:III
P.C. Callen, MPSC
G. Charnoff, Esq.
J.M. Hennigan
R.O. Bruggee, EPRI
INPO
PNSRC
J.F. Stietzel
E.L. Townley
Dottie Sherman, ANI Library