

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) EDWIN I. HATCH, UNIT 2	DOCKET NUMBER (2) 0 5 0 0 0 3 6 6	PAGE (3) 1 OF 0 2
--	---	-----------------------------

TITLE (4)
Failure to Test Refueling Platform Frame Mounted Auxiliary Hoist

EVENT DATE (5)			LER NUMBER (6)		REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES
07	16	84	84	006	00	08	14	84	
									DOCKET NUMBER(S) 0 5 0 0 0
									0 5 0 0 0

OPERATING MODE (9) 5	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)				
POWER LEVEL (10) 0 0 0	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(c)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)	
	<input type="checkbox"/> 20.406(a)(1)(i)	<input type="checkbox"/> 50.36(a)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(e)	
	<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 50.36(a)(2)	<input type="checkbox"/> 50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)	
	<input type="checkbox"/> 20.406(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input checked="" type="checkbox"/> 50.73(a)(2)(viii)(A)		
	<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)		
<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(x)			

LICENSEE CONTACT FOR THIS LER (12)

NAME T. L. Elton, Acting Superintendent of Regulatory Compliance	TELEPHONE NUMBER 9 1 2 3 6 7 - 7 8 5 1
AREA CODE	

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFAC TURER	REPORTABLE TO NRRDS	CAUSE	SYSTEM	COMPONENT	MANUFAC TURER	REPORTABLE TO NRRDS
D	L R	H O I	S B 9 0	N					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 07-17-84 engineering personnel determined that a control rod had been moved within the reactor pressure vessel with the refueling platform frame mounted auxiliary hoist prior to demonstrating operation of the hoist's loaded interlock as required by Tech. Specs. section 4.9.7.b. Upon determining that hoist operation was contrary to Tech. Specs. surveillance requirements, further hoist use was suspended. A procedure revision will be made before the hoist use is resumed. This event is reportable per 10CFR 50.73(a)(2)(i)(B), because an operation occurred which was prohibited by the plant's Technical Specifications.

8408220491 840814
PDR ADOCK 05000366
S PDR

IE 22
11

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) EDWIN I. HATCH, UNIT 2	DOCKET NUMBER (2) 0 5 0 0 0 3 6 6 8 4 - 0 0 6 - 0 0 0 0 2 OF 0 2	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		

TEXT (if more space is required, use additional NRC Form 365A's) (17)

On 07-17-84 with the reactor head removed, and during a routine procedure review, engineering personnel determined that a control rod had been moved within the reactor pressure vessel with the refueling platform (2F15-E003) frame mounted auxiliary hoist on 07-16-84 prior to demonstrating operation of the hoist's loaded interlock. Demonstration of the operation of the hoist's loaded interlocks prior to handling control rods or fuel assemblies in the reactor pressure vessel is required by Tech. Specs section 4.9.7.b. Therefore this event is contrary to the requirements of Tech. Specs. section 4.9.7.b., and is reportable per 10CFR 50.73(a)(2)(i)(B).

This event is the result of a procedure inadequacy. The "REFUELING INTERLOCKS AND HOIST LIMIT CHECKS" procedure (HNP-2-3940) did not include the Tech. Specs. surveillance requirement to demonstrate operation of the refueling platform (2F15-E003) FRAME MOUNTED hoist's loaded interlock. However the procedure (HNP-2-3940) did include all other Tech. Specs. surveillance requirements for the hoist.


When it was determined (on 07-17-84) that the procedure (HNP-2-3940) did not include the Tech. Specs. surveillance requirement to demonstrate the hoist's loaded interlock operation, an LCO was established and the hoist was removed from service on 07-19-84 per Tech. Specs. section 3.9.7 ACTION statement by attaching a tag to it per the "EQUIPMENT CLEARANCE AND TAGGING" procedure (HNP-501).

The refueling platform frame mounted hoist will not be used to handle fuel assemblies or control rods in the reactor vessel until after the procedure (HNP-2-3940) has been revised to include the Tech. Specs. surveillance requirement to satisfactorily demonstrate the hoist's loaded interlock operation.

There is no redundant or backup system for the refueling platform hoist's loaded interlock.

This non-repetitive event had no impact upon any other system in Unit 1, or Unit 2; nor did it affect the health and safety of the public.

Georgia Power Company
Post Office Box 439
Mableton, Georgia 31513
Telephone 912 367-7781
912 537-9444




Edwin I. Hatch Nuclear Plant

August 14, 1984
GM-84-672

PLANT E. I. HATCH
Licensee Event Report
Docket No. 50-366

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Attached is Licensee Event Report No. 50-366/1984-006. This report is required by 10CFR 50.73(a)(2)(i).


H. C. Nix
General Manager

HCN/TLE/vlt

xc: R. J. Kelly
R. E. Conway
J. T. Beckham, Jr.
P. D. Rice
K. M. Gillespie
Superintendent of Regulatory Compliance
R. D. Baker
Control Room
Document Control

IE 22

11