TELEDYNE OHIOCAST

1075 JAMES STREET - P.O. BOX 900 SPRINGFIELD, OHIO 45501 TELEPHONE (513) 325-7631 TELEX 20-5415

July 7, 1983

United States Nuclear Regulatory Commission Radioisotopes Licensing Branch Division of Fuel Cycle and Material Safety Washington, D.C. 20555

Gentlemen:

This letter is in reference to our license 34-00412-03.

Please be advised that an organizational structure change has been made at Teledyne Ohiocast.

The following change is in effect:

Assistant Safety Officer - G. Epley

Mr. Epley has been appointed to the position of Assistant Safety Officer to replace J. Mahajan, who has been transferred to other duties at Teledyne Ohiocast.

The following is a brief description of the education and training experience of Mr. Epley.

- 1. Seven years experience as a radiographer Level I at Teledyne Ohiocast.
- 2. Attained certification as Level II Radiographic Testing per SNT-TC-1A on 6/24/83.

An announcement of this change was made to the employees of the Radiography Department of Teledyne Ohiocast effective 7/5/83.

Mr. S. Hart, who is the acting Safety Officer, attained his Level III Radiographic Testing per SNT-TC-1A on 3/27/81. Since that time he has been employed as the Supervisor of all testing and inspection.

Should there be any questions or comments, I ask that they be directed to this writer.

8408230025 840712 NMS LIC30 34-00412-03 PDR

Sincerely, hu a Jordah

John A. Jordak Technical Director 13172

MEMORANDUM

TELEDYNE OHIOCAST

July 7, 1983

NOTICE

NOTICE

NOTICE

TO: All Employees - Radiographic Testing FROM: John A. Jordak - Technical Director

NRC License 34-00412-03 SUBJECT:

> As of 7/5/83, G. Epley will act in the capacity of Assistant Safety Officer for this department. He will assist S. Hart, who is the Safety Officer.

hn 4 Jordak

John A. Jordak

TELEDYNE OHIOCAST

July 27, 1983

1075 JAMES STREET - P.O. BOX 900 SPRINGFIELD, CHIO 45501 TELEPHONE (513) 325-7631 TELEX 20-5415

OPERATING INSTRUCTIONS FOR GAMMA INDUSTRIES SOURCE CHANGER

For Removal of Decayed Source and Installation of Replacement Source.

- 1.0 All source exchanges to be conducted by Safety Officer and will be conducted as follows:
 - 1. Be certain to have an operating survey meter on hand.
 - 2. Locate the source changer within two feet of the shielded head.
 - 3. Remove plug or source tube from the machine outlet.
 - 4. Remove ROUND PLUG from source changer. Save (NEW) source number plate.
 - 5. Connect the short source tube supplied to machine outlet and source changer outlet.
 - 6. Connect source position indicator control to machine lock box and extend control so that operator is positioned full 25 feet from machine.
 - 7. Run decayed source into source changer by turning control handle clockwise until source stops in the changer.
 - 8. At this point, the survey meter should be employed to insure that source has been safely located in shielded position.
 - 9. Disconnect short source tube at source changer and disengage disconnects, being careful not to pull out source.
 - 10. Replace ROUND PLUG, securing decayed source in changer.
 - 11. Remove HEX HEAD PLUG from source changer, being careful not to pull out source cable inside.
 - 12. Carefully pull the source cable disconnect only enough to allow joining of disconnects.
 - 13. Join disconnects on control cable and source cable.
 - 14. Connect short source tube to source changer outlet.
 - 15. Pull source into machine by turning control handle counter clockwise.
 - 16. After a monitor check has been made with a survey meter, remove short source tube.
 - 17. Replace HEX HEAD PLUG on empty source changer hole.

July 27, 1983

OPERATING INSTRUCTIONS FOR GAMMA INDUSTRIES SOURCE CHANGER

- 18. Remove decayed source number plate from plate holder on machine and replace with new source number plate attached to lead seal wire. Attach old source number plate to source changer cap plug by lacing seal wire provided through number plate when sealing returned source.
- 19. Two (2) Lead Seal wires have been furnished with your new source. One (1) is to be used for re-sealing source changer cap plugs and attaching old source number plate, and one (1) for sealing "U" Bolt Lock on changer box.
- 20. Two D.O.T. style shipping labels are included in the envelope. These are to be pasted over the similar labels on the shipping box. The blank spaces should be filled in as follows:

Principal Radioactive Content - Spell out: Iridium 192 or Cobalt 60, not IR 192.

Activity of Contents. Number of curies.

Transportation Index By radiation survey - MR/hr. at 3 ft.

21. Return the source changer containing short source tube to:

GAMMA INDUSTRIES 2255 Ted Dunham Avenue Baton Rouge, Louisiana 70821

KOWIPE LEAK TEST KIT PROCEDURE

- 1.0 PREPARING THE UNIT FOR LEAK TESTING
- 1.1 All leak testing will be performed by the Radiation Safety Officer.
- 1.2 A source is contained in the unit to be tested, be sure to use a survey meter to prevent exposure during all of the following procedures. The survey meter that will be used will be the CDV 700 Unit.
- 1.3 The source is contained in a remotely operated unit, disconnect the source tube from the shielded head after checking with the survey meter to make sure that the source is in a safe position within the head.
- 2.0 TAKING THE LEAK TEST SAMPLE
- 2.1 Open Kowipe Leak Test Kit
 - (a.) Disolve the contents of attached packet in a small volume of water.
 - (b.) Remove swab in packet on left. Dip cotton tip in solution and proceed with the wipe test by swabbing areas nearest and most accessible to the source.
 - (c.) Replace the swab in the same container from which it was removed.
 - (d.) Remove the second swab and perform the wipe test with the swab dry.
 - (e.) Return the swab to the proper container.

2.2 Measure the radiation level at the surface of the test tube.

NOTE: The instrument that you use for this measurement must be accurately calibrated, and it must have a scale that permits accurate reading of the radiation value given in these instructions.

- 2.3 If a reading of <u>more</u> than 0.5 mr/hr. is observed, follow the procedure given in Paragraph 3.0.
- 2.4 If a reading of <u>less</u> than 0.5 mr/hr. is observed, follow the procedure given in Paragraph 4.0.
- 3.0 HANDLING PROCEDURES FOR SAMPLES READING MORE THAN 0.5 MR/HR
- 3.1 If your test instrument shows a radiation level of more than 0.5 mr/hr. at the surface of the test tube, there may be gross contamination of the unit, and the following steps should be taken:
 - Put the test swab back in its place in the shipping container. DO NOT SEND IT TO GAMMA INDUSTRIES.
 - (2) Immediately remove the radiography unit or source storage container from service. Keep the leak test sample and the contaminated unit together in a safe place until decontamination personnel can take care of them.
 - (3) As soon as possible, call the nearest N.R.C. Operations Office. Inform them of your findings and subsequent actions.

(4) Contact Gamma Industries and provide them with the same information. Use the following address or telephone number:

> Gamma Industries 2255 Ted Dunham Avenue Baton Rouge, La. 70821 Attention: Radiation Safety Officer Telephone: (504) 383-7791

- 4.0 HANDLING PROCEDURES FOR SAMPLES READING LESS THAN 0.5 MR/HR
 4.1 If your test instrument shows a radiation level of <u>less</u> than 0.5 mr/hr. at the surface of the Kowipe Leak Test Kit, you mail the sample to Gamma Industries for further testing and certification. You are not required to return the sample by Railway Express. No radiation warning label need be affixed to the outside of the shipping container.
- 4.2 Be sure the requested information is completed to properly identify the source.
- 4.3 Return the Kowipe Leak Test Kit to Gamma Industries for analysis (same address as 3.1 item 4)

PREPARED BY: Stim / Sat

Steve Hart Safety Officer

GAMMA RADIANION

To describe a gammaray, we must first lock at the construction of an atom. Several fundamental parts (or particles) of the atom must first be described.

- (A) Electron a negative charged particle orbiting around a central mass.
- (B) Proton a positive charged particle in the central meas of an atom.
- (C) Neutron a neutral particle having no electrical charge in the contral mass.

Therefore, an atom is a central mass of protons and neutrons with orbiting electrons. Since an atom has no electrical charge, the number of electrons equal the number of protons.

The number of protons or electrons define the atomic number, and the atomic weight is the sum of the neutrons and protons. All the known elements such as carbon, iodine, lead, gold, etc. are composed of electrons, protons and neutrons, these and many more elements may exist in one or more forms having the same atomic number, but having a different atomic weight. When the atomic weight of an element is different from its stable or standard known form or determined weight. it is called an isotops. Many isotopes are "stable", that is, they remain as is without change, other isotopes are "unstable" in that they may change spontaneously. The unstable isotope may release energy in this change, this energy may be in the form of alpha, beta and/or gamma radiation, such isotopes are termed radicactive.

The use of a magnetic field gives us an idea of what the parts of the energy of the radioactive isotope is made of, the alpha particle goes to the negative pole; therefore, the alpha particle is positive in charge, the beta particle is drawn to the positive pole. Therefore it is negative, and the campa radiation does not go to either pole; therefore, it must be neutral and we may assume it to be an energy wave such as sound or light or X-ray.

What are alpha and bata rays? Alpha and beta rays are not rays at all, but particles. Alpha rays (particles) are holium atoms that are positively charged because of the loss of two electrons. Esta rays (particles) are very high speed electrons.

Some facts about alpha and beta particles -

- (1) Alpha "rays" are entirely absorbed in an inch or two of air, or even a sheet of paper.
- (2) Beta "rays" can be detected after traveling several yards or in about 1/4" of plastic.
- (3) While both alpha and beta "reys" ionize (charge the air negative or positive) gases through which they pass, the alpha particle ionizes more than the bota particle.

What are ganna rays? Camba rays are waves of energy. Some facts about gains rays -

- (1) Genera rays are similar to X-rays except gamma rays are of much shorter wave length.
- (2) Gamme rays are not detected by electric or magnetic fields.
- (3) Games rays ionice gases through which they pass.
- (4) Gamma rays are detectable after passing through steel, conerste, lead, etc.
- (5) The effectuation of genue rays passing through a material is a function of the density of the material:

Canna rays are electromagnetic photons, identical in nature with X-rays and for this reason it is possible to use radioactive inotopss as a substitute for X-rays.

UNITS OF RADJATION DOSE

Curie: The original usage was the quantity of radon in equilibrium with one gram of radium. Later the definition was "that quantity of material which undergoes the same number of disintegrations per second as one gram of radium".

A curie is now defined as that quantity of radioactive material which undergoes 37 billion disintegrations per second. (Symbol C)

Reentgen: Unit of radiation intensity only, is now defined as that quantity of radiation, that ionizes lee of air to produce one electrostatic unit of electricity of either sign, or; that quantity of radiation such that the associated corpuscular emassion per 0.001293 group of air produces in air ions carrying one electrostatic unit of quantity of electricity of either sign. (Symbol R)

Rad: The unit of absorbed dose which is 100 ergs per gram of material and is the measure of the energy imparted to matter by ionizing particles per unit mass of irradiated material at the phase of interest.

<u>Rem:</u> The reentgen-equivilant-man. That quantity of any type of ionizing radiation which, when absorbed by man, produces an effect equivalent to the absorption by man of one roontgen of X or gamma radiation.

The following are considered equivalent to a doss of one rem -

- 1 Roontgon of X or gamma radiation.
- 1 Rad of X, garma, or bata radiation.
- 0.1 Ead of neutrons or high energy provone.
- 0.05 Ead of particles heavier than protons with sufficient energy to reach the leas of the eye (alpha and accelorated dauterons).

15472

3

Milliourie: 1/1000 of a curie, 1000 milliouries are required to make . eno curie. (Symbol me)

Milliram: 1/1000 of a row, 1000 millireas are required to make one rem. (Symbol mr)

Microcurio: 1/1,000,000 of a curio, one million microcuries required to make one curio. (Symbol gc)

HAZARDS OF EXCERSIVE RADILITICH

Exposure by radiation occurs to all humans, animals and matter. This exposure is natural and is in the form of cosmic rays. These cosmic rays average about 0.1 R/year at sea level; in higher altitudes such as Denver it may be as high as 0.5 R/year. An x-ray examination may be as high as 0.5 R to 5 R per exposure, while a fluorescopic examination may produce 10 to 20 R per minute of exposure.

The present A.E.C. regulations limit exposure decages to 1.25 E per calendar quarter to the whole body, genads, eyes and blood forming parts except where specific requirements are not. This amounts to less than 100 mr/week. The total accumulative decage should not exceed 5 times your age at the last birthday less 5 minus 18 (5 (age-18)). This is no more than an average of 5 R for each year after your 18th birthday. The maximum doce in one weak should not enceed 300 mr (when permission is granted). Emergency emposures to 25 Rems once in a lifetime is assumed to have no affect on radiation telerance.

The estimated doze for varying degree of injury might be put into table form as follows:

Dose Rate	Period of time	Effect
500 R/day	2 days	Death nearly 100%
100 R/day	Until doath	Average survival time 15 days, 100% death 30 days.
60 R/day	10 days.	Death or high rate of crippling injuries
30 R/day	10 days	Moderate disabilities
10 R/day	365 days	Some deaths
3 R/day	Fow months	No drop in efficiency
0.5 R/day	Many months	No large scale drop in

The effect of acute radiation cosage to the whole body is:

0-25 R 25-50 R 50-100 R 100-200 R 200-400 R 400 R 600 R or more

No obvious injury Blood change - no injury Blood change, some injury Injury, possible disability Injury and disability, death possible Death to 50% 100% Death

es:

1

METHODS OF CONTROLLING RADIATION. DOSE

The three methods of controlling radiation dose are (1) shielding (2) distance and (3) time.

A short description is included along with an example or two for each method of control. In actual practice all three methods are used at the same time, only under very rare circumstances would one or two methods be ignored. Therefore, for field use or calculations for safe operations each part must be applied when calculations for radiation protection are made to determine what the radiation will be.

Shielding

One of the means of protection against exposure to radiation is the placement of some material between the source of radiation and the individual. This process is called shielding.

Shielding, or to be more correct, the absorption of radiation, reduces the intensity of radiation from isotopes according to the shielding thickness and density.

The effectiveness of the shielding material varies according to its density and also varies according to the radiation emitted from the various isotopes.

The thickness of a material required to reduce radiation intensity to one half or one tenth of its previous value is called its half value layer (HVL) or its tenth value layer (TVL). The following tables are the values for common materials with Colbalt and Iridium:

Mater	ial	C. 60	I _R 192
Lead	1/10 1/2	1.62" 0.49"	0.64" 0.19"
Concr	ete 1/10	8.6"	6.2"
Alumi	num 1/2	2.6"	1.9"
Iron	1/10 1/2	2.90"	2.0" 0.61"

The following are examples for shielding problems:

Example (1) How much lead is required to reduce 15000 mr/hr C_0^{60} Radiation intensity to 15 mr/hr?

	Radiation	Pb (TVL	.) Inches
Solution	15000 nur/h 1500 mr/h	r 0 r .1	01.62
	150 mr/h 15 mr/h	r 3.	4.86

Example (1) continued -

Answer - 4.86 inches load required.

Example (2) How much concrete is required to reduce Iridium radiation intensity from 25000 mr/hr to 2.5 mr/hr?

	Radiat	ion	Concrete	(TVL)	Inches
Solution	25000 2500 250 250	mr/hr mr/hr mr/hr mr/hr	0 1 2 3		0 6.2 12.4 18.6
	2.5 1	mr/hr	4		24.8

Answer - 24.8 inches of concrete required.

The attached chart may be used to calculate the amount of lead or concrete required by use of a reduction factor. An example of this would be 50,000 mr/hr of Cobalt down to 5 mr/hr. This is a reduction of 50,000 mr/hr 10,000 per the chart 35 inches of concrete are required.

Distanco

The best retection from radiation is some shielding material, the heavier (or denser) the material the batter, but shielding materials are not always available in a useable shape or quantity. Therefore, another protection for radiation safety must be used. This is distance between the source of radiation and the individual.

The method for calculation of distance and radiation intensity is the inverse square low. Since X-rays and gamma-rays travel in straight lines in all directions, it can be said that if an operator is two feet away from a source he will receive 1/4 the radiation he would receive if he were one feet away. $I = \frac{1}{12}$.

More often the operator is concerned with determing what an intensity will be at a new or unknown distance. These then are unknowns to him and can be calculated from the known distance and known intensity, hence the following formula.

IU = DK	DK	IU Ir	Intensity Unknown Intensity Known		
-K	20-	DK2 .	Distance X Distance	of	Known
		D112 .	Distance X Distance	05	Unknown

From this one formula all distances or intensity factors can be calculated.

The following is the radiation emitted from one curie of Cobalt or Iridium in mr/hr.

Isotopa	1 Moter *		1 Foot
C060	1350		14500
IR ¹⁹²	550	(1, 1)	5900

(* 1 Meter equals 39.37 inches)

Example (1) 1 Curie of Cobalt. What is its intensity at 5 feet?

IU IK						
IU			1	x	1	foot2
14,500	mr/hr		5	x	5	foot2
	<u>IU</u> <u>IK</u> <u>IU</u> <u>14,500</u>	$\frac{IU}{IK} = \frac{DK^2}{DU^2}$ $\frac{IU}{14,500 mr/hr}$	$\frac{IU}{IK} = \frac{DK^2}{DU^2}$ $\frac{IU}{14,500 \text{ mr/hr}}$	$\frac{IU}{IK} = \frac{DK^2}{DU^2}$ $\frac{IU}{14,500 \text{ mr/hr}} = \frac{1}{5}$	$\frac{IU}{IK} = \frac{DK^2}{DU^2}$ $\frac{IU}{14,500 \text{ mr/hr}} = \frac{1 \text{ x}}{5 \text{ x}}$	$\frac{IU}{IK} = \frac{DK^2}{DU^2}$ $\frac{IU}{14,500 \text{ mr/hr}} = \frac{1 \times 1}{5 \times 5}$

 $IU = 14,500 \, mr/hr$

Answer IU = 580 mr/hr

Example (2) 0.5 curie of Iridium. What intensity at 3 feet?

Solution

6 1

n 0.5 curlo = 0.5 x 5900 mr/hr at 1 foot 0.5 curlo = 2950 mr/hr

 $\frac{I_U}{I_K} = \frac{D_K^2}{D_U^2}$ $\frac{I_U}{I_U} = \frac{1 \times 1 \text{ foot}^2}{3 \times 3 \text{ foot}^2}$ $\frac{I_U}{Mr/hr} = \frac{2950 \text{ mr/hr}}{9}$

Answer

IU = 339 mr/hr

EXAMPLES USING TIME

1 hour = 60 minutes 1 minuto = 60 seconds

Example (1) If the radiation at a given point was 20000 mr/hr, what would be the maximum time you could remain there to get a case of less than 11 mr?

> Solution: (a) 20000 mr/hr 60 min/hr

(b)	\$\$3.3	mr,	min
(b)	333.9	mr	min
	60 8	CC,	min

(c) 5.55 mr/sec x 2 sec

5.

Answer 11.10 mr for 2 seconds

Example (2) How many mr would you receive in 10 seconds from

radiation of 15000 mr/hr?

Solutions	(a)	12000	mr/hr	
		.00	min/nr	

(b)	250 mr/min	
	250 mr/min	
	60 scc/min	

(a) 4.16 mr/sec

(d) 4.16 mr/sec x 10 sec.

Anowor:

41.6 mr

WORKING TIME

9

When shielding is not available for protection against radiation and the area in which you must work is restricted, one other means of safety from radiation remains and that is the amount of time of exposure you can telerate. The determination is straight forward.

> 1 hour equals 60 minutes 1 minute equals 60 seconds 1 hour equals 3600 seconds

(Example 1)

How many seconds could you remain in a radiation area where the intensity is 6000 mr/hr if you do not want to receive over 10 mr.

 $\frac{6000 \text{ mr/hr} \div 3600 \text{ sec/hr}}{\frac{6000}{3000} \text{ mr/sec} = \frac{5}{3} \text{ mr/sec}}$ $\frac{10 \text{ mr} \div \frac{5}{3} \text{ mr/sec}}{\frac{10 \text{ mr}}{5} \text{ mr/sec}} = \frac{6 \text{ seconds}}{5}$

(Example 2) If you remained in a radiation of 10000 mr/hr for 30 seconds how much radiation would you receive?

Solution:

10000 mr/hr = 3600 sec/hr

10000 mr/hr 3800 sec/hr

mr/sec

2.22 mr/sec x 30 sec

Answer 66.6 mr

BOORUM & PEASE "Note

RADIATION DETECTION

Uso of Radiation Survey Instrumenta

Survey moters used for detection of radiation are of the ionization type. In an ionization chamber when ionization occurs in a gas in the presence of an electric field, the ions will move in opposite directions, each going to the electrodes having the charge opposite that of the ion. If the electrodes are connected to a battery, the ions reaching the electrodes will give up their charge and become neutral again, but at the expense of removing charge from the battery. This results in a current flow through the battery and the external circuit. This current, though extremely small, can be measured in torms of radiation intensity required to produce ionization. Instruments of this type are used for health monitoring and survey work.

The actual manual operation is as follows: the instrument is turned to the battery check or filament position which is useful as a quick check to see if the instrument is operable and allowed to warm up. Some instruments have a zero point on the control knob, others are adjusted for zero when on a given scale. The instruments have three ranges, 100X, 10X and 1X in this order, the reason for the descending order is to protect the instrument from going off scale, and possibly bending the indicator order. The scales will measure in the case of the Nuclear Chicage 2586, 2500 mr/hr, 250 mr/hr and 25 mr/hr. The ranges of the Tracerlab SU-1-E are 1500 mr/hr, 150 mr/hr and 15 mr/hr. The instruments are to be used in any case of emergency or where control and survey are to be made as required by AEC regulations Part 20, 30 and 34.

Another type of radiation instrument is the Geiger Counter. This type of instrument is used in areas where radiation intensity is low, where ionization type instruments are not accurate (in our case it is impractical although it might be accurate enough). The Geiger Counter can be used for measurement of low intensity because of the amplification within its ionization chamber as well as the amplification circuits. Each bit of radiation entering the Geiger tube produces an avalanche of ions; each avalanche can deflect a needle or can produce a click or can light a lamp because of the amplification circuit. The Nucleonic Uranium Finder and the Tracerlab Laboratory monitors are this type of instrument. These instruments can be used for monitoring or for reen surveys, but should not be used for any of the surveys required by the N.R.C. unless permission has been given for specific applications.

Calibration Ferformed by Gamma Industries, eve on each instrument.

every three months

The ionization instruments are calibrated in the following manner. Using a known source (type, curage and radiation intensity at one foot), rings are drawn or distances measured for different levels of radiation for each range, two levels for each scale range are required The intensity is calculated for the distances and the ranges to be calibrated. The source location and the center of the ionization tube are lined up. The source is exposed and a reading made, care should be used to protect the person doing the calibration and all who may be around him. Each of the three ranges, the 100X, 10X and 1X, are checked in this manner. Each scale must read + or - 20% to be acceptable for use.

Limitations

The ionization type instruments should not be used where low intensity radiation is present because of its inaccuracies at low intensity ranges.

Geiger Counters chould not be used where high radiation intensity is used because of its tendency to "slug" or to become "inoperable" due to an excess amount of ionization. Each avalanche of ions causes some audible or visible reaction. If these avalanches are so rapid that the Geiger tube cannot recover from the provious avalanche, which may have eccured only a fraction of a second earlier, the audible or visible signal will not register until the avalanches are again reduced. This tendency to "slug" makes this instrument unsatisfactory for emergency or survey work, but does not limit its usefulness as a monitoring tool.

1420

Y.

Survey Techniques

With the knowledge of the source, strength and type of source, it is an easy matter to determine what are safe limits as required by the N.R.C. regulations in Part 20, 30 and 3%. Once the required shielding and distances are laid out, a survey should be made with a calibrated survey (ionization) mater to check the calculated requirements for restricted and radiation areas.

Where a room is built for the specific purpose of containing a radiation source, signs should be affined warning of the presence of radicactive material and also within the room areas of high radiation should be posted, and entries locked or kept under constant surveilance.

Where an outside area is to be used the area must be completely ringed off with rope, wire, fencing, etc. and the radiation areas must be posted and the restricted areas kept under constant surveilance. Signs must notify the passerby of the presence of radioactive materials to reduce the chance of exposure. The area laid out must be surveyed to be sure that the calculated limits of radiation are correct.

The survey technique is very simple thereafter - use the survey mater to check calculations of radiation, use the survey mater to be sure of the presence of radiation, use the survey mater to be sure of the roturn of the isotope to its storage or shielded position, use the survey mater as the best protection against accidental exposure. The knowledge of where radiation exists, how much, and from what direction are the first requirements to setting up protection, and a survey is the only sure method for the radiographer to determine its presence.

9.1.9.4.1

11

12.

PERSONNEL MONITORING FOUIPMENT

Film Endra -

A film sacgo is a piece of photographic film in a waterproof case. An outer case holds the film and metallic filters which discriminate between different energy ranges, (beta, gamma and x-reys). The film hadyo has two parts - a cummulativo (13 wook) part and a wookly part. Incoo films are developed and the blackening erfoct on the film is indicativo of the radiation received by the bacigo and the wearer. An advantage of the film badge is that a record is made which cannot bo altered or lost through improper reading and recording. A disadvantago is the desage received cannot be determined until after development of the film.

Pockot Docimator -

This increment is a quarte fiber electrometer with a microscope to allow it to be read. During the morning the desimeter is charged so the scale reads zero. During the day the wearer may read it at any time and determine the amount of radiation received. The advantage of this instrument is that an operator finding he is receiving too much radiation can adjust his technique to reduce his exposure.

Pocket Chambors -

The pocket chamber is an ionization chamber which is not read directly. The pocket chamber is charged and read on a separate piece of apparatus. The principle of operation is simply this: the pocket chamber is a special form of condenser which discharges during exposure to radiation. The charger is the reading portion of this instrument which also contains the quartz fiber which indicates the amount of radiation received by the pocket chamber and the wearer.

Radiographic Equipmont

The radioactive isotopes will be used in Budd Co. (Camma Corp., Nuclear Systems and presently called Tatnal Measuring Systems) machines. These machines are for remote handling of the isotopes. The Cobalt-60 is contained in the Model 52 Multitren machine which can hold two sources of Cobalt up to 30 curies.

will hold up to 60 curies of Iridium 192. Model 100 will hold up to 100 curies of Iridium 192

The construction of these machines is as follows - the "head" is made of lead and is covered with Aluminum. Within the head is an "S" tube which stores the isotope, the front of the "S" tube is a colimation cone; the back is connected to a lock box.

At the front of the "S" tube a projection tube of woven copper is connected. This guides or locates the source for exposure. At the back is a lock box which is connected to the control cable. This consists of a 46 foot cable and two 23 foot guide tubes. The guide tubes and cable are connected to a crank. The crank moves the "source projection cable" in and out when exposures are to be made.

One end of the cable is silver soldered to prevent it from unraveling; the other end is swagged to a coupling or "disconnect".

The source itself is in a stainless steel capsule which is welced together and swagged to a woven wire on one end; on the other end of this wire is swagged a coupling or "disconnect".

The source coupling is connected to the source projection cable and the guide tube screwed into the lock box and the projection tube is screwed into the "S" tube in the head, and the set-up is complete except for unlocking the head to start the process of radiographic exposures.

When not in use the radioactive isotopes are stored in the head and are locked by the use of a special type lock which fits over the woven wire that is connected to the sealed source. This makes removal of the isotope from the head impossible except in cases of emergency or vandalism.

The N.R.C. regulations set the limits for radiation from the surface of storage containers. These must be adhered to in order to produce a safe operation.

1. 2.