

#### UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

April 17, 1992

Docket No. 50-271

LICENSEE: VERMONT YANKEE NUCLEAR POWER CORPORATION

FACILITY: VERMONT YANKEE NUCLEAR POWER STATION

MEETING SUMMARY OF APRIL 8, 1992 MEETING TO SUBJECT:

DISCUSS VERMONT YANKEE REACTOR VESSEL

FLAWS (TAC NO. M83100)

On April 8, 1992, the NRC staff met with Vermont Yankee Nuclear Power Corporation (the licensee) concerning indications found in the reactor vessel head and cylindrical section at Vermont Yankee Nuclear Power Station (VY). A list of attendees is provided in Enclosure 1. The slides presented by the licensee are included in Enclosure 2.

The following items were discussed during the meeting:

#### High level of confidence

In its April 5, 1992 letter, the licensee stated "The sampling performed by Vermont Yankee provides a high level of confidence that cladding indications do not penetrate into the basemetal." The licensee stated that the meaning of high level of confidence is a level in excess of 95% confidence that 95% of the indications do not extend from the cladding into the base metal.

#### Machine weld laydown vs manual weld laydown of cladding

The licensee stated that cladding by machine weld laydown was less sensitive to cracking than cladding by manual weld laydown.

### Fracture Mechanics Analysis

The licensee presented the results of its Fracture Mechanics Analysis. The licensee's fracture mechanics analysis indicated that cracks would not grow to an unacceptable size for at least 39,000 hours (4.5 years) of operation. Some further fracture mechanics information was requested by the staff which the licensee agreed to provide by April 10, 1992.

## Future Inspection Plans

The staff expressed an interest in the licensee's future inspection plans.

NAC FILE CENTER COPY

9204280034 920417 PDR ADDCK 05000271

The licensee committed to provide a complete plan for future actions no later than 30 days prior to the next scheduled outage.

#### Past Records

The licensee committed to review past inspection records for any reported indications in the cladding of the reactor vessel.

original signed by

Patrick M. Sears, Project Manager Project Directorate 1-3 Division of Reactor Projects - I Office of Nuclear Reactor Regulat

#### Enclosures:

List of Attendees
 Licensee Slides

cc: See next page

OFC	:PDI-3/LA :	PDJ-3 XPM : EMCB	: PDI-3/ADI		
	- 1 / ///	PSears:mw:Jwiggins		7.7	1
DATE	: 4 1/92 :	0/10/92 :4/16/92	: 4/17/9		

DISTRIBUTION:
Docket File 50-271
NRC & Local PDRs
PDI-3 reading file
T. Murley/F. Miraglia
J. Partlow
S. Varga
J. Calvo
V. Nerses
W. Butler
P. Sears
M. Rushbrook
OGC
E. Jordan
David Smith
B. Elliot
E. Trottier
R. Hermann
J. Wiggins
ACRS (10)
R. Lobel, MS17G-21
J. Linville, Region I

Mr. L. A. Tremblay, Senior Licensing Vermont Yankee Engineer

Mr. J. Gary Weigand President & Chief Executive Officer Vermont Yankee Nuclear Power Corp. R.D. 5, Box 169 Ferry Road Brattleboro, Vermont 05301

Mr. John DeVincentis, Vice President Yankee Atomic Electric Company 580 Main Street Bolton, Massachusetts 01740-1398

Regional Administrator, Region I U. S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, Pennsylvania 19406

R. K. Gad, III Ropes & Gray One International Place Boston, Massachusetts 02110-2624

Mr. W. P. Murphy, Senior Vice President, Operations Vermont Yankee Nuclear Power Corporation R.D. 5, Box 169 Ferry Road Brattleboru, Vermont 05301

Mr. Richard P. Cedano, Commissioner Vermont Department of Public Service 120 State Street, 3rd Floor Montpelier, Vermont 05602

Public Service Board State of Vermont 120 State Street Montpelier, Vermont 05602

Chairman, Board of Selectmen Town of Vernon Post Office Box 116 Vernon, Vermont 05354-0116

G. Dana Bisbee, Esq. Office of the Attorney General Environmental Protection Bureau State House Annex 25 Capitol Street Concord, New Hampshire 03301-6937

Mr. James Pelletier Vice President - Engineering Vermont Yankee Nuclear Power Corp. P. O. Box 169, Ferry Road Brattleboro, Vermont 05301

Resident Inspector Vermont Yankee Nuclear Power Station U.S. Nuclear Regulatory Commission P. O. Box 176 Vernon, Vermont 05354

Chief, Safety Unit Office of the Attorney General One Ashburton Place, 19th Floor Boston, Massachusetts 02108

Mr. David Rodham, Director Massachusetts Civil Defense Agency 400 Worcester Road P.O. Box 1496 Framingham, Massachusetts 01701-0317 ATTN: James Muckerheide

Mr. Raymond N. McCandless Vermont Division of Occupational and Radiological Health Administration Building Montpelier, Vermont 05602

Vermont you he best to tressure best Cladefulications MRC Presentation 4/8/92

attendance

Name

Pavid E Smith Barry Elliot KA Herman,

J.T. W1661NS

Warren Hurphy FRANK HELIN

STORE HOL-MAN

Tome OHora ZEN LETTENS

Ant DEMIDORER

Carl Larsen

PAT SEARS

organization.

NRR/FINEB NRR / EMCB

KUS/MI3

ENO STRIFF NRR/EMEB

Varmont you Kor

VERNER YMAKEE

YANKEE ATOMIC Jander Attaine

STRUCTURE luternhy Associate

Yankee Atomic

NRR/PDI-3

Phone

301 504-2711

301 50 + 2709

30.500-1427

301-534-1733

301-504-2795

802-257-5271

80 457-507

508-779-6711

508-779-6711

408-978-8200

508 -606-0291

301-504-2021

Vermont Yankee

Reactor Pressure Vessel

Clad Indications

1992 Refueling

NRC Presentation
April 8, 1992

Warren Murphy (VYNPC) - Senior Vice President and Manager of Operations

Frank Helin (VYNPC) - Project Engineer


John Hoffman (YAEC) - Engineering Manager

Carl Larsen (YAEC) - ISI Level III

Tom O'Hara (YAEC) - Senior Engineer

Ken Willens (YAEC) - Principal Engineer

Art Deardorff (SIA) - Associate



## Sequence of Events

- -Under head examination conducted as recommended by GE SIL 539
- -Linear rust indications observed visually
- One indication manually explored to determine depth and character. Indication became tighter and more diffuse as depth increased, indicative of IGSCC
- -A number of indications were ultrasonically evaluated to determine depths
- -All flaws examined in this phase were sized to be within the nominal clad thickness of 3/16"
- -Independent of this activity the In-Vessel Visual Examination (IVVI) was underway as part of Inservice Inspection Program
- -IVVI observed a rust indication adjacent to one of the four Dryer Support Brackets

- -Area was ultrasonically examined from outside the reactor vessel
- -No indication of flaw propagation into the basemetal or lack of bond was observed
- -IVVI also reported some visual rust indications on inside surface of pressure vessel
- -IVVI Team reviewed the photographs of the under head condition and concluded that the conditions were similar

# **Engineering Evaluation**

-Engineering concluded that the condition was stress corrosion cracking of the stainless steel clad

-Cladding one layer of 309 low carbon stainless steel for machine deposited clad and two layers (309/308) for manually deposited clad

- -Based on prior experience it was concluded that the low carbon properties were probably lost during welding due to carbon pickup from the basemetal
- -Cladding was furnace sensitized during vessel heat treatment process
- -Weld metal can develop IGSCC depending on carbon/ferrite ratio
- -Industry studies show negligible probability of propagation beyond the clad

## Follow-on Actions

- -Fracture mechanics studies performed for added assurance of safe plant operation
- -Analyses based on reactor vessel stress analysis
- -Consideration given to welding residual stress in clad and pressure vessel welds

- -Worst case condition shows minimum of three cycles before a flaw would exceed Code allowable size. (For this to occur it must be assumed that flaw initiated just prior to shutdown and that it grows at worst case rate)
- -Additional UT evaluations conducted on reactor vessel head flange cladding
- -Eight locations 45 degrees apart were selected to ensure areas representative of the entire surface were examined
- -Starting location was 0 Degree azimuth for ready reference in future inspections
- -Sixty (60) indications were sized. All were within the clad thickness
- -Portions of the circumferential indications at upper head region and flange/head weld were UT'd. A number of UT reflectors were observed. None were identified to be greater than the clad thickness

-Four additional areas on the reactor head flange inside surface were examined. Forty two (42) additional UT indications were sized. All were within the clad thickness

-Thirty two (32) indications were UT examined on the vessel shell flange cladding. All were determined to be within the clad thickness

-Ferrite readings were taken at 24 locations on the head flange and twelve locations on the shell flange. All readings were in excess of 5 percent, with the majority greater than 7.5 percent. This would rule out microfissuring, which can occur in low ferrite stainless steel weld metal


-Metal chips were removed from the head and shell flange cladding. The chemical analysis showed high carbon content (0.079 w/o and 0.111 w/o respectively). This supports previous judgement concerning possible carbon pickup from the basemetal during welding

-Follow-on evaluations all support original conclusion that condition is due to IGSCC of cladding


- -More probable in manual clad regions due to low carbon content of machine welded clad (greater tolerance for carbon pickup)
- -Very low likelihood of propagation into low alloy steel basemetal
- -Detailed UT investigation of dryer support bracket indication, which is now known to be at least nine years old, demonstrates no propagation beyond the clad

## VESSEL/HEAD FLANGE/EVALUATION

- · STRESSES
  - Pressure/Bolt-up from Original Stress Report
  - Clad Stress
  - Weld Residual Stress
- FRACTURE MECHANICS MODEL
  - 360° Circumferential Crack in Cylinder
- CRACK GROWTH LAWS
  - SCC: Ford & Andresen Low Sulfur Law
  - Fatigue: ASME Section XI, Appendix A (Negligible)
- ALLOWABLE FLAW SIZE DETERMINED PER ASME SECTION XI, IWB-3600



## B.Z FLANGE CONFIGURATION




\* Par PAD TO G OF 1ST DIEING GALLET USED TO CAMPUTE PERCEUTE USED TO CAMPUTE PERCEUTE

PRUICIPAL SIZESSEN SOURCE OF TABULATED VALUES - See Pgs. I-S1-A32/43

HEAD FLANGE	DIS	DISPLACEMENTS			MEMUrane Stroises		Bunding	
PRELOAD PO	NORMAI	mor Up	RETATION	men. Cha	HOOP STHO	men.	Hoer Hoer	
	***************************************							
	A STORY OF THE SAME AND							
1 + 7	700535	- co 3 9 4	*.acco 5	- 63	- 5-4	1516	474	
2 + 4.379 **	7,50444	100416	-,00022	-93	-427	2353	757	
3 + 7	7,00298	,00431	000-7	-92	-16	3374	1152	
4 1	-, 000004	.00435	T.500 P/	-76	700	4352	1526	
5 +	** ******	.55-21	00172	-40	15/4/	5274	1524	
6+	19101	.00377	- 20166	21	3457	5169	1923	
7 +	.01935	.00264	-, 50007	106	5547	4086	1544	
8 +	101920	.55104	712324	212	7995	1157	763	
9 +	.03910	T. 0001 P	722217	331	10490		- 1:50	
12 +	.047/4		700107	-45	(1,470)	- 12716	- 1040	
	199 0 491	7 50554	,52277	654	13050	-27615	- 12.000	
	ER . 54792	.c::::::::::::::::::::::::::::::::::::	. 20100	878	12460	-77/92	-11440	
	4.50	255.4	. 20105	973	11070	-46757	-1-12	
	103539	.25 TE/	122350	- 5185	4004	5757	1700	
15	05:27	0.0	.53-79	-6537	-15100	-/33/3	200	

FARE ON RE ## + Bending = Tension on INSIDE


Checked by 7 5 Date 0/33/13 Rav. Ha Date 1 Rav. Ha. Date Rav. Ha.



27.26 83

Location No. 1


Location No. 10




Location No. 14

# MERIDIONAL STRESS DISTRIBUTIONS (Applied Stress)






## CLAD STRESS DISTRIBUTION



WELD RESIDUAL STRESS DISTRIBUTION (Cosine Distribution)



# Vermont Yankee Vessel Head



8 Resid./20 Clad

0 Resid./10 Clad



# VESSEL ADJACENT TO STEAM DRYER BRACKET

- STRESSES
  - Pressure
  - Thermal
  - Clad
  - Bracket Loads
- · FRACTURE MECHANICS MODEL
  - 360° Circumferential Crack in Cylinder
- · CRACK GROWTH LAWS
  - SCC: Ford & Andresen Low Sulfur Law
  - Fatigue: ASME Section XI, Appendix A (Negligible)
- ALLOWABLE FLAW SIZE DETERMINED PER ASME SECTION XI, IWB-3600



## VERMONT YANKEE STEAM DRYER BRACKET

SCC GROWTH (OPERATING CONDITIONS)

