

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Turkey Point Unit 3	DOCKET NUMBER (2) 0 5 0 0 0 2 5 0	PAGE (3) 1 OF 0 1
---	--------------------------------------	----------------------

TITLE (4)
Technical Specification - Missed Surveillance

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
07	21	84	84	022	000	08	20	84	Turkey Point Unit 4		0 5 0 0 0 2 5 1
									N/A		0 5 0 0 0

OPERATING MODE (9) N	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)									
POWER LEVEL (10) 1 0 0	20.402(b)	20.405(c)	50.73(a)(2)(iv)	73.71(b)						
	20.405(a)(1)(i)	50.36(c)(1)	50.73(a)(2)(v)	73.71(c)						
	20.405(a)(1)(ii)	50.36(c)(2)	50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)						
	20.405(a)(1)(iii)	X 50.73(a)(2)(i)	50.73(a)(2)(viii)(A)							
	20.405(a)(1)(iv)	50.73(a)(2)(iii)	50.73(a)(2)(viii)(B)							
20.405(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(ix)								

LICENSEE CONTACT FOR THIS LER (12)

NAME Randall D. Hart, Licensing Engineer	TELEPHONE NUMBER AREA CODE: 3 0 5 2 4 5 - 2 9 1 0
--	--

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (if yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

On Saturday, July 21 and Sunday, July 22, the daily calibration of the nuclear power range (thermal power calculation) was not performed as required by Technical Specification (TS) 4.1, Table 4.1-1, item 1 for Unit 3 and Unit 4, respectively. The root cause was a licensed operator oversight that resulted in the calculation not being done while performing Operating Procedure 0204.2, Schedule of Periodic Tests, Checks, and Operating Evaluations. The missed calculations were not discovered until Monday morning, July 23, 1984. Immediate corrective actions taken were the following:

- 1) A check was made to see if the calculation had been done for Unit 3 on July 22. It had been completed and revealed no abnormalities.
- 2) A check was made to see if the calculations had been completed for both Unit 3 and Unit 4 on Monday, July 23, 1984. The calculations had been completed and revealed no abnormalities.
- 3) An additional calculation was done for Unit 4 on Monday, July 23, 1984, and revealed no abnormalities.
- 4) Supervisory discussions were held with the licensed operator and Plant Supervisor - Nuclear on the importance of performing the required surveillances and understanding the significance of their actions.

The health and safety of the public were not affected. Similar occurrences: LER 250-80-012.

8408270203 840820
PDR ADOCK 05000250
S PDR

IE 22



August 20, 1984
PNS-LI-84-294

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Gentlemen:

Re: Reportable Event 84-22
Turkey Point Unit 3
Date of Event: July 21, 1984
Technical Specification - Missed Surveillance

The attached Licensee Event Report is being submitted pursuant to the requirements of 10 CFR to provide notification of the subject event.

Very truly yours,

A handwritten signature in cursive script, appearing to read "J. W. Williams, Jr.", is written over the typed name.

J. W. Williams, Jr.
Group Vice President
Nuclear Energy

JWW/PLP/js

Attachment

cc: J. P. O'Reilly, Region II, USNRC
Harold F. Reis, Esquire
File 933.1

1022
1/1