

Southern Nuclear Operating Company  
Post Office Box 1295  
Birmingham, Alabama 35201  
Telephone 205 868-5086



Southern Nuclear Operating Company

*the southern electric system*

J. D. Woodard  
Vice President  
Farley Project

April 24, 1992

10 CFR 50.73

Docket No. 50-348


U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

Joseph M. Farley Nuclear Plant - Unit 1  
Licensee Event Report No. LER 92-002-00

Gentlemen:

Joseph M. Farley Nuclear Plant, Unit 1, Licensee Event Report No. LER 92-002-00 is being submitted in accordance with 10 CFR 50.73. If you have any questions, please advise.

Respectfully submitted,

  
J. D. Woodard

JDW/EFB:map 2182

Enclosure

cc: Mr. S. D. Ebnetter  
Mr. G. F. Maxwell

9204290422 920424  
PDR ADOCK 05000348  
S PDR

JE22

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Joseph M. Farley Nuclear Plant		DOCKET NUMBER (2) 05000348	PAGE (3) 1 OF 3
---	--	-------------------------------	--------------------

TITLE (4)  
Missed Fire Watch Due To Personnel Error

EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQ NUM	REV	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)	
03	30	92	92	002	00	04	24	92	J.M. Farley - Unit 2	05000364	
										05000	

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR (11)

OPERATING MODE (9) 1	20.402(i)	20.405(c)	50.73(a)(2)(iv)	73.71(b)
POWER LEVEL 100	20.405(a)(1)(i)	50.36(c)(1)	50.73(a)(2)(v)	73.71(c)
	20.405(a)(1)(ii)	X 50.36(c)(2)	50.73(a)(2)(vii)	OTHER (Specify in Abstract below)
	20.405(a)(1)(iii)	50.73(a)(2)(i)	50.73(a)(2)(viii)(A)	
	20.405(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(viii)(B)	
	20.405(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

NAME D. N. Morey, General Manager - Nuclear Plant	TELEPHONE NUMBER AREA CODE 205 899-5156
--	---

COMPLETE ONE LINE FOR EACH FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORT TO NRPDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORT TO NRPDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	X NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
---	------	-------------------------------	-------	-----	------

ABSTRACT (16)

At approximately 1000 on 3-30-92, a Shift Foreman Operating (SFO) recognized that an hourly fire watch patrol required by Technical Specification 3.3.3.9 was not being performed. The fire detection system, 1SW-111, for the Service Water Intake Structure (SWIS) went into spurious alarm at 0846 and was therefore inoperable. The required hourly fire watch was not established until 1025.

Detection System 1SW-111 had been declared inoperable prior to this event on 3-18-92 at 1715. This LCO and the required fire watch on 1SW-111 were cleared at 1850 on 3-19-92. The Unit 1 Unit Operator (UO) properly removed this LCO from his relief checksheet. However, he did not relay this information to the Operator At The Controls (OATC), and subsequently, the OATC continued to record 1SW-111 as being inoperable. When 1SW-111 alarmed on 3-30-92 at 0846, the OATC did not initiate an investigation nor did he inform the SFO of the alarm because he believed the system was already inoperable and that the required fire watches were established.

This event was caused by personnel error due to inadequate communication between the control room operators regarding the operability of 1SW-111.

A fire watch was established within one hour of the SFO's discovery that the system was inoperable. The personnel involved in this incident have been reinstructed on the importance of proper communication. In addition, the incident will be discussed with all on-shift operations personnel.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (5)			PAGE (3)	
		YEAR	SEQ NUM	REV		
Joseph M. Farley Nuclear Plant	05000343	92	002	00	2	OF 3

TEXT

Plant and System Identification:

Westinghouse - Pressurized Water Reactor  
Energy Industry Identification System codes are identified in the text as [XX].

Summary of Event

At approximately 1000 on 03-30-92, it was recognized that an hourly fire watch patrol required by Technical Specification 3.3.3.9 was not being performed on SWIS detection system 1SW-111 [IC].

Description of Event

At approximately 1000 on 3-30-92, the SFO discovered that fire detection system 1SW-111, at the SWIS, was in spurious alarm without the required established fire watch. It was determined that it had been alarming since 0846. The OATC had not informed the SFO because his turnover sheet incorrectly reflected that the system was inoperable and was being covered by a fire watch.

1SW-111 was inoperable and the fire watch required by Technical Specification 3.3.3.9 was not established within the one hour required from the spurious alarm at 0846.

Further investigation revealed that a prior LCO and fire watch on 1SW-111 was cleared at 1850 on 3-19-92. The Unit 1 UO had properly removed this LCO from his relief checksheet. However, he did not relay this information to the OATC, and subsequently, the OATC continued to record 1SW-111 as being an LCO until the problem was identified on 3-30-92.

The required fire watch was established within one hour of discovering that the system was inoperable. System 1SW-111 was returned to service at 0016 on 4-4-92.

Cause of Event

This event was caused by personnel error in that the control room operators failed to communicate revised equipment/system operability status.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (5)			PAGE (3)	
		YEAR	SEQ NUM	REV		
Joseph M. Farley Nuclear Plant	05000348	92	002	00	3	OF 3

TEXT

Reportability Analysis and Safety Assessment

This event is reportable because the hourly fire watch required by Technical Specification 3.3.3.9 was not performed.

This area is normally inspected every four hours by the operations systems operator; and a systems operator had completed a tour of the structure at 0815 on the day of this event.

This event had no effect on plant operation. No fire occurred during the time that the fire watch was not performed. The health and safety of the public was not affected by this event.

Corrective Action

The fire watch was established within one hour of discovering that the system was inoperable.

In addition, the personnel involved in this incident have been reinstructed on the importance of proper communication and this event will be discussed with all on-shift operations personnel.

Additional Information

This event would not have been more severe if it had occurred under different operating conditions.

Unit 1 was operating at approximately 100% power at the time of this event. Unit 2 was shutdown for the 8th Refueling Outage.

No components failed during this event.

The following LERs involved personnel errors in establishing and maintaining fire watches:

Unit 1 (Docket Number 05000348): LERs 84-013-00, 84-015-00, 84-022-00, 86-013-00, 87-006-00, 88-004-00, 90-001-00, 91-001-00

Unit 2 (Docket Number 05000364): LERs 84-007-00, 85-007-00, 85-013-00, 88-004-00, 88-005-00, 90-002-00