

Duke Power Company
Oconee Nuclear Generation Department
P.O. Box 1439
Seneca, SC 29679

J. W. HAMPTON
Vice President
(803)885-3499 Office
(803)885-3564 Fax



DUKE POWER

December 19, 1995

**U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555**

**Subject: Oconee Nuclear Station Unit
Docket Nos. 5-269, -270, -287
Licensee Event Report 269/95-07**

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a) (1) and (d), attached is Licensee Event Report 269/95-07, concerning the past inoperability of the Low Pressure Injection System.

This report will be supplemented to address root cause and other LER content requirements after further investigation is complete.

This report is being submitted in accordance with 10 CFR 50.73 (a) (2) (ii) (A).

Very truly yours,

for J. W. Hampton
J. W. Hampton
/fts

Attachment

**cc: Mr. S.D. Ebner
Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, GA 30323**

**INPO Records Center
700 Galleria Parkway
Atlanta, GA 30339-5957**

**Mr. L. A. Wiens
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555**

**Mr. P. E. Harmon
NRC Resident Inspector
Oconee Nuclear Station**

9512260304 951219
PDR ADDCK 05000269
S PDR

200078

JE22

NRC FORM 366 (4-98)		U.S. NUCLEAR REGULATORY COMMISSION				APPROVED OMD NO. 3150-0104 EXPIRES: 04/30/98					
LICENSEE EVENT REPORT (LER)								ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50 C HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503			
FACILITY NAME (1) Oconee Nuclear Station, Unit One						DOCKET NUMBER (2) 05000 269		PAGE (3) 1 of 1			
TITLE (4) Low Pressure Injection System Technically Inoperable											
EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER(S)	
12	06	95	95	07	00	12	19	95		05000	
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR (Check one or more of the following) (11)									
N		20.402(b)		20.405(c)		50.73(a)(2)(iv)		73.71(b)			
POWER LEVEL (10)		20.405(a)(1)(i)		50.36(c)(1)		50.73(a)(2)(v)		73.71(c)			
0		20.405(a)(1)(ii)		50.36(c)(2)		50.73(a)(2)(vii)		OTHER (Specify in Abstract below and in Text, NRC Form 366A)			
		20.405(a)(1)(iii)		50.73(a)(2)(i)		50.73(a)(2)(viii)(A)					
		20.405(a)(1)(iv)		X 50.73(a)(2)(ii)(A)		50.73(a)(2)(viii)(B)					
		20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(x)					
LICENSEE CONTACT FOR THIS LER (12)											
NAME							TELEPHONE NUMBER				
L. V. Wilkie, Safety Review Manager							AREA CODE				
							(803)	885-3518			
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)											
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS		
F	BI	V	F130	YES							
SUPPLEMENTAL REPORT EXPECTED (14)											
X	YES (if yes, complete EXPECTED SUBMISSION DATE)			NO	EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR		
							02	05	96		
ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single-space typewritten lines) (16)											
<p>* DATE: November 6, 1995 Unit Status: Refueling Shutdown</p> <p>During testing, the Low Pressure Service Water (LPSW) flow to the 1A Low Pressure Injection (LPI) Cooler would not increase from approximately 2500 gpm to 5100 gpm as required. The key which locks the 1LPSW-254 (1A LPI Cooler Outlet Block Valve) valve stem to the valve operator was found out of the keyway, allowing the butterfly valve to partially close.</p> <p>On December 6, 1995, it was determined that flow induced vibration caused the key to come out and the butterfly valve to partially close. Therefore, Engineering concluded that the valve could not be assured to operate under all the design basis conditions. Due to the potential for reduced LPSW flow to the 1A LPI cooler, the 1A LPI train was declared technically inoperable from December 3, 1992 to November 6, 1995. Assuming a single failure of the 1B LPI train along with the failure mode associated with valve 1LPSW-254, heat removal from the LPI coolers could have been degraded following a design basis loss of coolant accident. The degraded heat removal from the LPI coolers would not have interrupted LPI flow to the core or resulted in challenges to the containment design pressure. However, the degraded LPI cooler heat removal capacity could have resulted in exceeding the environmental qualification (EQ) limits on containment temperature and pressure. The impact of the degraded containment heat removal on equipment qualification is still under evaluation.</p> <p>The valve was modified to prevent the key from vibrating out of the keyway. This report will be supplemented to address root cause and other LER content requirements after further investigation is complete.</p>											