NRC For (9-83)	- 386						ENSE		NT RE	PORT	(LER)	U.S. NU A E	CLEAR REGULAT	ORY COMMI	BION
						LIC	ENGE			roni	(LEA)				
FACILIT	Y NAME (11 0 m (Tono	rat	ing S	tation	- 1	Init	2			DOCKET NUMBER	(2)	PAGE	130
-	6) 6)	em c	Jene	Lau	ing b	cación			-			0 15 10 10		-11 1060	ſ
	Bot	h Co	onta	inn	nent S	pray S	yste	ems I	nope	rable	e in Mod	le 4			
EVENT DATE (5) LER NUMBER (6)				REPORT DAYE (7) OTHE				FACILITY NA	A FACILITIES INVOLVED (8) AMES DOCKET NUMBER(S)						
NUMBER NUMBER							0 15 0 0 0 0			1					
017	216	814	81 4	1-	0 11 19	-010	018	214	8 4				0.5.0.0		
0	ERATING	-	-	EPORT	IS SUBMITTI	D PURSUANT	TO THE P	REQUIREM	ENTS OF 1	D CFR §: /	Check one or more	of the fallowing) (1	1)	1-11	
MODE (9) 4 20.402(b) POWER LEVEL (10) 0 0 20.406(a)(1)(i) 20.406(a)(1)(ii) 20.406(a)(1)(iii) 20.406(a)(1)(iii) 20.406(a)(1)(iii) 20.406(a)(1)(iii) 20.406(a)(1)(iii) 20.406(a)(1)(iv) 20.406(a)(1)(iv) 20.406(a)(1)(iv)					20,405(c) 50,73(s)(2)(iv) 50,35(c)(1) X 50,73(s)(2)(v) 50,36(c)(2) 50,73(s)(2)(vi) 50,73(s)(2)(vii) 50,73(s)(2)(ii) 80,73(s)(2)(vii) 50,73(s)(2)(vii) 50,73(s)(2)(iii) 80,73(s)(2)(vii) 50,73(s)(2)(vii) 50,73(s)(2)(iii) 50,73(s)(2)(vii) 50,73(s)(2)(vii)				50.73(a)(2)(iv) 50.73(a)(2)(v) 50.73(a)(2)(vii) 50.73(a)(2)(viii) 50.73(a)(2)(viii) 50.73(a)(2)(viii) 50.73(a)(2)(x)	73.71(b) 73.71(c) OTHER (Specify in A) Delow and in Text, NI 366A)		pecify in Abet in Text, NRC i	Net Form		
NAME							ICENSEE	CONTACT	FOR THIS	LER (12)			TELEPHONE NUM	ARER	
	J.	L.R	lupp									AREA CODE	3 3 9 -	- 4 3	0 9
	T			Τ.	COMPLETE	ONE LINE FOR	EACH C	OMPONEN	T FAILURE	DESCRIBE	D IN THIS REPOI	RT (13)	1 1		
CAUSE	SYSTEM	COMP	ONENT	-	TURER	TO NPRDS			CAUSE	SYSTEM	COMPONENT	TURER	TO NPRDS		
1.1.1													1		
				1			<u>+</u>					+	-		
			11				<u> </u>							L	•
					SOFFLEME	INTAL REPORT	EAPECT	20 (14)				EXPECTI	ED MONT	H DAY	YFAR
YE	S Ilf yes, a	omplete E	XPECTEL	SUBA	ISSION DATE			X NO		-		DATEO	5)		1
On In Co sp Mo re bo wh Co Sp wa of we Co The of ree mi 100	Cul tegr olin ecif de c ques th C ile ndit ray s di the re s ntai e in com ques tiga CFR	y 26 ated g Sy ic R hang ts w onta the ion Syst tag atis nmen cide muni t. ting 50.7	operations operations	984 era tor th mat tor to to to to to to to to to to to to to	, a co ting I quipme Coola e proo de rea Spray as in eratic be op the Sh ordere ily te y Syst attri , and the Co m, its) (v) (I	ontrol: Procedu ent to ant Sys cedure ady. If y Pumps Mode a on 3.6 berable hift St ed an o ested a tems we buted insuff ontain s inope ().	led ure be stem was Alth s we 4. .2.1 e in uper oper and ere to fici ment erab	coold No. 0 admin temp rev: ough re in Howe requ Mode vison abil: retur inope perso ent Spra ility	down 6 req nistr perat iewed the nadve ver, uires es 1, r imm ity t rned erabl onnel instr ay Sy y is	to M uire ativ ures and tagg rten Tech two 2, dest to a est to a err ucti stem repo	cde 5 w s vario ely cle . In a the ap ing req tly cle nical S indepe 3 and 4 tely au on the n operal r appro or; a co ons whe serves rtable	as being us Emerg ared and nticipat propriat uests we ared and pecifica ndent Co . When thorized pumps. ble stat ximately ombinati n issuir as an a in accor	g perfor gency Co l tagged tion of te taggi ere corr l tagged tion Li ontainme the err l the re Both pu tus. The three to of 1 ing the t inccident	med. ore 1, at the ng cect, 1 mitin ent cor elease mps hours ack aggin th	a a
		840 PDR 5	8300 ADC	400 ICK	0 8408	24 9311 PDR					1	CE 22			

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

Salem Generating Station	DOCKET NUMBER	LER NUMBER	PAGE
Unit 2	05000311	84-019-00	2 OF 4

PLANT AND SYSTEM IDENTIFICATION:

Westinghouse - Pressurized Water Reactor

Energy Industry Identification System (EIIS) codes are identified in the text as [XX].

IDENTIFICATION OF OCCURRENCE:

Depressurization and Cooling Systems - Both Containment Spray Systems Inoperable

Event Date: 07/26/84

Report Date: 08/24/84

This report was initiated by Incident Report No. 84-116

CONDITIONS PRIOR TO OCCURRENCE:

Mode 4 - Rx Power 000 % - Unit Load 0000 MWe

DESCRIPTION OF OCCURRENCE:

Following a reactor trip/safety injection on July 25, 1984, it was necessary to place the Unit in Mode 5 in order to facilitate a thorough investigation and effect the required repairs. For the circumstances surrounding the reactor trip and safety injection, see LER 84-018-00.

At 0339 hours, July 26, 1984, while performing the controlled cooldown to Mode 5 in accordance with Integrated Operating Procedure 6 (IOP-6), "Hot Standby to Cold Shutdown", both Containment Spray Pumps [BE] were inadvertently cleared and tagged for the Shift Supervisor, while the Unit was still in Mode 4. This action is prohibited by Technical Specifications; i.e., Technical Specification Limiting Condition For Operation 3.6.2.1 requires two (2) independent Containment Spray Systems to be operable in Modes 1, 2, 3 and 4.

At approximately 0530 hours, July 26, 1984, while monitoring the progress of the cooldwown, the Shift Supervisor observed that both Containment Spray Pumps were tagged. Realizing that the Unit was in Mode 4, he immediately authorized the release of the tags, and instructed the NCO's to perform an operability test on the pumps. Technical Specification Limiting Condition For Operation 3.0.3 was entered retroactive to the time of occurrence. At 0551 hours, the tags were removed and the 4KV breakers for No. 21 and No. 22 Containment Spray Pumps were made operable. At 0634 hours, both pumps were satisfactorily tested and returned to service, and Technical Specification Limiting Condition For Operation 3.0.3 was terminated.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

Salem Generating Station	DOCKET NUMBER	LER NUMBER	PAGE
Unit 2	05000311	84-019-00	3 OF 4

APPARENT CAUSE OF OCCURRENCE:

IOP-6 requires various Emergency Core Cooling System equipment to be administratively cleared and tagged, at specific Reactor Coolant System [AB] temperatures. When the cooldown commenced, at 2000 hours, July 25, 1984, the Shift Supervisor reviewed the procedure and made the tagging requests ready, in anticipation of the pending mode changes. The tagging requests were turned over to the relieving shift at 2300 hours.

The relieving Shift Supervisor reviewed the tagging requests and the cooldown procedure, and upon entering Mode 4, instructed the Nuclear Control Operator (NCO) at the desk to have the equipment cleared and tagged. At this point, the Shift Supervisor became involved with other requirements of the cooldown procedure. Not differentiating the Technical Specification Mode requirements for the operability of the Containment Spray Pumps, the desk NCO initiated the tagging of the Emergency Core Cooling System pumps. The NCO at the Control Console, who was signing off the steps as he proceeded with the cooldown, apparently had no knowledge of the tagging of the Containment Spray Pumps.

The following personnel errors contributed to the occurrence:

- The Shift Supervisor failed to provide adequate instructions when issuing the tagging requests.
- (2) The desk NCO did not consult the procedure when initiating the tags.
- (3) There was a lack of communication between the two NCO's, in regard to the tagging of the pumps.

ANALYSIS OF OCCURRENCE:

The Containment Spray System is designed to provide the following functions:

- Containment cooling and depressurization, following a high energy line break (primary or secondary).
- (2) Addition of Sodium Hydroxide (NaOH) for removal of elemental iodine from the containment atmosphere, following a Loss of Coolant Accident (LOCA).

The Containment Fan Coil Units [BK] provide one-hundred percent (100%) backup for the containment cooling function; however, there is no backup for the NaOH addition function. Because the Unit was in Mode 4 at the time of this occurrence, the possibility of an accident requiring activation of the Containment Spray System was significantly reduced.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

Salem Generating Station	DOCKET	NUMBER	LER	NUMBER	PAGE
Unit 2	05000	311	84-0	019-00	4 OF 4

ANALYSIS OF OCCURRENCE: (cont'd)

Since the Containment Spray System serves only as an accident mitigating system, this event involved no immediate threat to the health or safety of the public. However, due to a condition, which alone could have prevented the fulfillment of the safety function of a system that is needed to mitigate the consequences of an accident, the event is reportable in accordance with the Code of Federal Regulations, 10CFR 50.73(a)(2)(v)(D).

CORRECTIVE ACTION:

All personnel involved in the occurrence were counseled concerning their actions. The occurrence was discussed in the Operations Department Newsletter, with the purpose of re-emphasizing the responsibilities of licensed operators when in the process of heatups and cooldowns.

muguchi for

General Manager-Salem Operations

JLR:tns

SORC Mtg 84-113



Public Service Electric and Gas Company P.O. Box E Hancocks Bridge, New Jersey 08038

Salem Generating Station

August 24, 1984

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Dear Sir:

SALEM GENERATING STATION LICENSE NO. DPR-75 DOCKET NO. 50-311 UNIT NO. 2 LICENSEE EVENT REPORT 84-019-00

This Licensee Event Report is being submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(v)(D). This report is required within thirty (30) days of discovery.

Sincerely yours,

support

J. M. Zupko, Jr. General Manager -Salem Operations

JR:kll

CC: Distribution

TEZZ 1/1 95 2189 (20M) 11 BT

The Energy People