U.S. NUCLEAR REGULATORY COMMISSION APPROVED OME NO 3150-0104 LICENSEE EVENT REPORT (LER) EXPIRES 4/31/88 FACILITY NAME (1) DOCKET NUMBER (2) Vermont Yan' Nuclear Power Station 1 OF 0 1 0 |5 | 0 | 0 | 0 | 2 | 7 | 1 Reactor Scram While Shut Down due to loss of Vital Bus LER NUMBER (6) REPORT DATE (7) OTHER FACILITIES INVOLVED (8) SEQUENTIAL FACILITY NAMES DAY DAY DOCKET NUMBER(S) YEAR YEAR YEAR 0 | 5 | 0 | 0 | 0 | 814 10 0 1 8 213 214 8 1 4 0 | 5 | 0 | 0 | 0 | THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR & (Check one or more of the fallowing) (11) MODE (8) 20.402(1) 50.73(a)(2)(le) 73.71(b) 30.406(a)(1)(D 90 36(a)(1) 80.73(a)(2)(v) 73.71(e) 0,0 20.406(a)(1)(8) 90 38(a)(2) 50 73(a)(2)(v4) OTHER ISpecify in Adverset below and in Test, NRC Form 365A) 20 ACRIA1(11(W) 60.73(a)(2)(i) 90.73(a)(2)(viii)(A) 20.405(a)(1)(h) 80,73(a)(2)(B) 80.73(a)(2)(viii)(B) 20.408(a)(1)(v) 80 73(4)(2)(0) 60.73(a)(2)(x) LICENSEE CONTACT FOR THIS LER (12) TELEPHONE NUMBER AREA CODE James P. Pelletier, Plant Manager 8,0,2 2,5,7,-,7,7,1,1 COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRISED IN THIS REPORT [13] MANUFAC. TURER TO NPROS SYSTEM COMPONENT CAUSE MANUFAC-TO NPROS CAUSE SYSTEM COMPONENT SUPPLEMENTAL REPORT EXPECTED (14) YEAR MONTH DAY EXPECTED YES III yes, complete EXPECTED SUBMISSION DATE! ABSTRACT (Limit to 1400 species, i.e., approximately fifteen single-spece typewritten lines) (16)

On 7/24/84 the reactor was shut down with the mode switch in the shut down position. A half scram was in due to repair work on "B" RPS MG set. While performing a second verification that the "B" diesel generator 4KV pot fuse drawer was racked in, the operator inadvertantly withdrew the drawer. This resulted in a loss of normal power to Bus 3 which caused a reactor scram on loss of power to the "A" RPS MG set. The operator immediately inserted the drawer allowing the "B" D.G. to auto sync to supply Bus 3 loads.

8408300488 840823 PDR ADDCK 05000271 PDR IE 22

NRC Form 366A

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85

FACILITY NAME (1)					DOCKET NUMBER (2)									LE	R NU		PAGE (3)								
						The state of					YEAR		SEO		NUMBER			NUMBER							
Vermont	Yankee	Nuclear	Power	Station	0	5	0	0	0	2	7	1	8	14	_	0	1	5	_	0,0	0	12	OF	0	12

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On 7/24/84 the reactor was shut down with the mode switch in the shut down position. A half scram signal was present due to repair work on the "B" RPS MG set. At approximately 12:54 PM, while performing a second verification that the "B" diesel generator 4KV Bus pot fuse drawer was racked in, the operator inadvertantly withdrew the drawer causing the 3Tl tie breaker to open de-energizing BUS 3 which resulted in a reactor scram on loss of power to the "A" RPS MG set. The operator immediately inserted the drawer allowing "B" diesel generator to auto sync to supply BUS 3 leads.

The cause of this event is due to insufficient instructions as to the proper method to verify that the 4 KV BUS pot fuse drawer is fully inserted. The corrective action will be to provide more detailed instructions as to the appropriate method to verify the pot fuse drawer insertion.

There have been no similar occurrences of this type reported to the Commission.

Based on the above there were no adverse consequences to the public health and safety.



VERMONT YANKEE NUCLEAR POWER CORPORATION

P. O. BOX 157 GOVERNOR HUNT ROAD VERNON, VERMONT 05354

VYV 84-430

August 23, 1984

U. S. Nuclear Regulatory Commission Document No. 50-271 Washington, D. C. 20555

REFERENCE: Operating License DPR-28

Docket No. 50-271

Reportable Occurrence No. LER 84-15

Dear Sirs:

As defined by 10CFR50.73, we are reporting the attached Reportable Occurrence as LER 84-15.

Very truly yours,

James P. Pelletier Plant Manager

RDP/cjm

cc: Regional Administrator
USNRC Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

IE22