

**DUKE POWER COMPANY**

P.O. BOX 33189

CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

August 22, 1984


Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Subject: Oconee Nuclear Station  
Docket No. 50-287  
RO-287/83-13 Supplement

Dear Sir:

This information supplements Reportable Occurrence Report RO-287/83-13 Revision 1 submitted January 9, 1984 concerning a containment isolation valve, 3CS-5, which was declared inoperable due to leakage past the seat. In accordance with the corrective actions stated in the report, an investigation into the valve failure was conducted. During the Unit 3 End of Cycle 7 Refueling Outage, valve 3CS-5 was checked to determine the cause for the leak past its seat. Leads to the motor were checked for proper motor wiring connections. The bonnet and limotorque operator were removed. The diaphragm was checked with no damage found. However, the diaphragm was replaced with a new one for the purpose of preventative maintenance. The valve was cycled with no additional problems being found.

Very truly yours,



Hal B. Tucker

JCP:slb

cc: Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

INPO Records Center  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339

Mr. J. C. Bryant  
NRC Resident Inspector  
Oconee Nuclear Station

8408300497 840822  
PDR ADOCK 05000287  
S PDR

IE22  
/0

Document Control Desk  
August 22, 1984  
Page 2

cc: Ms. Helen Nicolaras  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555