NRC Form 368 (9-43)									LIC	ENSE	E EVE	NT RE	PORT	U.S. NUCLEAR REQULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES 8/31/86				
St. Lucie Unit 1															and the same of	DEKET NUMBER (2) PAGE (S		
			RPS	S A	ctu	ati	on on	Lo	ss of	Loa	d							
EVENT DATE (6) LER NUMBER (6)							100	REPORT DATE (7)				OTHER	OTHER FACILITIES INVOLVED (8)					
MONTH	ONTH GAY		EAR	YEAR			NUMBER		REVISION NUMBER	MONTH	DAY	YEAR	NA			0 5 0 0 0 1		
0 7	2 6	8	4	8	4		006	-	00	0 8	2 7	8 4				0 1510 10	10111	
	RATING DGE (B)		1.	THE	_	-	SUBMITTE	D PU	RSUANT 1			ENTE OF 1		Chack one or more	of the following) (1			
POWE LEVE (10)	11			20.402(5) 20.406(a)(1)(l) 20.406(a)(1)(H) 20.406(a)(1)(H) 20.406(a)(1)(Iv) 20.406(a)(1)(v)					20.406(e) 90.38(e)(1) 90.36(e)(2) 90.73(e)(2)(ii) 90.73(e)(2)(iii)				X 80.73(a)(2)(v) 80.73(a)(2)(v) 80.73(a)(2)(vii) 80.73(a)(2)(viii)(A) 80.73(a)(2)(viii)(B) 90.73(a)(2)(x)			73.71(a) 73.71(a) OTHER (Specify in Abstract below and in Taxt, NRC Form 366A)		
PAME		-							L	ICENSEE	CONTACT	FOR THIS	LER (12)	1007.5				
Gerald E. Walling/Technical Staff								a1 :	Staff	Engineer					3 10 5	4 6 5 5 -		
		_			_		COMPLETE	ONE	LINE FOR	EACH CO	MPONEN	T FAILURE	DESCRIBE	D IN THIS REPOR				
CAUSE	SYSTEM COM		COMP	PONENT			MANUFAC- TURER		NPRDS			CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO MPROS	•	
х	J, J	JJ		Ш	W 1 2 0		N						111	111				
	l U																	

On 7-26-84, while operating at 99% power, the reactor was tripped by the RPS on a loss of load signal. All automatic functions performed as designed with the exception of the Steam Bypass and Control System (SBCS) which did not fully actuate. As a result, 5 steam generator safety relief valves lifted momentarily as required. All valves reset properly and the unit was stabilized at hot standby with no other problems.

MONTH

EXPECTED

DAY

YEAR

SUPPLEMENTAL REPORT EXPECTED (14)

Investigation revealed that a loose nut in the vacuum trip mechanism allowed pressure to equalize across the diaphragm giving a false low vacuum condition to the DEH which tripped the turbine. The RPS then tripped the reactor on loss of load from the DEH. The nut was replaced and secured with "Locktite" and all associated trip functions tested satisfactorily.

Investigation of the SBCS revealed a failed pressure transmitter which provides a header pressure input to the "Quick Open" logic circuit of the SBCS. Without this input, the SBCS did not quick open on the trip but modulated on a Tavg control program to bring RCS to a hot standby Tavg of 532 F.

Only 4 out of 5 SBCS values operate on Tavg control, and the value stroke time in the modulate mode is 20 seconds verses 3 seconds in the quick open mode, therefore the system did not react fast enough to prevent opening the S/G safety reliefs. The pressure transmitter was repaired, calibrated and returned to service. No adverse consequences to the health or safety of the public resulted from this event.

The unit was returned to power operation.

No further action is contemplated.

YES (If yes, complete EXPECTED SUBMISSION DATE)

ABSTRACT (Limit to 1400 spaces, 14, approximately fifteen single-space typewritten lines) (16)

8409040300 840827 PDR ADOCK 05000335 PDR



August 27, 1984 PNS-LI-84-302

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Gentlemen:

Re: Reportable Event 84-06

St. Lucie Unit 1

Date of Event: July 26, 1984 RPS Actuation on Loss of Load

The attached Licensee Event Report is being submitted pursuant to the requirements of 10 CFR to provide notification of the subject event.

Very truly yours,

J. W. Williams, Jr. Group Vice President

Nuclear Energy

JWW/PLP/js

Attachment

cc: J. P. O'Reilly, Region II, USNRC Harold F. Reis, Esquire File 933.1

> IE22 1/1