

CP&L

Carolina Power & Light Company

34 AUG 20 P 3:24
Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429

August 14, 1984

FILE: B09-13510C
SERIAL: BSEP/84-1781


Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW
Atlanta, GA 30323

BRUNSWICK STEAM ELECTRIC PLANT UNIT 2
DOCKET NO. 50-324
LICENSE NO. DPR-62
SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8 AND
PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (2-SR-84-12)

Dear Mr. O'Reilly:

On July 8, 1984, while performing the functional test of the automatic initiation feature of the Control Building High Velocity Air Control System, PT-46.4, it was discovered that a crack existed in the inner north wall of the Unit 2 computer room on the 49-foot elevation of the Control Building. It was determined the crack rendered the wall inoperable as a plant fire barrier. At the time Unit 2 was in a maintenance/refueling outage. An appropriate Unit 2 fire barrier LCO was initiated to permit repair of the wall. Required repairs to the wall were completed, and on July 18, 1984, it was returned to service. During the time period the subject wall was inoperable, appropriate fire watches were maintained. Carolina Power & Light is investigating the cause of the crack and generic concerns will be appropriately resolved.

Very truly yours,



C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/sdl/LETC1

Enclosure

cc: Mr. R. C. DeYoung
NRC Document Control Desk

8409100075 840814
PDR ADOCK 05000324
S PDR

OFFICIAL COPY

1/0 TE22