Georgia Power Company 40 Inverness Center Parkway Post Office Box 1295 Birmingham, Alabama 35201 Telephone 205 877-7122

C. K. McCoy Vice President, Nuclea Vogtle Project

14



1222

May 18, 1992

ELV-03761 000394

Docket No. 50-425

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D. C. 20555

Gentlemen:

VOGTLE ELECTRIC GENERATING PLANT LICENSEE EVENT REPORT FEEDWATER ISOLATION DUE TO STEAM GENERATOR WATER LEVEL SWELL

In accordance with 10 CFR 50.73, Georgia Power Company (GPC) hereby submits the enclosed report related to an event which occurred on April 28, 1992.

Sincerely

C. K. McCoy

CKM/NJS

Enclosure: LER 50-425/1992-006

xc: Georgia Power Company Mr. W. B. Shipman Mr. M. Sheiban NORMS

> <u>U. S. Nuclear Regulatory Commission</u> Mr. S. D. Ebneter, Regional Administrator Mr. D. S. Hood, Licensing Project Manager, NRR Mr. B. R. Bonser, Senior Resident Inspector, Vogtle

22006;

9205220186 920518 PDR ADDCK 05000425 S PDR

NRC Form 366 (6-89)	LIC	ENS	SEE EV	ENT RI	U.S. K	DCLEAR I	ER)	Y CONNIS	STON	APPPICIALD EXP1R	OHB A	0, <u>3150-</u> 1 30/92	0104	
FACILITY NAME (1)		VUC	TLE ELEC	TRIC GEN	FRATIN	G PLA	VT - UR	CIT 2		OCRET NUMBE	R (2	<u>}</u>	PAGE 1 OF	3
FEEDWATER ISOI	ATIO	4	TO STE	AM GENER	ATOR W	ATER	EVEL :	SWELL					konsed Miles	
EVENT DATE (5)	1	-	NUMBER	(6)	REPL	DAT DAT	E (7)		OTHER	FACILITIES	INVO	LVED (8)	
MONTH DAY YEAR	YEAR	-	SEQ NUM	REV	MONTH	YAG	YEAR	FACILITY NAMES			0 5 0 0 0			
0 4 2 8 9 2	9 2		005	0.0	05	18	92				05000			
OPERATING	THIS	REP	ORT 15 SU	BMITTED F	URSUAN	TOT	HE REQU	I REMEN	IS OF 10 CFR	(11)				
MODE (9)	1	0 40	2(b)		20.40	5(c)		X	50.73(a)(2)(iv)	7	3.71(b)		
POWER	1	20.405(a)(1)(i)			50.36(c)(1)				50.73(a)(2)(v)			73.71(c)		
LEVEL 000	1	20.405(a)(1)(i1)			50.36(c)(2)				50.73(a)(2)(vii)			OTHER (Specify in		
a national sector of the secto	1	0.40	5(2)(1)(1	11)	50.73	(a)(2)	(i)		50.73(a)(2	(VIII)(A)	A	Latract	below	0
	1	0.40	5(a)(1)(1	V)	50.73	(a)(2)	(11)		50.73(a)(2)(viii)(B)				
		0.40	5(0)(1)()	()	50.73	(a)(2)	(111)	50,73(a)(2)(x)						
				LICENS	EE CONT	ACT FO	R THIS	LER (1	5)					
NAME										TE	LEPH	ONE NUM	BER	
										AREA CODE				
MEHDI SHEIBANI	NUC	LEAR	SAFETY	AND COMP	LIANCE	<u>.</u>				706	826	5-3209		
Prophetics - Characteristic Statement Statement Statement		CC	OMPLETE O	NE LINE P	OR EAC	H FAIL	URE DES	CRIBED	IN THIS REP	ORT (13)				
CAUSE SYSTEM COMP	ONENT	M/ T	ANUFAC - URER	REPORT TO NPRDS			CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	RE	NPRDS		
										And the first set of the set				
		1			1	And a second sec								
		ei	IDDI ENENT	AL REPORT	EXPEC	TED (1		1				MONTH	LDAY	YEAR
						EXPECTED SUBMISSIO DATE (15)	N	HORTR	Len (- Can				
TESCIT YES, C	ompre	(e e)	KPECIED S	UDMISSIUN	URIC)	X	MO				-	na ha na	1	Lawrence
ADDIKACI (ID)														

On April 28, 1992, warmup and pressurization of the main steamlines was in progress per the instructions of Unit Operating Procedure (UOP) 12002-C, "Unit Heatup to Normal Operating Temperature and Pressure (Mode 4 to Mode 3)." After achieving a steamline pressure of 30 psig and a steamline temperature of 230 degrees Fahrenheit, operators initiated the opening of the loop 4 downstream main steam isolation valve (MSIV). The upstream loop 4 MSIV was already open. This unexpectedly caused the level in steam generator (SG) 4 to swell and exceed its Hi-Hi level setpoint, resulting in a feedwater isolation (FWI) at Oll5 EDT. The bypass feedwater regulating valves (BFRVs), which were open, automatically closed on receipt of the FWI signal. After restoring the proper level in SG 4, the BFRVs were reopened and normal plant heatup resumed.

The root cause of the event was procedure inadequacy. Procedure 12002-C did not contain adequate procedural cautions to prevent operators from opening the MSIV with a relatively high differential pressure. The procedure led operators to believe that a differential pressure of less than 50 psld across the MSIV was indication of sufficient steamline warming and pressurization. As evidenced by this event, this is not true at low steam generator pressure.

Due to this event, UOP 12002-C has been revised to ensure that an appropriate steamline temperature and pressure exists before opening the second MSIV in any loop.

NRC Form 356A (6-69)	U.S. LICENSEE EVENT REPOR TEXT CONTINUATION	APPROVED OHE NO 3150-0104 EXPIRES: 4/30/92						
FACILITY NAME (1))	DOCKET NUMBER (2)	LER NUMBER (5) PJ					
1			YEAR	SEQ NUM	REV		1	
VOGTLE ELECTR	LIC GENERATING PLANT - UNIT 2	05000425	9 2	006	0.0	2 OF	3	

A. REQUIREMENT FOR REPORT

This report is required per 10 CFR 50.73 (a)(2)(iv) because an unplanned automatic feedwater isolation (FWI) occurred.

B. UNIT STATUS AT TIME OF EVENT

At the time of the event, Unit 2 was in kode 4 (hot shutdown) at 0 percent of rated thermal power. Preparations for entry into Mode 3 (hot standby) were in progress. Reactor coolant system (RCS) temperature and pressure were approximately 337 degrees Fahrenheit and 378 psig, respectively. Steam generator (SG) water levels were being controlled manually by starting and stopping the motor driven auxiliary feedwater (AFW) pumps as necessary. Also, the condensate and feedwater system was on long cycle recirculation with the main and bypass feedwater isolation valves shut, the main feedwater regulating valves open. There was no inoperable equipment which contributed to the occurrence of this event.

C. DESCRIPTION OF EVENT

On April 28, 1992, warmup and pressurization of the main steamlines was in progress per the instructions of Unit Operating Procedure (UOP) 12002-C, "Unit Heatup to Normal Operating Temperature and Pressure (Mode 4 to Mode 3)." The atmospheric relief valves associated with SGs 1, 2, and 4 were open to maintain RCS temperature. To warm the main steamlines, the bypass isolation valves and the bypass control valves for the loop 3 and loop 4 main steam isolation valves (MSIVs) were open.

At 0115 EDT, steamline pressure was approximately 30 psig and steamline temperature was approximately 230 degrees Fahrenheit. This compared to SG pressures and temperatures of approximately 75 psig and 320 degrees Fahrenheit. Per the requirements of Procedure 12002-C, stap B4.3.1.e, opening the MSIVs should not be initiated until less than 50 psid exists across the valve disc. Since this procedure requirement was satisfied, operators opened the downstream loop 4 MSIV (the upstream loop 4 MSIV had previously been opened). This unexpectedly caused the level in SG 4 to swell from approximately 72-percent narrow range (NR) to approximately 90-percent NR. This exceeded the Hi-Hi level setpoint of 86-percent NR which resulted in a FWI and a turbine trip signal. The bypass feedwater regulating valves were the only components which were open/reset and which receive a FWI or turbine trip signal. Therefore, they were the only components which actuated. After restoring the appropriate level in SG 4, the FWI signal was reset at 0141 EDT. Long cycle recirculation was reestablished, and plant heatup was resumed per the instructions of the UOP.

NRC Form 355A (6-09)	U.S. LICENSEE EVENT REPO TEXT CONTINUATIO	NUCLEAR REGULATORY COMMISSION RT (LER) DN	APPROVED 048 NO 3) 50-0104 EXPIRES: 4/30/92						
FACILITY NAME (a na handan and an anna an anna a' anna a' anna a' anna a' anna a'	DOCKET NUMBER (2)	LER NUMBER (5) PAGE	PAGE (3)					
			YEAR STO NUM REV						
VOCTLE ELECT	RIC GENERATING PLANT - UNIT 2	05000425	92 006 00 3 OF	3					
TEXT	where we are a set of the state of the state of the set								

D. CAUSE OF EVENT

The root cause of the event was procedure inadequacy. Procedure 12002-C did not contain adequate procedural cautions to prevent operators from opening the MSIV with a relatively high differential pressure. The procedure led operators to believe a differential pressure of less than 50 psid across the MSIV is indication of sufficient steamline warming and pressurization. As evidenced in this event, this is not true at low steam generator pressure.

E. ANALYSIS OF EVENT

While the circumstances of this event resulted in a level swell in SG 4, this did not result in an unsafe plant condition. A FWI and a turbine trip signal occurred per design when the SG level reached the Hi-Hi level setpoint. The bypass feedwater regulating valves actuated to their proper position upon receipt of the FWI signal. Also, there was no detectable change in RCS temperature due to the change in level for SG No. 4. Based on these considerations, there was no adverse effect on plant safety or on the health and safety of the public.

F. COPRECTIVE ACTIONS

- Procedure 12002-C has been revised to require that steamline temperature and pressure be reasonably close to steam generator temperature and pressure before initiating the opening of the second MSIV in any loop.
- This event will be discussed during 1992 Licensed Operator Requalification Training.

G. ADDITIONAL INFORMATION

1. Failed Components Identification

None.

2. Previous Similar Events

None.

3. Energy Industry Identification System Codes

Main Steam System - SB Main Feedwater System - SJ Auxiliary Feedwater System - BA