LICENSEE EVENT REPORT (LER)														U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMS NO. 3150-0104 EXPIRES. 8/31/85									
FACILITY	NAME !	11	_		-										DOC	KET N	UMBE	R (2)		-	PA	GE (S	
Wash			Nuc	lear	P	ant	- 1	Init	2						0	5	0 10	0 1 0	13 8	17	1 0	0 12	
TITLE (4)				-														-					
RCIC	Isol	at	ion	s on	Hi	igh	Stea	m F	l ow														
EVENT DATE (6) LER NUMBER (6)								REI	PORT DA	отн	OTHER FACILITIES INVOLVED (E)												
MONTH	DAY	YEAR		YEAR SEQUENTIA				REVISION		MONTH	DAY	YEAR	FACILITY NAMES			DOCKET NUMBER(S)							
- 1 -	0 2	8	4 4	8 4		0 18	12		10	018	31.0	814						+	151				
0 8	2 13	0	-			-			10					Charle and as mi		a falla	mos!	_	1510	10	101	11	
	RATING DE (0)		5	-	20 402(b)					20 4064		ENTS OF 1	CFR §: (Check one or more of the following) (1					T	73,71(b)				
POWER LEVEL (10) 0 0 0				20.406(e)(1)(i) 20.406(e)(1)(ii)						50.36(e)(1))(2)		50.73(a)(2)(v) 50.73(a)(2)(vii) 50.73(a)(2)(viii)(A)					73,71(e) X OTHER (Specify in Abstract below and in Taxt, NRC Form 386.4)					
		20.406(a)(1)(iv) 20.406(a)(1)(iv) 20.406(a)(1)(v)					50.73(a)(2)(i) 50.73(a)(2)(ii) 50.73(a)(2)(iii)			50.73(a) (2) (viii) (S) 50.73(a) (2)(x)					50.72(b)(2)(ii)								
										LICENSEE	CONTACT	FOR THIS	LER (12)				_						
NAME													AREA CODE										
R. L. Koenigs, Compliance Engineer										EACH COMPONENT FAILURE DESCRIBED IN THIS R					5 0 9 3 7 7 PAT (13) Ext. 2279				71-	1-12151011			
		-	-								MAPONEN	TFAILURE	DESCRIBE	D IN THIS HE	ORT II	-		T		T			
CAUSE	SYSTEM	CC	COMPO	NENT	NENT MANUFAC			TO NPROS			CAUSE S		SYSTEM	SYSTEM COMPONENT		MANUFAC TURER			TO NPROS				
X	B _i N	P	D I	IS	В	0 8	10		N					11		1							
			1	1		1 1	1						1	111		1	1 1						
						SU	PPLEME	NTAL I	REPORT	EXPECTE	D (14)			Harl			XPEC	TED	A	HTMON	DAY	YEAR	
X YES III VM. complete EXPECTED SUBMISSION DATE!								NO NO						SUBMISSION DATE (15)				0:1	3 0	8 5			

On 8/2/84 and 8/23/84 the reactor was shutdown with the Reactor Core Isolation Cooling (RCIC) System in use to maintain reactor water level. On both dates spurious high steam flow isolations occurred. The isolations occurred at reactor pressures of between 150 to 300 psig.

It was verified that no steam leakage had occurred. After the 8/2/84 event the Condensate System was placed into operation to provide reactor water makeup. Following the 8/23/84 event the RCIC was returned to service.

8409100363 840830 PDR ADDCK 05000397 PDR NAC Form 386A
19-831

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED ONE NO. 3180-0104
EXPIRES 8/31/86

PAGE (3)

VEAR SEQUENTIAL REVISION NUMBER (8)

Washington Nuclear Plant - Unit 2

0 | 5 | 0 | 0 | 0 | 3 | 9 | 7 | 8 | 4 | -0 | 8 | 2 | -0 | 0 | 0 | 2 | 0 | 0 | 2

TEXT (If more specs is required, use additional MRC form 386A to (17)

Plant Conditions

| 8/2/84 | 8/23/84 |
| a) Power Level - 0% 0% |
| b) Operational Mode - 3* 3

Event

On 8/2/84 and 8/23/84, following reactor shutdowns (all control rods fully inserted) Reactor Core Isolation Cooling (RCIC) System isolations occurred while the RCIC system was being used to maintain reactor water level. The isolations resulted from Division II RCIC high steam flow signals, and occurred at reactor pressures of between 150-300 psig during reactor cooldown.

In both instances no other indications were present to support actual high steam flow conditions.

Immediate Corrective Action

Plant personnel inspected the piping for leaks and found none. Following the 8/2/84 event the Condensate System was placed in operation and used for reactor water level control. The reference leg for RCIC-DPIS-13B (instrument which originated signal) was filled with water and the instrument recalibrated.

After the 8/23/84 event the system was reinspected for leaks and the RCIC System returned to service.

Further Corrective Action

An investigation to determine the cause of these spurious trips has been initiated. An additional pressure transmitter will be placed in line with the Differential Pressure Indicating Switch for RCIC Div. 2 Isolation. This additional pressure transmitter will be connected to the Transient Data Analysis System for continuous recording. The Supply System will provide a follow-up to this LER with the results of the above investigation and any corrective actions which are identified.

Safety Significance

In both cases the Reactor had been shutdown (all control rods were full in) and all other safety systems were operational and in standby. In both cases there was no hazard to the safety of the Plant or that of the public.

^{*}Mode switch in refueling position to support SRM surveillance.

Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

Docket No. 50-397

August 30, 1984

Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Subject: NUCLEAR PLANT NO. 2

LICENSEE EVENT REPORT NO. 84-082

Dear Sir:

Transmitted herewith is Licensee Event Report No. 84-082 for WNP-2 Plant. This report is submitted in response to the report requirements of 10CFR50.73 and discusses the item of reportability, corrective action taken, and action taken to preclude recurrence.

This is the follow-up report to the verbal notification given at 0100 hours on August 2, 1984 and at 0205 August 23, 1984.

Very truly yours,

J. D. Martin (M/D 927M) WNP-2 Plant Manager

JDM:mm

Enclosure:

Licensee Event Report No. 84-082

cc: Mr. John B. Martin, NRC - Region V Mr. A. D. Toth, NRC - Site (901A) Ms. Dottie Sherman, ANI INPO Records Center - Atlanta, GA