

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1): Washington Nuclear Project - Unit 2  
DOCKET NUMBER (2): 050003977  
PAGE (3): 1 OF 03

TITLE (4): Isolation Actuation Instrumentation (Temperature Monitors)

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)		
*			84	03	3	0	1	08	3	08	4	050000

OPERATING MODE (9): 2  
POWER LEVEL (10): 001

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more of the following) (11)

<input type="checkbox"/>	20.402(b)	<input type="checkbox"/>	20.406(e)	<input checked="" type="checkbox"/>	50.73(a)(2)(iv)	<input type="checkbox"/>	73.71(b)
<input type="checkbox"/>	20.406(a)(1)(i)	<input type="checkbox"/>	50.36(e)(1)	<input type="checkbox"/>	50.73(a)(2)(v)	<input type="checkbox"/>	73.71(e)
<input type="checkbox"/>	20.406(a)(1)(ii)	<input type="checkbox"/>	50.36(e)(2)	<input type="checkbox"/>	50.73(a)(2)(vi)	<input checked="" type="checkbox"/>	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
<input type="checkbox"/>	20.406(a)(1)(iii)	<input type="checkbox"/>	50.73(a)(2)(i)	<input type="checkbox"/>	50.73(a)(2)(viii)(A)	<input type="checkbox"/>	50.72(b)(2)(ii)
<input type="checkbox"/>	20.406(a)(1)(iv)	<input type="checkbox"/>	50.73(a)(2)(ii)	<input type="checkbox"/>	50.73(a)(2)(viii)(B)	<input type="checkbox"/>	
<input type="checkbox"/>	20.406(a)(1)(v)	<input type="checkbox"/>	50.73(a)(2)(iii)	<input type="checkbox"/>	50.73(a)(2)(ix)	<input type="checkbox"/>	

LICENSEE CONTACT FOR THIS LER (12): R. L. Koenigs, Compliance Engineer  
TELEPHONE NUMBER: 509 377-2501  
AREA CODE: 509

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13): Ext. 2279

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC
X	I, J	- T I S R	279	N					

SUPPLEMENTAL REPORT EXPECTED (14):  
 YES (If yes, complete EXPECTED SUBMISSION DATE)  
 NO  
 EXPECTED SUBMISSION DATE (15): 12 01 84

ABSTRACT (Limit to 400 spaces, i.e. approximately fifteen single-space typewritten lines) (16)

During plant heatup isolations have occurred due to conservative initial setpoints of the Temperature Monitoring Switches which actuate the Nuclear Steam Supply Shutoff System (NSSSS).

Actuations on 4-12-84, 4-18-84, 4-19-84 and 8/14/84 caused isolation of the Reactor Water Cleanup (RWCU) system. The area of the alarm was inspected to verify there was no steam leakage. New setpoints were determined, the switches reset, and the RWCU system returned to service.

- \*Event 1 - 4/12/84
- Event 2 - 4/18/84
- Event 3 - 4/19/84
- Event 4 - 8/14/84

8409100415 840830  
PDR ADCK 05000397  
S PDR

IE 22  
111

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Washington Nuclear Project - Unit 2	DOCKET NUMBER (2)  0 5 0 0 0 2 9 7 8 4	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		- 0 3 3	- 0 1 1	0 2	OF	0 3	

TEXT (If more space is required, use additional NRC Form 388A's) (17)

Plant Operating Conditions Prior to the Events:

- a) Power Level 1%
- b) Operational Mode-2 (Startup)

During initial Plant heatup there have been four Nuclear Steam Supply Shutoff System (NSSSS) isolations of the Reactor Water Cleanup System (RWCU). The isolations were caused by the Leak Detection Temperature Monitors. Table 3.3.2-2 of the Technical Specifications is footnoted to point out that the Leak Detection Temperature Switch setpoints will be determined during the Startup Test Program. The present setpoints are set conservatively low and are adjusted to higher values when the existing setpoint is approached or reached.

Prior to increasing the setpoint an inspection of the area is made to insure temperature increases are not due to leaks. It is anticipated that other isolations may occur if a temperature setpoint is reached prior to increasing the setpoint as Plant heat load increases during the Startup Test Program.

When the final temperature switch setpoints have been determined, a supplement to this LER will be submitted and it will include the isolations reported in this LER and any subsequent isolations resulting from Leak Detection Temperature Monitors which have not been adjusted to their final setpoint.

On 4-12-84 a Division II Leak Detection Temperature Switch monitoring the RWCU pipe routing area actuated and initiated an NSSSS isolation signal which closed RWCU-V-1, causing the subsequent loss of the RWCU system. The temperature switch actuation was due to a conservative setting of the trip setpoint. An inspection of the pipe routing area found that there were no leaks and the temperature switch was adjusted to a higher value, which was still below the allowable value listed in Table 3.3.2-2 of the Technical Specifications. Per Technical Specification 3.3.2 the following note to Table 3.3.2-2 is quoted concerning listed setpoint values.

NOTE: "Initial setpoint. The final setpoint to be determined during startup test program."

The isolation signal to RWCU-V-1 was reset and the RWCU system was returned to service.

On 4-18-84 a Leak Detection Temperature Switch monitoring the RWCU Heat Exchanger Area actuated and initiated a sequence of events the same as described for the 4-12-84 isolation.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Washington Nuclear Project - Unit 2	DOCKET NUMBER (2)  0 5 0 0 0 2 9 7 8 4	LER NUMBER (5)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 4	0 3 3	0 1	0 3	OF	0 3

TEXT (If more space is required, use additional NRC Form 386A's) (17)

On 4-19-84 a Division I Leak Detection Temperature Switch monitoring the RWCU Pipe Routing Area actuated and initiated a sequence of events the same as described for the 4-12-84 isolation. The only difference was that Division I closes RWCU-V-4, the Outboard Containment Isolation Valve.

On 8-14-84 Division I and Division II Leak Detection (LD) System temperature switches actuated and initiated RWCU-V-1 and RWCU-V-4 closures. The sequence of events was the same as described for the 4-12-84 event except the setpoints (124°F) are now above those shown in Table 3.3.2-2.

These events posed no actual or potential safety problem as the leak detection interlocks generated isolation signals as designed and Plant Operators took the appropriate post isolation action.

## Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

Docket No. 50-397

August 30, 1984

Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Subject: NUCLEAR PLANT NO. 2  
LICENSEE EVENT REPORT NO. 84-033-01

Dear Sir:

Transmitted herewith is Licensee Event Report No. 84-033-01 for WNP-2 Plant. This report is submitted in response to the report requirements of 10CFR50.73 and discusses the item of reportability, corrective action taken, and action taken to preclude recurrence.

This is the follow-up report to the verbal notification given at 1825 hours on August 14, 1984.

Very truly yours,

*CM Powers for*

J. D. Martin (M/D 927M)  
WNP-2 Plant Manager

RLK:mm

Enclosure:

Licensee Event Report No. 84-033-01

cc: Mr. John B. Martin, NRC - Region V  
Mr. A. D. Toth, NRC - Site (901A)  
Ms. Dottie Sherman, ANI  
INPO Records Center - Atlanta, GA

IE22  
1/1