50-254



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D.C. 20555-0001

January 23, 1996

Mr. D. L. Farrar Manager, Nuclear Regulatory Services Commonwealth Edison Company Executive Towers West III 1400 OPUS Place, Suite 500 Downers Grove, IL 60515

SUBJECT: SAFETY EVALUATION RELATING TO THE DISCREPANCY OF THE RPV INTERNALS SEISMIC ANALYSIS AT QUAD CITIES, UNITS 1 AND 2 (TAC NOS. M93586 AND M93587)

Dear Mr. Farrar:

During the review of the seismic analyses for the Quad Cities, Units 1 and 2, shroud repair hardware design, a discrepancy was discovered in the nodal mass of the seismic models utilized in those analyses. Consequently, a new analysis was performed to confirm the seismic design adequacy of the existing shroud repair hardware design as well as other reactor pressure vessel (RPV) internals and the major vessel supports.

In the revised seismic analysis to confirm the adequacy of the existing shroud, the licensee refined the analytical techniques that resulted in higher safety margins. The refinements included a more realistic representation of the load sharing between the cracked shroud and the tie rod assembly.

A preliminary assessment of this nodal mass discrepancy was submitted to the staff on September 5, 1995 (Reference 1). The completed core shroud repair seismic analyses for Quad Cities, Units 1 and 2, was submitted to the staff on October 2, 1995 (Reference 2). In its submittal of October 31, 1995 (Reference 3), the licensee addressed the impact on the flaw evaluation of the core shroud at Quad Cities, Unit 1, and summarized the various evaluations performed earlier.

The staff has reviewed these submittals and based on its review has determined that the revised seismic analyses with the corrected mass in the seismic model will not change the conclusions of the staff's previous safety evaluations relative to the core shroud repair hardware for Quad Cities, Units 1 and 2, (Reference 4) and flaw evaluation of the core shroud cracking at Quad Cities, Unit 1 (Reference 5).

9601260033 960123 PDR ADOCK 05000254 PDR

NRC FILE CENTER COPY

D. L. Farrar

- 2 -

Nos. M93586 and M93587.

Our safety evaluation is enclosed. This concludes the activity related to TAC

Sincerely,

Original signed by:

Robert M. Pulsifer, Project Manager Project Directorate III-2 Division of Reactor Projects - III/IV Office of Nuclear Reactor Regulation

Docket Nos. 50-254, 50-265 Enclosure: Safety Evaluation cc w/encls: see next page

DISTRIBUTION: Docket File PUBLIC PDIII-2 r/f J. Roe (JWR) R. Capra C. Moore R. Pulsifer OGC, 0-15B18 ACRS, T-2E26 P. Hiland, RIII J. Rajan J. Strosnider R. Jones R. Hermann K. Kavanaugh

G. Carpenter

DOCUMENT NAME: QUAD\SEISMIC.SE

To receive a copy of this document, indicate in the box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

OFFICE	LA: PU1/11-2 (PM:PDIII-2 e	D;PDIII-2 F
NAME	C. Moore	R. Pulsifernim	R. Capra Ru
DATE	01/2496	01/22/96	01/23/96
AND THE ADDRESS OF THE OWNER.	ade entroit en antipatemente antipatement	OFFICIAL RECORD COPY	

250211

REFERENCES

- Letter, J. Schrage (ComEd) to the U.S. NRC Document Control Desk, Subject - "Dresden Station Units 2 and 3, Quad Cities Station Units 1 and 2, Design Basis Discrepancy Related to Core Shroud Seismic Calculations," dated September 5, 1995.
- Letter, P. Piet (ComEd) to the U.S. NRC Document Control Desk, Subject -"Dresden Station Units 2 and 3, Transmittal of the Dresden Design Documents for the Core Shroud Repair," dated October 2, 1995.
- Letter, P. Piet (ComEd) to the U.S. NRC Document Control Desk, Subject -"Dresden Nuclear Power Station Units 2 and 3; Quad Cities Nuclear Power Station, Units 1 and 2, Transmittal of the Quad Cities Design Documents for the Core Shroud Repair," dated October 31, 1995.
- Letter, Robert M. Pulsifer (NRC) to D. L. Farrar, (ComEd), Subject "Quad Cities Nuclear Power Station, Units 1 and 2, Safety Evaluation Regarding Core Shroud Repair (TAC Nos. M91301 and M91301)," dated June 8, 1995.
- Letter, John F. Stang (NRC) to D. L. Farrar, (ComEd), Subject -"Resolution of Generic Letter 94-03, Intergranular Stress Corrosion Cracking of Core Shrouds in Boiling Water Reactors at Dressden, Units 2 and 3, and Quad Cities Units 1 and 2 (TAC Nos. M90088, M900089, M90109 and M90110), " dated January 31, 1995.

D. L. Farrar Commonwealth Edison Company

cc:

Michael I. Miller, Esquire Sidley and Austin One First National Plaza Chicago, Illinois 60603

Mr. L. William Pearce Station Manager Quad Cities Nuclear Power Station 22710 206th Avenue North Cordova, Illinois 61242

U.S. Nuclear Regulatory Commission Quad Cities Resident Inspectors Office 22712 206th Avenue North Cordova, Illinois 61242

Chairman Rock Island County Board of Supervisors 1504 3rd Avenue Rock Island County Office Bldg. Rock Island, Illinois 61201

Illinois Department of Nuclear Safety Office of Nuclear Facility Safety 1035 Outer Park Drive Springfield, Illinois 62704

Regional Administrator U.S. NRC, Region III 801 Warrenville Road Lisle, Illinois 60532-4351

Richard J. Singer Manager - Nuclear MidAmerican Energy Company 907 Walnut Street P.O. Box 657 Des Moines, Iowa 50303

Brent E. Gale, Esq. Vice President - Law and Regulatory Affairs MidAmerican Energy Company One RiverCenter Place 106 East Second Street P.O. Box 4350 Davenport, Iowa 52808 Quad Cities Nuclear Power Station Unit Nos. 1 and 2

Document Control Desk-Licensing Commonwealth Edison Company 1400 Opus Place, Suite 400 Downers Grove, Illinois 60515

Warren Bilanin, EPRI Task Manager 3412 Hillview Avenue Palo Alto, California 94303

Robin Dyle, Technical Chairman BWRVIP Assessment Task Southern Nuclear Power Company Post Office Box 236 40 Inverness Center Parkway Birmingham, Alabama 35201