



LONG ISLAND LIGHTING COMPANY

SHOREHAM NUCLEAR POWER STATION

P.O. BOX 618, NORTH COUNTRY ROAD • WADING RIVER, N.Y. 11792

JOHN D. LEONARD, JR.
VICE PRESIDENT - NUCLEAR OPERATIONS

September 11, 1984

SNRC-1077

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC 20555

TDI Diesel Generators
Shoreham Nuclear Power Station - Unit 1
Docket No. 50-322

Dear Mr. Denton:

The Safety Evaluation Report, Transamerica Delaval, Inc., Diesel Generator Owner's Group Program Plan, dated August 13, 1984 (Owner's Group SER), was received at LILCO on August 21, 1984. We have also reviewed the Staff letter to the TDI Diesel Generator Hearing Board, dated August 24, 1984, as well as the Staff testimony dated August 30, 1984. LILCO understands that the Staff is considering whether any additional performance testing of diesel generator 101 or diesel generator 102 may be appropriate to provide added assurance regarding the crankshafts and the cam gallery area of the block. The purpose of this letter is to provide you with LILCO's reasons for concluding that additional testing is not required. In addition, given that the loads on the diesel generators in the event of a LOOP/LOCA are now predicted to be lower than those stated in the FSAR, this letter sets forth the basis for revising the loads in the FSAR and defines the "qualified load" pursuant to Section 2.3.2.3 of the Owner's Group SER.

Once the Staff has had an opportunity to review this revised load data, LILCO will revise the FSAR accordingly.

EDG Load

As stated in the Owner's Group SER, a more realistic consideration of the maximum Emergency Diesel Generator (EDG) load requirements and the use of a qualified load would result in enhanced component design margin relative to operation at the nameplate rating. LILCO concurs and believes that the implementation of a qualified load which is less than the EDG

8409130374 840911
PDR ADOCK 05000322
S PDR

13001
1/5

nameplate rating will result in a more reliable machine, while still ensuring that all LOOP/LOCA service load requirements can be accommodated. Accordingly, LILCO initiated an effort to refine the diesel generator required loads and presented in Table 8.3.1-1 of the FSAR. The purpose of this effort was to confirm that the SNPS maximum emergency service load requirements for a LOOP/LOCA are substantially below the EDG nameplate rating and also to justify the establishment of a more appropriate qualified load.

LILCO developed more representative diesel loads by using a combination of analytical and test methods. A review of FSAR Table 8.3.1-1 was performed, together with an analysis that verified the feasibility of deleting the automatic start logic from one of two Reactor Building service water pumps on EDG 103. The results of this analysis, reported to you in SNRC-1065, dated July 3, 1984, resulted in a substantial decrease in both the short term and continuous load requirements for EDG 103.

As SNRC-1065 indicated, bounding peak loads on the SNPS diesels during a LOOP/LOCA were as follows: 3475 kw continuous, and 3500 kw overload. These figures are still excessively conservative because they do not consider measured load data from the Integrated Electrical Test (IET) and individual system/component tests. SNRC-1065 did demonstrate, however, that the 3500kw/3900 kw estimates and safety loads developed during the construction permit stage were overestimated and are no longer appropriate. It should be noted that the previous overload rating of 3900 kw for all three engines was based on short term load requirements on EDG 103 which was formerly 3881 kw. Short term loads on the other two engines have always been below 3500 kw. Thus, the reduction of short term loads on EDG 103, as described in SNRC-1065, makes it appropriate to lower substantially the overload rating for all three engines.

The second phase of the load evaluation used the measured values from the recently completed IET and individual system/component tests as the basis for confirming that the service loads during a LOOP/LOCA event are lower than the current FSAR estimates and the engine nameplate ratings. The use of these test results to establish more appropriate diesel generator loads at the operating license stage of review is consistent with Regulatory Guide 1.9 and the Owner's Group SER.

Analysis of these test results indicates that the short term maximum loads for EDG 101, 102 and 103, representing conservative LOOP/LOCA service load requirements, are 3,291, 3,246, and 3,256 kw, respectively. Table I, attached, provides details on the development of these loads. Therefore, a short term maximum load of 3,300 kw will bound all three machines. Even this figure is conservative because many loads were assumed to be at their maximum levels while in actuality this is unlikely to be the case. Moreover, within twenty minutes after the start of an accident, loads lower than 3,200 kw for all three engines would likely be achieved by operator action to reduce core spray and RHR flow from runout to rated flow conditions.

Crankshaft Testing

As you know, preoperational testing and post-DRQR testing and inspections have been completed. Both the Staff SER as well as the August 24, 1984 letter recommend additional confirmatory testing of a lead diesel for a total of 750 hours of operation at qualified loads if credit is to be obtained for operation of the diesels above 185 BMEP. As we understand the Staff's current view, this testing should be performed to achieve the 10' cycle demonstration for crankshafts.

On August 24, prior to receipt of the Staff testimony and the letter of August 24, I committed LILCO to the performance of a 750 hour demonstration test for the purpose of confirming the acceptability of the crankshaft. This testing was to be performed at a load of 3300 kw. Based on recent discussions with the Staff concerning the crankshaft testing and in light of the discussion above on diesel loads, LILCO has concluded that there is no genuine technical need or justification requiring additional testing of the Shoreham diesels. Sufficient testing at 3,500 kw has already been accumulated on the potential test engine (EDG 101) to more than satisfy the testing requirement for the overload rating. Diesel Generator 101 has approximately 260 test hours at or above 3500 kw. This far exceeds the requirement for 62.5 hours at overload as required by the SER. In addition, of the approximately 260 test hours at or above 3,500 kw, 30.75 hours have been logged at or above 3600 kw. Crankshaft inspections were performed with satisfactory results after 100 hours at or above 3500 kw as part of the DR/QR Program. It is immaterial to the 10' cycle test on crankshafts when during the 750 hours the overload testing is performed.

Further, we are confident, based on our understanding of the Staff's consultants' methodology to determine crankshaft stresses, that they will determine that stresses on the crankshaft, at loads of 3300 kw and below, satisfy the DEMA standard. It is also important to note that ABS has certified the SNPS 13" x 12" crankshaft design and manufacture for 3500 kw.

Significantly, the Saudi Arabian units (Rafha) have accumulated over 6,000 hours at 3,300 kw (on one machine) without crankshaft failure (and many more hours at 3,200 kw on the others) as indicated in TDI letter to the American Bureau of Ships dated April 3, 1984 (attached). This operating experience, coupled with the LILCO data at 3500 kw provides the required assurance that these crankshafts are adequate for the loads outlined above.

Finally, I further believe that the DR/QR final reports, when reviewed by the Staff, will provide the necessary analytical justification to qualify the crankshafts. For all these reasons, therefore, I now conclude that this 750 hour test, which would have cost LILCO approximately \$1.4 million in materials, labor, consultants and fuel over and above the total Shoreham diesel recovery and DR/QR efforts of greater than \$8 million, is not warranted.

Cam Gallery


The Staff has also indicated that some testing would also be helpful in evaluating the cam gallery cracks. As agreed in our conversations with the Staff, 10' cycle/750 hour testing is inappropriate and not required with respect to these cracks. Metallurgical investigations by Failure Analysis Associates (FaAA) of the cam gallery cracks in the old EDG 103 block indicated that these are process cracks and have not propagated during engine operation. The EDG 103 cracks are characteristic of cracks found in the EDG 101 and EDG 102 cam galleries, although inspection reports indicate the cracking was more extensive in EDG 103. Based on the superior microstructure of the EDG 101 and 102 blocks as compared to the old EDG 103 block, less cracking in EDG 101 and 102 was expected and in fact noted. Moreover, even the cracks in EDG 103 had not propagated during more than 1200 hours of engine operation, nor had they affected engine operation, though LILCO will continue to monitor the cracks in the cam gallery areas in accordance with the recommendations of the Owner's Group DRQR Program. Therefore, no additional testing is necessary with respect to the cam gallery area.

Conclusion

I realize that this is a departure from our previous commitment. However, the issuance of the SER, extensive subsequent discussions with your staff, development of a lower qualified load, consideration of existing Shoreham and other pertinent field data and the cost of conducting the 750 hour test all dictate a different conclusion.

I appreciate the open dialogue and cooperation with your staff and remain available at any time to discuss any remaining concerns or aspects of this letter further.

Very truly yours,



John D. Leonard, Jr.
Vice President - Nuclear Operations

BRM:ck

Attachments

cc: P. Eselgroth
C. Petrone
All Parties Listed in Attachment I

ATTACHMENT I

Lawrence Brenner, Esq. ✓
Administrative Judge
Atomic Safety and Licensing
Board Panel
U. S. Nuclear Regulatory
Commission
Washington, DC 20555

Dr. George A. Ferguson ✓
Administrative Judge
Atomic Safety and Licensing
Board Panel
School of Engineering
Howard University
2300 6th Street, N.W.
Washington, DC 20059

Bernard M. Bordenick, Esq.
David A. Repka, Esq.
U. S. Nuclear Regulatory
Commission
Washington, D. C. 20555
*For Federal Express
7735 Old Georgetown Road
To Mailroom
Bethesda, MD 20814

James Dougherty, Esq.
3045 Porter Street NW
Washington, DC 20008

Ralph Shapiro, Esq.
Cammer and Shapiro, P.C.
9 East 40th Street
New York, NY 10016

Secretary of the Commission
U.S. Nuclear Regulatory
Commission
Washington, D.C. 20555

Atomic Safety and Licensing
Board Panel
U.S. Nuclear Regulatory
Commission
Washington, D.C. 20555

Herbert H. Brown, Esq. ✓
Lawrence Coe Lanpher, Esq.
Alan R. Dynner, Esq.
Kirkpatrick, Lockhart, Hill
Christopher & Phillips
8th Floor
1900 M. Street, N. W.
Washington, DC 20036

Mr. Marc W. Goldsmith
Energy Research Group
4001 Totten Pond Road
Waltham, MA 02154

MHB Technical Associates
1723 Hamilton Avenue
Suite K
San Jose, CA 95125

Stephen B. Latham, Esq.
Twomey, Latham & Shea
33 West Second Street
P. O. Box 398
Riverhead, NY 11901

Fabian G. Palomino, Esq.
Special Counsel to the Governor
Executive Chamber, Room 229
State Capitol
Albany, NY 12224

Atomic Safety and Licensing
Appeal Board Panel
U.S. Nuclear Regulatory
Commission
Washington, D.C. 20555

Robert E. Smith Esq.
Guggenheimer & Untermyer
80 Pine Street
New York, New York 10005

ATTACHMENT I

Attachment I
Page Two

Jay Dunkleberger Esq.
New York State Energy Office
Agency Building 2
Empire State Plaza
Albany, New York 12223

Jonathan D. Feinberg, Esq.
New York State
Department of Public Service
Three Empire State Plaza
Albany, New York 12223

Martin Bradley Ashare
Attn: Patricia A. Dempsey, Esq.
Suffolk County Attorney
H. Lee Dennison Building
Veterans Memorial Highway
Hauppauge, New York 11788

Dr. Peter A. Morris ✓
Administrative Judge
Atomic Safety and Licensing
Board Panel
U.S. Nuclear Regulatory
Commission
Washington, D. C. 20555

**Transamerica
Delaval**



Transamerica Delaval Inc.
Engine and Compressor Division
550 85th Avenue
P.O. Box 2161
Oakland, California 94621
(415) 577-7400

April 3, 1984

American Bureau of Shipping
65 Broadway
New York, NY 10006

Attention: Mr. Robert A. Giuffra
Principal Surveyor, Machinery

Subject: Report on Crankshaft Torsional Stresses
Transamerica Delaval Model DSR-48
Serial No. 74010/12
for Long Island Lighting Company

Dear Mr. Giuffra:

As discussed during the meeting on March 14 in your office between yourselves, Mr. Gene Montgomery of LILCO, Dr. Simon Chen of Power & Energy International, Dr. Paul Johnston of Failure Analysis Associates and myself, I am sending you four copies of the "Report on Crankshaft Torsional Stresses" for the three DSR-48 engine generator sets at LILCO's Shoreham plant.

You will note that the report has four sections and contains calculations, test data and operating experience which we consider relevant material to establish the adequacy of these DSR-48 engine generator sets.

The similarity between the DSR-48 referenced in the report are outlined in page 17 and 19. On page 28 are operating hours logged for similar DSR-48. Worthy of note are the Rafha engines which have operated between 5500 hours to 8250 hours at a load level between 3200 KW and 3300 KW. Due to the time constraint on this project, please give this matter your earliest attention. We look forward to receiving your approval.

Very truly yours,

TRANSAMERICA DELAVAL INC.
Engine & Compressor Division

Roland T. M. Yang
Manager Applied Mechanics

RTY:dmh

Enclosures

cc: G. Trussell
G. Montgomery
P. Johnston
ABS-San Francisco

SNPS-1 FSAR

REVISED TABLE 8.3.1-1 for DETERMINATION of

EMERGENCY DIESEL GENERATOR SYSTEM

LOOP+LOCA - QUALIFIED LOADS

Function	Nameplate Rating (Hp)	Total Plant Number	Number Required			Maximum Cold Demand (Kilowatts)	
			Design Basis Loss of Coolant Accident 0-10 Min	Loss of Offsite Power 10 Min on	Loss of Offsite Power (Hot Standby)	DG-101	DG-102
Core Spray Pump	1250	2	1	1	-	998	998
Residual Heat Removal Pump	1250	4	2	1	2	999	999
Service Water Pump	450	4	2	2	3	358	358
RBSVS and CRAC Water Chiller	292	4	2	2	2	235	235
RBSVS and CRAC Water Chiller Lube Oil Pump	.25	4	2	2	2	.2	.2
RBSVS Chiller Circ. Water Pump	75	4	2	2	2	▲ 32	▲ 32
RBSVS Chiller Cond. Water	20	4	2	2	2	76	76
RBSVS Unit Cooler	30	8	4	4	4	86	86
RBSVS Exhaust Fan	100	3	2	2	2	▲ 60.5	▲ 60.5
Reactor Building Exhaust Booster Fan	7.5	2	1	1	1	▲ 3.3	▲ 3.3
RBSVS Filter Reheat Coil	6.6 kW	2	1	1	1	6.6	6.6
RBCLCW Circ. Pump	100	3	2	2	2	80	80
Diesel Generator Air Compressor	10	6	-	-	-	-	-
Diesel Generator Fuel Oil Transfer Pump	.5	6	2	2	2	-	-
Diesel Generator Jacket Water Heater	36 kW	6	-	-	-	—(D)	—(D)
Diesel Generator Jacket Water Keep Warm Pump	2.5 kW	3	-	-	-	—(D)	—(D)
Diesel Generator Lube Oil Heater	20 kW	3	-	-	-	—(D)	—(D)
Diesel Generator Before & After Lube Oil Pump	5	2	-	-	-	—(D)	—(D)
Diesel Generator Heater	4.2 kW	3	-	-	-	—(D)	—(D)
Battery Charger (125 V)	60 kVa	3	2	2	2	20	20
120 V ac Instrument Power	100 kVa DG 101 100 kVa DG 102 50 kVa DG 103	3	2	2	2	80	80
120 V Nonemergency Feeds	65 kVa	-	-	-	X	—(A)	—(A)
Diesel Generator Room Vent Supply Fan	20	3	2	2	2	16	16
Battery Room Vent Supply Fan	2	3	2	2	2	1.6	1.6
Control Room Air Conditioning Unit	40	2	1	1	1	▲ 30.6	▲ 30.6
Control Room Vent Booster Fan	7.5	2	1	1	1	▲ 5.3	▲ 5.3

TI APERTURE CARD

NOTES: ① NOT A D/G 101 LOAD ⑤ LOCKED OUT FOR 10MIN ON LOCA,)
 ② NOT A D/G 102 LOAD MANUAL START AND MANUAL LINE-UP
 ③ NOT A D/G 103 LOAD
 ④ TRIPPED ON A LOCA/LOSS OF OFFSITE POWER
 ▲ ACTUAL MEASURED LOADS

Incident (watt)	...	REMARKS
102	DG-103	
98	- ⑤	NAMEPLATE VALUE
99	▲ 1898	→ AT LEAST 1 DIV. III PUMP WILL BE IN A LOOP WITH DIV. I OF II PUMP; RESULTING IN 100KW SAVINGS
55	.358	→ 1 DIV. III PUMP IN PAR TO LOCK (2) NO AUTO START
235	470	NAMEPLATE VALUE
.2	.4	NAMEPLATE VALUE
32	▲ 64	ACTUAL TEST DATA SHOWED LOAD VALUE OF 32KW vs. 60KW NAMEPLATE
16	32	NAMEPLATE VALUE
96	- ⑤	NAMEPLATE VALUE
6.5	▲ 60.5	
3	- ⑤	
6	- ⑤	NAMEPLATE VALUE
6	- ⑤	NAMEPLATE VALUE
-	-	} LOADS ARE CYCLIC & NOT CONTINUOUS; THEREFORE NOT INCLUDED IN TOTAL
-	-	
①	- ②	
①	- ②	
①	- ③	
①	- ②	
①	- ③	
5	17	FSAR VALUE
0	40	FSAR VALUE
①	- ③	
16	16	NAMEPLATE VALUE
1.6	1.6	NAMEPLATE VALUE
0.6	- ⑤	
1.3	- ⑤	

Also Available On
Aperture Card
8409130374 -01

SNPS-1 FSAR

TABLE B.3.1-1 (CONT'D)

Function	Nameplate Rating (Hp)	Total Plant Number	Number Required		Loss of Offsite Power (Hot Standby)	Maximum Core Demand (Kilowatts)	
			Design Basis Loss of Coolant Accident 0-10 Min	10 Min on		DG-101	DG
Emergency Switchgear, Relay & Computer Rooms Air Conditioning Unit	40	2	1	1	1	30.6	Δ 3
TSC Air Conditioning Unit	40 kW	1	-	1	1	-④	-
TSC Air Cooled Condenser	30 kW	1	-	1	1	-④	-
Emergency Switchgear, Relay & Computer Rooms Exhaust Fan	10	2	1	1	1	Δ 6.7	Δ 0
RBSVA Filter Room Exhaust Fan	3	2	1	1	1	2.4	0
Screened Exhaust Fan	10	2	1	1	1	8	0
Screened Interposing Relay Panel	1 kVa	1	1	1	1	-④	-
MCC Room Ventilation	.75	2	1	1	1	.5	-
LPCI M-G Set Room Ventilation	3	4	2	2	2	2.4	2
Unit Cooler MCC OB1 Room	1.5	1	1	1	1	-④	1
Spent Fuel Pool Cooling Water Pump	30	2	-	1	1	24	2
Loop Level Pump (CS, RHR, HPCI, RCIC)	7.5	4	4	2	4	12	1
Atmospheric Cont. - Hyd. Recombiner	109 kW	2	-	1	-	-④	-
MSIV-LCS Heaters	6.6 kW	4	-	-	-	-④	-
MSIV-LCS Blowers	4.4	3	-	-	-	-④	-
Radiation Monitoring	1	10	-	-	-	4.8	3
Lighting (Equivalent kW)	407.2 kW	-	-	-	X'''	-④	-
Fence Security Lighting	50 kW	-	-	-	X'''	34	-
Reactor Protection System M-G Set '''	25	2	-	-	2	Δ 17.3	Δ 17
Reactor Protection System Backup Transformer	25 kVa	1	-	-	1	-④	-
Battery Charger ±24 V Uninterruptible Power (Vital Bus) '''	3 kVa	4	-	-	-	-④	-
Uninterruptible Power (Security & Communications) '''	37.5 kVa	1	1	1	1	-④	-
Battery Charger (Security and Communication)	20 kVa '''	1	1	1	-	-④	-
Uninterruptible Power (Computer Bus) '''	20 kVa	1	-	-	-	-④	-
Control Rod Drive Pump '''	250	1	1	1	1	16	-
Drywell Cooling System Fan '''	25	2	-	-	1	-④	-
		8	-	-	4	-④	-

TI
APERTURE
CARD

Ident	...	REMARKS
102	DG-103	
0.6	— ©	
④	40	NAMEPLATE VALUE
④	30	NAMEPLATE VALUE
.7	— ©	
4	— ©	NAMEPLATE VALUE
	— ©	NAMEPLATE VALUE
6	— ©	NAMEPLATE VALUE
5	— ©	NAMEPLATE VALUE
4	48	NAMEPLATE VALUE
2	— ©	NAMEPLATE VALUE
4	— ©	NAMEPLATE VALUE
2	— ©	NAMEPLATE VALUE
①	— ©	
②	— ©	
③	— ©	
④	— ©	FSAR VALUE
⑤	— ©	
⑥	26	FSAR VALUE
3	— ©	
	— ©	
	— ©	
	30	FSAR VALUE
	16	FSAR VALUE
	4	FSAR VALUE
	— ©	FSAR VALUE
	— ©	
	— ©	

Also Available On
Aperture Card

8409180374-02

SNPS-T FSAR

TABLE B.3.1-1 (CONT'D)

Function	Nameplate Rating (Hp)	Total Plant Number	Number Required		Loss of Offsite Power (Not Standby)	Maximum Core Demand (kW)	
			Design Basis Loss of Coolant Accident 0-10 Min	10 Min on		DN-101	DN-102
Primary Containment Air Cooler Subfeed	2 kVa	2	-	-	1	-	-
Reactor Water Cleanup Recirc. Pump "A"	60	2	-	-	1	-	-
Suppression Pool Pump Back Pump	25	1	-	-	-	-	-
Main Turbine Turning Gear "A"	60	1	-	-	1	-	-
Main Turbine Piggyback Turning Gear Drive	0.5	1	-	-	1	-	-
Main Turbine Turning Gear Oil Pump "A"	40	1	-	-	1	-	-
Main Turbine Bearing Lift Pump "A"	5	7	-	-	7	-	-
Feedwater Turbine Turning Gear "A"	1.8	2	-	-	2	-	-
Feedwater Turbine Turning Gear Oil Pump "A"	10	2	-	-	2	-	-
RFP EHC Control Transformer	1.5 kVa	2	-	-	2	-	-
Standby Liquid Control Pump	40	2	-	-	-	-	-
Standby Liquid Control Main Heater "A"	10 kW	1	-	-	-	-	-
Standby Liquid Control Mixing Heater "A"	45 kW	1	-	-	-	-	-
Standby Liquid Control Heat Tracing	3 kVa	2	-	-	-	-	-
Heat Tracing Transformer	25 kVa	2	1	1	2	-	-
480 V R-G Set	200 "A"	4	2	2	2	-	-
Refueling Jib Crane	3.25	2	-	-	-	-	-
Refueling Platform Assembly	3.5	1	-	-	-	-	-
Motor Operated Valves	-	-	X	-	-	-	-
Nonoperating MOV's "A"	-	-	-	-	-	-	-

D/G 101 3290.8KW
 D/G 102 3246.2KW
 D/G 103 3256.3KW

Incident (watt)
102	09-103		
⑤	—	②	
⑦	—	③	
⑩	—	④	
⑫	—	⑤	
⑮	—	⑥	
⑰	—	⑦	
⑲	—	⑧	
⑳	—	⑨	
㉑	—	⑩	
㉓	—	⑪	
㉕	—	⑫	
㉗	—	⑬	
㉙	—	⑭	
㉛	—	⑮	
㉝	—	⑯	
㉟	—	⑰	
㊱	—	⑱	
㊳	—	⑲	
㊵	—	⑳	
㊷	—	㉑	
㊹	—	㉒	
㊻	—	㉓	
㊽	—	㉔	
㊿	—	㉕	
148			
—			
—			
—			
—			

REMARKS

FSAR VALUE
 MGSET WILL BE UNLOADED AFTER LPC/VLVA HAVE STROKED.
 NOT A CONTINUOUS LOAD

TI
 APERTURE
 CARD

Also Available On
 Aperture Card

8409180874-03