

Wayne H. Jens  
Vice President  
Nuclear Operations

DMB

Detroit  
Edison

Fermi-2  
6400 North Dixie Highway  
Newport, Michigan 48166  
(313) 586-4150

August 24, 1984  
EF2-69667

Mr. James G. Keppler  
Regional Administrator  
Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reference: (1) Fermi 2  
NRC Docket No. 50-341  
(2) Letter, D. A. Wells to J. G. Keppler,  
September 9, 1982, EF2-59393  
Subject: Final Report of 10CFR50.55(e) Item 77  
"1 Inch 3000# Carbon Steel Pipe Couplings and  
Caps"

This is Detroit Edison's final report of Item 77, "Linear Indications in 1 Inch 3000# Carbon Steel Pipe Couplings and Caps." Item 77 was originally reported as a potential deficiency on August 10, 1982, and was subsequently documented in Reference (2).

Description of Deficiency

During a warehouse inspection, Quality Control personnel identified linear indications in 1 inch 3000# carbon steel pipe caps manufactured by Capitol Manufacturing Company. The linear indications were identified in caps from Heat Number (HT) 0680. Records indicate that 195 caps had been received, of which 65 had been installed. A liquid penetrant (PT) examination was performed on 25 of the caps in storage, all 25 caps exhibited rejectable indications. Based on these inspections, all HT 0680 caps were considered rejectable. These caps were purchased by Wismer & Becker from Chicago Tube and Iron.

In addition, 200 1 inch 3000# carbon steel pipe couplings from HT 0680 were also received by Wismer and Becker, of which 77 had been issued for installation. A liquid penetrant examination was performed on 20 of the couplings

8409130481 840824  
PDR ADDOCK 05000341  
S PDR

AUG 30 1984

IE27  
1/0

Mr. James G. Keppler  
August 24, 1984  
EF2-69667  
Page 2

in storage, 12 exhibited rejectable indications. Based on these inspections all uninstalled couplings were considered rejectable; installed couplings required further examination.

#### Analysis of Safety Implications

Defects in carbon steel pipe couplings and caps could cause failure of the coupling or cap. Failure of these components could cause loss of safety component functions or system pressure boundary integrity, thus adversely affecting the safe operation of the plant.

#### Corrective Action

The following corrective actions have been taken to correct this deficiency:

- o The total number of caps and couplings received at Fermi 2 from Heat Number 0680 was determined.
- o PT inspections were performed on the warehouse stock caps and couplings. Unused caps and couplings from Heat Number 0680 were collected, segregated and removed from the Fermi site.
- o Based on the results of the PT inspections, all HT 0630 caps installed in safety related systems were removed. PT examinations were performed on all couplings installed in safety related systems. Couplings containing rejectable indications were removed. The corrective actions were documented and implemented on Deviation Disposition Requests, in accordance with the Quality Assurance Program.

This is Detroit Edison's final report on this item. If you have questions concerning this matter, please contact Mr. Lewis P. Bregni, (313) 586-5083.

Sincerely,

cc: Mr. P. M. Byron  
Mr. R. C. DeYoung  
Mr. R. C. Knop

