



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555-0001

April 17, 2020

Mr. Don Moul
Vice President, Nuclear Division and
Chief Nuclear Officer
NextEra Energy Point Beach, LLC
Mail Stop: NT3/JW
15430 Endeavor Drive
Jupiter, FL 33478

SUBJECT: POINT BEACH NUCLEAR PLANT, UNIT 1 – REVIEW OF THE SPRING 2019
STEAM GENERATOR TUBE INSPECTIONS DURING REFUELING
OUTAGE 38 (EPID L-2019-LRO-0084)

Dear Mr. Moul:

By letter dated October 12, 2019, (Agencywide Documents Access and Management System (ADAMS) Accession No. ML19287A002), NextEra Energy Point Beach, LLC (the licensee), submitted information to U.S. Nuclear Regulatory Commission (NRC), summarizing the results of their steam generator tube inspections performed during the spring 2019 refueling outage at Point Beach Nuclear Plant, Unit 1.

The NRC staff has completed its review of this report and concludes that the licensee provided the information required by their technical specifications. No additional follow up is required at this time. The staff's review is enclosed.

If you have any questions concerning this matter, please contact me at (301) 415-8371 or via e-mail at Mahesh.Chawla@nrc.gov.

Sincerely,

/RA/

Mahesh Chawla, Project Manager
Plant Licensing Branch III
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-266

Enclosure:
Staff Assessment

cc: ListServ

STAFF ASSESSMENT BY THE OFFICE OF NUCLEAR REACTOR REGULATION
REVIEW OF THE SPRING 2019 STEAM GENERATOR TUBE INSPECTION REPORT

NEXTERA ENERGY POINT BEACH, LLC

POINT BEACH NUCLEAR PLANT, UNIT 1

DOCKET NO. 50-266

By letter dated October 12, 2019, (Agencywide Documents Access and Management Systems (ADAMS) Accession No. ML19287A002), NextEra Energy, Inc. (the licensee) submitted information summarizing the results of the spring 2019 steam generator (SG) tube inspections that were performed at Point Beach Nuclear Plant (Point Beach), Unit 1, during refueling outage (RFO) 38.

Point Beach, Unit 1, has two Westinghouse 44F SGs each containing 3,214 thermally-treated Alloy 600 tubes. These SGs were installed during refueling outage 11 in 1983. The tubes have a nominal outside diameter of 0.875 inches, a nominal wall thickness of 0.050 inches. The tubes are supported by six stainless steel tube support plates and a baffle plate. The tube support plate holes are quatrefoil shaped. The U-bend region of the tubes in rows 1 through 8 was stress-relieved after bending.

The licensee provided the scope, extent, methods, and results of their SG tube inspections. In addition, the licensee described corrective actions, such as tube plugging, taken in response to the inspection findings. After reviewing the information provided by the licensee, the U.S. Nuclear Regulatory Commission (NRC) staff has the following comments/observations:

- A small grade wire was identified within the quatrefoil flow slot of the tube located at row 13, column 49 in SG A. No tube degradation was reported at the location of the foreign object and the tube was preventively plugged.
- Discoloration and missing cladding in the channel head were identified by the licensee in previous inspections. The licensee inspected the channel head and divider plate assemblies during RFO 38 and stated that the cladding defect does not appear to be growing. Additionally, no evidence of rust coloration was observed in RFO 38.
- A light coating of what appears to be magnetite was observed on the moisture separators with no degradation identified.
- Point Beach, Unit 1, observed primary-to-secondary leakage ranging from 0.00 to 0.08 gallons per day since RFO 36. The leakage has existed for several cycles and does not appear to be increasing.

Based on a review of the information provided, the NRC staff concludes that the licensee provided the information required by their technical specifications. In addition, the staff concludes that there are no technical issues that warrant follow-up action currently, since the inspections appear to be consistent with the objective of detecting potential tube degradation and the inspection results appear to be consistent with industry operating experience at similarly designed and operated units.

Enclosure

SUBJECT: POINT BEACH NUCLEAR PLANT, UNIT 1 – REVIEW OF THE SPRING 2019
 STEAM GENERATOR TUBE INSPECTIONS DURING REFUELING
 OUTAGE 38 (EPID L-2019-LRO-0084) DATED APRIL 17, 2020

DISTRIBUTION:

PUBLIC
 PM Reading File
 RidsNrrDorLpl3-1 Resource
 RidsNrrPMPointBeach Resource
 RidsOgcRp Resource
 RidsNrrDeDMLR Resource
 AHuynh, NRR
 AJohnson, NRR
 RidsAcrc_MailCTR Resource
 RidsNrrDorDpr Resource
 RidsRgn3MailCenter Resource
 RidsNrrLASRohrer Resource

ADAMS Accession No.: ML20097E887

*** Via Memorandum**

OFFICE	DORL/LPL3/PM*	DORL/LPL3/LA*	DE/DNRL/NCSSG/BC*
NAME	MChawla	SRohrer (R)	SBloom
DATE	04/07/2020	04/07/2020	03/11/2020
OFFICE	DORL/LPL3/BC*	DORL/LPL3/PM*	
NAME	NSalgado (RKuntz for)	MChawla	
DATE	04/17/2020	04/17/2020	

OFFICIAL RECORD COPY