

GPU Nuclear Corporation
Post Office Box 388
Route 9 South
Forked River, New Jerse, 08731-0388
609 971-4000
Writer's Direct Dial Number:

C321-92-2167 June 3, 1992

U.S. Muclear Regulatory Commission Attn: Document Control Drsk Washington, DC 20555

Dear Sir:

Subject:

Oyster Creek Nuclear Generating Station

Docket No. 50-219 Licensee Event Report

This letter forwards one (1) copy of Licensee Event Report 92-006.

John J. Barton

Vice President and Director

Oyster Creek

JJB/BDEM:jc Enclosure

cc:

Administrator, Region 1

Senior NRC Resident Inspector Oyster Creek NRC Project Manager

(LER-COVLTRS)

9206150441 520603 PDR ADOCK 05000219 IE27

NHC Form 2008 (9-83)		A TO POSITION AND ADDRESS AND ADDRESS.	LIC	ENSEE EVE	NT RE	PORT	(LER)	THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF TH		PPRO	R REGUL VED OMB ES 8/31/6	NO.		
FACILITY NAME (1)	r benatitiven removal.	AND DESCRIPTION OF THE PERSON OF	-	AMINE. AND DESCRIPTION OF THE PARTY OF THE P	-	THE REAL PROPERTY.	-	DOCK	ET NUMBER	121		and the last	FAO	2 (3)
Oyster Cre	ek							0 1	51010	10	2 (1-)	9	1 OF	0 13
		Relief V	alve Hi	gh Pressu	re Re	ief S	etpoint			domini	han skinesa			le manda man
Techni	cal Sp	ecificatio	on Limi	t Due to I	Drift									
EVENT DATE (8) LER NUMBER (6)				REPORT DATE	EPORT DATE (7) OTHER FACILITIES INVOLVED IS)							mar regiments		
MONTH! DAY YEAR YEAR		SEQUENTIAL	MONTH! DAY YEAR		FAGILITY NAMES			DOCKET NUMBERISI						
			NUMBER							0	5 0	0	0	
0 5 1 0 9 2	9 2	006	00	0 6 0 3	9 2					0	5 0	0	0	
OPERATING	THIS REP	ORT IS BUPMITTED	PURBUANT T	O THE REQUIREME	NTS OF 10	CFR 6: (C	heat one or more	with the	ferrawingi (1	1.1		NAME OF TAXABLE PARTY.		
POWER LEVEL (10) 110 (0	20.4 20.4	IG2(b) IG8(-1411) IG6(-1411) IG6(20.408(e) 50.38(e)(1) 50.38(e)(2) 50.73(e)(2)(i) 50.73(e)(2)(ii) 50.73(e)(2)(iii) CENSEE CONTACY	FOR THIS	50.73(a)(2)(ht) 50.73(a)(2)(vt) 50.73(a)(2)(vti) 50.73(a)(2)(vti)(A) 50.73(a)(2)(vti)(B) 60.73(a)(2)(xti)				73.71(b) 73.71(e) OTHER (Specify in Abstract becaused in Text, NRC Form 366A)				
NAME						-				TEL	EPHONE N	LIMB	ER.	
P. Cervenk	à								AREA CODE	9	7 1	-	4 18	914
		COMPLEYE O	NE LINE FOR	EACH COMPONENT	FAILURE	DESCRIBE	D IN THIS REPO	MY IT	31			-		
CAUSE SYSTEM CON	PONENT	MANUFAC- TURER	TO NPROS		CAUSE	SYSTEM	COMPONENT		MANUFAC- TURER		FIEPORTABLE TO NPROS			
		111					111				***			
														,
		SUPPLEMEN	TAL REPORT	EXPECTED IN					EXPECT	EO.	MO	NTH	DAY	YEAR
VES 175 VM P		SUBMISSION DATE		VI NO			1111111		SUBMISS DATE IS	KON				

On May 10, 1992 while performing an Electromatic Relief Valve (EMRV) Pressure Sensor surveillance, the "As Found" trip setpoint for the high pressure relief function on one EMRV was above that specified in the Technical Specifications. The cause of this occurrence is attributed to setpoint repeatability and instrument drift. The design setpoint repeatability can tolerate instrument drift up to 2.5 psig of the Technical Specification limit. Previous surveillance records indicate that these instruments frequently undergo additional drift within Technical Specification limits due to changing plant and environmental conditions. This occurrence is considered to have minimal safety significance as the utomatic depressurization function of the EMRVs is not affected by these pressure switches, all five EMRVs would have actuated to relieve pressure, and the Isolation Condenser System and turbine bypass valves were fully operable. The pressure switch was adjusted to actuate within the Technical Specification limit. A new pressure sensing system is to be installed in accordance with the Oyster Creek Integrated Schedule, which currently specifies the Cycle 15 refueling outage for completion of this project.

ABSTRACT /L//

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED ONE NO 3150-0104
EXPIRES 8/31/85

PAGE 131

Oyster Creek

0 15 10 10 10 12 11 19 9 1 2 --- 010 16 --- 010 012 0F 0 13

DATE OF DISCOVERY

The condition described within this report was discovered on May 10, 1992.

TEXT IN more apace a required, see element MRC Form 3864's/117

IDENTIFICATION OF OCCURRENCE

During the performance of an Electromatic Relief Valve (EIIC RV) Pressure Sensor Test and Calibration surveillance, one relief valve had a high pressure relief setpoint above that specified in the Plant Technical Specifications. This event is considered to be reportable as defined in 10 CFR.73(a)(2)(i)(B).

CONDITIONS PRIOR TO DISCOVERY

The reactor was at approximately 100% power, with a generator load of approximately 650 megawatts electric.

DESCRIPTION OF OCCURRENCE

On May 10, 1992 at approximately 2200 hours, while performing the Electromatic Relief Valve (EMRV) Pressure Sensor Test and Calibration surveillance, the "As Found" trip setpoint for the high pressure relief function on one EMRV was above that specified in the Technical Specifications. The technical specification limit for EMRV IA83A pressure sensor is 1079.1 psig. Sensor IA83A test results determined the setpoint was at 1081.0 psig.

APPARENT CAUSE OF OCCURRENCE

The cause of this occurrence is attributed to instrument setpoint repeatability and instrument drift due to changing plant and environmental conditions. The tolerance between the "As Left" instrument setpoint and the Technical Specification is 10 psig. The design accuracy for these sensors is ±7.5 psig. Therefore, design setpoint repeatability allows the "As Found" value to be within 2.5 psig of the Technical Specification limit.

A review of previous surveillance records indicated that these instruments frequently undergo additional drift during changes in plant pressure and operational conditions. A 2.5 psig additional drift beyond the 7.5 design tolerance would cause the instrument setpoint to exceed the Technical Specification limit. Instrument repeatability and drift cannot be improved due to the design of the switch used in this application.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

3 NUCLEAR REGULATORY COMMISSION APPROVED DMS NO. 3150-0104

EXPIRES B/31/85

NAME (1)	Commence Contract	-	2						
	DIMET NUMBER (2)				LER NUMBER IS	PAGE (3)			
Oyster Creek				*EAR	SEQUENTIAL NUMBER	REVERON			
	0 15	1010101	2,1,9	9,2	_ 0,6	_ 0,0	0 3 05	0 3	

ANALYSIS OF OCCURRENCE AND SAFETY SIGNIFICANCE

The EMRVs are part of the Automatic Depressurization System (ADS). This system is designed to depressurize the Reactor Coolant System (EIIS AB) during small break Loss-of-Coolant Accident conditions so that the low pressure Core Spray System (EIIS BM) can inject. The ADS function of the EMRVs is not affected by these switches. The EMRVs also provide a high pressure relief function for the reactor pressure vessel. Together with the high pressure scram function and the Isolation Condenser System (EIIS BL), the EMRVs limit pressure in the Reactor Coolant System during high pressure transients to prevent exceeding the system pressure safety limit of 1375 psig.

This occurrence is considered to have minimal safety significance since the ADS function of the EMRVs is not affected by these pressure switches, all five EMRVs would have actuated to relieve pressure, and the Isolation Condenser System and turbine bypass valves were fully operable. In addition, the reactor safety valves are designed to prevent reaching the Reactor Coolant System pressure safety limit of 1375 psig on a complete loss of EMRV relief capability.

CORRECTIVE ACTION

The pressure switch was immediately adjusted to actuate within the Technical Specification limit. A new pressure sensing system has been selected to replace the present switch used in this application. The sensors selected will have an accuracy that will improve setpoint repeatability. This modification is currently included in the Oyster Creek Integrated Schedule as a Cycle 15 refueling outage project.

SIMILAR EVENTS

LER	81-40	EMRV Pressure Sensor Test and Calibration
LER	81-51	EMRV High Pressure Sensor
LER	81-57	Reactor High Pressure Switch "B" EMRV
LER	82-24	EMRV Switch Out of Tech Spec Limit
LER	90-10	EMRV High Pressure Relief Setpoints Exceeded Tech Spec Limit Due