production and

Southern California Edison Company

23 PARKER STREET IRVINE, CALIFORNIA 92718

June 8, 1992

R. M. ROSENBLUM MUMADER OF NUCLEAR REGULATORY APPARE

206160075

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Subject: Docket No. 50-361 Special Report San Onofre Nuclear Generating Station, Unit 2

This report is being submitted according to Technical Specification (TS) 3.3.3.3, Action a, of Facility Operating License NPF-10, San Onofre Unit 2. The TS requires Southern California Edison (SCE) to submit a Special Report when the seismic monitoring instrumentation becomes inoperable for more than 30 days.

On May 7, 1992, with Unit 2 in Mode 1 at 100% power, steam generator base support strong motion accelerometer (SMA) 2XI-8020B was determined inoperable following performance of a routine monthly surveillance test. Specifically, the instrumentation did not respond to the calibration signal nor the natural frequency signal as required by Procedure S023-II-2.1.

Investigation results to date have not been able to establish when the SMA failed. Initial troubleshooting of the seismic instrumentation components and circuitry could not fully determine the cause of the deficiency. Further troubleshooting will require containment entry for accessing 2XI-8020B. Due to ALARA considerations during power operations, personnel are precluded from performing further investigative efforts. Troubleshooting and repair efforts for 2XI-8020B will be performed during the next Unit 2 shutdown of sufficient duration or the next Unit 2 refueling outage as allowed by Surveillance Requirements, 4.3.3.3.2.

If you require any additional information, please let me know.

AM Asenfl

cc: J. B. Martin, Regional Administrator, NRC Region V M. B. Fields, NRC Project Manager, San Onofre Units 2 and 3 C. W. Caldwell, NRC Senior Resident Inspector, San Onofre Units 1, 2&3

TE22

18LEPHONE (714) 454-4508