

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) **J. M. Farley - Unit 1** DOCKET NUMBER (2) **0 5 0 0 0 3 4 8 1** PAGE (3) **1 OF 0 2**

TITLE (4) **Hourly Fire Watch Patrol Posted Instead of Continuous Fire Watch**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)	
0 1	2 1	8 4	8 4	0 1 5	0 0	0 9	0 7	8 4	J.M. Farley-Unit 2	0 5 0 0 0 3 6 4	
										0 5 0 0 0	

OPERATING MODE (8) **1** THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)

20.402(b)	20.406(e)	50.73(a)(2)(iv)	73.71(b)
20.406(a)(1)(i)	50.38(e)(1)	50.73(a)(2)(v)	73.71(e)
20.406(a)(1)(ii)	X 50.38(e)(2)	50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
20.406(a)(1)(iii)	X 50.73(a)(2)(i)	50.73(a)(2)(viii)(A)	
20.406(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(viii)(B)	
20.406(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME **J. D. Woodard** TELEPHONE NUMBER **2 0 5 8 9 9 - 5 1 5 6**

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15)

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On August 8, 1984, during an Operations Quality Assurance Audit, it was determined that in two cases an hourly fire watch patrol had been posted instead of a continuous fire watch as required by Technical Specification 3.7.11.2. Administrative Procedures are being changed to provide more specific guidance concerning the posting of fire watches. Health/Safety of the public was not affected.

B409200010 B40907
PDR ADOCK 05000348
S PDR

FEZZ
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Joseph M. Farley - Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 4 8	LER NUMBER (6)			PAGE (3)		
		YEAR 8 4	SEQUENTIAL NUMBER 0 1 5	REVISION NUMBER 0 0		OF	

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On August 8, 1984, during the performance of an Operations Quality Assurance Audit, it was determined that in two cases an hourly fire watch patrol had been posted instead of a continuous fire watch as required by Technical Specification 3.7.11.2. In one case, on 1-21-84, Sprinkler System 1A-51 on Unit 1 was placed in override to allow Open Flame Permit work in the area. The other case occurred on 2-2-84 with Unit 2 in mode 1 at 100 percent power, when Sprinkler System 2A-27 was placed in override to facilitate construction activities. In both cases, a continuous fire watch had not been established within one hour as required by technical specifications. An hourly fire watch patrol had been posted instead.

These events were caused by personnel errors in that the shift foremen did not determine fire watch requirements properly when a Fire Protection System was inoperable. The individuals involved have been reinstructed. To prevent future occurrence, Administrative Procedures are being changed to provide more specific guidance in determining fire watch requirements. Also, an Operations Memo has been issued to further define fire watch requirements.

Mailing Address
Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Alabama 35291
Telephone 205 783-6090

R. P. McDonald
Senior Vice President
Flintridge Building



Alabama Power
the southern electric system

September 7, 1984

Docket No. 348
Docket No. 364


Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Sir:

Joseph M. Farley Nuclear Plant, Unit 1, Licensee Event Report No. LER 84-015-00 is forwarded in accordance with 10CFR50.73 to provide 30 day written notification of this occurrence.

If you have any questions, please advise.

Yours very truly,


R. P. McDonald

RPM/DSM:sam

Enclosure

xc: IE, Region II

IE22
1/1