

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)

INDIAN POINT UNIT 2

DOCKET NUMBER (2)

0 1 5 1 0 0 0 1 2 4 7

PAGE (3)

1 OF 21

TITLE (4)

REACTOR COOLANT PUMP UNDERTHROTTLE SETPOINT

EVENT DATE (5)

LER NUMBER (6)

REPORT DATE (7)

OTHER FACILITIES INVOLVED (8)

MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REGION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(9)
0	7	1984	84	009	-	00	081	884		0 1 5 1 0 0 0 1 2 4 7

OPERATING MODE (10)

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 50.73(a) (Check one or more of the following) (11)

OPERATING MODE (10)	0 0 0	20.402(b)	20.408(e)(i)	50.34(e)(1)	50.34(e)(2)	50.73(a)(2)(iv)	50.73(a)(2)(v)	50.73(a)(2)(vi)	50.73(a)(2)(vii)	73.71(a)
		20.408(e)(ii)(B)				X				73.71(a)
		20.408(e)(ii)(C)								OTHER /Specify in Attached Detail and in Text, NRC Form 364A.
		20.408(e)(ii)(D)								
		20.408(e)(ii)(E)								
		20.408(e)(ii)(F)								
		20.408(e)(ii)(G)								

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER
MICHAEL BLATT, DIRECTOR, REGULATORY AFFAIRS	9 1 4 5 2 6 5 1 2 7 1

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPPDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPPDS
X	J C	W L Y W I	2 0	Y					

SUPPLEMENTAL REPORT EXPECTED (14)

EXPECTED SUBMISSION DATE (15)

MONTH

DAY

YEAR

YES // If yes, complete EXPECTED SUBMISSION DATE

NO

ABSTRACT (Limit to 1400 words, i.e., approximately fifteen single-space typewritten lines) (16)

On July 19, 1984 during surveillance testing of the undervoltage reactor trip setpoint for the 6.9 KV buses it was observed that two out of four relays did not de-energize at the required set point. The cause was attributed to excessive mechanical friction. The plant was at cold shutdown for a refueling outage.

8409210018 840818
PDR ADDOCK 05000247
S PDR

IE 22
111

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104
EXPIRES 6/31/95

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (3)

PAGE

INDIAN POINT UNIT 2

0 5 | 0 | 0 | 0 | 2 | 4 | 7 | 8 | 4 — 0 0 9 — 0 0

2 OF 21

TEXT (If more space is required, use additional NRC Form 366A (1))

On July 19, 1984 a surveillance calibration pursuant to the Technical Specification requirements was performed of the setpoints for the undervoltage relays on the 6.9 KV buses which supply power to the reactor coolant pumps. The plant was at cold shutdown for a refueling outage.

The Technical Specifications require that the relays de-energize at an applied voltage no lower than 70% of the nominal bus voltage of 115 volts. The actual dropout voltages corresponded to 62% and 68%. Based on inspection and subsequent testing, the cause has been attributed to mechanical friction. It was determined that this friction could be reduced by repositioning the target mechanism. The target mechanism was corrected and the relays were adjusted to the proper settings. Operability was verified by subsequent testing.

The above relays are installed for the purpose of initiating a reactor trip in the event of an undervoltage condition to the reactor coolant pumps. The relays respond to undervoltage on the 6.9 KV bus through 60:1 potential transformers.

There were no previous similar events.

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

August 18, 1984


Re: Indian Point Unit No. 2
Docket No. 50-247
LER-84-009-00

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Sirs:

The attached Licenser Event Report LER-84-009-00 is hereby submitted in accordance with the requirements of 10 CFR Part 50.73.

Very truly yours,



attach.

cc: Dr. Thomas E. Murley,
Regional Administrator-Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511