

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) <b>EDWIN I. HATCH, UNIT 2</b>	DOCKET NUMBER (2) <b>0 5 0 0 0 3 6 6</b>	PAGE (3) <b>1 OF 0 2</b>
--	---	-----------------------------

TITLE (4)  
**SURVEILLANCE TESTING PERFORMED LATE**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0 8	1 4	8 4	8 4	0 1 5	0 0	0 9	1 0	8 4			0 5 0 0 0
DOCKET NUMBER(S) <b>0 5 0 0 0</b>											

OPERATING MODE (9) **5**

POWER LEVEL (10) **Q 0 0**

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)

<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(c)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input type="checkbox"/> 20.406(a)(1)(i)	<input type="checkbox"/> 50.36(c)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(e)
<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(vi)	<input type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 366A)
<input type="checkbox"/> 20.406(a)(1)(iii)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(vii)(A)	
<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(vii)(B)	
<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER
<b>Thomas L. Elton, Acting Supt. of Regulatory Compliance</b>	<b>9 1 2 3 6 7 1 7 8 5 1</b>
AREA CODE	

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS
<b>A</b>	<b>M/E</b>	<b>     </b>	<b>B 1 3 0</b>	<b>N</b>					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)  NO

EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

This 30 day LER is required by 10CFR 50.73(a)(2)(i)(B) because the surveillance required by Tech. Specs. section 4.7.8.b was not performed within the applicable time constraints.

The health and safety of the public were not affected by this event.

The cause of this event was personnel error. The importance and significance of performing required Tech. Specs. surveillance within the applicable time constraints will be stressed to the responsible group.

8409210243 840910  
PDR ADOCK 05000366  
S PDR

IE22  
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  EDWIN I. HATCH, UNIT 2	DOCKET NUMBER (2)  0 5 0 0 0 3 6 6 8 4 - 0 1 5 - 0 0 0 2 OF 0 2	LER NUMBER (8)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		

TEXT (If more space is required, use additional NRC Form 388A's) (17)

The performance of the "MONITORING SETTLEMENT OF SEISMIC CATEGORY 1 STRUCTURES" procedure (HNP-2-3475) meets the requirement of Tech. Specs. section 4.7.8.b. In order to meet the required frequency, plant personnel had scheduled the procedure to be performed no later than 08/13/84 (i.e., the due date of 06/28/84 plus a 45 day grace period as allowed by Unit 2 Tech. Specs. section 4.0.2); however, the required surveillance was not satisfactorily completed until 08/22/84. This failure to perform a Tech. Specs. surveillance at the required frequency constitutes an operation or condition prohibited by the plant's Technical Specifications, and is thus reportable per 10CFR50.73(a)(2)(i)(B).

This non-repetitive event is the result of personnel error. The group responsible for performing the surveillance waited until near the end of the grace period before beginning to perform the surveillance. Then when extra time was required due to the "badging process", they were not able to complete the surveillance within the Tech. Specs. time constraint.

The health and safety of the public were not affected by this event.

The importance and significance of performing required Tech. Specs. surveillance within the applicable time constraints will be stressed to the responsible group.

Georgia Power Company  
Post Office Box 439  
Baxley, Georgia 31513  
Telephone 912 367-7781  
912 537-9444




Edwin I. Hatch Nuclear Plant

September 10, 1984  
GM-84-737

PLANT E. I. HATCH  
Licensee Event Report  
Docket No. 50-366

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Attached is Licensee Event Report No. 50-366/1984-015. This report is required by 10CFR 50.73(a)(2)(i).

  
H. C. Nix  
General Manager

*JCE*  
HCN/TLE/vlt

xc: R. J. Kelly  
R. E. Conway  
J. T. Beckham, Jr.  
P. D. Rice  
K. M. Gillespie  
Superintendent of Regulatory Compliance  
R. D. Baker  
Control Room  
Document Control

IE22

1/1