

NOTICE OF VIOLATION

Wisconsin Electric Company

Docket No. 50-266
Docket No. 50-301

As a result of the inspection conducted from September 1 through October 15, 1988, and in accordance with the "General Policy and Procedures for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the following violation was identified:

10 CFR 50, Appendix B, requires in Part V, "Activities affecting quality shall be prescribed by documented instructions, procedures, or drawings, of a type appropriate to the circumstances and shall be accomplished in accordance with these instructions, procedures, or drawings."

Procedure ICP 2.1, "Periodic Test Reactor Protection and Safeguards Analog Channels I Through IV," which is a procedure affecting quality, requires in Step 2.20 of Appendix A that the "Unblock SI" bistable switch be placed in the trip position during performance of the test; and Step 2.49 of Appendix A requires that the bistable trip switch be returned to normal at the conclusion of the test.

Contrary to the above, on September 14, 1988, an instrument and control technician failed to return the "Unblock SI" bistable switch to the normal position after the test was completed even though Step 2.49 had been checked off as having been completed.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

OCT 28 1988

Dated _____

R C Knop

R. C. Knop, Chief
Reactor Projects Branch 3