



Idaho National Engineering Laboratory

Operated by the U.S. Department of Energy

Data Summaries of Licensee Event Reports of Inverters at U.S. Commercial Nuclear Power Plants January 1, 1976 to December 31, 1982

Sharon R. Brown
Mike Trojovsky

August 1984

8409280077 840831
PDR NUREG
CR-3867 R PDR

Prepared for the

U.S. Nuclear Regulatory Commission

Under DOE Contract No. DE-AC07-76IDO1570



Available from

GPO Sales Program
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

and

National Technical Information Service
Springfield, Virginia 22161

NOTICE

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, expressed or implied, or assumes any legal liability or responsibility for any third party's use, or the results of such use, of any information, apparatus, product or process disclosed in this report, or represents that its use by such third party would not infringe privately owned rights.

NUREG/CR-3867
EGG-2324
Distribution: RG, 1S

**DATA SUMMARIES OF LICENSEE EVENT REPORTS
OF INVERTERS AT U.S. COMMERCIAL
NUCLEAR POWER PLANTS
JANUARY 1, 1976 TO DECEMBER 31, 1982**

Sharon R. Brown
Mike Trojovsky

Published August 1984

EG&G Idaho, Inc.
Idaho Falls, Idaho 83415

Prepared for the
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555
Under DOE Contract No. DE-AC07-76ID01570
FIN No. A6393

ABSTRACT

This report describes a computer-based data file developed from Licensee Event Reports (LERs) of inverters in U.S. commercial nuclear power plants for the period January 1, 1976 to December 31, 1982. In addition to the creation of the file, summaries of data contained in the file were made to obtain data for risk assessment and statistical purposes. Gross constant failure rates were estimated for inverters found in selected systems. Explanations, figures, and summary tables of the results are provided.

SUMMARY

The Reliability and Statistics Branch of EG&G Idaho, Inc. reviewed Licensee Event Reports (LERs), both qualitatively and quantitatively, to extract reliability information, in support of the United States Nuclear Regulatory Commission's (USNRC's) effort to gather and analyze fault (failure and command fault) data concerning nuclear power plants. LERs submitted by the utilities to the USNRC from January 1, 1976 through December 31, 1982 pertaining to inverters, are the source of information used in this report. For the seven year period covered by this report, 21,424 LERs were manually screened and 145 were deemed as appropriate inverter events for this report. From the 145 applicable LERs, 161 one-line descriptions (involving 177 faults) were derived and entered into a data base. Of the 177 faults, 166 (94%) were classified as actual failures. The remaining 11 were identified as being command faults.

A computerized data base of component/system operational experiences categorized by standard reliability characteristics was developed to provide an efficient and accurate way of retrieving and sorting the various reliability data. In addition to developing a data base, summaries of data contained in the file were made to obtain data for risk and statistical purposes. Gross constant failure rates were estimated for inverters found in selected

systems. Explanations, figures, and summary tables of the results are provided.

The greatest majority of the inverter events reported described catastrophic failures of inverters (no output or inoperable). The fault mode reduced capability (operational but at a reduced capacity) was considered; however, only a few inverters exhibited this mode.

In PWR plants the essential ac electrical distribution system experienced most of the inverter faults, while in BWR plants the low pressure coolant injection system experienced most of the inverter faults. The overall failure rate calculated for inverters found in the essential ac distribution and low pressure coolant injection systems that experienced the fault mode inoperable was $1E-5$ failures per hour.

The component faults and failure rates summarized in this report should be interpreted as tentative gross indicators of true fault trends and failure rates. Because subjective judgments had to be made regarding pertinence of recorded events, and because some component faults may not be recorded in the LERs, the individual analyst should confirm the applicability of the component faults and failure rates for their specific uses.

FOREWORD

This report is one in a series summarizing the statistics of Licensee Event Reports (LERs) as recorded by the United States Nuclear Regulatory Commission (USNRC). The goal of the report is twofold: (a) to summarize the data for risk and statistical analyses, and (b) to obtain gross constant failure rate estimates.

Owing to the subjective judgments that had to be made regarding population sizes and pertinence of recorded events, and because some component faults may not be recorded in the LERs, the component failure rates estimated in this report should be interpreted as being only tentative gross indicators of the true failure rates. Furthermore, because LER reporting requirements can differ from plant to plant, comparisons of plant-to-plant failure rates should be interpreted with care; a higher failure rate may simply be because of stricter reporting requirements. The analyst must validate the applicability of the LER-derived failure rates for specific uses. As more data are collected and more analyses are performed in the future, improved failure rate estimates will be produced.

Failure rates are only one of many kinds of information presented in this report. Tables and discussions classify faults according to fault modes, fault causes, and systems affected. Gross time trends are examined. Human errors are identified as are common cause and recurring faults. Each LER analyzed is presented in a useful, summarized form, and all evaluations are presented so that analysts can modify the authors' calculations or perform their own evaluations if so desired.

R. C. Robinson
USNRC Project Manager
February 1984

The previous reports in this series of data summaries of the Licensee Event Reports are:

1. W. H. Hubble and C. F. Miller, *Data Summaries of Licensee Event Reports of Control Rods and Drive Mechanisms at U.S. Commercial Nuclear Power Plants January 1, 1972 to April 30, 1978*, NUREG/CR-1331, February 1980.
2. J. P. Poloski and W. H. Sullivan, *Data Summaries of Licensee Event Reports of Diesel Generators at U.S. Commercial Nuclear Power Plants January 1, 1976 to December 31, 1978*, NUREG/CR-1362, March 1980.
3. D. W. Sams and M. Trojovsky, *Data Summaries of Licensee Event Reports of Primary Containment Penetrations at U.S. Commercial Nuclear Power Plants January 1, 1976 to December 31, 1978*, NUREG/CR-1730, September 1980.
4. M. Trojovsky, *Data Summaries of Licensee Event Reports of Pumps at U.S. Commercial Nuclear Power Plants January 1, 1972 to September 30, 1980*, NUREG/CR-1205, Revision 1, January 1982.
5. C. F. Miller et al., *Data Summaries of Licensee Event Reports of Valves at U.S. Commercial Nuclear Power Plants January 1, 1976 to December 31, 1980*, NUREG/CR-1363, Revision 1, October 1982.
6. M. Trojovsky and S. R. Brown, *Data Summaries of Licensee Event Reports of Selected Instrumentation and Control Components at U.S. Commercial Nuclear Power Plants January 1, 1976 to December 31, 1981*, NUREG/CR-1740, Revision 1, July 1984.

ACKNOWLEDGMENTS

Sincere appreciation is expressed to the following persons for their assistance in the preparation of this report: Lee C. Cadwallader, Cynthia D. Gentillon, and Judy A. Steverson for their review of this report. John C. Culley and Alan J. Smith for their technical assistance in computer graphics and data base management. Linda Duncan, Jan Isom, and the Technical Publication Composition Staff for their conscientious and timely efforts in the word processing and text composition of this report.

CONTENTS

ABSTRACT	ii
SUMMARY	iii
FOREWORD	iv
ACKNOWLEDGMENTS	vi
NOMENCLATURE	xi
Terms	xi
Acronyms and Abbreviations	xii
INTRODUCTION	1
LER EVALUATION AND CODING METHODOLOGY	2
Scope	2
Component Boundaries	2
LER Selection	2
LER Classification	2
Fault/Failure	3
Fault Mode	3
Fault Cause	3
Event Classification (Age or Frequency of Use)	3
Type of Event	4
System	4
Event Date	5
Manufacturer	5
Activity Resulting in Discovery	5
Flagging	5
LER Rate Estimations	6
Data Collection	6
Populations	6
Time	6
Failures	7
LER Rate Estimations Performed	7
SUMMARY OF RESULTS	9
Engineering Data	9
NSSS Vendor	9
Plant-Specific Data	10

Yearly Data Summaries	10
Subcomponent	10
Fault Mode	10
Fault Cause	10
Human Factors	10
Electrical Malfunction	10
Fault Mode and Cause	10
System	10
Type of Event	10
Recurring Failure	17
Common Cause Failure	17
Recurring Common Cause Failure	18
Common Cause Command Fault	18
Event Classification	18
Activity Resulting in Discovery	18
Flagging	18
LER Rates	18
REFERENCES	29
APPENDIX A—DISCUSSION OF THE CAUSES OF VARIATIONS IN LER REPORTING	A-1
APPENDIX B—ONE-LINE LER CODING SCHEME	B-1
APPENDIX C—LER RATE ESTIMATION METHODS	C-1
APPENDIX D—INVERTER ONE-LINE DESCRIPTIONS SORTED BY NSSS VENDOR	D-1
APPENDIX E—INVERTER ONE-LINE DESCRIPTIONS SORTED BY HUMAN FACTORS	E-1
APPENDIX F—INVERTER ONE-LINE DESCRIPTIONS SORTED BY SYSTEM	F-1
APPENDIX G—INVERTER ONE-LINE DESCRIPTIONS SORTED BY TYPE OF EVENT	G-1
APPENDIX H—ADDITIONAL INFORMATION CONTAINED IN INVERTER ONE-LINE DESCRIPTIONS	H-1
APPENDIX I—LISTING OF LER NUMBERS	I-1
APPENDIX J—RESULTS OF THE INVERTER LER RATE ESTIMATIONS	J-1
FIGURES	
1. Summary of inverter faults by NSSS	9

2.	Summary of inverter faults by plant	11
3.	Summary of inverter faults by subcomponent	12
4.	Summary of inverter faults by fault mode	13
5.	Summary of inverter faults by fault cause	13
6.	Summary of inverter faults caused by human factors	14
7.	Summary of electrical malfunction failures by subcomponent	14
8.	Summary of inverter faults by PWR systems	16
9.	Summary of inverter faults by BWR systems	16
10.	Summary of inverter faults by type of event	17
11.	Summary of inverter faults by event classification	19
12.	Summary of inverter faults by activity resulting in discovery	19
13a.	Scatter plot of operating LER rates of essential ac electrical distribution static inverters, for Babcock & Wilcox plants, inoperable, command faults excluded	25
13b.	Scatter plot of operating LER rates of essential ac electrical distribution static inverters, for Combustion Engineering plants, inoperable, command faults excluded	25
13c.	Scatter plot of operating LER rates of essential ac electrical distribution static inverters, for Westinghouse plants, inoperable, command faults excluded	26
13d.	Scatter plot of operating LER rates of essential ac electrical distribution and low pressure coolant injection static inverters, for General Electric plants, inoperable, command faults excluded	26
13e.	Scatter plot summarizing operating LER rates of essential ac electrical distribution and low pressure coolant injection static inverters, inoperable, command faults excluded	27
14.	Scatter plot of operating LER rates of essential ac electrical distribution system static inverters, for General Electric plants, inoperable, command faults excluded	27
15.	Scatter plot of operating LER rates of low pressure coolant injection system static inverters, for General Electric plants, inoperable, command faults excluded	28

TABLES

1.	Accounting of inverter LERs	9
2.	Summary of inverter faults by year	12
3.	Summary of inverter faults by fault cause and fault mode	15
4.	Summary of input data for inverter LER rate estimations	21

5. Summary of LER rates by NSSS	28
B-1. General plant information	B-4
B-2. Codes used in one-line descriptions	B-12
B-3. Codes used in additional information one-line descriptions	B-13

NOMENCLATURE

This section contains terms, acronyms, and abbreviations.

Terms

1. **Component**—The largest entity of hardware for which data are most generally collected and expected to be available (e.g., pump with motor, valve with operator, amplifier, pressure transmitter). It is generally an off-the-shelf item procured by the system designer as a basic building block for their system. It would be distinguished from seals, bearings, nuts, bolts, and other piece parts from which the component is manufactured.
2. **System**—A collection of components arranged so as to provide a desired function (e.g., Containment Spray System, Residual Heat Removal System, High Pressure Coolant Injection System).
3. **Fault**—As used in the context of this report fault refers to failures and command faults. The terms failure or command fault will be used when referring to one or the other.
4. **Failure**—A subset of a fault that represents an irreversible state of a component such that it must be repaired in order for it to perform its design function. Failures are sometimes classified as primary or secondary failures. A primary failure is the so-called *random failure* found in the literature. It results from no external cause. A secondary failure results when the component is subject to conditions that exceed its design envelope (e.g., excessive voltage, pressure, shock, vibration, temperature). However, in classifying failures for this report, no distinction has been made between these two classifications.
5. **Command Fault**—An event in which the component did not function as required, not because of a failure in the component, but because of inputs or lack of inputs to the component as supplied by personnel, other components, or the environment external to the component. This is a reversible state of the component that can be corrected once the faulty input is corrected. No component repair is required.
6. **Common Cause Failure**—Two or more redundant components failing together or having the potential to fail within a relatively short period of time because of a single causal event. Multiple common cause failures are usually secondary failures.
7. **Fault Cause**—The identified cause and sequence of events that prevented the component from performing its intended function.
8. **Fault Mode**—The manner in which a component ceases to perform its intended function.
9. **Demand Failure or Fault Rate**—The probability (per demand) that a component will not operate properly when required to start, change state, or function.
10. **Operating Failure or Fault Rate**—The probability (per hour) of a failure or fault for those components required to operate or function for a period of time.
11. **Standby Failure or Fault Rate**—The probability (per hour) of a failure or fault for those components that are normally dormant or in a standby state until tested or required to operate or function for a period of time.

Acronyms and Abbreviations

ac	Alternating Current
ADJ	Adjusting
ADS	Automatic Depressurization System
AFW	Auxiliary Feedwater
ANNUNC, ANNUNCIATR	Annunciator
AUTO	Automatic
AUX	Auxiliary
B, BAB & WIL, B&W	Babcock & Wilcox
B/U	Backup
BATT, BTTRY	Battery
BC	Battery Charger
BRD	Board
BRKR	Breaker
BWR	Boiling Water Reactor
BWST	Borated Water Storage Tank
C, CE, COMB ENG	Combustion Engineering
C C COMD	Common Cause Command Fault
CABNT	Cabinet
CAP	Capacitor
CCW	Component Cooling Water
CHNL	Channel
CIRC	Circulating
CKT	Circuit
CNNCTN	Connection
CNTNMNT, CONT	Containment
CNTRL,CNTROL	Control
CNTRLLR	Controller
COM CAUSE	Common Cause
COMP, COMPON	Component
COOLG	Cooling
CR	Control Room
CRD	Control Rod Drive, Card
CSI	Containment Spray Injection
CVCS	Chemical Volume Control System
dc	Direct Current
DEENRGZD	Deenergized
DEENRGZG	Deenergizing
DETCTN	Detection
DFCTV	Defective
DFCTV PROC	Defective Procedures
DG, D/G	Diesel Generator
DHR(S)	Decay Heat Removal (System)
ECCS	Emergency Core Cooling System
ELEC DISTR	Essential ac Electrical Distribution
ELEC MALF	Electrical Malfunction
EMERG	Emergency
EOL	End of Life

EQUALZG	Equalizing
ESF	Engineered Safety Features
ESFAS	Engineered Safety Features Actuation System
FAB/CON/QC	Fabrication/Construction/Quality Control
FAILD	Failed
FAILR(S)	Failure(s)
FIRING CRD	Firing Circuit
FREQ	Frequency
FSAR	Final Safety Analysis Report
FUNCTN	Function
G, GE, GEN ELEC	General Electric
HPCI	High Pressure Coolant Injection
HPSI	High Pressure Safety Injection
HV	High Voltage
I&C	Instrumentation & Control
ICS	Integrated Control System
INADV	Inadvertent
INADQ	Inadequate
INITIATG	Initiating
INOP	Inoperable
INSTLD	Installed
INSTRMNTN	Instrumentation
INTRFC	Interface
LER	Licensee Event Report
LOSP	Loss of Off-Site Power
LPCI	Low Pressure Coolant Injection
LPCS	Low Pressure Core Spray
LPSI	Low Pressure Safety Injection
MAIN, MAINT	Maintenance
MALFUN	Malfunction
MAN	Manual
MCC	Motor Control Center
MECH MALF	Mechanical Malfunction
MFG	Manufacturing
MFR	Manufacturer
MG	Motor Generator
MOV	Motor Operated Valve
MS	Main Steam
NAT'L	Natural
NIH	National Institute of Health
NO	Number
NORMAL OP	Normal Plant Operation
NRC	Nuclear Regulatory Commission
NSIC	Nuclear Safety Information Center
NSSS	Nuclear Steam Supply System
OOS	Out Of Service

OP	Operating
OSCLTR	Oscillator
OV	Overvoltage
OVERHTG	Overheating
PCIS	Primary Containment Isolation System
PCS	Primary Coolant System
PER MAIN	Personnel Maintenance
PER OPER	Personnel Operation
PERS, PERSNL	Personnel
PER TEST	Personnel Testing
PPS	Plant Protection System
PRBLEM, PRBLMS	Problem(s)
PRESS	Pressure
PRTCTN	Protection
PRVNT	Prevent
PS	Power Supply
PWR	Pressurized Water Reactor, Power
PZR	Pressurizer
QA	Quality Assurance
QC	Quality Control
R C C COMD	Recurring Common Cause Command Fault
R C CAUSE	Recurring Common Cause
RCIC	Reactor Core Isolation Cooling
RCP	Reactor Coolant Pump
RCS	Reactor Coolant System
REC COMD	Recurring Command Fault
REC REVIEW	Record Review
REC'D	Received
REDUC CAP	Reduced Capability
REG	Regulator
RHR	Residual Heat Removal
RPLCD	Replaced
RPS	Reactor Protection System
RRP	Reactor Recirculation Pump
RSTR	Resistor
RTGB	Reactor Turbine General Board
RWCU	Reactor Water Cleanup
RWST	Refueling Water Storage Tank
RWT	Refueling Water Tank
RX	Reactor
S/U	Startup
SCR	Silicon Controlled Rectifier
SD, S/D	Shutdown
SEQ	Sequence
SERV WTR	Service Water
SFAS	Safety Features Actuation System
SG, S/G	Steam Generator
SHORTG	Shorting
SI	Safety Injection, Static Inverter
SIAS	Safety Injection Actuation System

STAT	Station
STM	Steam
SUP	Supply
SW	Switch, Service Water
SYS	System
TS	Technical Specification
TECH	Technician
TRBLSHTG	Troubleshooting
TRANSM, TX	Transmitter
TRANSFORMER	Transformer
TRANSISTOR	Transistor
TRP, TRPD	Trip, Tripped
TURB	Turbine
UPS	Uninterruptible Power Supply
USNRC	United States Nuclear Regulatory Commission
UV	Undervoltage
VENT, VENTILATN	Ventilation
VLTG, VOLT	Voltage
W, WESTING	Westinghouse
XFMR	Transformer
XIENT	Transient
XMITTER, XMTR	Transmitter
XSTR	Transistor

DATA SUMMARIES OF LICENSEE EVENT REPORTS OF INVERTERS AT U.S. COMMERCIAL NUCLEAR POWER PLANTS JANUARY 1, 1976 TO DECEMBER 31, 1982

INTRODUCTION

Licensee Event Reports (LERs) submitted between January 1, 1976 and December 31, 1982 that pertain to inverters have been evaluated and are presented herein, in support of the United States Nuclear Regulatory Commission's (USNRC's) continuing effort to gather and analyze fault (failure and command fault) data for active and passive components in nuclear power plants.

The data reported in the LERs were qualitatively evaluated and pertinent information (e.g., fault mode, fault cause, event date) contained in each LER describing an inverter event was coded into a one-line description of the event. Each one-line description was then stored in a computer-based data file for future use. Data in this computerized file can be searched, sorted, collated, retrieved, updated, and displayed by almost any item of information contained in the original LER. For example, plant, Nuclear Steam Supply System (NSSS) vendor, event date, fault mode, and fault cause data can all be accessed and manipulated by the analyst. This feature makes the one-line LER data base useful for obtaining various statistics for use in this report and future analyses.

Various failure rates (herein called *LER rates*) were estimated for inverters for each operating U.S. commercial nuclear power plant having population data, with the exception of three plants that were considered atypical for this report. These estimates were averaged to obtain inverter LER rates for the four NSSS vendors considered. Finally, specific plant failure data were averaged to obtain an LER rate for pressurized water reactors (PWRs), boiling water reactors (BWRs), and the aggregate of both reactor types.

LER rates are useful for probabilistic analyses such as gross risk and reliability evaluations.

However, when using the LER rates, the analyst must apply them with caution. LER rates reported herein are estimates based on the component failures reported in the LER system. These failures do not necessarily comprise all failures for any given component and, hence, may not represent the component's actual failure rate. There are various reasons why all failures may not be reported. For example, plant status (at power, cold shutdown, refueling) at the time of failure and the failure's impact on the system or subsystem are two factors that can influence whether or not a failure is reported. The estimation of exposure time during which failures can occur is another source of variation in the LER rates. This time depends on the number of selected components in the facility and the operating time of each component. Appendix A contains a further discussion on the variations in LER reporting.

The body of this report has two major parts. First, the methodology used in encoding the LERs is described. Included are the assumptions, definitions, and limitations used in carrying out the analysis. Next, a summary of the data according to various encoded characteristics is provided. In Appendix A, some of the causes for the variations in LER reporting are explained. Appendix B describes the LER coding scheme. Appendix C discusses the methods used to estimate the LER rates. Appendixes D through G contain sorts of the one-line descriptions by NSSS vendor, human factors, system, and type of event, respectively. Appendix H is a sort, by NSSS vendor, containing additional information not found in the previous one-line descriptions. For quick reference, Appendix I contains a listing of the LER numbers for the LERs included in this report. Appendix J contains the results of the LER rate estimations.

LER EVALUATION AND CODING METHODOLOGY

Scope

In the context of this report, an inverter is any static device that has the capability of converting dc power into ac power for loads requiring a reliable and constant power supply independent of the plants' normal and emergency ac power distribution systems.

Component Boundaries. Any electrical or mechanical piece of equipment that is required for the proper operation of the inverter, excluding any electrical or mechanical piece of equipment situated upstream or downstream of the input or output leads, respectively, was considered part of the inverter.

For this report, the term *component* refers to inverters. However, it was also possible to identify the faulted subcomponent that led to the faulted condition of the inverter. The twenty-two subcomponents identified for use are listed below (see also SUB COMP in Appendix B):

1. Annunciator control card
2. Capacitor
3. Choke
4. Control card/control module
5. Cooling fan
6. Diode
7. Driver board
8. Firing circuit
9. Frequency board
10. Fuse
11. Inductor
12. Oscillator
13. Power supply (internal)
14. Protection card
15. Rectifier
16. Relay
17. Resistor
18. Switch
19. Transformer
20. Transistor
21. Undervoltage coil
22. Voltage regulator.

LER Selection. In order to ensure completeness of the LERs pertaining to inverters the entire USNRC

LER file^a was obtained for the period January 1, 1976 through December 31, 1982.¹⁻² Additional information for several events was found in *Nuclear Power Experience*.³

The total number of LERs reviewed for this report was 21,424. However, not all of these LERs were used for this analysis with many having been excluded for one or more of the following reasons:

1. The LERs pertained to components outside the scope of this report.
2. The LERs were submitted by three plants considered atypical. These plants are Fort St. Vrain (gas-cooled), Humboldt Bay (BWR/1, 63 megawatts), and La Crosse (the only plant with Allis-Chalmers as the NSSS vendor). Also, Indian Point 1 differs from the 77 plants evaluated in this report, because it was shutdown and defueled prior to January of 1976. Consideration was given to Dresden 1, but any events after October 31, 1978 are not considered because of the extended shutdown which started on October 31, 1978, and which was still in effect on December 31, 1982. LERs submitted by Three Mile Island 1 and 2 prior to the March 28, 1979 accident are considered in this report. Events from either plant after that date are excluded, as Three Mile Island 2 is still shutdown, and Three Mile Island 1 is shutdown due to a restraining order.
3. The LERs were submitted prior to the date of initial criticality for the respective plant. Sequoyah 2 was the only exception to this case. Sequoyah 1 took the responsibility of submitting LERs that reported faults occurring to Sequoyah 2's inverters due to station or site related loads. Since Sequoyah 1 reported them after its date of initial criticality, they are included in the data base.

LER Classification

The purpose of this report is to provide reliability data, quantitative and qualitative, on inverters

a. Currently maintained by Oak Ridge National Laboratory.

in commercial nuclear power plants. A computerized data base of component/system operational experiences categorized by standard reliability characteristics was developed to provide an efficient and accurate way of retrieving and sorting the various reliability data.

The USNRC LER system contains a centralized source of component/system operational experiences of off-normal events in the nuclear industry. The USNRC LER file, however, is not a reliability data base. Therefore, direct transcription of these LERs for reliability purposes is not usually possible. At times, there is some correlation between what is coded in a LER and what is needed in the inverter reliability data base. In these cases, a direct transcription was made. However, the descriptive text of the LER provided the bulk of the information needed for the data base. This text also provided the mechanism to check for errors in any coded portions of the original LER—that portion providing information on system, component, component subcode, cause, etc.

Although most LERs contain only a single report involving one event (a failure or a command fault), some LERs contain multiple reports, each involving either single or multiple events. For the case where there existed multiple reports in the LER, an appropriate one-line data record was created in the data base for each report contained in the LER. For the case where the LER described multiple faults involving like components, information was encoded into the one-line data record to account for the number of faults.

A detailed explanation of the coding scheme is given in Appendix B. A discussion of the assumptions and definitions used to encode certain fields within the one-line data record is provided below. Four fields in each one-line data record contain items that are used for identification purposes: NSSS vendor, plant, LER number, and LER control number. These items need no explanation other than that provided in Appendix B.

Fault/Failure. As defined in the "Nomenclature" section, a fault refers to failures and command faults. A failure implies that a component must be repaired or replaced in order for it to perform as designed. A command fault is an event in which the component of interest does not fail, but is in the wrong state because of external inputs or lack of inputs. An inverter failing because an operator inadvertently opened the supply breaker is an example of a command fault.

Fault Mode. Initially, a cursory evaluation of the applicable LERs was conducted to ensure that the fault modes defined in this report would encompass the bulk of the LERs. Because of the lack of detailed information in most of the LER event descriptions, only two modes are defined. The modes are:

1. Reduced capability
2. Inoperable.

The reduced capability fault mode describes an event in which the component is operational but does not have full output capacity. Reduced capability implies some adjustment or corrective action was needed, but not replacement, for a component to reach full output capacity. An example of a reduced capability command fault is a technician setting the inverter voltage regulator incorrectly, while a reduced capability failure is voltage regulator setpoint drift (due to aging or other equipment related reasons).

The fault mode, inoperable, is used to describe events where there is no output from the component, or major component repair or replacement was needed. Command faults such as an open power supply breaker that prevents the inverter from supplying power to loads fall into the inoperable fault mode. Appendix B provides the details of the coding used to provide this information.

Fault Cause. The ten fault causes used are those stated in the respective LERs, and should be self-explanatory (see Appendix B). Most causes were identified by screening the cause description text of the LER. The cause stated in the text was entered in the one-line data record.

Event Classification (Age or Frequency of Use). Each component fault was reviewed to determine if the fault was related to the frequency of use (starts, stops, openings, closings, etc.) of the component or, simply, the age of the component. As the standby time or running time increases, the cumulative chance of an age-related fault increases. The cumulative chance of a frequency-of-use-related fault increases as the number of demands or cycles on the component increases. The number of demands or cycles is not necessarily a linearly-increasing function of time.

Knowing a relationship between age-related and frequency-related faults can aid in establishing or evaluating a testing policy. If frequency-related

faults predominate for a particular component, increased testing (which would place more demands on the component) may not be appropriate. Conversely, if age-related faults predominate, increased testing would be appropriate, because as the time interval between tests decreases, so does the chance of a component being unavailable. As an example of how such distinctions were made, a component that faulted because of electronic or electrical piece part deterioration was considered an age-related fault, while a component fault that resulted from a broken linkage arm or handswitch was considered a frequency-of-use-related fault.

All reports involving personnel error were classified as frequency, because it was felt that the probability of these events increased as the number of personnel interaction with the component increased. When a LER did not provide adequate cause information to enable one to determine the event classification, unknown was used to classify these events.

The original LERs do not contain a coded field indicating whether a fault is age- or frequency-related, nor is the reporting organization required to provide such an assessment in the text of the LER. Therefore, the code that appears in the one-line summaries is the result of a subjective review of the available information; other analysts may draw different conclusions.

Type of Event. Seven types of events are of special interest for risk/reliability consideration:

1. Recurring failure
2. Common cause failure
3. Recurring common cause failure
4. Command fault
5. Recurring command fault
6. Common cause command fault
7. Recurring common cause command fault.

The events not coded as one of these specified types are considered to be *random* failures. In the context of this report, random failures refer to occurrences that do not meet the definitions of the other types of events.

Recurring in this report means two or more LERs from a plant (unit) or plants at one site (e.g., Quad-Cities 1 and 2) reporting problems of a similar enough nature that some note should be taken. No attempt is made to compare events at Quad-Cities 1 with Zion 1 (i.e., to identify intersite faults). One other criterion for classifying an event as recurring is to have an LER state that "this is a recurring failure," or that "similar failures have been reported on this component."

A *common cause* failure classifies not only simultaneous failures of two or more components, but also includes single failures where the potential for two or more component failures exists. The latter are considered common cause candidates. If there was any doubt as to whether or not an event was common cause, the event was coded as common cause. An example of a common cause failure is water leaking from the roof causing short circuit failures of two or more inverters. If the same common cause was reported more than once at one plant, this was coded as *recurring common cause*.

A *command fault* is a fault where there is no actual physical failure of the component, but where the component is in the wrong state because of factors external to the component. External factors, such as human error or failure of a component that interfaces with the faulted component, account for most command faults. For example, if an inverter's dc supply breaker failed, leaving the inverter inoperable, it is not an inverter failure; the inverter would operate satisfactorily if power were available. However, if there was any doubt as to whether the fault was considered a failure or command fault, the fault was considered a failure. *Recurring command faults* describe events that include the criteria for both recurring and command faults. *Common cause command faults* occur when two or more components are affected by, or have the potential to be affected by, a single command fault. As before, these components do not experience an actual failure, but are in the wrong state due to input (or lack of input) from other components. An example of a common cause command fault is maintenance personnel incorrectly setting the output frequency of several inverters. When the reported problem was both a recurring and common cause command fault, the term *recurring common cause command fault* was used to identify the fault.

System. When performing a review of all the plants' Final Safety Analysis Reports (FSARs) it

was found that the inverters were in systems that provide constant, uninterruptible power to essential ac loads. The names of these systems varied from plant to plant, but the function and loads of the inverters found in these systems were relatively similar. The following list gives examples of these types of systems.

1. 120 and/or 240 Volt-ac Vital Instrument Power Supply System
2. 120 and/or 240 Volt-ac Essential Power System
3. 120 and/or 240 Volt Uninterruptible Power Supply (UPS) System.

Events occurring to inverters in these systems were coded as *Essential ac Electrical Distribution System*. The LERs also reference inverters that are assigned to specific loads in one system only (i.e., ADS, LPCI, HPCI, RCIC, and containment). Events occurring to inverters of this type were assigned the applicable system code.

One terminology conflict occurred in assigning systems to the one-liners in this manner. Vermont Yankee designated as 480 Vac UPS inverters that were felt to be LPCI inverters. These inverters were coded as LPCI inverters to be consistent with the other BWR plants that reported LPCI inverters, and to allow segregation of these inverters from the other smaller inverters (~200 kVA smaller) found in the UPS systems of other plants.

Event Date. The event date in the one-line data record corresponds to the event date reported in the LER. The LER event date, however, is not necessarily the date on which the fault occurred. There are instances when a component is discovered faulted and has obviously been faulted for a considerable time. The LER event date actually corresponds to the date the fault was discovered. The event date was assumed to correspond to the date of the component fault. Such an assumption, however, does not significantly impact any of the results presented in this report.

Manufacturer. The LERs provide a coded field for the manufacturer of a failed component. However, the manufacturer code in the LER is sometimes missing and sometimes not appropriate for the component coded in the data base. On occasion the manufacturer given in the LER was not the inverters'

manufacturer. References were made in the LER as to the inverters' subcomponent (e.g., relay, fuse, or capacitor) or to the failed component that was responsible for the inverters' command fault (e.g., an open circuit breaker). Due to these reporting variations no attempt was made to further evaluate the manufacturers reported. However, the codes are available in the data base should a more detailed study of the LERs be undertaken.

Activity Resulting in Discovery. Each one-line data record contains a code that indicates the activity taking place that led to the discovery of the event. In some instances, the activity was the cause of the event. Although the original LER contains a specific field for this information, the text of the LER is primarily relied upon to obtain this information.

Some examples of how the activity codes have been used are shown below.

Event	Activity
An alarm sounds during power operation.	Normal plant operation
An operator spotting a failure on a "walk-down" observation tour.	Normal plant operation
A component powered by an inverter (such as a valve) fails during a test due to inverter failure.	Normal plant operation
An inverter failing during a monthly test.	Testing

If a test is done at weekly (or greater) intervals it is considered testing; while at daily intervals it is considered normal plant operation.

Flagging. Each one-line data record was evaluated to determine whether or not the event might need to be *flagged* for possible future evaluation. Two specific types of events were flagged: (a) those inverter events that caused an inadvertent scram or accident (i.e., loss of coolant flow) and (b) those inverter events that failed to mitigate an accident

or inadvertent scram. For inverter events not meeting either of these conditions that deserved additional attention, a third code was used.

There are more fields contained in the data record that have not been presented here because they are self-explanatory and need little or no insight as to the methodology used to encode them into the data record. For information pertaining to these fields see Appendix B.

LER Rate Estimations

The scope of the LER rate estimation in this report is limited owing to the limited availability of component populations. In the sections below, the data for rate estimations and the estimations themselves are described.

Data Collection. The data necessary to estimate the LER rates are (a) the inverter population, (b) the exposure time, and (c) the number of inverter failures. These data were obtained from various sources. The following discussion presents the assumptions and sources used to arrive at the values for each of these data needs.

Populations. A comprehensive source of data from which to obtain all inverter populations within each plant was not found. The sources used to obtain the population data for each plant were the individual plant FSARs, USNRC's "Gray Books," and documented correspondence between the USNRC and the plants.⁴⁻⁸ The latter was used to resolve conflicts between inverter populations found in the FSARs and what was recorded in the LERs. Such conflicts occurred with eight plants: Fitzpatrick, Hatch 1 and 2, Oconee 1, 2, and 3, Millstone 2, and Vermont Yankee 1.

The four BWR plants (Fitzpatrick, Hatch 1 and 2, and Vermont Yankee 1) underwent major electrical modifications in order to provide an independent power supply to their LPCI valves which resulted in the addition of two LPCI inverters per plant or unit. If other BWR plants were required to make these electrical modifications and no faults occurred to these inverters warranting the submission of a LER, there would be no conflicts to identify and consequently no LPCI inverter population data for these plants. It is believed that these electrical modifications were a result of the reviews performed on all BWR plants when they were required

to modify their LPCI systems to prevent *run out* of the LPCI pumps. It has been assumed that these four BWR plants were the only BWR plants required to install LPCI inverters.

Millstone 2 added another inverter to the 125 Vdc vital instrument system before 1976. Oconee Nuclear Station started out with vital ac system inverters that had loads on them from all three units, and were shared between the three units, then switched to a vital ac system where the inverters were not shared between each unit. No other plants had shared inverters.

There were two inverters found at San Onofre 2 that had a LPCI suction header valve as the only load off each inverter. This type of power supply system was atypical of the rest of the PWR systems. Therefore, San Onofre 2's LPCI inverters were not included in the failure rate calculations.

Time. Generally, the exposure time for each inverter within a plant that was included in the LER rate estimates was either (a) the calendar hours from January 1, 1976 to December 31, 1982, for those plants that achieved initial criticality prior to January 1, 1976 (61,368 hours) or (b) the calendar hours from the date of initial criticality to December 31, 1982 for those plants that achieved initial criticality after January 1, 1976. The dates for plant initial criticality were obtained from the USNRC's "Gray Books."⁹ A secondary source of nuclear power plant information was *Commercial Nuclear Power Plants* published by NUS Corporation.¹⁰

This exposure time is based on the assumption that the inverters that were depicted in the plant's FSARs or their USNRC correspondence were operational and normally energized from the date of initial criticality. It is beyond the scope of this report to determine any down time an inverter may have experienced due to planned or unplanned maintenance.

The following is a discussion of the exceptions to the previous sets of criteria for establishing the exposure time for those inverters considered in the LER rate calculations.

The exposure time for the inverters found at Sequoyah 2 is the same exposure time placed on Sequoyah 1's inverters, even though Sequoyah 2 achieved initial criticality after Sequoyah 1. It was

obvious from the LERs that Sequoyah 1 had taken the responsibility of reporting the faults that occurred to Sequoyah 2's inverters due to station or site related loads that came off of Sequoyah 2's inverters.

The exposure times for those LPCI inverters that were installed after initial plant criticality were taken from the date ending the refueling outage when the LPCI modifications were estimated to have been completed. The following is a list of these plants' refueling outages and the completion dates of the outages.

Plant	Refueling	Date Ending the Refueling Outage
Fitzpatrick	1977	September 26, 1977
Hatch 1	1978	April 15, 1978
Vermont Yankee 1	1976	August 8, 1976

The modifications previously described for Hatch 2, Millstone 2, and Oconee occurred before initial criticality or before January 1, 1976 and hence are not exceptions.

Exposure times per inverter for the plants that added inverters after initial criticality are averaged over the plants' total inverter exposure time. For example, consider a plant having four inverters for three years (1976-1978) and six inverters for four years (1979-1982). Such a plant would have 36 inverter • years. This would be reported as though the plant had had six inverters for six years, or four inverters for nine years, etc. Integer values are needed for computing purposes, and six years would be chosen since this is less than the report time span of seven years.

Failures. The number of failures used in the calculation of the LER rates was extracted from the coded one-line LERs stored in the computer-based data file. Not all of the inverters that were coded were included in the LER rate estimates. Only those inverters that experienced the fault mode inoperable

and were part of the essential ac electrical distribution system or LPCI system were included in the LER rate estimates. Command faults were not combined (as in previous reports) with the failures to produce a second set of LER rates. Due to the scarcity of command faults found in the computer data base, the LER rate estimates that used command faults along with the failures would be similar to the LER rate estimates that used failures only.

In estimating LER rates for this report, each failure was assumed to be an individual random event, though in fact some events are suspected to be common cause. However, it is beyond the scope of this report to treat the common cause events differently when performing the LER rate estimates.

LER Rate Estimations Performed. Three sets of LER rates were estimated:

1. Operating failure rates, in failures per hour, that combined those inverters found in the following two sets.
2. Operating failure rates, in failures per hour, for those inverters found in the essential ac electrical distribution system.
3. Operating failure rates, in failures per hour, for those inverters found in the BWR system, LPCI.

During the collection of population data it was found that most of the inverters in the essential ac electrical distribution system have power ratings ranging from 5 to 50 kVA. All eight of the LPCI inverters have a 250 kVA rating. All of these inverters have basically the same principles of operation; however, the vast difference in the kVA ratings, and the loads off each inverter, between the two systems could lead to different failure rates between the inverters found in these two systems. In order to investigate this it is necessary to obtain the previously mentioned three sets of failure rates.

The computational formulas used to estimate the LER rates are discussed in Appendix C. Each set of the inverter failure rates were grouped as follows:

1. An LER rate for each licensed operating plant
2. An LER rate for each NSSS

3. An LER rate for PWRs and BWRs
4. An overall LER rate based on aggregating the failure data of each licensed operating plant.

In each of the above cases, if no population data were available for a particular LER rate calculation, then the applicable plant, NSSS, or reactor type (PWR or BWR) would be omitted from the calculation. For example, all but four plants were omitted from the LPCI inverter LER rate calculation since no LPCI inverters were known to exist for the omitted plants.

Chi-square confidence bounds were derived for each LER rate estimate. These confidence bounds are applicable only when all the components that are combined in an estimate have exactly the same LER rate. When components have different LER rates (e.g., because of individual component variations and different plant environments), the confidence interval describes only the average LER rate, not the individual component LER rates. The main use of these bounds is for comparisons. Narrow bounds apply to estimates that are based on more information (i.e., for a fixed LER rate, more failures and longer exposure times lead to narrow bounds).

SUMMARY OF RESULTS

Table 1 presents an accounting of the number of LERs used in this report. Of the 177 faults in the data file, 166 (94%) were classified as component failures. The remaining 11 were identified as being command faults.

Table 1. Accounting of inverter LERs

LERs	Numbers
Total screened	21,424
Total excluded after screening	21,279
Total coded	145
Total one-line data records created from the 145 LERs (8 LERs contained multiple reports resulting in 16 additional records)	161
Number of events contained in the 161 one-line data records (9 records contained multiple events resulting in 16 additional events)	177

Engineering Data

Presented in this engineering data summary are discussions, figures (bar graphs), and tables summarizing pertinent information contained in the data base. The figures and tables present the 177 faults by both failures and command faults. Many of the labels for the individual bars on the bar graphs had to be abbreviated; see the "Nomenclature" section for the full titles of these abbreviated labels. Percentages of the total number of faults associated with each variable can be found on each bar graph.

NOTE: The following discussion is based on raw counts and does not reflect differing numbers of inverters in different facilities. Thus, a relatively high incidence of events may not imply a relatively large failure rate. Failure rates are presented in the latter half of this summary.

NSSS Vendor. Figure 1 is a graph of the 177 faults by NSSS vendor. It is evident from




Figure 1. Summary of inverter faults by NSSS.

Figure 1 that Westinghouse reported the majority (43%) of the total faults. Refer to Appendix D for one-line descriptions sorted by NSSS vendor.

Plant-Specific Data. Figure 2 presents individual plant faults for all 77 plants in a highly visible form, grouped by NSSS vendor.

Yearly Data Summaries. This report covers a full seven years of inverter LERs. Time trends may not be discernable due to the scarcity of inverter faults reported during this time period but a yearly summary of inverter faults is presented in Table 2, for those who may be interested. Table 2 summarizes the inverter faults by year along with the plants cumulative calendar hours to provide a normalizing factor to account for new plants, or in the cases of Three Mile Island and Dresden 1, to account for the fact that data was not gathered after their extended shutdowns.

Subcomponent. Figure 3 presents the inverter faults by subcomponent. There were 58 (33%) faults coded unknown or not applicable in the subcomponent field. Fuses account for 17% (29) of the faults followed by capacitors with 13% (21) of the inverter faults.

Fault Mode. Figure 4 is a graph of the 177 faults by fault mode. It is evident from Figure 4 that inoperable failures accounted for the majority (162 or 92%) of the total faults.

Fault Cause. Figure 5 is a graph of the 177 faults by fault cause. It is evident from Figure 5 that electrical malfunction accounted for a major portion (97 or 55%) of the faults. There were 48 (27%) faults coded with unknown fault causes.

Human Factors. Figure 6 summarizes those failures and command faults caused by human factors. All faults related to personnel, design, fabrication, construction, quality control, and procedures were considered to fall into a general category of causes called human factors. Human factors account for 24 (14%) of the 177 faults. Of the 24 human factor faults, personnel errors during operation, maintenance, and testing account for 15 (63%) while design, fabrication, construction, quality control, and procedural errors account for the remaining 37%. Personnel maintenance is the largest single contributor to human factor faults at 42%, with design errors second with 25%.

Of the 24 human factor faults, 15 were identified as having involved acts of commission and 9 involved acts of omission. Refer to Appendix E for one-line descriptions sorted by human factors.

Electrical Malfunction. All the events caused by electrical malfunction resulted in failure. The fault cause electrical malfunction was a very broad term to classify the cause that led to the faulted inverter, especially when looking at an electrical piece of equipment such as an inverter. In order to get better insights as to what led to the electrical malfunction of an inverter, when it was not due to human factors, extreme environment, or mechanical malfunction, it is better to look at what subcomponent faulted that led to the electrical malfunction of the inverter. Most often this is the only insight obtainable that can lead to what caused the faulted condition of the inverter.

Figure 7 summarizes electrical malfunction failures by subcomponent. Electrical malfunction failures account for 97 (55%) of all the faults in this report. Of these 97 faults, capacitors accounted for the most with 20; and fuse failures are next with 18 failures.

Fault Mode and Cause. Table 3 summarizes the number of events in each fault mode by fault cause. Review of this table shows the major causes of faults for each fault mode. Electrical malfunction failures with the inoperable mode comprise the majority (96 or 56%) of the total inoperable mode. The next largest category consists of unknown failures with the inoperable mode with 26% (44) of the total inoperable mode.

System. Figures 8 and 9 present the inverter faults by system for both reactor types, PWR and BWR, respectively. Essential ac electrical distribution accounts for a large percentage of the faults. PWRs have 95% of their total faults attributing to this system while BWRs have 7%. The low pressure coolant injection (LPCI) system accounts for the majority of BWR system faults with 62%. Refer to Appendix F for one-line descriptions sorted by system.

Type of Event. Figure 10 presents a numerical summary of the faults by type of event, thus providing the analyst with an overall view of how the 177 faults are distributed as to type of event. No LERs involving the event categories command, recurring command, and recurring common cause command faults were found in this report.




Figure 2 Summary of inverter faults by plant.

Table 2. Summary of inverter faults by year

Year	Failures		Command Faults		Total		Calendar Hours ^a
	Number	Percent	Number	Percent	Number	Percent	
1976	18	11	1	9	19	11	473,040
1977	11	7	2	18	13	7	523,416
1978	24	14	2	18	26	15	558,216
1979	19	11	1	9	20	11	556,056
1980	39	23	1	9	40	23	566,088
1981	30	18	2	18	32	18	588,816
1982	25	15	2	18	27	15	616,584
Total	166		11		177		3,882,216

a. Hours are total calendar hours, for all operational plants considered in this report, during each year starting from January 1 of each year or the date of initial criticality.




Figure 3. Summary of inverter faults by subcomponent.




Figure 4. Summary of inverter faults by fault mode.




Figure 5. Summary of inverter faults by fault cause.




Figure 6. Summary of inverter faults caused by human factors.




Figure 7. Summary of electrical malfunction failures by subcomponent.

Table 3. Summary of inverter faults by fault cause and fault mode

Fault Cause	Fault Mode											
	Reduced Capability				Inoperable				Fault Cause Total			
	Failures		Command Faults		Failures		Command Faults		Failures		Command Faults	
	Number	Percent	Number	Percent	Number	Percent	Number	Percent	Number	Percent	Number	Percent
Unknown	3	75	0	—	44	27	1	10	47	28	1	9
Personnel Operation	0	—	0	—	3	2	1	10	3	2	1	9
Personnel Maintenance	0	—	0	—	5	3	5	50	5	3	5	45
Personnel Testing	0	—	0	—	0	—	1	10	0	—	1	9
Design Error	0	—	0	—	5	3	1	10	5	3	1	9
Fabrication/Construction/ Quality Control	0	—	1	100	1	1	0	—	1	1	1	9
Defective Procedures	0	—	0	—	1	1	0	—	1	1	0	—
Extreme Environment	0	—	0	—	5	3	1	10	5	3	1	9
Electrical Malfunction	1	25	0	—	96	59	0	—	97	58	0	—
Mechanical Malfunction	0	—	0	—	2	1	0	—	2	1	0	—
FAULT MODE TOTAL	4		1		162		10		166		11	




Figure 8. Summary of inverter faults by PWR systems.




Figure 9. Summary of inverter faults by BWR systems.




Figure 10. Summary of inverter faults by type of event.

A total of 33 (19%) events were regarded as common cause candidates. All the command faults were in this category. A total of 54 (31%) events were recurring. The following subsections discuss the various types of events in detail.

Appendix G provides a listing of one-line descriptions, sorted by type of event, for all types of events with the exception of random events. Using the information in this appendix, the analyst can identify the specific kinds of problems that are occurring and also which plants are experiencing these problems.

Recurring Failure. Recurring failures accounted for 49 (28%) of the total number of inverter faults. Of these, 31 (63%) were reported by PWR plants and 18 (37%) were reported by BWR plants.

All 31 (100%) of the PWR recurring failures occurred in the essential ac electrical distribution

system. The low pressure coolant injection system contained 12 (67%) of the 18 recurring failures reported by BWR plants.

All 49 of the recurring failures resulted in the inoperable failure mode, with 24 (49%) caused by electrical malfunction.

Common Cause Failure. There were 17 (10%) inverter failures coded as common cause failures. Of these, PWR plants reported 14 (82%) while 3 (18%) were reported by BWR plants. All 14 (100%) of the PWR common cause failures occurred in the essential ac electrical distribution system. The BWR common cause failures were distributed as follows: 2 in the reactor core isolation cooling system and 1 in the low pressure coolant injection system.

Of the 17 common cause failures, 15 (88%) resulted in the inoperable failure mode during normal plant operation, and 12 (71%) were classified

as frequency related events. Common cause failure causes were distributed as follows: 5 (29%) each for electrical malfunction and personnel maintenance, 3 (8%) for extreme environment, and 2 (12%) each for personnel operation and unknown.

Recurring Common Cause Failure. There were 5 (3%) inverter failures coded as recurring common cause failures. All 5 (100%) were reported by PWR plants. Of the 5 PWR recurring common cause failures 4 occurred in the essential ac electrical distribution system.

All 5 of the recurring common cause failures resulted in the inoperable failure mode during normal plant operation. Of the 5 failures, 4 were coded as being caused by electrical malfunctions and 1 failure was caused by fabrication/construction/quality control.

Common Cause Command Fault. Eleven (6%) of the 177 inverter faults were coded as common cause command faults. Eight (73%) were reported by PWR plants and 3 (27%) were reported by BWR plants.

Of the 8 PWR common cause command faults, 7 (88%) occurred in the essential ac electrical distribution system and 1 (13%) occurred in the containment system. Two of the 3 BWR common cause command faults occurred in the essential ac electrical distribution system with the remaining fault occurring in the low pressure coolant injection system.

Ten (91%) of the common cause command faults were coded as being in the inoperable fault mode. As expected, the majority of the common cause command faults were classified as being frequency related.

Event Classification. Figure 11 presents the inverter faults by event classification. Age and frequency accounted for approximately the same percentage of faults with 37% and 34%, respectively. The LER cause description was the primary source used to determine whether an event was demand or time related. The quality of these descriptions prevented the classification of 29% of the 177 events. The classification method is subjective and care should be exercised when using this data.

Activity Resulting in Discovery. Figure 12 presents a graph of the number of faults by the

activity in progress that lead to the discovery of the fault. The majority (158 or 89%) of the 177 faults were discovered during normal plant operations.

Flagging. Thirty-four (19%) of the 177 events were flagged. Twenty-three (13%) events were found to have caused an inadvertent scram or accident. Seven records, involving eleven inverters, were flagged for possible future reference (see Appendix H). These did not cause an inadvertent scram or accident, but it was felt that the events recorded in the LER (not necessarily the inverter events) may have had a very minor to major impact on the safe operation of the plant. Extreme care should be used in interpreting events that were flagged as being particularly safety-significant, because such interpretations among different people may vary widely.

There were no inverters, probably due to their functions and placements within a nuclear power plant, that failed to mitigate an accident.

LER Rates

Table 4 summarizes the input data used for the LER rate estimations. As stated earlier, three sets of LER rates were estimated:

1. One estimate that included both the inverters in the essential ac distribution system and those found in the BWR LPCI system.
2. One estimate for those found in the essential ac distribution system.
3. One estimate for those found in the BWR LPCI system.

Not all the faults recorded in the data base qualified as an input to these estimates. In order for the faults to be qualified they were required to meet the following set of criteria.

1. The inverter faults were found in the essential ac distribution system or the LPCI system depending upon which LER estimate was performed
2. These faults were failures (i.e., not command faults)
3. The inverters were categorized in the inoperable fault mode.




Figure 11. Summary of inverter faults by event classification.




Figure 12. Summary of inverter faults by activity resulting in discovery.

Not all plants qualified to be considered in the LER rate estimates. As can be seen from Table 4 many BWR plants had no inverters in the LPCI system or essential ac distribution system.

NOTE: All the BWR plants that did not use inverters in their essential ac distribution system incorporated the use of motor, or motor-motor-generator sets to accomplish the same goal as the inverters do in other plants.

The above selection criteria resulted in 137 (of 162) inoperable failures being selected for LER rate analysis. Omitted are 25 inoperable failures from other systems (5 PWR, 20 BWR). The presentation in Table 4 allows the analyst to modify the data and corresponding LER rates if known differences exist.

Appendix J contains inverter LER rate estimations. The results of each estimate are in the form of up to five pages of computer output; as many as four pages for the plants of each of the four NSSS vendors, and one page containing Final Statistics. The Final Statistics section for each estimate contains the averaged NSSS vendor LER rates, averaged PWR LER rates, and an overall LER rate.

Along with the LER rates contained in this Final Statistics section, the upper 95% confidence limit and lower 5% confidence limit are calculated and expressed as a factor of the LER rate point estimate. To obtain the upper 95% limit, multiply the given LER rate point estimate by the upper multiple associated with this estimate. To obtain the corresponding lower 5% confidence limit, divide the LER rate estimate by the lower divisor associated with this point estimate. In other words:

multiply X.X times Y.YE-YY to obtain upper 95% confidence limit

and

divide Z.Z into Y.YE-YY for lower 5% confidence limit

where

X.X = upper 95% confidence multiplier

Y.YE-YY = LER rate point estimate and

Z.Z = lower 5% confidence divisor.

Figures 13a through 15 show the individual plant variation associated with the LER rate estimations by plotting the specific plant LER rates associated with the inoperable fault mode (see Appendix J for data).

These plots illustrate plant-to-plant variability in LER rate estimates within a vendor. An arrow for a lower confidence bound and the comment *lower bound = 0* indicate that the associated point estimate has no recorded faults and has been obtained from Equations C-6 through C-8. The arrows are employed to indicate a zero lower bound since it is impossible to actually show zero on the logarithmic scales used in the following figures. The LER rate plotted for a plant that reported no failures is the 50% point estimate for that plant (see Appendix C for calculation methodology).

The primary purpose for plotting the bounds is for comparisons. In examining these scatter plots, note that the point estimate of the operating failure rate increases with an increasing number of failures, and the width of the confidence interval decreases. Conversely, a small number of failures will lead to a smaller point estimate with a larger confidence interval (assuming the time is constant). This is because the width of the confidence bounds on a logarithmic scale is sensitive to changes in the number of failures.

The failure data are plotted by increasing failure rates. Scales vary between plots because the scale is automatically adjusted by the values associated with the plant having the highest upper 95% confidence limit and the lowest 5% confidence limit. Outliers are not necessarily indicators of exceptionally good or bad performers. That is, the plots should not be interpreted at face value without considering some of the underlying causes for LER variation (see Appendix A).

Table 5 summarizes the NSSS vendor's inverter rates.

Table 4. Summary of input data for inverter LER rate estimations

<u>Plant Name (Code)</u>	<u>System</u>	<u>Inverter Population</u>	<u>Hours Per Component</u>	<u>Total Failures</u>
BABCOCK & WILCOX^a				
Arkansas Nuclear 1 (AR1)	Essential ac	5	61368	0
Crystal River 3 (CR3)	Essential ac	5	52272	6
Davis-Besse 1 (DB1)	Essential ac	6	47232	7
Oconee 1 (OE1)	Essential ac	7	61368	3
Oconee 2 (OE2)	Essential ac	7	61368	0
Oconee 3 (OE3)	Essential ac	7	61368	5
Rancho Seco 1 (RS1)	Essential ac	4	61368	1
Three Mile Island 1 (T11)	Essential ac	4	28392	0
Three Mile Island 2 (T12)	Essential ac	5	8784	1
NSSS Total				23
COMBUSTION ENGINEERING^a				
Arkansas Nuclear 2 (AR2)	Essential ac	5	35712	0
Calvert Cliffs 1 (CC1)	Essential ac	5	61368	0
Calvert Cliffs 2 (CC2)	Essential ac	5	53352	2
Fort Calhoun 1 (FC1)	Essential ac	6	61368	1
Maine Yankee (MY1)	Essential ac	5	61368	0
Millstone 2 (M12)	Essential ac	6	61368	5
Palisades (PA1)	Essential ac	4	61368	0
San Onofre 2 (S02)	Essential ac LPCI ^b	5 —	3816 —	0 —
St. Lucie 1 (SL1)	Essential ac	5	58680	6
NSSS Total				14
WESTINGHOUSE^a				
Beaver Valley 1 (BV1)	Essential ac	4	58248	8

Table 4. (continued)

<u>Plant Name (Code)</u>	<u>System</u>	<u>Inverter Population</u>	<u>Hours Per Component</u>	<u>Total Failures</u>
WESTINGHOUSE ^a (continued)				
Cook 1 (DC1)	Essential ac	4	61368	5
Cook 2 (DC2)	Essential ac	4	42192	2
Farley 1 (JF1)	Essential ac	7	47304	5
Farley 2 (JF2)	Essential ac	7	14544	3
Ginna (RG1)	Essential ac	2	61368	0
Haddam Neck (HN1)	Essential ac	2	61368	1
Indian Point 2 (IP2)	Essential ac	2	61368	0
Indian Point 3 (IP3)	Essential ac	3	59064	0
Kewaunee (KE1)	Essential ac	7	61368	0
McGuire 1 (MG1)	Essential ac	6	12264	2
North Anna 1 (NA1)	Essential ac	5	41568	2
North Anna 2 (NA2)	Essential ac	5	22392	0
Point Beach 1 (PT1)	Essential ac	2	61368	0
Point Beach 2 (PT2)	Essential ac	2	61368	0
Prairie Island 1 (PR1)	Essential ac	6	61368	2
Prairie Island 2 (PR2)	Essential ac	6	61368	1
Robinson 2 (R02)	Essential ac	2	61368	0
Salem 1 (SA1)	Essential ac	4	53088	7
Salem 2 (SA2)	Essential ac	4	21024	1
San Onofre 1 (SO1)	Essential ac	3	61368	2
Sequoyah 1 (SE1)	Essential ac	4	21840	1
Sequoyah 2 (SE2)	Essential ac	4	21840	12
Summer 1 (SM1)	Essential ac	6	1704	0
Surry 1 (SU1)	Essential ac	3	61368	0

Table 4. (continued)

<u>Plant Name (Code)</u>	<u>System</u>	<u>Inverter Population</u>	<u>Hours Per Component</u>	<u>Total Failures</u>
WESTINGHOUSE (continued)				
Surry 2 (SU2)	Essential ac	3	61368	1
Trojan (TR1)	Essential ac	5	61368	3
Turkey Point 3 (TU3)	Essential ac	2	61368	0
Turkey Point 4 (TU4)	Essential ac	2	61368	0
Yankee-Rowe 1 (YR1)	Essential ac ^c	—	—	—
Zion 1 (ZI1)	Essential ac	4	61368	2
Zion 2 (ZI2)	Essential ac	4	61368	3
NSSS Total				63
GENERAL ELECTRIC ^a				
Big Rock Point 1 (BP1) ^d	Essential ac LPCI	— —	— —	— —
Browns Ferry 1 (BF1)	Essential ac ^c	—	—	—
Browns Ferry 2 (BF2)	Essential ac ^c	—	—	—
Browns Ferry 3 (BF3)	Essential ac ^c	—	—	—
Brunswick 1 (BR1)	Essential ac	2	54624	0
Brunswick 2 (BR2)	Essential ac	2	61368	0
Cooper Station (CO1)	Essential ac	2	61368	1
Dresden 1 (DR1) ^d	Essential ac LPCI	— —	— —	— —
Dresden 2 (DR2)	Essential ac ^c	—	—	—
Dresden 3 (DR3)	Essential ac ^c	—	—	—
Duane Arnold (DA1)	Essential ac ^c	—	—	—
Fitzpatrick (FP1)	Essential ac ^c LPCI	— 2	— 46152	— 9
Grand Gulf 1 (GG1)	Essential ac	6	3672	0

Table 4. (continued)

<u>Plant Name (Code)</u>	<u>System</u>	<u>Inverter Population</u>	<u>Hours Per Component</u>	<u>Total Failures</u>
GENERAL ELECTRIC ^a (continued)				
Hatch 1 (EN1)	Essential ac	1	61368	0
	LPCI	2	41328	8
Hatch 2 (EN2)	Essential ac	1	39408	0
	LPCI	2	39408	7
La Salle 1 (LS1)	Essential ac	1	4656	0
Millstone 1 (MI1)	Essential ac ^c	—	—	—
Monticello (MO1)	Essential ac ^c	—	—	—
Nine Mile Point 1 (NMI)	Essential ac ^c	—	—	—
Oyster Creek 1 (OC1)	Essential ac ^c	—	—	—
Peach Bottom 2 (PB2)	Essential ac	1	61368	0
Peach Bottom 3 (PB3)	Essential ac	1	61368	0
Pilgrim 1 (PI1)	Essential ac ^c	—	—	—
Quad-Cities 1 (QC1)	Essential ac ^c	—	—	—
Quad-Cities 2 (QC2)	Essential ac ^c	—	—	—
Susquehanna 1 (SQ1)	Essential ac	2	2712	0
Vermont Yankee 1 (VY1)	Essential ac ^c	—	—	—
	LPCI	2	56088	12
NSSS Total				37
GRAND TOTAL				137

- a. Static inverters are not incorporated in LPCI systems, unless noted otherwise.
- b. San Onofre 2's LPCI static inverters were considered atypical.
- c. Motor- or motor-generator sets instead of static inverters are incorporated in these systems.
- d. No population data available.




Figure 13a. Scatter plot of operating LER rates of essential ac electrical distribution static inverters, for Babcock & Wilcox plants, inoperable, command faults excluded.




Figure 13b. Scatter plot of operating LER rates of essential ac electrical distribution static inverters, for Combustion Engineering plants, inoperable, command faults excluded.




Figure 13c. Scatter plot of operating LER rates of essential ac electrical distribution static inverters, for Westinghouse plants, inoperable, command faults excluded.




Figure 13d. Scatter plot of operating LER rates of essential ac electrical distribution and low pressure coolant injection static inverters, for General Electric plants, inoperable, command faults excluded.




Figure 13e. Scatter plot summarizing operating LER rates of essential ac electrical distribution and low pressure coolant injection static inverters, inoperable, command faults excluded.




Figure 14. Scatter plot of operating LER rates of essential ac electrical distribution system static inverters, for General Electric plants, inoperable, command faults excluded.




Figure 15. Scatter plot of operating LER rates of low pressure coolant injection system static inverters, for General Electric plants, inoperable, command faults excluded.

Table 5. Summary of LER rates by NSSS

NSSS	System	Total Failures	Total Population Hours	Operating Failure Rate (Failures/Hour)
Babcock & Wilcox	Essential ac LPCI ^a	23	2,543,280	9.0E-06
	Combined	23	2,543,280	9.0E-06
Combustion Engineering	Essential ac LPCI ^a	14	2,353,368	5.9E-06
	Combined	14	2,353,368	5.9E-06
Westinghouse	Essential ac LPCI ^a	63	5,630,112	1.1E-05
	Combined	63	5,630,112	1.1E-05
PWRs	Essential ac LPCI ^a	100	10,526,760	9.5E-06
	Combined	100	10,526,760	9.5E-06
General Electric (BWRs)	Essential ac	1	610,344	1.6E-06
	LPCI	36	365,952	9.8E-05
	Combined	37	976,296	3.8E-05
Overall	Essential ac	101	11,137,104	9.1E-06
	LPCI	36	365,952	9.8E-05
	Combined	137	11,503,056	1.2E-05

a. LPCI inverters were found not to be incorporated at the plants within these groupings, or in the case of San Onofre 2, were considered atypical.

REFERENCES

1. NIH-LER data base 1976 - 1981.
2. Oak Ridge National Laboratory, *Licensee Event Report (LER) Compilation*, NURFG/CR-2000, Vol. 1 - 2, March 1982 - January 1984.
3. *Nuclear Power Experience*, Encino, California (a copyright publication of nuclear plant equipment problems, updated monthly).
4. U.S. Nuclear Regulatory Commission, *Operating Units Status Report—Licensed Operating Reactors*, NUREG/CR-0020, Vol. 1, No. 2, October 1977.
5. Power Authority of New York State, correspondence to USNRC, 1976 - 1977.
6. U.S. Nuclear Regulatory Commission, *Operating Units Status Report—Licensed Operating Reactors*, NUREG/CR-0020, Vol. 2, No. 5, May 1978.
7. Georgia Power, correspondence to USNRC, 1974 - 1978.
8. U.S. Nuclear Regulatory Commission, *Operating Units Status Report—Licensed Operating Reactors*, NUREG-0020-9, September 1976.
9. U.S. Nuclear Regulatory Commission, *Operating Units Status Report—Licensed Operating Reactors*, NUREG/CR-0020, Vol. 8, No. 1, January 1984.
10. NUS Corporation, *Commercial Nuclear Power Plants*, 16th ed., February 1984.

APPENDIX A

DISCUSSION OF THE CAUSES OF VARIATIONS IN LER REPORTING

APPENDIX A

DISCUSSION OF THE CAUSES OF VARIATIONS IN LER REPORTING

There are generally two criteria used by the utilities to determine reporting requirements for faults; these are: (a) technical specifications for each individual plant and (b) the LER reporting guide, Regulatory Guide 1.16.^{A-1} The technical specifications for plants licensed prior to January 1, 1976, were independently written by individual plants without any planned uniformity among plants. All plants licensed after this date use standardized technical specifications that helped to create more uniform reporting. Three plants (Calvert Cliffs 1, Yankee-Rowe 1, and Brunswick 2) that received operating licenses prior to 1976 converted to standard technical specifications in 1977. In addition to technical specification standardization there have been changes in the rules that govern LER reporting since 1976. These updated rules and the standardized technical specifications are expected to result in more uniform LER reporting after January 1, 1976. But pre-1976 LER data, as well as LER data reported by plants that are not subject to standard technical specifications, will show considerable variation.

The above *mechanical* causes for LER reporting variations are explicable and expected. However, there are additional reporting variations. Differences in interpretation of the rules for submit-

ting LER reports cause some variation. Also, variation is caused by the difficulty in determining the extent of safety and nonsafety systems and therefore, by the questions of what faults are or are not required to be reported. Finally, variation can be caused by the degree of importance assigned to the LER reports by management of the individual utilities. Such variation in both the quantity and quality of LERs submitted by similar plants may appear where one would expect a more uniform reporting.

One thing that seems to have most hindered the development of uniform reporting is the lack of agreement about the purpose of a LER. Many persons feel that LERs are intended to highlight problem areas within the safety systems. Some feel that the LERs ought to be used to highlight generic problem areas. Many of these same people do not feel that these uses are compatible with the need to determine fault rate information. These differing viewpoints may be an additional reason for the variations in the quality and quantity of LERs received by the United States Nuclear Regulatory Commission. For further discussion of the causes of variations in LER reporting, see Reference A-2.

References

- A-1. U.S. Nuclear Regulatory Commission, *Reporting of Operating Information—Appendix A Technical Specification*, U.S. Nuclear Regulatory Commission Regulatory Guide 1.16, Rev. 4, August 1975.
- A-2. Gerald L. Boner and Harvey W. Hanners, *Enhancement of Onsite Emergency Diesel Generator Reliability*, University of Dayton Research Institute, NUREG/CR-0660, 1979, pp. I-4,5, IV-5,6, V-10, and V-13.

APPENDIX B
ONE-LINE LER CODING SCHEME

CONTENTS

ONE-LINE LER CODING SCHEME	B-4
NSSS Vendor (NSSS)	B-4
Plant (PLANT)	B-4
Control/NSIC Number (CONTROL OR NSIC NUMBER)	B-9
Event Date (EVENT DATE)	B-9
Component (COMP)	B-9
Subcomponent (SUB COMP)	B-9
System (SYSTEM)	B-9
Fault Mode and Cause (MODE & CAUSE)	B-9
Activity Resulting in Discovery (ACTIVITY)	B-10
Type of Event (TYPE)	B-10
Event Classification (CLASS)	B-10
Number of Faults (FAULT #)	B-10
Fault Mode Description (MODE DESCRIPTION)	B-10
Fault Cause Description (CAUSE DESCRIPTION)	B-10
Additional Information	B-11
NSIC Volume/Number (NSIC VOLUME NUMBER)	B-11
LER Number (LER NUMBER)	B-11
Report Type (REPORT TYPE)	B-11
Manufacturer (MANUFACTURER CODE)	B-11
Repair Time (REPAIR TIME)	B-11
Flagging (FLAGGING)	B-11
References	B-11

TABLES

B-1. General plant information	B-4
B-2. Codes used in one-line descriptions	B-12
B-3. Codes used in additional information one-line descriptions	B-13

APPENDIX B

ONE-LINE LER CODING SCHEME

In order to extract as much pertinent information as possible from the information provided in the original LER, and, at the same time, try to restrict the information to one line of computer output per LER, the following coding scheme was developed.

In general, the order of the discussion that follows is the order in which the various fields appear in the one-line descriptions of the inverter events. The headings used for the corresponding fields in the one-line descriptions are contained in parentheses following the topic headings used below.

NSSS Vendor (NSSS)

The NSSS field indicates the vendor associated with the plant submitting the LER report. A

1-character field is used to store and display the vendor code. This field can be used as a sort key. The following list gives the code and corresponding NSSS vendor.

Code	NSSS Vendor
B	Babcock & Wilcox
C	Combustion Engineering
W	Westinghouse
G	General Electric

Plant (PLANT)

A 3-character field was used to identify the commercial power plant responsible for submitting each LER. Table B-1 provides a list of the plants and codes and also supplies other plant information. B-1 The PLANT field can be used as a sort key.

Table B-1. General plant information

Plant Name (Docket Number)	Plant Code	Design Electrical Rating (MWe)	Date of Initial Criticality	Date of Commercial Operation	Location (State)	Architect/Engineer	Constructor
BABCOCK & WILCOX							
Arkansas Nuclear One 1 (50-313)	AR1	850	08/06/74	12/19/74	AR	Bechtel	Bechtel
Crystal River 3 (50-302)	CR3	825	01/14/77	03/13/77	FL	Gilbert Associates	J. A. Jones Construction
Davis-Besse 1 (50-346)	DB1	906	08/12/77	07/31/78	OH	Bechtel	Bechtel
Oconee 1 (50-269)	OE1	887	04/19/73	07/15/73	SC	Duke & Bechtel	Duke Power
Oconee 2 (50-270)	OE2	887	11/11/73	09/09/74	SC	Duke & Bechtel	Duke Power
Oconee 3 (50-287)	OE3	887	09/05/74	12/16/74	SC	Duke & Bechtel	Duke Power
Rancho Seco 1 (50-312)	RS1	918	09/16/74	04/17/75	CA	Bechtel	Bechtel
Three Mile Island 1 ^a (50-289)	TI1	819	06/05/74	09/02/74	PA	Gilbert Associates	United Engineers & Constructors, Inc.
Three Mile Island 2 ^a (50-320)	TI2	906	03/28/78	12/30/78	PA	Burns & Roe	United Engineers & Constructors, Inc.

Table B-1. (continued)

Plant Name (Docket Number)	Plant Code	Design Electrical Rating (MWe)	Date of Initial Criticality	Date of Commercial Operation	Location (State)	Architect/Engineer	Constructor
COMBUSTION ENGINEERING							
Arkansas Nuclear One 2 (50-368)	AR2	912	12/05/78	03/26/80	AR	Bechtel	Bechtel
Calvert Cliffs 1 (50-317)	CC1	845	10/07/74	05/08/75	MD	Bechtel	Bechtel
Calvert Cliffs 2 (50-318)	CC2	845	11/30/76	04/01/77	MD	Bechtel	Bechtel
Fort Calhoun 1 (50-285)	FC1	478	08/06/73	06/20/74	NB	Gibbs, Hill, Durham & Richardson, Inc.	Gibbs, Hill, Durham & Richardson, Inc.
Maine Yankee (50-309)	MY1	825	10/23/72	12/28/72	ME	Stone & Webster	Stone & Webster
Millstone 2 (50-336)	MI2	870	10/17/75	12/26/75	CT	Bechtel	Bechtel
Palisades (50-255)	PA1	805	05/24/71	12/31/71	MI	Bechtel	Bechtel
San Onofre 2 (50-361)	SO2	1087	07/26/82	08/19/83	CA	Bechtel	Bechtel
St. Lucie 1 (50-335)	SL1	830	04/22/76	12/21/76	FL	Ebasco	Ebasco
WESTINGHOUSE							
Beaver Valley 1 (50-334)	BV1	835	05/10/76	10/01/76	PA	Stone & Webster	Stone & Webster
Cook 1 (50-315)	DC1	1030	01/18/75	08/27/75	MI	American Electric Power Service Corporation	American Electric Power Service Corporation
Cook 2 (50-316)	DC2	1100	03/10/78	07/01/78	MI	American Electric Power Service Corporation	J. A. Jones Construction
Farley 1 (50-348)	JF1	829	08/09/77	12/01/77	AL	Southern Services, Inc.	Bechtel
Farley 2 (50-364)	JF2	829	05/05/81	07/30/81	AL	Southern Services, Inc.	Bechtel
Ginna (50-244)	RG1	470	11/08/69	07/01/70	NY	Gilbert Associates	Bechtel
Haddam Neck (50-213)	HN1	582	07/24/67	01/01/68	CT	Stone & Webster	Stone & Webster

Table B-1. (continued)

Plant Name (Docket Number)	Plant Code	Design Electrical Rating (MWe)	Date of Initial Criticality	Date of Commercial Operation	Location (State)	Architect/Engineer	Constructor
Indian Point 2 (50-247)	IP2	873	05/22/73	08/01/74	NY	United Engineers & Constructors, Inc.	Westinghouse Development Corp.
Indian Point 3 (50-286)	IP3	965	04/06/76	08/30/76	NY	United Engineers & Constructors, Inc.	Westinghouse Development Corp.
Kewaunee (50-305)	KE1	535	03/07/74	06/16/74	WI	Pioneer Services & Engineering	Pioneer Services & Engineering
McGuire 1 (50-369)	MG1	1180	08/08/81	12/01/81	NC	Duke Power	Duke Power
North Anna 1 (50-338)	NA1	907	04/05/78	06/06/78	VA	Stone & Webster	Stone & Webster
North Anna 2 (50-339)	NA2	907	06/12/80	12/14/80	VA	Stone & Webster	Stone & Webster
Point Beach 1 (50-266)	PT1	497	11/02/70	12/21/70	WI	Bechtel	Bechtel
Point Beach 2 (50-301)	PT2	497	05/30/72	10/01/72	WI	Bechtel	Bechtel
Prairie Island 1 (50-282)	PR1	530	12/01/73	12/16/73	MN	Fluor Pioneer, Inc.	Northern States Power Company
Prairie Island 2 (50-306)	PR2	530	12/17/74	12/21/74	MN	Fluor Pioneer, Inc.	Northern States Power Company
Robinson 2 (50-261)	RO2	700	09/20/70	03/07/71	SC	Ebasco	Ebasco
Salem 1 (50-272)	SA1	1090	12/11/76	06/30/77	NJ	Public Services & Gas Co.	United Engineers & Constructors, Inc.
Salem 2 (50-311)	SA2	1115	08/08/80	10/13/81	NJ	Public Services & Gas Co.	United Engineers & Constructors, Inc.
San Onofre 1 (50-206)	SO1	436	06/14/67	01/01/68	CA	Bechtel	Bechtel
Sequoyah 1 (50-327)	SE1	1148	07/05/80	07/01/81	TN	Tennessee Valley Authority	Tennessee Valley Authority
Sequoyah 2 (50-328)	SE2	1148	11/05/81	06/01/82	TN	Tennessee Valley Authority	Tennessee Valley Authority
Summer 1 (50-395)	SM1	900	10/22/82	01/01/84	SC	Gilbert Associates	Daniel International
Surry 1 (50-280)	SU1	788	07/01/72	12/22/72	VA	Stone & Webster	Stone & Webster

Table B-1. (continued)

Plant Name (Docket Number)	Plant Code	Design Electrical Rating (MWe)	Date of Initial Criticality	Date of Commercial Operation	Location (State)	Architect/Engineer	Constructor
Surry 2 (50-281)	SU2	788	03/07/73	05/01/73	VA	Stone & Webster	Stone & Webster
Trojan (50-344)	TR1	1130	12/15/75	05/20/76	OR	Bechtel	Bechtel
Turkey Point 3 (50-250)	TU3	693	10/20/72	12/14/72	FL	Bechtel	Bechtel
Turkey Point 4 (50-251)	TU4	693	06/11/73	09/07/73	FL	Bechtel	Bechtel
Yankee-Rowe 1 (50-029)	YR1	175	08/19/60	01/01/61	MA	Stone & Webster	Stone & Webster
Zion 1 (50-295)	ZI1	1040	06/19/73	12/31/73	IL	Sargent & Lundy	Commonwealth Edison
Zion 2 (50-304)	ZI2	1040	12/24/73	09/17/74	IL	Sargent & Lundy	Commonwealth Edison
GENERAL ELECTRIC							
Big Rock Point 1 (50-155)	BP1	72	09/27/62	03/29/63	MI	Bechtel	Bechtel
Browns Ferry 1 (50-259)	BF1	1065	08/17/73	08/01/74	AL	Tennessee Valley Authority	Tennessee Valley Authority
Browns Ferry 2 (50-260)	BF2	1065	07/20/74	03/01/75	AL	Tennessee Valley Authority	Tennessee Valley Authority
Browns Ferry 3 (50-296)	BF3	1065	08/08/76	03/01/77	AL	Tennessee Valley Authority	Tennessee Valley Authority
Brunswick 1 (50-325)	BR1	821	10/08/76	03/18/77	NC	United Engineers & Constructors, Inc.	Brown & Root
Brunswick 2 (50-324)	BR2	821	03/20/75	11/03/75	NC	United Engineers & Constructors, Inc.	Brown & Root
Cooper Station (50-298)	CO1	778	02/21/74	07/01/74	NB	Burns & Roe	Burns & Roe
Dresden 1 ^b (50-010)	DR1	200	10/15/59	07/04/60	IL	Bechtel	Bechtel
Dresden 2 (50-237)	DR2	794	01/07/70	06/09/70	IL	Sargent & Lundy	United Engineers & Constructors, Inc.
Dresden 3 (50-249)	DR3	794	01/31/71	11/16/71	IL	Sargent & Lundy	United Engineers & Constructors, Inc.

Table B-1. (continued)

Plant Name (Docket Number)	Plant Code	Design Electrical Rating (MWe)	Date of Initial Criticality	Date of Commercial Operation	Location (State)	Architect/Engineer	Constructor
Duane Arnold (50-331)	DA1	538	03/23/74	02/01/75	IA	Bechtel	Bechtel
Fitzpatrick (50-333)	FP1	821	11/17/74	07/28/75	NY	Stone & Webster	Stone & Webster
Grand Gulf 1 (50-416)	GG1	1250	08/01/82	1983	MS	Bechtel	Bechtel
Hatch 1 (50-321)	EN1	777	09/12/74	12/31/75	GA	Bechtel	Georgia Power Co.
Hatch 2 (50-366)	EN2	784	07/04/78	09/05/79	GA	Bechtel	Georgia Power Co.
La Salle 1 (50-373)	LS1	1078	06/21/82	NA	IL	Sargent & Lundy	Commonwealth Edison
Millstone 1 (50-245)	M11	660	10/26/70	03/01/71	CT	Ebasco	Ebasco
Monticello (50-263)	MO1	545	12/10/70	06/30/71	MN	Bechtel	Bechtel
Nine Mile Point 1 (50-220)	NM1	620	09/05/69	12/01/69	NY	Niagara Mohawk Power Corporation	Stone & Webster
Oyster Creek 1 (50-219)	OC1	650	05/03/69	12/01/69	NJ	Burns & Roe	Burns & Roe
Peach Bottom 2 (50-277)	PB2	1065	09/16/73	07/05/74	PA	Bechtel	Bechtel
Peach Bottom 3 (50-278)	PB3	1065	08/07/74	12/23/74	PA	Bechtel	Bechtel
Pilgrim 1 (50-293)	PI1	655	06/16/72	12/01/72	MA	Bechtel	Bechtel
Quad-Cities 1 (50-254)	QC1	789	10/18/71	02/18/73	IL	Sargent & Lundy	United Engineers & Constructors, Inc.
Quad-Cities 2 (50-265)	QC2	789	04/26/72	03/10/73	IL	Sargent & Lundy	United Engineers & Constructors, Inc.
Susquehanna 1 (50-387)	SQ1	1065	09/10/82	06/08/83	PA	Bechtel	Bechtel
Vermont Yankee 1 (50-271)	VY1	514	03/24/72	11/30/72	VT	Ebasco	Ebasco

a. Plant shutdown since 03/28/79.

b. Plant shutdown since 10/31/78.

Control/NSIC Number (CONTROL OR NSIC NUMBER)

To identify each one-line record within the data file, and to provide a cross-reference with the actual LER submitted to the USNRC, the unique six-digit control number assigned to the report by the USNRC was entered into the control number field. LERs received after December 31, 1981 were assigned a number by the Nuclear Safety Information Center (NSIC). There were some instances of several different reports being listed in the narrative summary of a single LER. To accommodate this situation, an alphabetic character was added to the six-digit number in order to separately identify each report. Thus, traceability back to the original LER number was maintained, yet each report remained unique. When a single LER reported more than one instance of the same event (e.g., "fuses in inverters 2 and 6 blew") in the summary description, an asterisk (*) was placed after the control number to flag the coded one-line description as containing multiple events. The corresponding number of events was then entered in the FAULT # field so that each event could be accounted for. The control number field can be used as a sort field, but it is primarily intended for data record identification within the data file.

Event Date (EVENT DATE)

A six-digit field was used to record the date of the event: two digits each, for the month, day, and year. The EVENT DATE corresponds to the event date listed in the LER for each event. The month, day, or year can be used as sort keys.

Component (COMP)

The static inverter was identified as the principal component and coded as SI.

Subcomponent (SUB COMP)

This field lists the types of inverter subcomponents identified in the LERs. Some related types are combined under one code, as shown in the following list. This field can be used as a sort key.

Code	Subcomponent
AC	Annunciator control card
CC	Firing circuit
CF	Cooling fan
CH	Choke
CL	Control card/control module
CP	Capacitor
DB	Driver board
DI	Diode
FB	Frequency board
FS	Fuse
IN	Inductor
OS	Oscillator
PC	Protection card
PS	Power supply (internal)
RC	Rectifier
RE	Relay
RS	Resistor
SW	Switch
TR	Transformer
TS	Transistor
UV	Undervoltage coil
VR	Voltage regulator
UU	Unknown/not applicable

System (SYSTEM)

A 1-character field is used to indicate the system that the inverter was a part of or the system that the inverter was supplying power to, whichever was applicable. This field can be used as a sort key. The following is a list of system codes and descriptions.

Code	System
A	Automatic Depressurization System (ADS)
C	Containment (includes isolation control)
E	Essential ac electrical distribution
H	High pressure coolant injection (HPCI)
L	Low pressure coolant injection (LPCI)
Q	Reactor core isolation cooling (RCIC) (BWRs only)
P	Unknown

Fault Mode and Cause (MODE & CAUSE)

A 3-character field indicates the fault code. A 1-character subordinate field indicates the mode and

a 2-character subordinate field indicates the cause. The following scheme was used to encode the various modes and causes identified in the LERs. Either field can be used as sort keys.

Code	Fault Mode
A	Reduced capability
B	Inoperable

Code	Fault Cause
00	Unknown
01	Personnel operation
02	Personnel maintenance
03	Personnel testing
04	Design error
05	Fabrication/construction/quality control
06	Defective procedures
07	Extreme environment
08	Electrical malfunction
09	Mechanical malfunction

Activity Resulting in Discovery (ACTIVITY)

A 1-character code was used to indicate the activity taking place that caused or led to the discovery of the event. Any activity not specifically identified was considered to be *during normal plant operation*. This field can be used as a sort key. The coding scheme for this field is as follows.

Code	Activity
M	Maintenance
N	Normal plant operation
R	Records review
T	Testing
U	Unknown

Type of Event (TYPE)

A 1-character field indicates the type of event identified in the LER. A blank in this field implies a random event. This field can be used as a sort key. The following scheme was used to identify the event types.

Code	Type of Event
B	Recurring Common Cause Failure
C	Common Cause Failure
R	Recurring Failure
S	Command Fault
T	Recurring Command Fault
U	Common Cause Command Fault
V	Recurring Common Cause Command Fault
Blank	Random Failure

Event Classification (CLASS)

A 1-character field was used to classify the events as age-related or frequency-of-use-related. A **D** in this field was used for frequency-of-use-related events, and a **T** was used for age-related events. If no determination could be made, a **U** was inserted in this field. This field can be used as a sort key.

Number of Faults (FAULT #)

The FAULT # field, mentioned in the Control/NSIC Number paragraph, was used to store a count of the number of events per one-line LER description. A blank in this field implies that the value of this field is one. Should there be more than one event per LER, the corresponding number of events is entered in this field.

Fault Mode Description (MODE DESCRIPTION)

The LER narrative summary of the mode was condensed into a 50-character alphanumeric field. This field provides a short, concise description of the mode. It is not a sort field.

Fault Cause Description (CAUSE DESCRIPTION)

A 41-character alphanumeric field was used for a narrative description of the cause. If no cause was reported, this field provided additional space for a description of the LER. It is not a sort field.

In order to provide as much information as possible in both the MODE and CAUSE DESCRIPTIONS, many words are abbreviated and many acronyms are used. Most of these acronyms can be found in the "Nomenclature" section at the beginning of this report.

Table B-2 provides the codes used in the one-line descriptions and is presented as a summary of the preceding discussion. One of these coding sheets will precede each sort of one-line descriptions in this report so that the reader need not continually refer to this appendix.

Additional Information

Because of space limitations, additional information pertaining to manufacturer and various other items of interest is listed separately. Table B-3 provides the codes used in the additional information one-line descriptions. A discussion of the additional information fields follows.

NSIC Volume/Number (NSIC VOLUME NUMBER). This field was provided in order to identify the location of newer LERs located in the *Licensee Event Report (LER) Compilation* prepared from the data file of the Nuclear Safety Information Center (NSIC).^{B-2}

LER Number (LER NUMBER). In addition to a plant docket number, each plant assigns a number to each LER that it submits. This number is assigned sequentially within each calendar year to every LER submitted by the plant. At the end of the calendar year the plant LER number will start again with 001 for the next year. A 3-character field was used to indicate the LER number associated with a particular plant. LER NUMBER can be used as a sort key, although it is primarily intended for data record identification within the data file.

Report Type (REPORT TYPE). The Report Type was taken directly from the LER. The letter **A** is

used to indicate two-week reports, **B** is used to indicate 30-day reports, and **C** is used to indicate other types of reports. This information was not found in the NSIC data base's NUREG/CR-2000. Report Type is a sort field.

Manufacturer (MANUFACTURER CODE). A 4-character alphanumeric field is used to identify the manufacturer given in the LER. A blank was used in the manufacturer field, if no manufacturer was given in the LER. The codes used for the various manufacturers were taken from Exhibit J of the *Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File*.^{B-3} The manufacturer field can be used as a sort key.

One should be cautious in using this manufacturer information because the manufacturer code in the LER is sometimes missing and sometimes not appropriate for the component coded in the data base.

Repair Time (REPAIR TIME). The REPAIR TIME field is a three-digit field used to store component repair time, when available, in hourly units.

Flagging (FLAGGING). Each one-line data record was evaluated to determine whether or not the event might need to be "flagged" for possible future evaluation. The letter **A** was used to identify those components which caused an inadvertent scram or accident (e.g., loss of coolant flow) upon failure, and **B** was used to identify those components which failed to mitigate an accident. In order to flag those events which we thought should have additional attention brought to them and were not included in the previous two codes, the letter **C** was used. FLAGGING is a sort field.

The fields contained in the Additional Information section are found in the one-line descriptions in Appendix H.

References

- B-1. U.S. Nuclear Regulatory Commission, *Operating Units Status Report—Licensed Operating Reactors*, NUREG/CR-0020, Vol. 8, No. 1, January 1984.
- B-2. *Licensee Event Report (LER) Compilation*, NUREG/CR-2000, Vol. 1-2, March 1982-January 1984.
- B-3. *Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File*, NUREG-0161, July 1977.

Table B-2. Codes used in one-line descriptions

FAULT MODE			CODES USED IN LER ONE-LINE DESCRIPTIONS		ACTIVITY RESULTING IN DISCOVERY	
CODE	DESCRIPTION		CODE	DESCRIPTION	CODE	DESCRIPTION
A	REDUCED CAPABILITY		00	UNKNOWN		
B	INOPERABLE		01	PERSONNEL OPERATION	M	MAINTENANCE
			02	PERSONNEL MAINTENANCE	N	NORMAL PLANT OPERATION
			03	PERSONNEL TESTING	R	RECORDS REVIEW
			04	DESIGN ERROR	Y	TESTING
			05	DEACTIVATION/CONSTRUCTION/QUALITY CONTROL	U	UNKNOWN
			06	DEACTIVATION PROCEDURES		
			07	ENVIRONMENT		
			08	ELECTRICAL MALFUNCTION		
			09	MECHANICAL MALFUNCTION		
SYSTEM		SUBCOMPONENT		NSSS VENDOR		
CODE	DESCRIPTION	CODE	DESCRIPTION	CODE	DESCRIPTION	
A	AUTOMATIC DEPRESSURIZATION SYSTEM (ADS)	AC	ANNUNCIATOR CONTROL CARD	B	BABCOCK & WILCOX	
C	CONTAINMENT (INCLUDES ISOLATION CONTROL)	CC	FIRING CIRCUIT	C	COMBUSTION ENGINEERING	
E	ESSENTIAL AC ELECTRICAL DISTRIBUTION	CF	COOLING FAN	M	WESTINGHOUSE	
H	HIGH PRESSURE COOLANT INJECTION (HPCI)	CH	CHUKE	G	GENERAL ELECTRIC	
L	LOW PRESSURE COOLANT INJECTION (LPCI)	CI	CONTROL CARD/CONTROL MODULE			
PC	REACTOR CORE ISOLATION COOLING (RCIC)	CP	CAPACITOR	COMPONENT		
Q	UNKNOWN	DB	DRIVER BOARD	CODE	DESCRIPTION	
		DI	DIODE	SI	STATIC INVERTER	
		FB	FREQUENCY BOARD			
		FS	FUSE	EVENT CLASSIFICATION		
		IN	INDUCTOR	CODE	DESCRIPTION	
		OS	OSCILLATOR	D	FREQUENCY	
		PC	PROTECTION CARD	Y	AGE	
		PS	POWER SUPPLY (INTERNAL)	U	UNKNOWN	
		RA	RECTIFIER			
		RE	RELAY			
		RS	RESISTOR			
		SW	SWITCH			
		TR	TRANSFORMER			
		TS	TRANSISTOR			
		UV	UNDERVOLTAGE COIL			
		VR	VOLTAGE REGULATOR			
		UU	UNKNOWN/NOT APPLICABLE			
TYPE OF EVENT						
CODE	DESCRIPTION					
B	RECURRING COMMON CAUSE FAILURE					
C	COMMON CAUSE FAILURE					
F	RECURRING FAILURE					
U	COMMAND FAULT					
V	RECURRING COMMAND FAULT					
W	COMMON CAUSE COMMAND FAULT					
X	RECURRING COMB IN CAUSE COMMAND FAULT					
Y	RANDOM FAILURE					
Z						
BLANK						

B-12

Table B-3. Codes used in additional information one-line descriptions

ADDITIONAL CODES USED IN LER ONE-LINE DESCRIPTIONS

<u>MANUFACTURER CODE</u>		<u>FLAGGING</u>	
<u>CODE</u>	<u>DESCRIPTION</u>	<u>CODE</u>	<u>DESCRIPTION</u>
A400	ASCO VALVES	A	FAILED COMPONENT CAUSED AN ACCIDENT
C100	CCO BATTERIES, DIVISION OF ELTRA CORP.	B	COMPONENT FAILED TO MITIGATE AN ACCIDENT
C700	CYBEREX INC.	C	SAFETY SIGNIFICANT
G000	GENERAL ELECTRIC CO.		
G100	GOULDS COMPANY (GOULDS)		
G200	GUARDIAN ELECTRIC		
I202	ITE IMPERIAL CORPORATION		
L040	LAMBDA ELECTRONICS		
L200	LUNDELL CONTROLS - TECHNOLOGY INC.		
O200	OLA BASIC INDUSTRIES		
O200	OLA ELECTRIC COMPANY		
O200	OLA STATE CONTROLS, INC.		
S300	STATIC PRODUCTS		
T240	TOPAZ ELECTRONICS		
W120	WESTINGHOUSE ELECTRIC CORPORATION		
W121	WESTINGHOUSE ELECTRIC COMPANY (ELEV DIV)		
BLANK	UNKNOWN		

<u>REPORT TYPE</u>	
<u>CODE</u>	<u>DESCRIPTION</u>
A	2-WEEK REPORTS
B	30-DAY REPORTS
C	OTHER

APPENDIX C
LER RATE ESTIMATION METHODS

APPENDIX C

LER RATE ESTIMATION METHODS

To estimate the Licensee Event Report (LER) fault rates for components, the following well-known statistical methods were used for Type-I censored data with replacement.^{C-1}

The general methods for estimating rates on an hourly basis and on a demand basis are

$$\hat{\lambda}(\text{hourly}) = \frac{N}{T} \quad (\text{C-1})$$

$$\hat{\lambda}(\text{demand}) = \frac{N}{D} \quad (\text{C-2})$$

where

- $\hat{\lambda}$ = estimated fault rate
- N = number of reported component faults
- T = total time accrued by all components
- D = total number of demands on all components.

The general computational formulas, Equations (C-1) and (C-2), may be applied to particular situations. The fault rate for a component in a particular plant is estimated by setting

- N = N_i
- T = T_i
- D = D_i

where

- N_i = number of component faults in plant i
- T_i = total accrued hours of all like components in plant i
- D_i = total accrued number of demands on all like components in plant i.

In a similar manner, fault rates may be estimated for components manufactured by a particular ven-

dor, for components in a particular plant type (PWR or BWR), or for components present in all plants.

Confidence limits for hourly fault rates were based on the assumption that the underlying component fault distributions are exponential; therefore, the resulting LER data are representable by a Poisson process. In demand evaluations, N is binomially distributed. However, since the probability of fault is small and the number of demands is large, the Poisson distribution may be used to approximate this variable. The generalized formulas for estimating 100(1 - α)% confidence limits on the fault rates are

$$\frac{\chi_{\alpha/2}^2(2N)}{2T} \leq \lambda(\text{hourly}) \leq \frac{\chi_{1-\alpha/2}^2(2N+2)}{2T} \quad (\text{C-3})$$

and

$$\frac{\chi_{\alpha/2}^2(2N)}{2D} \leq \lambda(\text{demand}) \leq \frac{\chi_{1-\alpha/2}^2(2N+2)}{2D} \quad (\text{C-4})$$

where

- $\chi_a^2(b)$ = the chi-square variate at cumulative probability **a** with **b** degrees of freedom.

In these equations, α is the fraction left out of the intervals. For example, for 90% confidence limits α is 0.10, α/2 is 0.05, and the upper limit uses the 95th percentile.

If D is small, then the Poisson approximation of the binomial distribution is not adequate, and 100(1 - α)% confidence limits for the demand fault rate are

$$\begin{aligned} \frac{NF_L}{D - N + 1 + NF_L} &\leq \lambda(\text{demand}) \\ &\leq \frac{(N + 1)F_U}{D - N + (N + 1)F_U} \end{aligned} \quad (\text{C-5})$$

where

$$F_L = F_{\alpha/2}(2N, 2D - 2N + 2)$$

$$F_U = F_{1-\alpha/2}(2N + 2, 2D - 2N)$$

$$F_{a(b,c)} = \text{F variate at cumulative probability } a \text{ with } b \text{ and } c \text{ degrees of freedom.}$$

As before, for 90% confidence limits the 0.05 and 0.95 quantities are used ($\alpha = 0.10$).

In this work, hourly rate confidence limits were always based on Equation (C-3). Demand rate confidence limits were based on Equation (C-4) if $D - N \geq 100$, and on Equation (C-5) otherwise.

The lower limits in Equations (C-3), (C-4), and (C-5) are not defined in cases where no faults are observed ($N = 0$). Zero is the appropriate lower limit in these cases. However, Equations (C-1) and (C-2) also give zero as the point estimate when $N = 0$. More realistic point estimates for such cases are

$$\hat{\lambda} = \frac{\chi_{0.50}^2(2N+1)}{2T} \quad (C-6)$$

and

$$\hat{\lambda} = \frac{\chi_{0.50}^2(2N+1)}{2D} \quad (C-7)$$

then

$$\hat{\lambda} = \frac{(2N+1)F_M}{2D - 2N + 1 + (2N+1)F_M} \quad (C-8)$$

where

$$F_M = F_{0.50}(2N + 1, 2D - 2N + 1)$$

and the F and χ^2 distribution percentile and degree of freedom notations are as defined above.

Equation (C-6) applies for hourly rates, while Equation (C-7) is used with the upper bound from Equation (C-4) and Equation (C-8) is used with

Equation (C-5). Equations (C-6) and (C-7) are applicable to faults occurring according to a Poisson distribution regardless of the number of faults observed. A similar comment applies to Equation (C-8) and the binomial distribution. Typical estimates from Equation (C-6) are in the following table for comparison with Equation (C-1). Equation (C-6) has been used in other fault data studies, such as Reference C-2.

N	$\hat{\lambda}$
30	30.15/T
20	20.15/T
10	10.15/T
5	5.15/T
2	2.18/T
1	1.19/T
0	0.23/T

The estimates of Equations (C-6) through (C-8) can be obtained in two ways. The first is to consider shrinking the confidence intervals of Equations (C-3), (C-4), and (C-5) to the case where $\alpha = 1.00$ and both $\alpha/2$ and $1-\alpha/2$ are 0.5. Because of the differing degrees of freedom, the intervals do not shrink to a single point. The equations use an average for the differing degrees of freedom. Because the estimates use 50th percentiles, they are related to medians.

The second way of considering Equations (C-6) through (C-8) uses the medians directly. In a Bayesian context, λ is regarded as a random variable. With Poisson sampling and a noninformative conjugate prior distribution, the posterior distribution for the occurrence rate has a gamma distribution with parameters^{C-3}

$$(\alpha, \beta) = (N + 1/2, 1/T). \quad (C-9)$$

Because the gamma distribution with parameters $(N, 2)$ is identical to the chi-square distribution with $2N$ degrees of freedom,^{C-4} Equation (C-6) can be shown to be the median of the distribution described by Equation (C-9). Using a similar relation between beta and F distributions, Equation (C-8) can be derived as the median of the posterior fault rate distribution obtained in sampling from a binomial distribution with a noninformative conjugate prior distribution.

In summary, Equations (C-6), (C-7), and (C-8) describe median point estimates for the fault rate. They can be used when $N=0$, and are more conservative in that case than the point estimates given in Equations (C-1) and (C-2). In this work, they are used with, respectively, the upper confidence limits in Equations (C-3), (C-4), and (C-5) whenever no faults are observed.

In estimating the above confidence limits, all components in the sample were assumed to have exactly the same true fault rate. No effort was made to account for possible variations arising from the mixture of populations having different true fault rates. For further discussion of the assumptions and limitations of these confidence limits, see References C-1 and C-5.

References

- C-1. L. J. Bain, *Statistical Analysis of Reliability and Life-Testing Models*, New York: Marcel Dekker, Inc., 1978, p. 157.
- C-2. *NPRDS 1978 Annual Reports of Cumulative System and Component Reliability*, NUREG/CR-0942, Southwest Research Institute, September, 1979.
- C-3. G. E. P. Box and G. C. Tiao, *Bayesian Inference in Statistical Analysis*, Addison-Wesley, Reading, MA, 1973.
- C-4. N. R. Mann, R. E. Shafer, and N. D. Singpurwalla, *Methods for Statistical Analysis of Reliability and Life Data*, New York: John Wiley and Sons, Inc., 1974.
- C-5. N. L. Johnson and S. Kotz, *Discrete Distributions*, New York: John Wiley and Sons, Inc., 1969, pp. 58-59 and 96.

APPENDIX D
INVERTER ONE-LINE DESCRIPTIONS
SORTED BY NSSS VENDOR

CODES USED IN LER ONE-LINE DESCRIPTIONS

<u>FAULT MODE</u>	
<u>CODE</u>	<u>DESCRIPTION</u>
A	REDUCED CAPABILITY
B	INOPERABLE

<u>SYSTEM</u>	
<u>CODE</u>	<u>DESCRIPTION</u>
A	AUTOMATIC DEPRESSURIZATION SYSTEM (ADS)
B	CONTAINMENT (INCLUDES ISOLATION CONTROL)
C	ESSENTIAL AC ELECTRICAL DISTRIBUTION
D	HIGH PRESSURE COOLANT INJECTION (HPCI)
E	LOW PRESSURE COOLANT INJECTION (LPCI)
F	REACTOR CORE ISOLATION COOLING (RCIC)
G	UNKNOWN

<u>TYPE OF EVENT</u>	
<u>CODE</u>	<u>DESCRIPTION</u>
B	RECURRING COMMON CAUSE FAILURE
C	COMMON CAUSE FAILURE
D	RECURRING FAILURE
E	COMMAND FAULT
F	RECURRING COMMAND FAULT
G	COMMON CAUSE COMMAND FAULT
H	RECURRING COMMON CAUSE COMMAND FAULT
BLANK	RANDOM FAILURE

<u>FAULT CAUSE</u>	
<u>CODE</u>	<u>DESCRIPTION</u>
00	UNKNOWN
01	PERSONNEL OPERATION
02	PERSONNEL MAINTENANCE
03	PERSONNEL TESTING
04	DESIGN ERROR
05	FABRICATION/CONSTRUCTION/QUALITY CONTROL
06	DEFECTIVE PROCEDURES
07	EXTREME ENVIRONMENT
08	ELECTRICAL MALFUNCTION
09	MECHANICAL MALFUNCTION

<u>SUBCOMPONENT</u>	
<u>CODE</u>	<u>DESCRIPTION</u>
AC	ANNUNCIATOR CONTROL CARD
CC	FIRING CIRCUIT
CF	COOLING FAN
CH	CHOKE
CCM	CONTROL CARD/CONTROL MODULE
CD	CAPACITOR
DB	DRIVER BOARD
DI	DIODE
FB	FREQUENCY BOARD
FUSE	FUSE
IND	INDUCTOR
OSC	OSCILLATOR
PC	PROTECTION CARD
PS	POWER SUPPLY (INTERNAL)
R	RECTIFIER
REL	RELAY
RES	RESISTOR
SW	SWITCH
TR	TRANSFORMER
TS	TRANSISTOR
UV	UNDERVOLTAGE COIL
VR	VOLTAGE REGULATOR
UU	UNKNOWN/NOT APPLICABLE

<u>ACTIVITY RESULTING IN DISCOVERY</u>	
<u>CODE</u>	<u>DESCRIPTION</u>
M	MAINTENANCE
N	NORMAL PLANT OPERATION
R	RECORDS REVIEW
T	TESTING
U	UNKNOWN

<u>MSSS VENDOR</u>	
<u>CODE</u>	<u>DESCRIPTION</u>
B	BABCOCK & WILCOX
C	COMBUSTION ENGINEERING
W	WESTINGHOUSE
G	GENERAL ELECTRIC

<u>COMPONENT</u>	
<u>CODE</u>	<u>DESCRIPTION</u>
SI	STATIC INVERTER

<u>EVENT CLASSIFICATION</u>	
<u>CODE</u>	<u>DESCRIPTION</u>
D	FREQUENCY
T	AGE
U	UNKNOWN

 INVERTER ONE-LINE DESCRIPTIONS SORTED BY N555 VENDOR

UNION	PLANT	CONTROL OR NSIC NUMBER	EVENT DATE	MODE	STATUS	SYSTEM	MODE	CAUSE	ACTIVITY	TYPE	CLASS	FAULT	MODE DESCRIPTION	CAUSE DESCRIPTION
B	CR3	017321	030277	SI	DI	E	B	B	N	T			"B" INVERTER FAILED, CAUSED RX TRIP	OUTPUT DIODE FAILED
B	CR3	019021	090277	SI	RC	E	B	B	N	D			"D" INVERTER FAILED	SILICON CONTROLLED RECTIFIER DEFECTIVE
B	CR3	019523	102677	SI	UU	E	B	B	N	U			"A" INVERTER FAILED	NO CAUSE GIVEN
B	CR3	021210	042578	SI	UU	E	A	0	N	U	D		INVERTER 3A TRIPPING--WRONG FUSES INSTLD IN VITAL/	BUS 3A DURING CONSTRUCTION/TESTING PHASE
B	CR3	022361	081978	SI	UU	E	B	B	N	B	D		INVERTER VBIT-1A FAILED-120VAC VITAL BUS 3A NO PWR	ELECTRONIC COMPONENT FAILRS W/ IN VBIT-1A
B	CR3	037006	041181	SI	DI	E	B	0	N	R	T		INVERTER "D" FAILED. INADQ VENT CAUSED OVERHTG //	SHORTED DIODE & BLEW FUSE
B	CR3	038100	071481	SI	FS	E	B	0	M	C	D		"A" INVERTER FAILED DEENRGZD 120 AC VITAL BUS #3A	INADV SHORTED STAT BATT DURING MAINTENANC
B	DB1	027478	110579	SI	RS	E	B	0	N	D			BLOWN FUSE ON INVERTER YV2 OUTPUT	OPEN RESISTOR IN LOGIC PS OF INVERTER YV2
B	DB1	032367A	082280	SI	FS	E	B	0	N	B	D		FAILURE OF YV-2 INVERTER INPUT FUSE	EXACT CAUSE OF FUSE FAILURE UNDETERMINED
B	DB1	032367B	082380	SI	FS	E	B	0	N	B	D		FAILURE OF YV-2 INVERTER INPUT FUSE	EXACT CAUSE OF FUSE FAILURE UNDETERMINED
B	DB1	033270	111280	SI	FS	E	B	0	T	C	D		GROUNDED YV2 INVERTER INPUT FUSE TOOK OUT Y2 BUS	GROUNDDED OSCILLOSCOPE USED BY I&C PERSONL
B	DB1	039149	101881	SI	DI	E	B	0	N	T			ESSENTIAL 120VAC INVERTER YV3 FAILED	RESISTOR/DIODE ON +15VDC LOGIC PS FAILED
B	DB1	173542	040982	SI	FS	E	B	0	N	C	D		OUTPUT FROM YV2 INVERTER TO Y2 BUS WAS LOST	FUSE BLEW DUE TO PERSONNEL MAINTENANCE
B	DB1	175395	060882	SI	RC	E	B	0	N	C	T		ESSENTIAL INVERTER YV2 FAILED	COMP FAILR W/ IN REGULATED RECTIFIER YRF2
B	DE1	036123	011881	SI	FS	E	B	0	N	D			IDID VITAL INVERTER DC INPUT FUSE BLEW	POOR CNMCTN &/OR COMP PRBLMS IN LOGIC CRD
B	DE1	036241A	012581	SI	FS	E	B	0	N	D			IDID VITAL INVERTER DC INPUT FUSE BLEW	BLOWN FUSES
B	DE1	036241B	012581	SI	UU	E	B	0	N	U			IDIB INVERTER TRIPPED	EXACT CAUSE UNKNOWN
B	DE1	036241C	012581	SI	UU	E	B	0	M	U	D		IDID INVERTER TRIPPED	PERS OPENED AC OUTPUT BRKR MISTAKENLY
B	DE3	016137	091276	SI	CP	E	B	0	N	T			THE 3 DIB VITAL BUS INVERTER FAILED	DIELECTRIC OF INPUT FILTER CAP BROKE DOWN
B	DE3	027697	111079	SI	FS	E	B	0	N	D			ICS POWER LOST DUE TO INVERTER(KI) FAILED	BLOW FUSES
B	DE3	031182A	050780	SI	FS	E	B	0	N	R	D		LOST AC VITAL INST BUS DUE TO INVERTER FAILURE	BLOWN FUSES
B	DE3	031182B	050980	SI	FS	E	B	0	N	R	D		LOST AC VITAL INST BUS DUE TO INVERTER FAILURE	BLOWN FUSES/FAULTY TRANSISTOR
B	DE3	031182C	051680	SI	TS	E	B	0	N	D			INVERTER 3DIB TRIPPED WHEN POWER WAS TRANSFERRED /	/TO IT. BYPASS SWITCH POSSIBLY CLOSED.
B	RS1	026111	042279	SI	UV	E	B	0	U	R	D		S1A VITAL POWER INVERTER FAILED	DESIGN DEFICIENCY IN U-V ₀ COIL
B	T12	021952	032978	SI	CL	E	B	0	N	T			VITAL BUS INVERTER FAILD TO FUNCTN PROPERLY	FAULTY INVERTER CNTRL MODULE AND FUSE
C	CC1	179674	110982	SI	UU	E	B	0	M	U	D		RX S/D DUE TO INVERTER DC FEEDER BREAKER TRIP	CONTRACTOR INADV TRPD OPEN INPUT BREAKER
C	CC2	017009	010677	SI	FS	E	B	0	N	T	D		B PHASE COMPUTER INVERTER DC INPUT FUSE OPENED	CURRENT SURGE DUE TO SWITCHING OPERATION
C	CC2	183012	122882	SI	FS	E	B	0	N	U			#22 INVERTER OUTPUT FUSE BLEW	SUSPECTED CAUSE--IMPROPER FUSE TYPE USED
C	FC1	020085	122577	SI	VR	E	B	0	N	T			D CHANNEL INSTRUMENT INVERTER FAILED	CONSTANT VOLTAGE REGULATOR FAILED
C	M12	026871	010579	SI	CP	E	B	0	N	T			INVERTER NO. 4 FAILED	CAPACITORS AND OSCILLATOR BOARD FAILED

INVERTER ONE-LINE DESCRIPTIONS SORTED BY NSSS VENDOR

PLANT	CONTROL OR NSIC NUMBER	EVENT DATE	COMP	SCHEMATIC	MODE	CAUSE	CLASS	FAULT #	MODE DESCRIPTION	CAUSE DESCRIPTION
C MI2	172670*	010682	SI	FS	E	B02	N	C D 2	FUSES IN INVERTERS 2 AND 6 BLEW	SHORTED TEST LEAD FAILED CIRCUIT
C MI2	175402*	060682	SI	FS	E	B07	N	C D 2	LOSS OF 120VAC (VIAC-1) BLOWS FUSES IN ESFAS CABNT	ROOF LEAK SHORTED 2 INVERTERS #5,6
C SL1	015004	052976	SI	DS	E	B08	N	T	1C STATIC INVERTER FAILED(PS FOR AC INST,120 VOLT)	FAILED OSCILLATOR CIRCUIT BOARD
C SL1	175209A	062282	SI	UU	E	B00	N	R U	OUTPUT BRKR OF 1A STATYC INVERTER OPENED	NO APPARENT CAUSE COULD BE FOUND
C SL1	175209B	062382	SI	DS	E	B08	N	R U	1A STATIC INVERTER OUTPUT BREAKER OPENED	OSCILLATOR CIPCUIT BOARD REPLACED
C SL1	181486	122082	SI	UU	E	B00	N	R U	1A INVERTER OUTPUT BRK OPENED;1/4 120VAC BUS LOST	NO APPARENT CAUSE OF FAILURE
C SL1	181729	122582	SI	FB	E	B00	N	R U	1A INVERTER OUTPUT BRK OPENED;1/4 120VAC BUS LOST	DEFECTIVE OUTPUT FREQUENCY MODULE
C SL1	181038	123082	SI	DS	E	B08	M	T	1A INVERTER OUTPUT BRK OPENED;1/4 120VAC BUS LOST	FREQUENCY OSCILLATOR HAD DRIFTED
W BV1	014692	051076	SI	CP	E	B08	N	R T	INVERTER NO. 3 FAILED	OUTPUT FILTER CAPACITOR FAILED
W BV1	015102	052776	SI	CP	E	B03	N	R T	INVERTER NO. 1 FAILED	OUTPUT FILTER CAPACITOR FAILED
W BV1	015213	062376	SI	UU	E	B00	U	U	INVERTER NO. 3 APPARENTLY FAILED	NO CAUSE GIVEN
W BV1	016280	102276	SI	RC	E	B08	N	R T	VITAL BUS INVERTER NO. 3 FAILED	SCRS AND OUTPUT FUSE FOUND BAD
W BV1	016360	110676	SI	UU	E	B03	N	U D	INVERTER NO. 2 WAS MOMENTARILY OUT OF SERVICE	OUTPUT WAS SHORTED OUT BY PERSONNEL
W BV1	017014	121576	SI	DI	E	B08	N	R T	NO. 1 VITAL BUS INVERTER FAILED	1 DIODE AND TWO FUSES FOUND FAILED
W BV1	023209	010278	SI	UU	E	A00	N	U	OUTPUT FREQUENCY OF NO. 4 INVERTER OSCILLATING	NO CAUSE GIVEN
W BV1	025332	012079	SI	UU	E	B00	N	U	NO. 3 VITAL BUS INVERTER FAILED	FAULTY COMPONENTS
W BV1	027140	091879	SI	DS	E	A08	N	T	NO. 4 VITAL BUS INVERTER FREQUENCY FOUND SPIKING	FAULTY OSCILLATOR CARD
W BV1	028012	092079	SI	UU	E	B00	N	U	NO. 4 VITAL BUS INVERTER FAILED. RX TRIP OCCURRED //	AND SAFETY INJECTION OCCURRED. NO CAUSE
W BV1	031239	050480	SI	FS	E	B08	N	R D	PWR LOST TO #4 VITAL BUS INVERTER DUE TO BLOWN //	MAIN PS FUSE. CAUSE UNKNKNW
W BV1	173454	041482	SI	UU	E	B02	N	U D	NO. 3 INVERTER TRIPPED	PERSONNEL MAINTENANCE
W DC1	017804	042177	SI	FS	E	B08	N	D	#4 INVERTER FAILED, CAUSED RX TRIP & SI	BLOWN FUSE
W DC1	025643*	032379	SI	UU	E	B01	N	C D 2	TWO VITAL BUS INVERTERS FAILED SIMULTANEOUSLY	PARTS FAILED DUE TO DC SURGE. PERSONNEL
W DC1	032503	083180	SI	DI	E	B08	N	R T	SHORTED DIODE IN CRID IV INVERTER	DIODE FAILED DUE TO NORMAL END OF LIFE
W DC1	182697	082382	SI	UU	E	B08	N	D	AB EMERG DIESEL GENERATOR INVERTER FAILED. SOLID	STATE COMP, XFMR GATE, SHORTING BRD RPLCD
W DC2	022280	061378	SI	DI	E	B08	N	C T	INVERTER FAILURE	DEFECTIVE DIODES AND SCR'S
W DC2	037613	061281	SI	CP	E	B08	N	B T	FAILURE IN 120VAC VITAL BUS (CRID II)	C-2 CAPACITOR FAILED ALSO BLEW A FUSE
W HN1	018775	071977	SI	UU	E	B07	N	C T	STATIC INVERTER FAILED	AMBIENT TEMP 40 DEG C. ABOVE DESIGN
W IP2	022867	102278	SI	UU	C	B00	N	U	4.5KVA STATIC INVERTER FAILD DEFNRGZG CONT PRESS //	SAFEGUARDS LOGIC. DEFECTIVE INVERTER
W JF1	021597	022178	SI	UU	E	B00	N	U	120V VITAL BUS A DEENRGZD WHEN INVERTER A TRIPPED	EXACT CAUSE NOT IDENTIFIED
W JF1	021592	022378	SI	CP	E	B08	N	R D	120VAC VITAL BUS B DEENRGZD WHEN INVERTER 1B TRPD	FAULTY CAPACITOR WAS REPLACED

INVERTER ONE-LINE DESCRIPTIONS SORTED BY NSSS VENDOR

PLANT	CONTROL OR NSIC NUMBER	EVENT DATE	COMP	STATUS	MODE	CAUSE	FAULT #	MODE DESCRIPTION	CAUSE DESCRIPTION
W JF1	021594	050978	SI UU	E 800 N	U			120VAC VITAL BUS A DEENRGZD WHEN INVERTER A TRPD	EXACT CAUSE NOT IDENTIFIED
W JF1	021591	053078	SI CP	E 808 N R	D			120VAC BUS D DEENRGZD WHEN INVERTER 1D TRIPPED	CAPACITOR IN INVERTER FAILED
W JF1	025439	011679	SI CH	E 808 N	T			1B INVERTER TRIPPED (PS FOR 120V VITAL AC)	VARIOUS INTERNAL COMPONENTS FAILED
W JF2	038879	092381	SI UU	E 800 M	U			INVERTER 2A TRPD--120VAC VITAL BUS 2A DEENERGIZED	TRANSIENT VOLTAGE SPIKE--CAUSE UNKNOWN
W JF2	173252	031682	SI FS	E 808 N	D			INVERTER NO. 28 FAILED	FUSE BLEW IN VOLTAGE REGULATOR
W JF2	176547	072282	SI UU	E 800 N	U			INVERTER NO. 26 FAILED CAUSING LOSS OF POWER TO S/	/UB COOLING MONITOR AND HZ MONITOR
W MG1	174673	061382	SI RC	E 808 N	D			INVERTER EVIA INOP--LOST VITAL INST PWR CAUSD RX//	TRIPS. SCR SHORTING CKT BRD REPLACED
W MG1	174671	062482	SI CP	E 808 N	T			STATIC INVERTER EVIA HALFUNC--RHR ISOL VLV CLOSED	3 CAP IN OUTPUT CVT CAP BANK FAILED
W NA1	031217	052380	SI FS	E 808 N	D			LOST VITAL BUS 1-III. CAUSE UNKNOWN--POSSIBLY //	VLTG SURGE TO DC/AC INVERTER BLEW 2 FUSES
W NA1	032608	090880	SI UU	E 800 N	U			LOST PWR TO 120VAC VITAL BUS 1-IV	INVERTER SUPPLY BRKR FOUND OPEN
W NA2	037674*	060381	SI UU	E 800 N C	U 2			VOLTAGE TRANSIENT THRU VITAL BUS INVERTERS 2-III//	& 2-IV. CAUSE UNKNOWN
W PR1	015104	061576	SI TR	E 808 N R	T			NO. 13 INVERTER FAILED (PS TO INSTRUMENT BUS 113)	REGULATING TRANSFORMER ON OUTPUT FAILED
W PR1	017425	031477	SI CP	E 808 N R	T			NO. 11 INVERTER FAILED	CAP ON OUTPUT SOLA TRANSFORMER FAILED
W PR2	032962	100480	SI TR	E 808 N	T			#23 INVERTER FAILED DEENRGZG PANEL 213	CONSTANT VOLTAGE TRANSFORMER FAILED
W SA1	022426	082178	SI DI	E 808 N	T			VITAL INST BUS INVERTER 1A FUSES BLOWN	FAILED DIODE IN CNTRL CKT BRD
W SA1	022420	082778	SI CL	E 808 N R	T			1A INVERTER FAILD--FAILD ELECTRONIC COMP ON MASTER	//LOGIC CKT BRD CAUSD BLOWN FUSES
W SA1	023232	112778	SI TR	E 808 N R	T			LOST 1B VITAL INSTRUMENT BUS	OUTPUT XFRMR IN SUPPLY INVERTER FAILED
W SA1	023230	120878	SI UU	E 800 N	U			INVERTER DIDN'T SWITCH TO B/U BATTERY SUPPLY	NO CAUSE COULD BE DETERMINED
W SA1	023513	012679	SI UU	E 800 N	U			1B VITAL INSTRUMENT BUS INVERTER FAILED	NO CAUSE. INADVERTANT SI OCCURRED
W SA1	027523	110579	SI CF	P 809 N	T			LOST METEOROLOGICAL INSTR/PWR SUP INVERTER FAILED	SEIZED MOTOR BEARINGS IN COOLING FAN
W SA1	030231	012380	SI SW	P 805 N B	D			LOST METEOROLOGICAL INSTRUMENT	INVERTER HAD MAN NOT AUTO SW--MFG ERROR
W SA1	039242	102981	SI UU	E 800 N	U			INADV SI DUE TO LOSS OF VITAL BUS 1A INVERTER	CAUSE UNKNOWN
W SA1	039344	110681	SI UU	E 800 N	U			INADV SI DUE TO LOSS OF 1A VITAL INST BUS INVERTER	CAUSE UNKNOWN
W SA2	181466	112982	SI PS	E 808 N	D			INVERTER PS FAILED CAUSD P-250 COMPUTER TO SHUTDOWN	PS PROBLEM FROM FAILED OSCILLATOR CKT BRD
W SE1	032879A	092780	SI UU	E 800 N	U			VITAL INVERTER 2-IV OUTPUT BRKR TRIPPED	CAUSE NOT IDENTIFIED
W SE1	032879B	100180	SI SW	E 808 N	T			VITAL INVERTER 2-IV OUTPUT BRKR TRIPPED	BAD AUX SW ON THE K11 RELAY
W SE1	032977	101480	SI CC	E 808 N	T			VITAL INVERTER 2-III OUTPUT BRKR TRIPPED	FIRING CKT CLOCK CARD RBS FAILED
W SE1	033295	111180	SI FS	E 808 N	D			VITAL INVERTER 1-I OUTPUT BRKR TRIPPED	INVERTER 1-I OUTPUT FUSES HAD BLOWN
W SE1	033296*	111880	SI UU	E 800 N R	U 9			9 VITAL INVERTER 2-III FAILURES BETWEEN 11-9-80G//	11-23-80. NO CAUSES GIVEN
W SE1	036667	013081	SI UU	E 802 M	U D			CONDUIT/CABLE SUPPLYING PWR TO VITAL INVERTER 1-IV	/WAS CUT. CONSTRUCTION PERSONNEL ERROR

INVERTER ONE-LINE DESCRIPTIONS SORTED BY N555 VENDOR

PLANT	CONTROL OR N555 NUMBER	EVENT DATE	CONTR	STATUS	MODE	CAUSE	TYPE	CLASS	FAULT #	MODE DESCRIPTION	CAUSE DESCRIPTION	
W S01	019998	082376	SI	PS	E	800	N	U		VITAL BUS #1 TRANSFERRED TO B/U POWER SOURCE	COMPONENT FAILURE IN #1 INVERTER. NO CAUSE	
W S01	018440	061477	SI	CP	E	808	N	T		DC INPUT FUSE OF UPS INVERTER OPENED	CAPACITORS IN BANKS C-4, C-6 HAD FAILED	
W S01	020878A	031578	SI	CP	C	808	N	T		"A" INVERTER FAILED (ONE OF TWO FOR CSAS LOGIC)	CAPACITOR AND CHOKE IN OUTPUT SIDE FAILED	
W S01	020878B	031578	SI	UU	C	804	N	U	D	"B" INVERTER FOR CSAS TRIPPED ON TRANSFER	TRANSFER SWITCH WAS TOO FAST	
W S01	021743	060778	SI	CP	P	808	N	D		DC INPUT FUSE FOR MOV-850C INVERTER OPENED	GE CAPACITOR 28F5108 AND SCR-2 FAILED	
W SU2	179196	101082	SI	IN	E	808	N	T		FAILED VITAL BUS-3 INVERTER/TURB RUNBACK, RX, TRP, SI	STATION BATT INVERTER INDUCTOR SHORTED	
W TR1	033305	111280	SI	UU	E	800	T	U		3 VITAL PREFERRED INSTR BUSES ON SAME EMERG TRAIN	#4 INVERTER APPARENTLY FAILED--NO CAUSE	
W TR1	039071	100481	SI	RE	E	808	N	T		LOST PREFERRED INST BUS Y11--STATIC INVERTER OUTPT	//CURRENT SENS RELAY FAILED. NAT'L EOL	
W TR1	172719	011682	SI	UU	E	800	N	R	U	INVERTER NO. 2 FAILED. CAUSED INADVERTANT SI	NO CAUSE GIVEN.	
W ZI1	025150	011279	SI	UU	E	800	N	U	U	INV 114 TRPD. FOUND 2.5KVA INV SECTION FAULTY.	LOOSE CONTACT IN DC BREAKER	
W ZI1	026916	081379	SI	TR	E	808	N	T		INSTRUMENT INVERTER 114 TRIPPED	5KVA TRANSFORMER REPLACED	
W ZI1	037631	052881	SI	TR	E	808	N	R	D	INST INVERTER 114 FAILED	XFRMR SHORTED BY HI INVERTER CIRC CURRENT	
W ZI2	020356	082077	SI	TR	E	808	N	D		INVERTER NO. 213 FAILED (INSTRUMENT INVERTER)	SLAVE TRANSFORMER FAILED BY OVERHEATING	
W ZI2	031066	041180	SI	RC	E	808	N	T		INSTRUMENT INVERTER 214 FAILED	SCR FAILED IN SLAVE UNIT OF INVERTER	
W ZI2	037995	050781	SI	TR	E	808	N	D		LOST POWER TO INVERTER 213	XFRMR SHORTD BY HI INVERTER CIRC CURRENT	
G BF1	038008	070481	SI	CL	P	808	T	R	T	ALARM PANEL XA-55-8E INVERTER INOPERABLE	FAILED INVERTER CONTROL CARD	
G BF3	027049	091579	SI	AC	P	808	N	T		ANNUNC PANEL XA-55-208 INOP INVERTER PRINTED CKT//	CARD FAILED DUE TO NATURAL AGING	
G BP1	022658	091078	SI	FS	C	804	N	R	D	BLOWN FUSE IN POWER SUPPLY INVERTER	XIENT SUP VLTG PROBLEM--NEEDS DUMMY LOAD	
G BP1	025806	031979	SI	FS	C	804	N	D		CONTAINMENT VACUUM RELIEF LOOP POWER SUPPLY INVER/	/TER FOUND INOPERABLE. BLOWN PS FUSE	
G BP1	026880	061679	SI	FS	C	804	N	R	D	CNTNMHT VACUUM RELIEF PS INVERTER FUSE RLEW	SUSCEPTIBLE TO INPUT SURGE	
G BP1	037801A	061781	SI	PS	A	808	M	R	T	RX DEPRESSURIZATION LOOP B INVERTER FOUND INOP.	DEFECTIVE ELECTRONIC COMPONENTS	
G BP1	037801B	062381	SI	PS	A	808	M	R	T	RX DEPRESSURIZATION LOOP B INVERTER FOUND INOP.	DEFECTIVE ELECTRONIC COMPONENTS	
G BR1	017085*	011777	SI	UU	E	802	M	U	D	2	CNTRL VLTG PS SET BELOW EQUALZG VLTG CAUSED TRIP	I&C TECH ERROR IN EQUALZG PLANT BATTERIES
G BR2	030364	020480	SI	UU	Q	800	N	U		STM LEAK DETCTN "A" LOGIC INVERTER'S HV TRPD LOW	NO CAUSE GIVEN	
G CO1	037646	050581	SI	CP	E	806	T	D		STATIC INVERTER 1A'S SPIKE SUPPRESSOR CAP FAILED	AGED ELECTROLYTIC CAP/IMPROPR DP PROCEDUR	
G EN1	016840	112776	SI	CP	Q	808	N	T		RCIC PS INVERTER E51-K603 FAILED	SHORTED CAPACITOR IN OUTPLT TRANSFORMER	
G EN1	033842	073180	SI	UU	L	807	N	U	T	B LPCI INVERTER TRPD THUS B LOOP OF RHR INOPERABLE	HI AMBIENT TEMPERATURE IN INVERTER ROOM	
G EN1	032376	082180	SI	UU	L	807	N	R	T	"B" LPCI INVERTER TRIPPED	HI AMBIENT TEMPERATURE IN INVERTER ROOM	
G EN1	037947A	061081	SI	SW	L	800	N	R	U	B LPCI INVERTER R44-5003 TRPD ON HIGH TEMPERATURE	DEFECTIVE SWITCH IN INVERTER LEG	
G EN1	037947D	061681	SI	UU	L	800	N	R	U	2	B LIPCI INVERTER 2R44-5003 TRIPPED	UNKNOWN CAUSE

INVERTER ONE-LINE DESCRIPTIONS SORTED BY MSSS VENDOR

PLANT	CONTROL	EVENT	DATE	SYMBOL	STATUS	ACILITY	CAUSE DESCRIPTION	MODE DESCRIPTION	CAUSE DESCRIPTION
G EN1	0379478	061888	SI	SW L	800	M R U Z	B LPCI INVERTER R44-5003 TRIPPED		DFTV SWITCHES IN INVERTER LEGS
G EN1	037947C	062181	SI	SW L	800	M R U	B LPCI INVERTER R44-5003 TRIPPED		DEFECTIVE SWITCH IN INVERTER LEG
G EN1	177682	091182	SI	CP L	808	M D	"A" LPCI INVERTER FAILED. OUTPUT FILTER CAPACITOR/		/R INSULATION SPAT, FAILED FUSES & CAP'S
G EN2	022024	071778	SI	FB L	808	N T	STATIC INVERTER(2R44-5002) OUTPUT BREAKER TRIPPED		FREQUENCY CARBIDE PART #A13A9) FAILED
G EN2	023200	120878	SI	PC L	808	N T	STATIC INVERTER (2R44-5003) DC OUTPUT BRKR TRIPPED		AC/DC PROTECTION CARD(A13A12) FAILED
G EN2	027611	111779	SI	RE L	808	N T	"B" LPCI INVERTER TRIPPED		FAILED RELAY IN INVERTER FAILED
G EN2	027848A	121979	SI	FS Q	808	N C D	"A" PS FOR RCIC STEAM LEAK DETECTION FAILED		FUSES BLEW DUE TO CURRENT SURGE
G EN2	027848B	122079	SI	FS Q	808	N C D	"B" PS FOR RCIC STEAM LEAK DETECTION FAILED		FUSES BLEW DUE TO CURRENT SURGE
G EN2	030041	011780	SI	UU H	808	N T	HPCI AUTO FLO CNTRL PWR INVERTER'S HV TRPD LOW		INSTRUMENT DRIFT
G EN2	030241	020280	SI	CP Q	808	T T	RCIC REMOTE FLD CNTRL LOOP POWER INVERTER TRIPPED		DFTV INPUT FILTER CAPACITORS
G EN2	030980	042480	SI	UU Q	800	M R U	REC'D RCIC LEAK DETECTION LOGIC PWR FAILURE ALARM		COMPONENT FAILURE OF INVERTER
G EN2	036952	042181	SI	CL L	808	N U	"A" LPCI INVERTER 2R44-5002 TRPD		LOGIC FAILURE CAUSED TRIP
G EN2	038501	090481	SI	VR L	808	N T	B LPCI INVERTER 2R44-5003 TRPD		GATE FIRING MODULE VOLTAGE REGULATOR FAIL
G EN2	171785	112681	SI	CC L	808	M T	B LPCI INVERTER (2R44-5003) TRPD DUE TO LEG FAN FAILURE		LEAD TO WIRE WOUND RESISTOR TOUCHED RSTR
G EN2	178916	100182	SI	CF L	809	M T	INVERTER(2R44-5003) TRPD DUE TO LEG FAN FAILURE		#4 INVERTER LEG FAN BEARING FAILED
G FPI	013966	010376	SI	RS Q	808	N D	RCIC STATIC INVERTER(12-801A) FAILED		
G FPI	015625	081576	SI	UU H	800	N U	HPCI INVERTER 23-INV-79 TRIPPED AND WOULD NOT RES/		START. NO CAUSE FOUND, INVERTER REPLACED
G FPI	021432	051878	SI	RC L	808	N T	LPCI INVERTER/CHARGER TRPD LOST B LPCI INDPNDNT //		PWR. FAILED SCR'S IN INVERTER/CHARGER
G FPI	030177	012380	SI	CP L	808	N U	LPCI INDPNDNT PS "A" INVERTER TRIPPED		INVERTER CNTRL CKT CAPACITORS FAILED
G FPI	032373A	081280	SI	CL L	808	N T	"B" LPCI INVERTER TRIPPED		AC VOLTAGE/CURRENT CNTRL LOGIC CARD A12
G FPI	032373B	082280	SI	CL L	808	N T	"B" LPCI INVERTER TRIPPED		INVERTER LEG GATE FIRE CNTRL CKT FAILED
G FPI	032373C	090580	SI	AC L	808	N T	"B" LPCI INVERTER TRIPPED		ANNUNCIATOR/CONTROL CARD 2 FAILED
G FPI	032373D	090680	SI	AC L	808	N T	"B" LPCI INVERTER TRIPPED		ANNUNCIATOR/CONTROL CARD 2 FAILED
G FPI	032718	091380	SI	CL L	808	N T	"B" LPCI INVERTER TRIPPED		LOGIC CARD A2 FAILED
G FPI	037379	051581	SI	CP L	808	N R D	LPCI MOV INDEPENDENT POWER SUPPLY INVERTER A TRPD		SHORTED CAP IN GATE FIRING MODULE "A1A"
G FPI	181727	121582	SI	CL L	808	N D	"A" LPCI INVERTER TRIPPED DUE TO ELECTRICAL FAILURE		GATE TIMING CONTROL CARD FAILED
G PR2	017210	021977	SI	UU Q	800	N U	RCIC STATIC INVERTER 2-13-90 TRIPPED WITHOUT AUTO/		"A" MATIC RESET. NO CAUSE FOUND
G PR2	021247	041878	SI	TS Q	808	N T	INVERTER FAILD PWEPS RCIC'S CNTRLR & INSTRMNT		DFTV TRANSISTOR IN AUTO-RESET CIRCUIT
G PR2	021248	042478	SI	UU H	800	N U	HPCI STATIC INVERTER TRIPPED		NO FAULT COULD BE FOUND WITH THE INVERTER
G P11	038673	091281	SI	CP Q	808	N D	FAILED INVERTER CAUSED GROUND FAULT ON 125VDC SYS		FAILED CAP IN DC/AC INVERTER

INVERTER ONE-LINE DESCRIPTIONS SORTED BY MSSS VENDOR

PLANT	CONTROL OR INVERTER NUMBER	EVENT DATE	C O M P	C S O U M B P	S Y S T E M	C A T E G O R Y	A C T I V E	C L A S S I F I C A T I O N	MODE DESCRIPTION	CAUSE DESCRIPTION
G VY1	015519	081376	SI	SM	L	B04	N	D	A 250 KVA UPS OUTPUT BREAKER TRIPPED	NOISE IN AN UNUSED STATIC SWITCH
G VY1	015965	092076	SI	FS	L	B08	N	D	MOTOR CONTROL CENTER B9A LOST POWER DUE TO "A" UP / JS TRIPPED. BLOWN INVERTER LEG FUSE	
G VY1	016272	101976	SI	CL	L	B08	N	R	UPS-1B TRIPPED WHEN OPENING VALVE RHR-278	POSSIBLE LOGIC PROBLEM
G VY1	016485	111876	SI	VR	L	B08	N	R	UPS-1B TRIPPED WHILE TESTING RHR-278 VALVE	VOLTAGE REGULATOR AND SYSTEM LOGIC PROBLEM
G VY1	016500*	112976	SI	DB	L	B08	N	R	UPS-1A AND UPS-1B TRIPPED WHILE TESTING LPCI VALVE 1A HAD FAILED DRIVE BOARD-1B HAD BAD REG	
G VY1	021542	053078	SI	FS	L	B08	N	D	250KVA UNINTERRUPTIBLE PWR SUPPLY TRIPPED	BLOWN INVERTER LEG FUSE(2A16F2)
G VY1	021768	061978	SI	UU	L	B00	N	U	LOSS OF VLT6 TO MCC-898	UNINTERRUPTIBLE POWER SUPPLY(UPS-1B) TRPD
G VY1	021842	062978	SI	PC	L	B08	N	T	250KVA UPS TRPD DUE TO INVERTER LEG FUSE(2A19F21) BLEW WHEN GATE INTRFC/PRTCTN LOGIC MALFUN	
G VY1	032080	071880	SI	FS	L	B08	N	C	LOGIC PS BRD FAILED. 250KVA UNINTERRUPTIBLE PS // TRPD DUE TO BLOWN LOGIC PS FUSE	
G VY1	173401	020682	SI	CP	L	B08	N	T	UPS-B AC GROUND AND BLOWN FUSE ALARM HAS RECEIVED SUPPRESSION CAPACITOR FAILED BLOWING FUSE	
G VY1	172882	022382	SI	CP	L	B08	N	T	UPS "B" TRAIN TRIPPED	SHORTED CAPACITOR DUE TO AGE

APPENDIX E
INVERTER ONE-LINE DESCRIPTIONS
SORTED BY HUMAN FACTORS

CONTENTS

Personnel Operation	E-1
Personnel Maintenance	E-2
Personnel Testing	E-3
Design Error	E-4
Fabrication/Construction/Quality Control	E-5
Defective Procedures	E-6

CODES USED IN LER ONE-LINE DESCRIPTIONS

<u>FAULT MODE</u>		<u>FAULT CAUSE</u>		<u>ACTIVITY RESULTING IN DISCOVERY</u>	
<u>CODE</u>	<u>DESCRIPTION</u>	<u>CODE</u>	<u>DESCRIPTION</u>	<u>CODE</u>	<u>DESCRIPTION</u>
A	REDUCED CAPABILITY	00	UNKNOWN	M	MAINTENANCE
B	INOPERABLE	01	PERSONNEL OPERATION	N	NORMAL PLANT OPERATION
-----		02	PERSONNEL MAINTENANCE	R	RECORDS REVIEW
<u>SYSTEM</u>		03	PERSONNEL TESTING	Y	TESTING
<u>CODE</u>	<u>DESCRIPTION</u>	04	DESIGN ERROR	U	UNKNOWN
A	AUTOMATIC DEPRESSURIZATION SYSTEM (ADS)	05	COMMUNICATION/CONSTRUCTION/QUALITY CONTROL	-----	
C	CONTAINMENT (INCLUDES ISOLATION CONTROL)	06	DEFECTIVE PROCEDURES	<u>NSSS VENDOR</u>	
E	ESSENTIAL AC ELECTRICAL DISTRIBUTION	07	UNSATISFACTORY ENVIRONMENT	<u>CODE</u>	<u>DESCRIPTION</u>
H	HIGH PRESSURE COOLANT INJECTION (HPCI)	08	ELECTRICAL MALFUNCTION	B	BABCOCK & WILCOX
L	LOW PRESSURE COOLANT INJECTION (LPCI)	09	MECHANICAL MALFUNCTION	C	COMBUSTION ENGINEERING
R	REACTOR CORE ISOLATION COOLING (RCIC)			M	WESTINGHOUSE
U	UNKNOWN			G	GENERAL ELECTRIC
-----				-----	
<u>TYPE OF EVENT</u>		<u>SUBCOMPONENT</u>		<u>COMPONENT</u>	
<u>CODE</u>	<u>DESCRIPTION</u>	<u>CODE</u>	<u>DESCRIPTION</u>	<u>CODE</u>	<u>DESCRIPTION</u>
B	RECURRING COMMON CAUSE FAILURE	AC	ANNUNCIATOR CONTROL CARD	-----	
C	COMMON CAUSE FAILURE	CC	FIRING CIRCUIT	<u>EVENT CLASSIFICATION</u>	
U	RECURRING FAILURE	CF	COOLING FAN	<u>CODE</u>	<u>DESCRIPTION</u>
U	COMMAND FAULT	CH	CHOKER	SI	STATIC INVERTER
U	RECURRING COMMAND FAULT	CM	CONTROL CARD/CONTROL MODULE	-----	
U	COMMON CAUSE COMMAND FAULT	CP	CAPACITOR	D	FREQUENCY
U	RECURRING COMMON CAUSE COMMAND FAULT	DB	DRIVER BOARD	T	AGE
BLANK	RANDOM FAILURE	DI	DIODE	U	UNKNOWN
		FB	FREQUENCY BOARD		
		FU	FUSE		
		IN	INDUCTOR		
		OS	OSCILLATOR		
		PR	PROTECTION CARD		
		PS	POWER SUPPLY (INTERNAL)		
		RE	RECTIFIER		
		RE	RELAY		
		RS	RESISTOR		
		SW	SWITCH		
		TR	TRANSFORMER		
		TR	TRANSISTOR		
		UV	UNDERVOLTAGE COIL		
		VR	VOLTAGE REGULATOR		
		UU	UNKNOWN/NOT APPLICABLE		

PERSONNEL OPERATION

PLANT	CONTROL OR INSTRUMENT NUMBER	EVENT DATE	COMP	SUB	SYSTEM	MODE	CAUSE	TYPE	CLASS	FAO #
R 0E3	031182C	051680	SI	TS	E	BO1	N	D		
C CCL	179674	110982	SI	UU	E	BO1	M	U	D	
M DC1	029643*	032379	SI	UU	E	BO1	N	C	D	2

MODE DESCRIPTION	CAUSE DESCRIPTION
INVERTER 3DIB TRIPPED WHEN POWER WAS TRANSFERRED / 7TO IT. BYPASS SWITCH POSSIBLY CLOSED.	
RX S/D C/DIE TO INVERTER DC FEEDER BREAKER TRIP	CONTRACTOR INADY TRPD OPEN INPUT BREAKER
TWO VITAL BUS INVERTERS FAILED SIMULTANEOUSLY	PARTS FAILED DUE TO DC SURGE. PERSONNEL

PERSONNEL MAINTENANCE

N S S S	P L A N T	CONTROL OR NSIC NUMBER	EVENT DATE	C O M P	C O D E	S Y S T E M	M O D E	C A U S E	A C T I V E	T Y P E	C L A S S	F A U L T	MODE DESCRIPTION	CAUSE DESCRIPTION
B	CR3	038100	071481	SI	FS	E	802	H	C	D			"A" INVERTER FAILED DEENRGZD 120 AC VITAL BUS #3A	INADV SHORTED STAT BATT DURING MAINTENANC
B	DD1	033270	111280	SI	FS	E	802	T	C	D			GROUNDING YV2 INVERTER INPUT FUSE TOOK OUT Y2 BUS	GROUNDING OSCILLOSCOPE USED BY IEC PERSNL
B	DB1	173542	040982	SI	FS	E	802	N	C	D			OUTPUT FROM YV2 INVERTER TO Y2 BUS WAS LOST	FUSE BLEW DUE TO PERSONNEL MAINTENANCE
B	DE1	036241C	012581	SI	UU	E	802	H	U	D			IDID 1 INVERTER TRIPPED	PERS OPENED AC OUTPUT BRKR MISTAKENLY
C	M12	172670*	010682	SI	FS	E	802	N	C	D	Z		FUSES IN INVERTERS 2 AND 6 BLEW	SHORTED TEST LEAD FAILED CIRCUIT
W	BV1	173454	041482	SI	UU	E	802	N	U	D			NO. 3 INVERTER TRIPPED	PERSONNEL MAINTENANCE
W	SE1	036667	013081	SI	UU	E	802	H	U	D			CONDUIT/CABLE SUPPLYING PWR TO VITAL INVERTER 1-I/	/WAS CUT. CONSTRUCTION PERSONNEL ERROR
G	BRI	017085*	011777	SI	UU	E	802	H	U	D	Z		CNTRL VLTG PS SET BELOW EQUALZG VLTG CAUSED TRIP	I&C TECH ERROR IN EQUALZG PLANT BATTERIES

PERSONNEL TESTING

<u>ZONE</u>	<u>PLANT</u>	<u>CONTROL OR NSIC NUMBER</u>	<u>EVENT DATE</u>	<u>AREA</u>	<u>UNIT</u>	<u>DESCRIPTION</u>	<u>MODE DESCRIPTION</u>	<u>CAUSE DESCRIPTION</u>
W B V 1		016360	110676	\$I	UU	E B 03 H U D	INVERTER NO. 2 WAS MOMENTARILY OUT OF SERVICE	OUTPUT WAS SHORTED OUT BY PERSONNEL

DESIGN ERROR

<u>NU</u>	<u>P</u>	<u>CONTROL</u>	<u>EVENT</u>	<u>C</u>	<u>C</u>	<u>ACTIVITY</u>	<u>CLAS</u>	<u>FAUL</u>	<u>MODE DESCRIPTION</u>	<u>CAUSE DESCRIPTION</u>		
<u>US</u>	<u>L</u>	<u>OR</u>	<u>DATE</u>	<u>OMP</u>	<u>SUN</u>	<u>MODE</u>	<u>TYPE</u>	<u>TY</u>				
<u>NT</u>	<u>NSIC</u>	<u>NUMBER</u>										
B	RSI	026111	042279	SI	UV	E	804	U	R	D	S1A VITAL POWER INVERTER FAILED	DESIGN DEFICIENCY IN U.V. COIL
M	S01	020878B	031578	SI	UU	C	804	M	U	D	"B" INVERTER FOR CSAS TRIPPED ON TRANSFER	TRANSFER SWITCH WAS TOO FAST
G	BPI	022658	091078	SI	FS	C	804	N	R	D	BLOWN FUSE IN POWER SUPPLY INVERTER	XIENT SUP VLTG PROBLEM--NEEDS DUMMY LOAD
G	BPI	025806	031979	SI	FS	C	804	N		D	CONTAINMENT VACUUM RELIEF LOOP POWER SUPPLY INVERTER FOUND INOPERABLE. BLOWN PS FUSE	
G	BPI	026880	061679	SI	FS	C	804	N	R	D	CNTNMNT VACUUM RELIEF PS INVERTER FUSE BLEW	SUSCEPTIBLE TO INPUT SURGE
G	VY1	015519	081376	SI	SW	L	804	N		D	A 250 KVA UPS OUTPUT BREAKER TRIPPED	NOISE IN AN UNUSED STATIC SWITCH

FABRICATION/CONSTRUCTION/QUALITY CONTROL

N S S	P L A N T	CONTROL OR NSIC NUMBER	EVENT DATE	C O M P	C O U N T	S E R I A L	M O D E L	C A U S E	A C T I V I T Y	T Y P E	C L A S S	F A U L T	#	<u>MODE DESCRIPTION</u>		<u>CAUSE DESCRIPTION</u>	
														MODE DESCRIPTION	CAUSE DESCRIPTION		
B	CR3	021210	042578	SI	UU	E	A05	M	U	D				INVERTER 3A TRIPPING--WRONG FUSES INSTLD IN VITAL/ BUS 3A DURING CONSTRUCTION/TESTING PHASE			
M	SA1	030231	012380	SI	SW	P	B05	N	B	D				LOST METEOROLOGICAL INSTRUMENT			INVERTER HAD MAN HCT AUTO SW--MFG ERROR

DEFECTIVE PROCEDURES

<u>UN</u>	<u>PLAN</u>	<u>CONTROL OR NSIC NUMBER</u>	<u>EVENT DATE</u>	<u>CON</u>	<u>SUB</u>	<u>SYSTEM</u>	<u>MODE</u>	<u>CAUSE</u>	<u>TYPE</u>	<u>FACILITY</u>	<u>MODE DESCRIPTION</u>	<u>CAUSE DESCRIPTION</u>
6	COL	037646	050581	SI	CP	E	B06	T	D		STATIC INVERTER 1A'S SPIKE SUPPRESSOR CAP FAILED	AGED ELECTROLYTIC CAP/IMPROPR OP PROCEDUR

APPENDIX F
INVERTER ONE-LINE DESCRIPTIONS
SORTED BY SYSTEM

CONTENTS

PWR SYSTEMS

Containment (Includes Isolation Control)	F-1
Essential ac Electrical Distribution	F-2
Unknown	F-6

BWR SYSTEMS

Automatic Depressurization	F-7
Containment (Includes Isolation Control)	F-8
Essential ac Electrical Distribution	F-9
High Pressure Coolant Injection	F-10
Low Pressure Coolant Injection	F-11
Reactor Core Isolation Cooling	F-13
Unknown	F-14

CODES USED IN LER ONE-LINE DESCRIPTIONS

FAULT MODE		FAULT CAUSE		ACTIVITY RESULTING IN DISCOVERY	
CODE	DESCRIPTION	CODE	DESCRIPTION	CODE	DESCRIPTION
A	REDUCED CAPABILITY	00	UNKNOWN	M	MAINTENANCE
B	INOPERABLE	01	PERSONNEL OPERATION	N	NORMAL PLANT OPERATION
-----		02	PERSONNEL MAINTENANCE	R	RECORDS REVIEW
SYSTEM		03	PERSONNEL TESTING	T	TESTING
CODE	DESCRIPTION	04	DESIGN ERROR	U	UNKNOWN
A	AUTOMATIC DEPRESSURIZATION SYSTEM (ADS)	05	FABRICATION/CONSTRUCTION/QUALITY CONTROL	-----	
C	CONTROL SYSTEM (INCLUDES ISOLATION CONTROL)	06	DEFECTIVE PROCEDURES	NSSS VENDOR	
E	ESSENTIAL AC ELECTRICAL DISTRIBUTION	07	EXTREME ENVIRONMENT	CODE	DESCRIPTION
H	HIGH PRESSURE COOLANT INJECTION (HPCI)	08	ELECTRICAL MALFUNCTION	B	BABCOCK & WILCOX
L	LOW PRESSURE COOLANT INJECTION (LPCI)	09	MECHANICAL MALFUNCTION	C	COMBUSTION ENGINEERING
Q	REACTOR CORE ISOLATION COOLING (RCIC)			M	WESTINGHOUSE
P	UNKNOWN			G	GENERAL ELECTRIC
-----		SUBCOMPONENT		-----	
TYPE OF EVENT		CODE	DESCRIPTION	COMPONENT	
CODE	DESCRIPTION			CODE	DESCRIPTION
B	RECURRING COMMON CAUSE FAILURE	AC	ANNUNCIATOR CONTROL CARD	SI	STATIC INVERTER
C	COMMON CAUSE FAILURE	CC	FIRING CIRCUIT	-----	
R	RECURRING FAILURE	CF	COOLING FAN	EVENT CLASSIFICATION	
C	COMMAND FAULT	CH	CHOKE	CODE	DESCRIPTION
R	RECURRING COMMAND FAULT	CL	CONTROL CARD/CONTROL MODULE	D	FREQUENCY
C	COMMON CAUSE COMMAND FAULT	CP	CAPACITOR	T	AGE
R	RECURRING COMMON CAUSE COMMAND FAULT	DB	DRIVER BOARD	U	UNKNOWN
BLANK	RANDOM FAILURE	D	DIODE	-----	
		FB	FREQUENCY BOARD		
		F	FUSE		
		I	INDUCTOR		
		O	OSCILLATOR		
		P	PROTECTION CARD		
		PS	POWER SUPPLY (INTERNAL)		
		R	RECTIFIER		
		REL	RELAY		
		RES	RESISTOR		
		S	SWITCH		
		TR	TRANSFORMER		
		TS	TRANSISTOR		
		UV	UNDERVOLTAGE COIL		
		VR	VOLTAGE REGULATOR		
		UU	UNKNOWN/NOT APPLICABLE		

PWR -- CONTAINMENT (INCLUDES ISOLATION CONTROL)

<u>TIME</u>	<u>P</u>	<u>CONTROL</u>	<u>OR</u>	<u>NSIC</u>	<u>EVENT</u>	<u>DATE</u>	<u>AREA</u>	<u>SUB</u>	<u>SYSTEM</u>	<u>MODE</u>	<u>CAUSE</u>	<u>ACTIVITY</u>	<u>CLASS</u>	<u>FAULT</u>	<u>MODE DESCRIPTION</u>	<u>CAUSE DESCRIPTION</u>		
W IP2	022867	102278	SI	UU	C	800	N	U								*5KVA STATIC INVERTER FAILED DEENRGZG CONT PRESS //	SAFEGUARDS LOGIC, DEFECTIVE INVERTER	
W S01	020878A	031578	SI	CP	C	808	N	T								*A* INVERTER FAILED (ONE OF TWO FOR CSAS LOGIC)	CAPACITOR AND CHOKE IN OUTPUT SIDE FAILED	
W S01	020878B	031578	SI	UU	C	804	N	U	D								*B* INVERTER FOR CSAS TRIPPED ON TRANSFER	TRANSFER SWITCH WAS TOO FAST

PMR --- ESSENTIAL AC ELECTRICAL DISTRIBUTION

NO	SYSTEM	CONTROL OR NSIC NUMBER	EVENT DATE	COM ON BP	SYMPTOM	CAUSE DESCRIPTION	MODE DESCRIPTION	CAUSE DESCRIPTION
B	CR3	017321	030277	SI	DI	E 808 M T	"B" INVERTER FAILED CAUSED RX TRIP	OUTPUT DIODE FAILED
B	CR3	019021	090277	SI	RC	E 808 N D	"D" INVERTER FAILED	SILICON CONTROLLED RECTIFIER DEFECTIVE
B	CR3	019523	102677	SI	UU	E 800 M U	"A" INVERTER FAILED	NO CAUSE GIVEN
B	CR3	021210	042578	S	UU	E 405 M U D	INVERTER 3A TRIPPING--WRONG FUSES INSTLD IN VITAL/	BUS 3A DURING CONSTRUCTION/TESTING PHASE
B	CR3	022361	081978	SI	UU	E 808 M B D	INVERTER V817-1A FAILED--120VAC VITAL BUS 3A NO PMR	ELECTRONIC COMPONENT FAILERS W/ IN V817-1A
B	CR3	037006	041181	SI	DE	E 807 M R T	INVERTER "DM" FAILED. INADQ VENT CAUSED OVERHTG //	SHORTED DIODE & BLEW FUSE
B	CR3	038100	071481	SI	FS	E 802 M C D	"A" INVERTER FAILED DEEN6GZD 120 AC VITAL BUS #3A	INADV SHORTED STAT BATT DURING MAINTENANC
B	DB1	027478	110579	SI	RS	E 808 M D	BLOWN FUSE ON INVERTER YV2 OUTPUT	OPEN RESISTOR IN LOGIC PS OF INVERTER YV2
B	DB1	032367A	082280	SI	FS	E 808 N B D	FAILURE OF YV-2 INVERTER INPUT FUSE	EXACT CAUSE OF FUSE FAILURE UNDETERMINED
B	DB1	032367B	082380	SI	FS	E 808 N B D	FAILURE OF YV-2 INVERTER INPUT FUSE	EXACT CAUSE OF FUSE FAILURE UNDETERMINED
B	DB1	033270	111280	SI	FS	E 802 T C D	GROUNDING YV2 INVERTER INPUT FUSE TOOK OUT Y2 BUS	GROUNDING OSCILLOSCOPE USED BY I&C PER SML
B	DB1	039149	101881	SI	DI	E 808 M T	ESSENTIAL 120VAC INVERTER YV3 FAILED	RESISTOR/DIODE ON +15VDC LOGIC PS FAILED
B	DB1	173542	040982	SI	FS	E 802 M C D	OUTPUT FROM YV2 INVERTER TO Y2 BUS WAS LOST	FUSE BLEW DUE TO PERSONNEL MAINTENANCE
B	DB1	175395	060882	SI	RC	E 808 N C T	ESSENTIAL INVERTER YV2 FAILED	COMP FAILR W/ IN REGULATED RECTIFIER YRF2
B	DE1	036123	011881	SI	FS	E 808 M D	IDID VITAL INVERTER DC INPUT FUSE BLEW	POOR CNNECTN S/DR COMP PRBLMS IN LOGIC CRD
B	DE1	036241A	012581	SI	FS	E 808 N D	IDID VITAL INVERTER DC INPUT FUSE BLEW	BLOWN FUSES
B	DE1	036241B	012581	SI	UU	E 800 N U	IDIB INVERTER TRIPPED	EXACT CAUSE UNKNOWN
B	DE1	036241C	012581	SI	UU	E 802 M U D	IDID INVERTER TRIPPED	PERS OPENED AC OUTPUT BRKR MISTAKENLY
B	DE3	016137	01276	SI	CP	E 808 N T	THE 3 DEB VITAL BUS INVERTER FAILED	DIELECTRIC OF INPUT FILTER CAP BROKE DOWN
B	DE3	027697	111079	SI	FS	E 808 N D	ICS POWER LOST DUE TO INVERTER(K1) FAILED	BLOW FUSES
B	DE3	031182A	050780	SI	FS	E 808 N R D	LOST AC VITAL INST BUS DUE TO INVERTER FAILURE	BLOWN FUSES
B	DE3	031182B	050980	SI	FS	E 808 N R D	LOST AC VITAL INST BUS DUE TO INVERTER FAILURE	BLOWN FUSES/FAULTY TRANSISTOR
B	DE3	031182C	051680	SI	TS	E 801 M D	INVERTER 301B TRIPPED WHEN POWER WAS TRANSFERRED /	TO IT. BYPASS SWITCH POSSIBLY CLOSED.
B	RS1	026111	042279	SI	UV	E 804 U R D	S1A VITAL POWER INVERTER FAILED	DESIGN DEFICIENCY IN U, V, COIL
B	T12	021952	032978	SI	CL	E 808 N T	VITAL BUS INVERTER FAILD TO FUNCYN PROPERLY	FAULTY INVERTER CNTRL MODULE AND FUSE
C	CC1	179674	110982	SI	UU	E 801 M U D	RX S/D DUE TO INVERTER DC FEEDER BREAKER TRIP	CONTRACTOR INADV TRPD OPEN INPUT BREAKER
C	CC2	017009	010677	SI	FS	E 808 T D	B PHASE COMPUTER INVERTER DC INPUT FUSE OPENED	CURRENT SURGE DUE TO SWITCHING OPERATION
C	CC2	183012	122882	SI	FS	E 800 N U	#22 INVERTER OUTPUT FUSE BLEW	SUSPECTED CAUSE--IMPROPER FUSE TYPE USED
C	FC1	020085	122577	SI	VR	E 808 M T	D CHANNEL INSTRUMENT INVERTER FAILED	CONSTANT VOLTAGE REGULATOR FAILED
C	MI2	026871	010579	SI	CP	E 808 N T	INVERTER NO. 4 FAILED	CAPACITORS AND OSCILLATOR BOARD FAILED

PWR -- ESSENTIAL AC ELECTRICAL DISTRIBUTION

N S S	P L A N Y	CONTROL OR NSIC NUMBER	EVENT DATE	C O M P	C O U N T	M O D E	C A U S E	F A U L T	C A U S E	F A U L T	#	MODE DESCRIPTION	CAUSE DESCRIPTION
C	MI2	172670*	010682	SI	FS	E	B02	N	C	D	2	FUSES IN INVERTERS 2 AND 6 BLEW	SHORTED TEST LEAD FAILED CIRCUIT
C	ME2	175402*	060682	SI	FS	E	B07	N	C	D	2	LOSS OF 120VAC (VIAC-1) BLOWS FUSES IN ESFAS CABNT	ROOF LEAK SHORTED 2 INVERTERS #5,6
C	SL1	015004	052976	SI	OS	E	B08	N	T			1C STATIC INVERTER FAILED(PS FOR AC INST, 120 VOLT)	FAILED OSCILLATOR CIRCUIT BOARD
C	SL1	175205A	062282	SI	UU	E	B00	N	R	U		OUTPUT BRKR OF 1A STATIC INVERTER OPENED	NO APPARENT CAUSE COULD BE FOUND
C	SL1	175205b	062382	SI	OS	E	B08	N	R	U		1A STATIC INVERTER OUTPUT BREAKER OPENED	OSCILLATOR CIRCUIT BOARD REPLACED
C	SL1	181486	122082	SI	UU	E	B00	N	R	U		1A INVERTER OUTPUT BRK OPENED;1/4 120VAC BUS LOST	NO APPARENT CAUSE OF FAILURE
C	SL1	181729	122582	SI	FB	E	B00	N	R	U		1A INVERTER OUTPUT BRK OPENED;1/4 120VAC BUS LOST	DEFECTIVE OUTPUT FREQUENCY MODULE
C	SL1	181038	123082	SI	OS	E	B08	M	T			1A INVERTER OUTPUT BRK OPENED;1/4 120VAC BUS LOST	FREQUENCY OSCILLATOR HAD DRIFTED
W	BV1	014692	051076	SI	CP	E	B08	N	R	T		INVERTER NO. 3 FAILED	OUTPUT FILTER CAPACITOR FAILED
W	BV1	015102	052776	SI	CP	E	B08	N	R	T		INVERTER NO. 1 FAILED	OUTPUT FILTER CAPACITOR FAILED
W	BV1	015213	062376	SI	UU	E	B00	U	U			INVERTER NO. 3 APPARENTLY FAILED	NO CAUSE GIVEN
W	BV1	016280	102276	SI	RC	E	B08	N	R	T		VITAL BUS INVERTER NO. 3 FAILED	SCRS AND OUTPUT FUSE FOUND BAD
W	BV1	016360	110676	SI	UU	E	B03	N	U	D		INVERTER NO. 2 WAS MOMENTARILY OUT OF SERVICE	OUTPUT WAS SHORTED OUT BY PERSONNEL
W	BV1	017014	121576	SI	DE	E	B08	N	R	T		NO. 1 VITAL BUS INVERTER FAILED	3 DIODE AND TWO FUSES FOUND FAILED
W	BV1	023209	010278	SI	UU	E	A00	N	U			OUTPUT FREQUENCY OF NO. 4 INVERTER OSCILLATING	NO CAUSE GIVEN
W	BV1	025332	012079	SI	UU	E	B00	N	U			NO. 3 VITAL BUS INVERTER FAILED	FAULTY COMPONENTS
W	BV1	027140	091879	SI	OS	E	A08	N	T			NO. 4 VITAL BUS INVERTER FREQUENCY FOUND SPIKING	FAULTY OSCILLATOR CARD
W	BV1	028012	092079	SI	UU	E	B00	N	U			NO. 4 VITAL BUS INVERTER FAILED. RX TRIP OCCURRED/	/AND SAFETY INJECTION OCCURRED. NO CAUSE
W	BV1	031239	050480	SI	FS	E	B08	N	R	D		PWR LOST TO #4 VITAL BUS INVERTER DUE TO BLOWN //	MAIN PS FUSE. CAUSE UNKNOWN
W	BV1	173454	041482	SI	UU	E	B02	N	U	D		NO. 3 INVERTER TRIPPED	PERSONNEL MAINTENANCE
W	DC1	017804	642177	SI	FS	E	B08	N	D			#4 INVERTER FAILED, CAUSED RX TRIP & SI	BLOWN FUSE
W	DC1	025643*	032379	SI	UU	E	B01	N	C	D	2	TWO VITAL BUS INVERTERS FAILED SIMULTANEOUSLY	PARTS FAILED DUE TO DC SURGE. PERSONNEL
W	DC1	032503	083180	SI	DE	E	B08	N	R	T		SHORTED DIODE IN CRID IV INVERTER	DIODE FAILED DUE TO NORMAL END OF LIFE
W	DC1	182697	082382	SI	UU	E	B08	N	D			AB EMERG DIESEL GENERATOR INVERTER FAILED. SOLID	STATE COMP, XFMR GATE, SHORTING BRD RPLCD
W	DC2	022280	061378	SI	DI	E	B08	N	C	T		INVERTER FAILURE	DEFECTIVE DIODES AND SCR'S
W	DC2	037613	061281	SI	CP	E	B08	N	B	T		FAILURE 'N 120VAC VITAL BUS (CRID II)	C-2 CAPACITOR FAILED ALSO BLEW A FUSE
W	HN1	018775	071977	SI	UU	E	B07	N	C	T		STATIC INVERTER FAILED	AMBIENT TEMP 40 DEG C. ABOVE DESIGN
W	JF1	021593	022178	SI	UU	E	B00	N	U			120V VITAL BUS A DEENRGZD WHEN INVERTER A TRIPPED	EXACT CAUSE NOT IDENTIFIED
W	JF1	021592	022378	SI	CP	E	B08	N	R	D		120VAC VITAL BUS B DEENRGZD WHEN INVERTER 1B TRPD	FAULTY CAPACITOR WAS REPLACED
W	JF1	021594	050978	SI	UU	E	B00	N	U			120VAC VITAL BUS A DEENRGZD WHEN INVERTER A TRPD	EXACT CAUSE NOT IDENTIFIED

PWR -- ESSENTIAL AC ELECTRICAL DISTRIBUTION

UNION	PLANT	CONTROL OR NSIC NUMBER	EVENT DATE	COND P	CU SUB	STATUS	MODE	CAUSE	ACTIVITY	CLASS	FAULT #	MODE DESCRIPTION	CAUSE DESCRIPTION
W	JF1	021591	053078	SI	CP	E	808	N	R	D		120VAC BUS D DEENERGZD WHEN INVERTER 1D TRIPPED	CAPACITOR IN INVERTER FAILED
W	JF1	025439	011679	SI	CH	E	808	N	T			1B INVERTER TRIPPED (PS FOR 120V VITAL AC)	VARIOUS INTERNAL COMPONENTS FAILED
W	JF2	038879	092781	SI	UU	E	800	M	U			INVERTER 2A TRPD--120VAC VITAL BUS 2A DEENERGIZED	TRANSIENT VOLTAGE SPIKE--CAUSE UNKNOWN
W	JF2	173252	031682	SI	FS	E	808	N	D			INVERTER NO. 28 FAILED	FUSE BLEW IN VOLTAGE REGULATOR
W	JF2	176542	072282	SI	UU	E	800	N	U			INVERTER NO. 2G FAILED CAUSING LOSS OF POWER TO S/	/UB COOLING MONITOR AND H2 MONITOR
W	HG1	174673	061382	SI	RC	E	808	N	D			INVERTER EVIA INOP--LOST VITAL INST PWR CAUSD RX//	TRIPS. SCR SHORTING CKT BRD REPLACED
W	HG1	174671	062482	SI	CP	E	808	N	T			STATIC INVERTER EVIA MALFUNC--RHR ISOL VLV CLOSED	3 CAP IN OUTPUT CVT CAP BANK FAILED
W	NA1	031217	052380	SI	FS	E	808	N	D			LOST VITAL BUS 1-III. CAUSE UNKNOWN--POSSIBLY //	VLTG SURGE TO DC/AC INVERTER BLEW 2 FUSES
W	NA1	032608	090880	SI	UU	E	800	N	U			LOST PWR TO 120VAC VITAL BUS 1-IV	INVERTER SUPPLY BRKR FOUND OPEN
W	NA2	037674*	060381	SI	UU	E	800	N	C	U	2	VOLTAGE TRANSIENT THRU VITAL BUS INVERTERS 2-III//	& 2-IV. CAUSE UNKNOWN
W	PR1	015104	061576	SI	TR	E	808	N	R	T		NO. 13 INVERTER FAILED (PS TO INSTRUMENT BUS 113)	REGULATING TRANSFORMER ON OUTPUT FAILED
W	PR1	017425	031477	SI	CP	E	808	N	R	T		NO. 11 INVERTER FAILED	CAP ON OUTPUT SOLA TRANSFORMER FAILED
W	PR2	032962	100480	SI	TR	E	808	N	T			#23 INVERTER FAILED DEENERGZG PANEL 213	CONSTANT VOLTAGE TRANSFORMER FAILED
W	SA1	022426	082178	SI	DI	E	808	N	T			VITAL INST BUS INVERTER 1A FUSES BLOWN	FAILD DIODE IN CNTRL CKT BRD
W	SA1	022420	082778	SI	CL	E	808	N	R	T		1A INVERTER FAILD--FAILD ELECTRONIC COMP ON MASTER	//LOGIC CKT BRD CAUSD BLOWN FUSES
W	SA1	023232	112778	SI	TR	E	808	N	R	T		LOST 1B VITAL INSTRUMENT BUS	OUTPUT XFRRR IN SUPPLY INVERTER FAILED
W	SA1	023230	120878	SI	UU	E	800	N	U			INVERTER DIDN'T SWITCH TO B/U BATTERY SUPPLY	NO CAUSE COULD BE DETERMINED
W	SA1	023513	012679	SI	UU	E	800	N	U			1B VITAL INSTRUMENT BUS INVERTER FAILED	NO CAUSE. INADVERTANT SI OCCURRED
W	SA1	039242	102981	SI	UU	E	800	N	U			INADV SI DUE TO LOSS OF VITAL BUS 1A INVERTER	CAUSE UNKNOWN
W	SA1	039344	110681	SI	UU	E	800	N	U			INADV SI DUE TO LOSS OF 1A VITAL INST BUS INVERTER	CAUSE UNKNOWN
W	SA2	161466	112982	SI	PS	E	808	N	D			INVERTER PS FAILED CAUSD P-250 COMPUTER TO SHUTDWN	PS PROBLEM FROM FAILED OSCILLATOR CKT BRD
W	SE1	032879A	092780	SI	UU	E	800	N	U			VITAL INVERTER 2-IV OUTPUT BRKR TRIPPED	CAUSE NOT IDENTIFIED
W	SE1	032879B	100180	SI	SW	E	808	N	T			VITAL INVERTER 2-IV OUTPUT BRKR TRIPPED	BAD AUX SW ON THE K11 RELAY
W	SE1	032977	101480	SI	CC	E	808	N	T			VITAL INVERTER 2-III OUTPUT BRKR TRIPPED	FIRING CKT CLOCK CARD RBS FAILED
W	SE1	033295	111180	SI	FS	E	808	N	D			VITAL INVERTER 1-I OUTPUT BRKR TRIPPED	INVERTER 1-I OUTPUT FUSES HAD BLOWN
W	SE1	033296*	111880	SI	UU	E	800	N	R	U	9	9 VITAL INVERTER 2-III FAILURES BETWEEN 11-9-806//	11-23-80. NO CAUSES GIVEN
W	SE1	036667	013081	SI	UU	E	802	M	U	D		CONDUIT/CABLE SUPPLYING PWR TO VITAL INVERTER 1-I/	/WAS CUT. CONSTRUCTION PERSONNEL ERROR
W	SD1	015998	082376	SI	PS	E	800	N	U			VITAL BUS #1 TRANSFERRED TO B/U POWER SOURCE	COMPONENT FAILURE IN #1 INVERTER. NO CAUSE
W	SD1	018440	061477	SI	CP	E	808	N	T			DC INPUT FUSE OF UPS INVERTER OPENED	CAPACITORS IN BANKS C-4,C-6 HAD FAILED
W	SU2	179196	101082	SI	IN	E	808	N	T			FAILED VITAL BUS-3 INVERTER/TURB RUNBACK, RX, TRP, SI	STATION BATT INVERTER INDLECTOR SHORTED

PWR --- ESSENTIAL AC ELECTRICAL DISTRIBUTION

PLANT SYSTEM	CONTROL OR INSTRIC NUMBER	EVENT DATE	C M P	C S O M P	C S O M P	S W A U D S	A C T I V E	F A U L T C L A S S I F I C A T I O N	MODE DESCRIPTION	CAUSE DESCRIPTION
W TRI	033305	111280	SI	UU	E	800	T	U	3 VITAL PREFERRED INSTR BUSES ON SAME EMERG TRAIN	#4 INVERTER APPARENTLY FAILED--NO CAUSE
W TRI	039071	100481	SI	RE	E	808	M	T	LOST PREFERRED INST BUS Y11--STATIC INVERTER OUTPT	//CURRENT SENSING RELAY FAILED. NAT'L EOL
W TRI	172719	011682	SI	UU	E	800	M	U	INVERTER NO. 2 FAILED. CAUSED INADVERTANT SI	NO CAUSE GIVEN.
W ZII	025150	011279	SI	UU	E	800	M	U	INV 114 TRPD. FOUND 2.5KVA INV SECTION FAULTY.	LOOSE CONTACT IN DC BREAKER
W ZII	026916	081379	SI	TR	E	808	M	T	INSTRUMENT INVERTER 114 TRIPPED	5KVA TRANSFORMER REPLACED
W ZII	037631	052881	SI	TR	E	808	M	R	INST INVERTER 114 FAILED	XFRMR SHORTED BY HI INVERTER CIRC CURRENT
W ZI2	020356	082077	SI	TR	E	808	N	D	INVERTER NO. 213 FAILED (INSTRUMENT INVERTER)	SLAVE TRANSFORMER FAILED BY OVERHEATING
W ZI2	031066	041180	SI	RC	E	808	N	T	INSTRUMENT INVERTER 214 FAILED	SCR FAILED IN SLAVE UNIT OF INVERTER
W ZI2	037995	050781	SI	TR	E	808	N	D	LOST POWER TO INVERTER 213	XFRMR SHORTD BY HI INVERTER CIRC CURRENT

PWR -- UNKNOWN

<u>EVENT</u>	<u>PLANT</u>	<u>CONTROL OR NSIC NUMBER</u>	<u>EVENT DATE</u>	<u>COMP</u>	<u>SD</u>	<u>OP</u>	<u>MODE</u>	<u>CLASS</u>	<u>STATUS</u>	<u>CAUSE #</u>	<u>MODE DESCRIPTION</u>	<u>CAUSE DESCRIPTION</u>
W	SA1	027523	110579	SI	CF	P	809	N	T		LOST METEOROLOGICAL INSTR/PWR SUP INVERTER FAILED	SEIZED MOTOR BEARINGS IN COOLING FAN
W	SA1	030231	012380	SI	SM	P	805	N	B	D	LOST METEOROLOGICAL INSTRUMENT	INVERTER HAD MAN NCT AUTO SW--MFG ERROR
W	SO1	021743	060778	SI	CP	P	808	N	D		DC INPUT FUSE FOR MOV-850C INVERTER OPENED	GE CAPACITOR 28F5108 AND SCR-2 FAILED

BWR -- AUTOMATIC DEPRESSURIZATION

<u>PLANT</u>	<u>CONTROL OR NSIC NUMBER</u>	<u>EVENT DATE</u>	<u>COMP</u>	<u>SYSTEM</u>	<u>MODE</u>	<u>CAUSE</u>	<u>CLASS</u>	<u>FAULT #</u>	<u>MODE DESCRIPTION</u>	<u>CAUSE DESCRIPTION</u>	
G BPI	037801A	061781	SI	PS	A	808	H	R	T	RX DEPRESSURIZATION LOOP B INVERTER FOUND INOP.	DEFECTIVE ELECTRONIC COMPONENTS
G BPI	037801B	062381	SI	PS	A	808	H	R	T	RX DEPRESSURIZATION LOOP B INVERTER FOUND INOP.	DEFECTIVE ELECTRONIC COMPONENTS

BWR -- CONTAINMENT (INCLUDES ISOLATION CONTROL)

PLANT	CONTROL OR NSIC NUMBER	EVENT DATE	MODE	STATUS	REASON	CLASSIFICATION	DESCRIPTION	CAUSE DESCRIPTION	
G BPI	022658	091078	SI	FS	C	B04	N R D	BLOWN FUSE IN POWER SUPPLY INVERTER	XIENT SUP VLTG PROBLEM--NEEDS DUMMY LOAD
G BPI	025806	031979	SI	FS	C	B04	N D	CONTAINMENT VACUUM RELIEF LOOP POWER SUPPLY INVERTER FOUND INOPERABLE. BLOWN PS FUSE	
G BPI	026880	061679	SI	FS	C	B04	N R D	CNTNMNT VACUUM RELIEF PS INVERTER FUSE BLEW	SUSCEPTIBLE TO INPUT SURGE

BWR -- ESSENTIAL AC ELECTRICAL DISTRIBUTION

N S S	P L A N T	CONTROL OR NSIC NUMBER	EVENT DATE	C O M P	C O M B	S H O U L D	M O D E	C A U S E	A C T I V E	T Y P E	C U R R E N T	F A U L T	<u>MODE DESCRIPTION</u>		<u>CAUSE DESCRIPTION</u>
G	BRI	017085*	011777	SI	UU	E	B02	M	U	D	2		CNTRL VLTG PS SET BELOW EQUALZG VLTG CAUSED TRIP	I&C TECH ERROR IN EQUALZG PLANT BATTERIL	
G	CD1	037646	050581	SI	CP	E	B06	T			D		STATIC INVERTER 1A'S SPIKE SUPPRESSOR CAP FAILED	AGED ELECTROLYTIC CAP/INPROPR DP PROCECUR	

BWR --- HIGH PRESSURE COOLANT INJECTION

SYSTEM	CONTROL POINT	EVENT DATE	CODE	MODE	CAUSE	MODE DESCRIPTION	CAUSE DESCRIPTION	
G EN2	030041	011780	SI	UU	H	808	N	HPCI AUTO FLD CNTRL PWR INVERTER'S HV TRPD LOW INSTRUMENT DRIFT
G FP1	015625	081576	SI	UU	H	800	N	HPCI INVERTER 23--INV--79 TRIPPED AND WOULD NOT RES/ /TART. NO CAUSE FOUND, INVERTER REPLACED
G PB2	021248	042478	SI	UU	H	800	N	HPCI STATIC INVERTER TRIPPED NO FAULT COULD BE FOUND WITH THE INVERTER

BWR -- LOW PRESSURE COOLANT INJECTION

CONTROL EVENT NUMBER	EVENT DATE	UNIT	MODE DESCRIPTION	CAUSE DESCRIPTION
G EN1 033842	073180	SI UU L 807 M U T	B LPCI INVERTER TRIP THUS B LOOP OF RHR INOPERABLE	HI AMBIENT TEMPERATURE IN INVERTER ROOM
G EN1 032376	082180	SI UU L 807 H R T	"B" LPCI INVERTER TRIPPED	HI AMBIENT TEMPERATURE IN INVERTER ROOM
G EN1 037947A	061081	SI SW L 800 N R U	B LPCI INVERTER R44-5003 TRIP ON HIGH TEMPERATURE	DEFECTIVE SWITCH IN INVERTER LEG
G EN1 037947D	061681	SI UU L 800 N R U 2	B LPCI INVERTER 2R44-5003 TRIPPED	UNKNOWN CAUSE
G EN1 037947B	061881	SI SW L 800 N R U 2	B LPCI INVERTER R44-5003 TRIPPED	DEFECTIVE SWITCHES IN INVERTER LEGS
G EN1 037947C	062181	SI SW L 600 N R U	B LPCI INVERTER R44-5003 TRIPPED	DEFECTIVE SWITCH IN INVERTER LEG
G EN1 177682	091182	SI CP L 808 N D	"A" LPCI INVERTER FAILED, OUTPUT FILTER CAPACITOR	/R INSULATION SPAT, FAILED FUSES & CAP'S
G EN2 022024	071778	SI FB L 808 N T	STATIC INVERTER (2R44-5002) OUTPUT BREAKER TRIPPED	FREQUENCY CARD (EXIDE PART #A13A9) FAILED
G EN2 023200	120878	SI PC L 808 N T	STATIC INVERTER (2R44-5003) DC OUTPUT BRKR TRIPPED	AC/DC PROTECTION CARD (A13A12) FAILED
G EN2 027611	111779	SI RE L 808 N T	"B" LPCI INVERTER TRIPPED	FAILED RELAY IN INVERTER FAILED
G EN2 036952	042181	SI CL L 808 N U	"A" LPCI INVERTER 2R44-5002 TRIP	LOGIC FAILURE CAUSED TRIP
G EN2 038501	090481	SI VR L 808 N T	B LPCI INVERTER 2R44-5003 TRIP	GATE FIRING MODULE VOLTAGE REGULATOR FAIL
G EN2 171785	112681	SI CC L 808 M T	B LPCI INVERTER (2R44-5003) GAVE HI PHASE CURRENTS	FAILED GATE FIRING MODULE
G EN2 178916	100182	SI CF L 809 M T	INVERTER (2R44-5003) TRIP DUE TO LEG FAN FAILURE	#4 INVERTER LEG FAN BEARING FAILED
G FPI 021432	041878	SI RC L 808 M T	LPCI INVERTER/CHARGER TRIP LOST B LPCI INDEPENDENT //	PWR. FAILED SCR'S IN INVERTER/CHARGER
G FPI 030177	012380	SI CP L 808 M U	LPCI INDEPENDENT PS "A" INVERTER TRIPPED	INVERTER CTRL CKT CAPACITORS FAILED
G FPI 032373A	081280	SI CL L 808 M T	"B" LPCI INVERTER TRIPPED	AC VOLTAGE/CURRENT CTRL LOGIC CARD A12
G FPI 032373B	082280	SI CL L 808 M T	"B" LPCI INVERTER TRIPPED	INVERTER LEG GATE FIRE CTRL CKT FAILED
G FPI 032373C	090580	SI AC L 808 M T	"B" LPCI INVERTER TRIPPED	ANNUNCIATOR/CONTROL CARD 2 FAILED
G FPI 032373D	090580	SI AC L 808 M T	"B" LPCI INVERTER TRIPPED	ANNUNCIATOR/CONTROL CARD 2 FAILED
G FPI 032718	091380	SI CL L 808 M T	"B" LPCI INVERTER TRIPPED	LOGIC CARD A2 FAILED
G FPI 037379	031581	SI CP L 808 M R D	LPCI MOV INDEPENDENT POWER SUPPLY INVERTER A TRIP	SHORTED CAP IN GATE FIRING MODULE "A1"
G FPI 101727	121582	SI CL L 808 N D	"A" LPCI INVERTER TRIPPED DUE TO ELECTRICAL FAILURE	GATE TIMING CONTROL CARD FAILED
G VVI 015519	081376	SI SW L 804 M D	A 250 KVA UPS OUTPUT BREAKER TRIPPED	NOISE IN AN UNUSED STATIC SWITCH
G VVI 015965	092076	SI FS L 808 M D	MOTOR CONTROL CENTER 89A LOST POWER DUE TO "A" UP / S	TRIPPED, BLOWN INVERTER LEG FUSE
G VVI 016272	101976	SI CL L 808 M R T	UPS-1B TRIPPED WHEN OPENING VALVE RHR-278	POSSIBLE LOGIC PROBLEM
G VVI 016489	111876	SI VR L 808 M R T	UPS-1B TRIPPED WHILE TESTING LPCI VALVE	VOLTAGE REGULATOR AND SYSTEM LOGIC PROBLEM
G VVI 016500*	112976	SI DB L 808 M R T 2	UPS-1A AND UPS-1B TRIPPED WHILE TESTING LPCI VALVE	1A HAD FAILED DRIVER BOARD, 1B HAD BAD REG
G VVI 021542	043078	SI FS L 808 N D	250KVA UNINTERRUPTIBLE PWR SUPPLY TRIPPED	BLOWN INVERTER LEG FUSE (2A18F2)
G VVI 021768	061978	SI UU L 800 M U	LOSS OF VLTG TO MCC-898	UNINTERRUPTIBLE POWER SUPPLY (UPS-1B) TRIP

BWR -- LOW PRESSURE COOLANT INJECTION

<u>PLANT</u>	<u>CONTROL OR NSIC NUMBER</u>	<u>EVENT DATE</u>	<u>CODE</u>	<u>STATUS</u>	<u>MODE</u>	<u>CAUSE</u>	<u>TYPE</u>	<u>CLASS</u>	<u>FAULT</u>	<u>MODE DESCRIPTION</u>	<u>CAUSE DESCRIPTION</u>
G VY1	021842	062973	SI	PC	L	B08	N	T		250KVA UPS TRPD DUE TO INVERTER LEG FUSE(2A19F2)//	BLEW WHEN GATE INTRFC/PRTCIN LOGIC MALFUN
G VY1	032080	071880	SI	FS	L	B08	N	C	D	LOGIC PS BRD FAILED. 250KVA UNINTERRUPTIBLE PS //	TRPD DUE TO BLOWN LOGIC PS FUSE
G VY1	173401	020682	SI	CP	L	B08	N	T		UPS-B AC GROUND AND BLOWN FUSE ALARM WAS RECEIVED	SUPPRESSION CAPACITOR FAILED BLOWING FUSE
G VY1	172882	022382	SI	CP	L	B08	N	T		UPS "B" TRAIN TRIPPED	SHORTED CAPACITOR DUE TO AGE

BWR -- REACTOR CORE ISOLATION COOLING

UNCLAS	PLAN	CONTROL OR NSIC NUMBER	EVENT DATE	CON	SUB	S	M	C	A	T	C	F	A	MODE DESCRIPTION	CAUSE DESCRIPTION
														MODE DESCRIPTION	CAUSE DESCRIPTION
G	BR2	030364	020480	SI	UU	Q	800	N	U					STM LEAK DETCTN "A" LOGIC INVERTER'S HV TRPD LOW	NO CAUSE GIVEN
G	EN1	016840	112776	SI	CP	Q	808	N	T					RCIC PS INVERTER E51-K603 FAILED	SHORTED CAPACITOR IN OUTPUT TRANSFORMER
G	EN2	027848A	121979	SI	FS	Q	808	N	C	D				"A" PS FOR RCIC STEAM LEAK DETECTION FAILED	FUSES BLEW DUE TO CURRENT SURGE
G	EN2	027848B	122079	SI	FS	Q	808	N	C	D				"B" PS FOR RCIC STEAM LEAK DETECTION FAILED	FUSES BLEW DUE TO CURRENT SURGE
G	EN2	030241	020280	SI	CP	Q	808	T	T					RCIC REMOTE FLD CNTRL LOOP POWER INVERTER TRIPPED	DFCTV INPUT FILTER CAPACITORS
G	EN2	030980	042480	SI	UU	Q	800	N	R	U				REC'D RCIC LEAK DETECTION LOGIC PWR FAILURE ALARM	COMPONENT FAILURE OF INVERTER
G	FP1	013966	010376	SI	RS	Q	808	N	D					RCIC STATIC INVERTER(12-801A) FAILED	LEAD TO WIRE WOUND RESISTOR TOUCHED RSTR
G	P82	017210	021977	SI	UU	Q	800	N	U					RCIC STATIC INVERTER 2-13-90 TRIPPED WITHOUT AUTO/	MATIC RESET. NO CAUSE FOUND
G	P82	021247	041978	SI	TS	Q	808	N	T					INVERTER FAILD POWERS RCIC'S CNTRLR & INSTRMNTN	DFCTV TRANSISTOR IN AUTO-RESET CIRCUIT
G	P11	038673	091281	SI	CP	Q	808	N	D					FAILED INVERTER CAUSED GROUND FAULT ON 125VDC SYS	FAILED CAP IN DC/AC INVERTER

BWR --- UNKNOWN

CONTROL SYSTEM NUMBER	EVENT DATE	CONTROL SYSTEM CODE	SYMBOL CODE	CAUSE CODE	ALARM TYPE	MODE DESCRIPTION	CAUSE DESCRIPTION
S BF1 038008	070481	SI CL P 808	T R T	ALARM PANEL XA-55-8E	INVERTER	INDOPERABLE	FAILED INVERTER CONTROL CARD
S BF3 027049	091979	SI AC P 808	H T	ANNUNC PANEL XA-55-208	INOP INVERTER	PRINTED CKT//	CARD FAILED DUE TO NATURAL AGING

APPENDIX G

**INVERTER ONE-LINE DESCRIPTIONS
SORTED BY TYPE OF EVENT**

CONTENTS

Recurring Common Cause Failure	G-1
Common Cause Failure	G-2
Recurring Failure	G-3
Common Cause Command Fault	G-5

CODES USED IN LER ONE-LINE DESCRIPTIONS

<u>FAULT MODE</u>		<u>FAULT CAUSE</u>		<u>ACTIVITY RESULTING IN DISCOVERY</u>	
<u>CODE</u>	<u>DESCRIPTION</u>	<u>CODE</u>	<u>DESCRIPTION</u>	<u>CODE</u>	<u>DESCRIPTION</u>
A	REDUCED CAPABILITY	00	UNKNOWN	M	MAINTENANCE
B	INOPERABLE	01	PERSONNEL OPERATION	N	NORMAL PLANT OPERATION
-----		02	PERSONNEL MAINTENANCE	R	RECORDS REVIEW
<u>SYSTEM</u>		03	PERSONNEL TESTING	T	TESTING
<u>CODE</u>	<u>DESCRIPTION</u>	04	DESIGN ERROR	U	UNKNOWN
A	AUTOMATIC DEPRESSURIZATION SYSTEM (ADS)	05	CONSTRUCTION/QUALITY CONTROL	-----	
C	CONTAINMENT (INCLUDES ISOLATION CONTROL)	06	PROCEDURES	<u>NSSS VENDOR</u>	
E	ESSENTIAL AC ELECTRICAL DISTRIBUTION	07	ENVIRONMENT	<u>CODE</u>	<u>DESCRIPTION</u>
H	HIGH PRESSURE COOLANT INJECTION (HPCI)	08	MECHANICAL MALFUNCTION	B	BABCOCK & WILCOX
L	LOW PRESSURE COOLANT INJECTION (LPCI)	09	MALFUNCTION	C	COMBUSTION ENGINEERING
R	REACTOR CORE ISOLATION COOLING (RCIC)	-----		M	METTINGHOUSE
U	UNKNOWN	<u>SUBCOMPONENT</u>		G	GENERAL ELECTRIC
-----		<u>CODE</u>	<u>DESCRIPTION</u>	-----	
<u>TYPE OF EVENT</u>		AC	ANNUNCIATOR CONTROL CARD	<u>COMPONENT</u>	
<u>CODE</u>	<u>DESCRIPTION</u>	CC	FIRING CIRCUIT	<u>CODE</u>	<u>DESCRIPTION</u>
B	RECURRING COMMON CAUSE FAILURE	CF	COOLING FAN	SI	STATIC INVERTER
C	COMMON CAUSE FAILURE	CH	CHOKES	-----	
R	RECURRING FAILURE	CM	CONTROL CARD/CONTROL MODULE	<u>EVENT CLASSIFICATION</u>	
U	COMMON CAUSE COMMAND FAULT	CP	CAPACITOR	<u>CODE</u>	<u>DESCRIPTION</u>
BLANK	RANDOM FAILURE	DB	DRIVER BOARD	0	FREQUENCY
-----		DI	DIODE	T	AGE
		FB	FREQUENCY BOARD	U	UNKNOWN
		FU	FUSE	-----	
		IN	INDUCTOR		
		OS	OSCILLATOR		
		PC	PROTECTION CARD		
		PS	POWER SUPPLY (INTERNAL)		
		RF	RECTIFIER		
		RS	RESISTOR		
		SC	SCR		
		TF	TRANSFORMER		
		TR	TRANSISTOR		
		UC	UNDERVOLTAGE COIL		
		VR	VOLTAGE REGULATOR		
		UU	UNKNOWN/NOT APPLICABLE		

RECURRING COMMON CAUSE FAILURE

SYSTEM	PLANT	CONTROL OR NSIC NUMBER	EVENT DATE	MODE	SUB	SCHEDULE	REASON	CAUSE	EFFECT	STATUS	REMARKS	MODE DESCRIPTION	CAUSE DESCRIPTION
B	CR3	022361	081978	SI	UU	E	808	N	B	D		INVERTER VBIT-1A FAILED-120VAC VITAL BUS 3A NO PWR	ELECTRONIC COMPONENT FAILRS W/ IN VBIT-1A
B	DB1	032367A	082280	SI	FS	E	808	A	B	D		FAILURE OF YV-2 INVERTER INPUT FUSE	EXACT CAUSE OF FUSE FAILURE UNDETERMINED
B	DB1	032367B	082380	SI	FS	E	808	N	B	D		FAILURE OF YV-2 INVERTER INPUT FUSE	EXACT CAUSE OF FUSE FAILURE UNDETERMINED
W	DC2	037613	061281	SI	CP	E	808	N	B	T		FAILURE IN 120VAC VITAL BUS (CRID II)	C-2 CAPACITOR FAILED ALSO BLEW A FUSE
W	SA1	030231	012380	SI	SW	P	805	N	B	D		LOST METEOROLOGICAL INSTRUMENT	INVERTER HAD MAN NOT AUTO SW--MFG ERROR

COMMON CAUSE FAILURE

CONTROL NUMBER	EVENT DATE	CO. OR BR.	SYSTEM	MODE DESCRIPTION	CAUSE DESCRIPTION
B CR3 038100	071481	SI FS E	802 M C D	"A" INVERTER FAILED DEEMRGED 120 AC VITAL BUS #3A	INADV SHORTED STAT BATT DURING MAINTENANCE
B DB1 033270	111280	SI FS E	802 T C D	GROUNDING YV2 INVERTER INPUT FUSE TOOK OUT Y2 BUS	GROUNDING OSCILLOSCOPE USED BY I&C PERSONEL
B DB1 173542	040982	SI FS E	802 N C D	OUTPUT FROM YV2 INVERTER TO Y2 BUS WAS LOST	FUSE BLEW DUE TO PERSONNEL MAINTENANCE
B DB1 175395	060882	SI RC E	808 N C T	ESSENTIAL INVERTER YV2 FAILED	COMP FAILR W/ IN REGULATED RECTIFIER YVRF2
C MI2 172670*	010682	SI FS E	802 N C D 2	FUSES IN INVERTERS 2 AND 6 BLEW	SHORTED TEST LEAD FAILED CIRCUIT
C MI2 175402*	060682	SI FS E	807 N C D 2	LOSS OF 120VAC (VIAC-1) BLOWS FUSES IN ESFAS CABMT	ROOF LEAK SHORTED 2 INVERTERS #5 & 6
W DC1 025643*	032379	SI UU E	801 N C D 2	TWO VITAL BUS INVERTERS FAILED SIMULTANEOUSLY	PARTS FAILED DUE TO AC SURGE, PERSONNEL
W DC2 022280	061378	SI DI E	808 M C T	INVERTER FAILURE	DEFECTIVE DIODES AND SCRS
W HNI 018775	071977	SI UU E	807 N C T	STATIC INVERTER FAILED	AMBIENT TEMP 40 DEG C, ABOVE DESIGN
W NA2 037674*	060381	SI UU E	400 N C U 2	VOLTAGE TRANSIENT THRU VITAL BUS INVERTERS 2-III// 6 2-IV.	CAUSE UNKNOWN
G EN2 027848A	121979	SI FS Q	808 N C D	"A" PS FOR RCIC STEAM LEAK DETECTION FAILED	FUSES BLEW DUE TO CURRENT SURGE
G EN2 027848B	122079	SI FS Q	808 N C D	"B" PS FOR RCIC STEAM LEAK DETECTION FAILED	FUSES BLEW DUE TO CURRENT SURGE
G VY1 032080	071880	SI FS L	808 N C D	LOGIC PS BRD FAILED, 250KVA UNINTERRUPTIBLE PS //	TRPD DUE TO BLOWN LOGIC PS FUSE

RECURRING FAILURE

CONTROL NO.	EVENT DATE	SYMBOL	MODE DESCRIPTION	CAUSE DESCRIPTION
B CR3 037006	041181	SI DI E 807 N R T	INVERTER "D" FAILED. INADQ VENT CAUSED OVERHTG //	SHORTED DIODE & BLEW FUSE
B DE3 031182A	050780	SI FS E 808 N R D	LOST AC VITAL INST BUS DUE TO INVERTER FAILURE	BLOWN FUSES
B DE3 031182B	050980	SI FS E 808 N R D	LOST AC VITAL INST BUS DUE TO INVERTER FAILURE	BLOWN FUSES/FAULTY TRANSISTOR
B RS1 026111	042279	SI UV E 804 U R D	S1A VITAL POWER INVERTER FAILED	DESIGN DEFICIENCY IN U-V. COIL
C 5L1 175205A	062282	SI UU E 800 N R U	OUTPUT BRKR OF 1A STATIC INVERTER OPENED	NO APPARENT CAUSE COULD BE FOUND
C 5L1 175205B	062382	SI 05 E 808 N R U	1A INVERTER OUTPUT BRK OPENED 1/4 120VAC BUS LOST	OSCILLATOR CIRCUIT BOARD REPLACED
C 5L1 181486	122082	SI UU E 800 N R U	1A INVERTER OUTPUT BRK OPENED 1/4 120VAC BUS LOST	NO APPARENT CAUSE OF FAILURE
C 5L1 181729	122982	SI FB E 800 N R U	1A INVERTER OUTPUT BRK OPENED 1/4 120VAC BUS LOST	DEFECTIVE OUTPUT FREQUENCY MODULE
W BV1 014692	051076	SI CP E 808 N R T	INVERTER NO. 3 FAILED	OUTPUT FILTER CAPACITOR FAILED
W BV1 015102	052776	SI CP E 808 N R T	INVERTER NO. 1 FAILED	OUTPUT FILTER CAPACITOR FAILED
W BV1 016280	102276	SI RC E 808 N R T	VITAL BUS INVERTER NO. 3 FAILED	SCRS AND OUTPUT FUSE FOUND BAD
W BV1 017014	121576	SI DI E 808 N R T	NO. 1 VITAL BUS INVERTER FAILED	1 DIODE AND TWO FUSES FOUND FAILED
W BV1 031239	050480	SI FS E 808 N R D	PHR LOST TO #4 VITAL BUS INVERTER DUE TO BLOWN //	MAIN PS FUSE. CAUSE UNKNOWN
W DC1 032503	083180	SI DI E 808 N R T	SHORTED DIODE IN CRID IV INVERTER	DIODE FAILED DUE TO NORMAL END OF LIFE
W JF1 021592	022378	SI CP E 808 N R D	120VAC VITAL BUS B DEENRG2D WHEN INVERTER 18 TRPD	FAULTY CAPACITOR WAS REPLACED
W JF1 021591	053078	SI CP E 808 N R D	120VAC BUS D DEENRG2D WHEN INVERTER 1D TRIPPED	CAPACITOR IN INVERTER FAILED
W PR1 015104	061576	SI TR E 808 N R T	NO. 13 INVERTER FAILED (PS TO INSTRUMENT BUS 113)	REGULATING TRANSFORMER ON OUTPUT FAILED
W PR1 017425	031477	SI CP E 808 N R T	NO. 11 INVERTER FAILED	CAP ON OUTPUT SCLA TRANSFORMER FAILED
W SA1 022420	082778	SI CL E 808 N R T	1A INVERTER FAILD---FAILED ELECTRONIC COMP ON MASTER	//LOGIC CKY BRD CAUSED BLOWN FUSES
W SA1 023232	112778	SI TR E 808 N R T	LOST 18 VITAL INSTRUMENT BUS	OUTPUT XFMR IN SUPPLY INVERTER FAILED
W SE1 033296*	111880	SI UU E 800 N P U 9	9 VITAL INVERTER 2-III FAILURES BETWEEN 11-9-806//	11-23-80. NO CAUSES GIVEN
W TR1 172719	041682	SI UU E 800 N R U	INVERTER NO. 2 FAILED. CAUSED INADVERTANT SI	NO CAUSE GIVEN.
W Z11 037631	052881	SI TR E 808 N R D	INST INVERTER 114 FAILED	XFMR SHORTED BY HI INVERTER CIRC CURRENT
G BF1 038008	070481	SI CL P 808 T R T	ALARM PANEL XA-55-8E INVERTER IMOPERABLE	FAILED INVERTER CONTROL CARD
G BP1 022658	091078	SI FS C 804 N R D	BLOWN FUSE IN POWER SUPPLY INVERTER	XIENT SUP VLTG PROBLEM--NEEDS DUMMY LOAD
G BP1 026880	061679	SI FS C 804 N R D	CNTNMNT VACUUM RELIEF PS INVERTER FUSE BLEW	SUSCEPTIBLE TO INPUT SURGE
G BP1 037801A	061781	SI PS A 708 M R T	RX DEPRESSURIZATION LOOP B INVERTER FOUND INOP.	DEFECTIVE ELECTRONIC COMPONENTS
G BP1 037801B	062381	SI PS A 808 M R T	RX DEPRESSURIZATION LOOP B INVERTER FOUND INOP.	DEFECTIVE ELECTRONIC COMPONENTS
G EN1 032376	082180	SI UU L 807 N R T	"B" LPCI INVERTER TRIPPED	HI AMBIENT TEMPERATURE IN INVERTER ROOM
G EN1 037947A	061081	SI SW L 800 N R U	B LPCI INVERTER RA4-S003 TRPD ON HIGH TEMPERATURE	DEFECTIVE SWITCH IN INVERTER LEG

RECURRING FAILURE

PLANT	CONTROL	EVENT DATE	MODE DESCRIPTION	CAUSE DESCRIPTION	
G EN1	037947D	061681	SI UU L BCO M R U 2	B LIPCI INVERTER 2R44-5003 TRIPPED	UNKNOWN CAUSE
G EN1	037947B	061881	SI SW L 800 M R U 2	B LPCI INVERTER R44-5003 TRIPPED	DEFECTIVE SWITCHES IN INVERTER LEGS
G EN1	037947C	062181	SI SW L 800 M R U	B LPCI INVERTER R44-5003 TRIPPED	DEFECTIVE SWITCH IN INVERTER LEG
G EN2	030980	042480	SI UU Q 800 M R U	REC'D RCIC LEAK DETECTION LOGIC PWR FAILURE ALARM	COMPONENT FAILURE OF INVERTER
G FPL	037379	051561	SI CP L 808 M R D	LPCI MOV INDEPENDENT POWER SUPPLY INVERTER A TRPD	SHORTED CAP IN GATE FIRING MODULE "A1"
G VY1	016272	101976	SI CL L 808 M R T	UPS-1B TRIPPED WHEN OPENING VALVE RHR-27B	POSSIBLE LOGIC PROBLEM
G VY1	016485	111876	SI VR L 808 M R T	UPS-1B TRIPPED WHILE TESTING RHR-27B VALVE	VOLTAGE REGULATOR AND SYSTEM LOGIC PROBLEM
G VY1	016500*	112976	SI DB L 808 M R T 2	UPS-1A AND UPS-1B TRIPPED WHILE TESTING LPCI VALVE 1A	1A HAD FAILED DRIVER BOARD, 1B HAD BAD REG

COMMON CAUSE COMMAND FAULT

CONTROL OR SYSTEM NUMBER	EVENT DATE	LOCATION	MODE DESCRIPTION	CAUSE DESCRIPTION
B CR3 021210	042578	SI UU E A05 N U D	INVERTER 3A TRIPPING--WRONG FUSES INSTLD IN VITAL/	BUS 3A DURING CONSTRUCTION/TESTING PHASE
B OE1 036241C	012581	SI UU E B02 M U D	101D INVERTER TRIPPED	PERS OPENED AC OUTPUT BRKR MISTAKENLY
C CC1 179674	110982	SI UU E B01 M U D	RX S/D DUE TO INVERTER DC FEEDER BREAKER TRIP	CONTRACTOR INADV TRPD OPEN INPUT BREAKER
M BV1 016360	110676	SI UU E B03 N U D	INVERTER MD. 2 WAS MOMENTARILY OUT OF SERVICE	OUTPUT WAS SHORTED OUT BY PERSONNEL
M BV1 173454	041482	SI UU E B02 N U D	MD. 3 INVERTER TRIPPED	PERSONNEL MAINTENANCE
M SE1 036667	013081	SI UU E B02 M U D	CONDUIT/CABLE SUPPLYING PWR TO VITAL INVERTER 1-1/	/ WAS CUT. CONSTRUCTION PERSONNEL ERROR
M S01 0208788	031578	SI UU C B04 M U D	-B INVERTER FOR CSAS TRIPPED ON TRANSFER	TRANSFER SWITCH WAS TOO FAST
M Z11 025150	081279	SI UU E B00 N U U	INV 114 TRPD. FOUND 2.5KVA INV SECTION FAULTY.	LOOSE CONTACT IN DC BREAKER
G BR1 017085*	011777	SI UU E B02 M U D 2	CNTRL VLTG PS SET BELOW EQUALZG VLTG CAUSED TRIP	I&C TECH ERROR IN EQUALZG PLANT BATTERIES
G EN1 033842	073180	SI UU L B07 N U T	B LPCI INVERTER TRPD THUS B LOOP OF RHR INOPERABLE	HI AMBIENT TEMPERATURE IN INVERTER ROOM

APPENDIX H

**ADDITIONAL INFORMATION CONTAINED IN
INVERTER ONE-LINE DESCRIPTIONS**

CODES USED IN LER ONE-LINE DESCRIPTIONS

<u>FAULT MODE</u>		<u>FAULT CAUSE</u>		<u>ACTIVITY RESULTING IN DISCOVERY</u>	
<u>CODE</u>	<u>DESCRIPTION</u>	<u>CODE</u>	<u>DESCRIPTION</u>	<u>CODE</u>	<u>DESCRIPTION</u>
A	REDUCED CAPABILITY	00	UNKNOWN	M	MAINTENANCE
B	INOPERABLE	01	PERSONNEL OPERATION	N	NORMAL PLANT OPERATION
-----		02	PERSONNEL MAINTENANCE	R	RECORDS REVIEW
<u>SYSTEM</u>		03	PERSONNEL TESTING	T	TESTING
<u>CODE</u>	<u>DESCRIPTION</u>	04 <td>DESIGN ERROR</td> <td>U</td> <td>UNKNOWN</td>	DESIGN ERROR	U	UNKNOWN
A	AUTOMATIC DEPRESSURIZATION SYSTEM (ADS)	05	FABRICATION/CONSTRUCTION/QUALITY CONTROL	-----	
C	CONTAINMENT (INCLUDES ISOLATION CONTROL)	06	FABRICATION/CONSTRUCTION/QUALITY CONTROL	<u>NSSS VENDOR</u>	
E	ESSENTIAL AC ELECTRICAL DISTRIBUTION	07	OPERATIVE PROCEDURES	<u>CODE</u>	<u>DESCRIPTION</u>
H	HIGH PRESSURE COOLANT INJECTION (HPCI)	08	ATMOSPHERIC ENVIRONMENT	B	BABCOCK & WILCOX
L	LOW PRESSURE COOLANT INJECTION (LPCI)	09	ELECTRICAL MALFUNCTION	C	COMBUSTION ENGINEERING
R	REACTOR CORE ISOLATION COOLING (RCIC)		MECHANICAL MALFUNCTION	W	WESTINGHOUSE
U	UNKNOWN			G	GENERAL ELECTRIC
-----				-----	
<u>TYPE OF EVENT</u>		<u>SUBCOMPONENT</u>		<u>COMPONENT</u>	
<u>CODE</u>	<u>DESCRIPTION</u>	<u>CODE</u>	<u>DESCRIPTION</u>	<u>CODE</u>	<u>DESCRIPTION</u>
B	RECURRING COMMON CAUSE FAILURE	AC	ANNUNCIATOR CONTROL CARD		
C	COMMON CAUSE FAILURE	CC	FIRING CIRCUIT		
R	RECURRING FAILURE	CF	COOLING FAN		
S	COMMAND FAULT	CH	CHOKES		
T	RECURRING COMMAND FAULT	CM	CONTROL CARD/CONTROL MODULE		
U	COMMON CAUSE COMMAND FAULT	CP	CAPACITOR		
V	RECURRING COMMON CAUSE COMMAND FAULT	DB	DRIVER BOARD		
BLANK	RANDOM FAILURE	D	DIODE		
		FB	FREQUENCY BOARD		
		F	FUSE		
		I	INDUCTOR		
		O	OSCILLATOR		
		P	PROTECTION CARD		
		PS	POWER SUPPLY (INTERNAL)		
		R	RECTIFIER		
		RT	RELAY		
		R	RESISTOR		
		S	SWITCH		
		T	TRANSFORMER		
		TS	TRANSISTOR		
		U	UNDERVOLTAGE COIL		
		VR	VOLTAGE REGULATOR		
		UU	UNKNOWN/NOT APPLICABLE		
				<u>EVENT CLASSIFICATION</u>	
				<u>CODE</u>	<u>DESCRIPTION</u>
				D	FREQUENCY
				T	AGE
				U	UNKNOWN

ADDITIONAL CODES USED IN LER ONE-LINE DESCRIPTIONS

MANUFACTURER CODE	DESCRIPTION	CODE	DESCRIPTION	FLAGGING
01	VERDES, DIVISION OF ELTRA CORP.	A	FAILED COMPONENT CAUSED AN ACCIDENT	
02	ALCOHOLIC BEVERAGE CO.	B	COMPONENT FAILED TO MITIGATE AN ACCIDENT	
03	ALCOHOLIC BEVERAGE CO.	C	SAFETY SIGNIFICANT	
04	ALCOHOLIC BEVERAGE CO.			
05	ALCOHOLIC BEVERAGE CO.			
06	ALCOHOLIC BEVERAGE CO.			
07	ALCOHOLIC BEVERAGE CO.			
08	ALCOHOLIC BEVERAGE CO.			
09	ALCOHOLIC BEVERAGE CO.			
10	ALCOHOLIC BEVERAGE CO.			
11	ALCOHOLIC BEVERAGE CO.			
12	ALCOHOLIC BEVERAGE CO.			
13	ALCOHOLIC BEVERAGE CO.			
14	ALCOHOLIC BEVERAGE CO.			
15	ALCOHOLIC BEVERAGE CO.			
16	ALCOHOLIC BEVERAGE CO.			
17	ALCOHOLIC BEVERAGE CO.			
18	ALCOHOLIC BEVERAGE CO.			
19	ALCOHOLIC BEVERAGE CO.			
20	ALCOHOLIC BEVERAGE CO.			
21	ALCOHOLIC BEVERAGE CO.			
22	ALCOHOLIC BEVERAGE CO.			
23	ALCOHOLIC BEVERAGE CO.			
24	ALCOHOLIC BEVERAGE CO.			
25	ALCOHOLIC BEVERAGE CO.			
26	ALCOHOLIC BEVERAGE CO.			
27	ALCOHOLIC BEVERAGE CO.			
28	ALCOHOLIC BEVERAGE CO.			
29	ALCOHOLIC BEVERAGE CO.			
30	ALCOHOLIC BEVERAGE CO.			
31	ALCOHOLIC BEVERAGE CO.			
32	ALCOHOLIC BEVERAGE CO.			
33	ALCOHOLIC BEVERAGE CO.			
34	ALCOHOLIC BEVERAGE CO.			
35	ALCOHOLIC BEVERAGE CO.			
36	ALCOHOLIC BEVERAGE CO.			
37	ALCOHOLIC BEVERAGE CO.			
38	ALCOHOLIC BEVERAGE CO.			
39	ALCOHOLIC BEVERAGE CO.			
40	ALCOHOLIC BEVERAGE CO.			
41	ALCOHOLIC BEVERAGE CO.			
42	ALCOHOLIC BEVERAGE CO.			
43	ALCOHOLIC BEVERAGE CO.			
44	ALCOHOLIC BEVERAGE CO.			
45	ALCOHOLIC BEVERAGE CO.			
46	ALCOHOLIC BEVERAGE CO.			
47	ALCOHOLIC BEVERAGE CO.			
48	ALCOHOLIC BEVERAGE CO.			
49	ALCOHOLIC BEVERAGE CO.			
50	ALCOHOLIC BEVERAGE CO.			
51	ALCOHOLIC BEVERAGE CO.			
52	ALCOHOLIC BEVERAGE CO.			
53	ALCOHOLIC BEVERAGE CO.			
54	ALCOHOLIC BEVERAGE CO.			
55	ALCOHOLIC BEVERAGE CO.			
56	ALCOHOLIC BEVERAGE CO.			
57	ALCOHOLIC BEVERAGE CO.			
58	ALCOHOLIC BEVERAGE CO.			
59	ALCOHOLIC BEVERAGE CO.			
60	ALCOHOLIC BEVERAGE CO.			
61	ALCOHOLIC BEVERAGE CO.			
62	ALCOHOLIC BEVERAGE CO.			
63	ALCOHOLIC BEVERAGE CO.			
64	ALCOHOLIC BEVERAGE CO.			
65	ALCOHOLIC BEVERAGE CO.			
66	ALCOHOLIC BEVERAGE CO.			
67	ALCOHOLIC BEVERAGE CO.			
68	ALCOHOLIC BEVERAGE CO.			
69	ALCOHOLIC BEVERAGE CO.			
70	ALCOHOLIC BEVERAGE CO.			
71	ALCOHOLIC BEVERAGE CO.			
72	ALCOHOLIC BEVERAGE CO.			
73	ALCOHOLIC BEVERAGE CO.			
74	ALCOHOLIC BEVERAGE CO.			
75	ALCOHOLIC BEVERAGE CO.			
76	ALCOHOLIC BEVERAGE CO.			
77	ALCOHOLIC BEVERAGE CO.			
78	ALCOHOLIC BEVERAGE CO.			
79	ALCOHOLIC BEVERAGE CO.			
80	ALCOHOLIC BEVERAGE CO.			
81	ALCOHOLIC BEVERAGE CO.			
82	ALCOHOLIC BEVERAGE CO.			
83	ALCOHOLIC BEVERAGE CO.			
84	ALCOHOLIC BEVERAGE CO.			
85	ALCOHOLIC BEVERAGE CO.			
86	ALCOHOLIC BEVERAGE CO.			
87	ALCOHOLIC BEVERAGE CO.			
88	ALCOHOLIC BEVERAGE CO.			
89	ALCOHOLIC BEVERAGE CO.			
90	ALCOHOLIC BEVERAGE CO.			
91	ALCOHOLIC BEVERAGE CO.			
92	ALCOHOLIC BEVERAGE CO.			
93	ALCOHOLIC BEVERAGE CO.			
94	ALCOHOLIC BEVERAGE CO.			
95	ALCOHOLIC BEVERAGE CO.			
96	ALCOHOLIC BEVERAGE CO.			
97	ALCOHOLIC BEVERAGE CO.			
98	ALCOHOLIC BEVERAGE CO.			
99	ALCOHOLIC BEVERAGE CO.			
00	ALCOHOLIC BEVERAGE CO.			

REPORT TYPE
 A - 2-WEEK REPORTS
 B - 30-DAY REPORTS
 C - OTHER

 ADDITIONAL INFORMATION CONTAINED IN INVERTER ONE-LINE DESCRIPTIONS

N S S S	P L A N T	CONTROL OR NSIC NUMBER	NSIC		M A N U F A C T U R E	M O D E	M A N U F A C T U R E	C O M P	S E C T O R	F L A G S	M O D E D E S C R I P T I O N	C A U S E D E S C R I P T I O N
			V O L U M E	N U M B E R								
B	CR3	017321	020	A	DI	S250				A	"B" INVERTER FAILED, CAUSED RX TRIP	OUTPUT DIODE FAILED
B	CR3	019021	115	B	RC	S250					"D" INVERTER FAILED	SILICON CONTROLLED RECTIFIER DEFECTIVE
B	CR3	019523	137	B	UU	S250					"A" INVERTER FAILED	NO CAUSE GIVEN
B	CR3	021210	028	B	UU	I202					INVERTER 3A TRIPPING--WRONG FUSES INSTLD IN VITAL/	BUS 3A DURING CONSTRUCTION/TESTING PHASE
B	CR3	022361	042	B	UU	S250					INVERTER VBIT-1A FAILED--120VAC VITAL BUS 3A NO PWR	ELECTRONIC COMPONENT FAILS W/ IN VBIT-1A
B	CP3	037006	021	B	DI					A	INVERTER "D" FAILED. INADQ VENT CAUSED OVERHTG //	SHORTED DIODE & BLEW FUSE
B	CR3	038100	046	B	FS	C173				A	"A" INVERTER FAILED DEENRGZD 120 AC VITAL BUS #3A	INADV SHORTED STAT BATT DURING MAINTENANC
B	DB1	027478	107	B	RS	C782	60				BLOWN FUSE ON INVERTER YV2 OUTPUT	OPEN RESISTOR IN LOGIC PS OF INVERTER YV2
B	DB1	032367A	064	C	FS					6	FAILURE OF YV-2 INVERTER INPUT FUSE	EXACT CAUSE OF FUSE FAILURE UNDETERMINED
B	DB1	032367B	064	C	FS					4	FAILURE OF YV-2 INVERTER INPUT FUSE	EXACT CAUSE OF FUSE FAILURE UNDETERMINED
B	DB1	033270	081	B	FS					2 A	GROUNDING YV2 INVERTER INPUT FUSE TOOK OUT Y2 BUS	GROUNDING OSCILLOSCOPE USED BY IEC PERSONL
B	DB1	039149	066	B	DI	C782	35				ESSENTIAL 120VAC INVERTER YV3 FAILED	RESISTOR/DIODE ON +15VDC LOGIC PS FAILED
B	DB1	173542	1 7	020	FS						OUTPUT FROM YV2 INVERTER TO Y2 BUS W/LJ LOST	FUSE BLEW DUE TO PERSONNEL MAINTENANCE
B	DB1	175395	1 9	029	RC						ESSENTIAL INVERTER YV2 FAILED	COMP FAILR W/ IN REGULATED RECTIFIER YRF2
B	DE1	036123	002	B	FS						IDID VITAL INVERTER DC INPUT FUSE BLEW	POOR CNNECTN &/OR COMP PRBLMS IN LOGIC CRD
B	DE1	036241A	003	B	FS	E355					IDID VITAL INVERTER DC INPUT FUSE BLEW	BLOWN FUSES
B	DE1	036241B	003	B	UU	E355					IDIB INVERTER TRIPPED	EXACT CAUSE UNKNOWN
B	DE1	036241C	003	B	UU	E355					IDID INVERTER TRIPPED	PERS OPENED AC OUTPUT BRKR MISTAKENLY
B	DE3	016137	016	A	CP						THE 3 DIR VITAL BUS INVERTER FAILED	DIELECTRIC OF INPUT FILTER CAP BROKE DOWN
B	DE3	027697	013	A	FS	E355				C	ICS POWER LOST DUE TO INVERTER(KI) FAILED	BLOW FUSES
B	DE3	031182A	008	B	FS	E355					LOST AC VITAL INST BUS DUE TO INVERTER FAILURE	BLOWN FUSES
B	DE3	031182B	008	B	FS	E355					LOST AC VITAL INST BUS DUE TO INVERTER FAILURE	BLOWN FUSES/FAULTY TRANSISTOR
B	DE3	031182C	008	B	TS	E355					INVERTER 3DIB TRIPPED WHEN POWER WAS TRANSFERRED /	TO IT. BYPASS SWITCH POSSIBLY CLOSED.
B	RS1	026111	003	B	UV	W120					S1A VITAL POWER INVERTER FAILED	DESIGN DEFICIENCY IN U.V. COIL
B	T12	021952	021	B	CL	S250					VITAL BUS INVERTER FAILED TO FUNCTN PROPERLY	FAULTY INVERTER CNTRL MODULE AND FUSE
C	CC1	174574	2 2	068	UU					A	RX S/D DUE TO INVERTER DC FEEDFR BREAKER TRIP	CONTRACTOR INADV TRPD OPEN INPUT BREAKER
C	CC2	017009	009	B	FS	E355					B PHASE COMPUTER INVERTER DC INPUT FUSE OPENED	CURRENT SURGE DUE TO SWITCHING OPERATION
C	CC2	187012	2 7	055	FS	E355					#22 INVERTER OUTPUT FUSE BLEW	SUSPECTED CAUSE--IMPROPER FUSE TYPE USED

ADDITIONAL INFORMATION CONTAINED IN INVERTER ONE-LINE DESCRIPTIONS

PLANT CONTROL OR NSIC NUMBER	NSIC	UNIT NUMBER	MANUFACTURE	MODE DESCRIPTION	CAUSE DESCRIPTION
C FC1 020085	042 B	VP S250	D CHANNEL INSTRUMENT INVERTER FAILED	CONSTANT VOLTAGE REGULATOR FAILED	
C M12 026871	001 B	CP S250	INVERTER NO. 4 FAILED	CAPACITORS AND OSCILLATOR BOARD FAILED	
C M12 172670*	1 5 002	FS	FUSES IN INVERTERS 2 AND 6 BLEW	SHORTED TEST LEAD FAILED CIRCUIT	
C M12 175402*	1 9 024	FS S250	LOSS OF 120VAC (VIAC-1) BLOWS FUSES IN ESFAS CABIN	POOF LEAK SHORTED 2 INVERTERS #5,6	
C S11 015004	026 B	CS G195	1C STATIC INVERTER FAILED FOR AC INST, 120 VOLT	FAILED OSCILLATOR CIRCUIT BOARD	
C S11 175205A	1 9 026	UU	OUTPUT BRKR OF 1A STATIC INVERTER OPENED	NO APPARENT CAUSE COULD BE FOUND	
C S11 175205B	1 9 026	CS	1A STATIC INVERTER OUTPUT BREAKER OPENED	OSCILLATOR CIRCUIT BOARD REPLACED	
C S11 181486	2 5 068	UU G195	1A INVERTER OUTPUT BRK OPENED 1/4 120VAC BUS LOST	NO APPARENT CAUSE OF FAILURE	
C S11 181729	2 5 067	FB A499	1A INVERTER OUTPUT BRK OPENED 1/4 120VAC BUS LOST	DEFECTIVE OUTPUT FREQUENCY MODULE	
C S11 181038	2 4 071	CS	1A INVERTER OUTPUT BRK OPENED 1/4 120VAC BUS LOST	FREQUENCY OSCILLATOR HAD TRIPED	
W BV1 014692	029 B	CP S379	INVERTER NO. 3 FAILED	OUTPUT FILTER CAPACITOR FAILED	
W BV1 015102	038 B	CP S379	INVERTER NO. 1 FAILED	OUTPUT FILTER CAPACITOR FAILED	
W BV1 015213	044 B	UU S379	INVERTER NO. 3 APPARENTLY FAILED	NO CAUSE GIVEN	
W BV1 016280	074 C	RC S379	VITAL BUS INVERTER NO. 3 FAILED	SCRS AND OUTPUT FUSE FOUND BAD	
W BV1 016360	081 C	UU	INVERTER NO. 2 WAS MOMENTARILY OUT OF SERVICE	OUTPUT WAS SHORTED OUT BY PERSONNEL	
W BV1 017014	093 B	DI	NO. 1 VITAL BUS INVERTER FAILED	1 DIODE AND TWO FUSES FOUND FAILED	
W BV1 023209	002 B	UU	OUTPUT FREQUENCY OF NO. 4 INVERTER OSCILLATING	NO CAUSE GIVEN	
W BV1 025332	006 B	UU S379	NO. 3 VITAL BUS INVERTER FAILED	FAULTY COMPONENTS	
W BV1 027140	038 B	CS	NO. 4 VITAL BUS INVERTER FREQUENCY FOUND SPIKING	FAULTY OSCILLATOR CARD	
W BV1 028012	039 C	UU S379	NO. 4 VITAL BUS INVERTER FAILED. RX TP. P OCCURRED	AND SAFETY INJECTION OCCURRED. NO CAUSE	
W BV1 031239	028 B	FS	PWR LOST TO #4 VITAL BUS INVERTER DUE TO BLOWN //	MAIN PS FUSE. CAUSE UNKNOWN	
W BV1 173454	1 7 015	UU	NO. 3 INVERTER TRIPPED	PERSONNEL MAINTENANCE	
W DC1 017804	022 B	FS W120	#4 INVERTER FAILED, CAUSED RX TRIP & SI	BLOWN FUSE	
W DC1 025643*	022 C	UU S250	TWO VITAL BUS INVERTERS FAILED SIMULTANEOUSLY	PARTS FAILED DUE TO DC SURGE. PERSONNEL	
W DC1 032503	020 B	DI S250	SHORTED DIODE IN CRID IV INVERTER	DIODE FAILED DUE TO NORMAL END OF LIFE	
W DC1 182697	2 7 076	UU 118	AB EMERG DIESEL GENERATOR INVERTER FAILED. SOLID	STATE COMP, XFMR GATE, SHORTING BRD RPLCD	
W DC2 022280	062 B	DI S250	INVERTER FAILURE	DEFECTIVE DIODES AND SCRS	
W DC2 037613	027 B	CP	FAILURE IN 120VAC VITAL BUS (CRID II)	C-2 CAPACITOR FAILED ALSO BLEW A FUSE	

 ADDITIONAL INFORMATION CONTAINED IN INVERTER ONE-LINE DESCRIPTIONS

UNKN PLANT	CONTROL OR NSIC NUMBER	NSIC		SUBC CLASS	SUB BP	M ANU FACT UC R ED RE	SUB CLASS	F L A G G I N G	MODE DESCRIPTION	CAUSE DESCRIPTION
		VOLUME	NUMBER							
W HN1	018775		013	C	UU	W120			STATIC INVERTER FAILED	AMBTENT TEMP 40 DEG C. ABOVE DESIGN
W IP2	022867		031	C	UU	S250			.5KVA STATIC INVERTER FAILD DEENRGZG CONT PRESS //	SAFEGUARDS LOGIC. DEFECTIVE INVERTER
W JF1	021593		030	B	UU	W120			120V VITAL BUS A DEENRGZD WHEN INVERTER A TRIPPED	EXACT CAUSE NOT IDENTIFIED
W JF1	021592		031	B	CP	W120			120VAC VITAL BUS B DEENRGZD WHEN INVERTER 1B TRPD	FAULTY CAPACITOR WAS REPLACED
W JF1	021594		029	B	UU	W120			120VAC VITAL BUS A DEENRGZD WHEN INVERTER A TRPD	EXACT CAUSE NOT IDENTIFIED
W JF1	021591		032	B	CP	W120			120VAC BUS D DEENRGZD WHEN INVERTER 1D TRIPPED	CAPACITOR IN INVERTER FAILED
W JF1	025439		002	B	CH	W120			1B INVERTER TRIPPED (PS FOR 120V VITAL AC)	VARIOUS INTERNAL COMPONENTS FAILED
W JF2	038879		040	B	UU	W120	11		INVERTER 2A TRPD--120VAC VITAL BUS 2A DEENERGIZED	TRANSIENT VOLTAGE SPIKE--CAUSE UNKNOWN
W JF2	173252	1	7	011	FS				INVERTER NO. 2B FAILED	FUSE BLEW IN VOLTAGE REGULATOR
W JF2	176542	1	11	032	UU				INVERTER NO. 26 FAILED CAUSING LOSS OF POWER TO S/	/UB COOLING MONITOR AND H2 MONITOR
W MG1	174673	1	9	052	RC	S250		A	INVERTER EVIA INDP--LOST VITAL INST PWR CAUSD RX//	TRIPS. SCR SHORTING CKT BRD REPLACED
W MG1	174671	1	9	053	CP	S250			STATIC INVERTER EVIA MALFUNC--RHR ISOL VLV CLOSED	3 CAP IN OUTPUT CVT CAP BANK FAILED
W NA1	031217		047	A	FS	S250		A	LOST VITAL BUS 1-III. CAUSE UNKNOWN--POSSIBLY //	VLTG SURGE TO DC/AC INVERTER BLEW 2 FUSES
W NA1	032608		080	B	UU	S250			LOST PWR TO 120VAC VITAL BUS 1-IV	INVERTER SUPPLY BRKR FOUND OPEN
W NA2	037674*		055	C	UU	W121		C	VOLTAGE TRANSIENT THRU VITAL BUS INVERTERS 2-III//	& 2-IV. CAUSE UNKNOWN
W PR1	015104		030	B	TR	S245			NO. 13 INVERTER FAILED (PS TO INSTRUMENT BUS 113)	REGULATING TRANSFORMER ON OUTPUT FAILED
W PR1	017425		008	B	CP	S245			NO. 11 INVERTER FAILED	CAP ON OUTPUT SOLA TRANSFORMER FAILED
W PR2	032962		029	B	TR	S245			#23 INVERTER FAILED DEENRGZG PANEL 213	CONSTANT VOLTAGE TRANSFORMER FAILED
W SA1	022426		051	B	DI				VITAL INST BUS INVERTER 1A FUSES BLOWN	FAILD DIODE IN CNTRL CKT BRD
W SA1	022420		057	B	CL				1A INVEPTER FAILD--FAILD ELECTRONIC COMP ON MASTER	//LOGIC CKT BRD CAUSD BLOWN FUSES
W SA1	023232		073	C	TR			A	LOST 1B VITAL INSTRUMENT BUS	OUTPUT XFRMR IN SUPPLY INVERTER FAILED
W SA1	023230		076	B	UU	L045			INVERTER DIDN'T SWITCH TO B/U BATTERY SUPPLY	NO CAUSE COULD BE DETERMINED
W SA1	023513		074	A	UU			A	1B VITAL INSTRUMENT BUS INVERTER FAILED	NO CAUSE. INADVERTANT SI OCCURRED
W SA1	027523		072	B	CF		74		LOST METEOROLOGICAL INSTR/PWR SUP INVERTER FAILED	SEIZED MOTOR BEARINGS IN COOLING FAN
W SA1	030231		006	B	SW		17		LOST METEOROLOGICAL INSTRUMENT	INVERTER HAD MAN NOT AUTO SW--MFG ERROR
W SA1	039242		107	B	UU			A	INADV SI DUE TO LOSS OF VITAL BUS 1A INVERTER	CAUSE UNKNOWN
W SA1	039344		110	B	UU			A	INADV SI DUE TO LOSS OF 1A VITAL INST BUS INVERTER	CAUSE UNKNOWN
W SA2	181466	2	5	145	PS	S250			INVERTER PS FAILED CAUSD P-250 COMPUTER TO SHUTDWN PS	PROBLEM FROM FAILED OSCILLATOR CKT BRD

ADDITIONAL INFORMATION CONTAINED IN INVERTER ONE-LINE DESCRIPTIONS

N O T E	P L A N T	CONTROL OR NSIC NUMBER	NSIC		R E P O R T T Y P E	M A N U F A C T U R E R	C O U N T E R	R E M A R K S	F L A G G I N G	M O D E D E S C R I P T I O N	C A U S E D E S C R I P T I O N
			V O L U M E	N U M B E R							
	W SE1	032879A	166	B	UU	S379				VITAL INVERTER 2-IV OUTPUT BRKR TRIPPED	CAUSE NOT IDENTIFIED
	W SE1	032879B	166	B	SW	S379				VITAL INVERTER 2-IV OUTPUT BRKR TRIPPED	BAD AUX SW ON THE K11 RELAY
	W SE1	032977	169	B	CC	S379	8			VITAL INVERTER 2-III OUTPUT BRKR TRIPPED	FIRING CKT CLOCK CARD R85 FAILED
	W SE1	033295	185	B	FS		2			VITAL INVERTER 1-I OUTPUT BRKR TRIPPED	INVERTER 1-I OUTPUT FUSES HAD BLOWN
	W SE1	033296*	187	B	UU	S379				9 VITAL INVERTER 2-III FAILURES BETWEEN 11-9-80&11-23-80.	NO CAUSES GIVEN
	W SE1	036667	011	A	UU	S250	5			CONDUIT/CABLE SUPPLYING PWR TO VITAL INVERTER 1-I/	WAS CUT. CONSTRUCTION PERSONNEL ERROR
	W S01	015998		B	PS	W120				VITAL BUS #1 TRANSFERRED TO B/U POWER SOURCE	COMPONENT FAILURE IN #1 INVERTER. NO CAUSE
	W S01	018440	008	B	CP	G080	8			DC INPUT FUSE OF UPS INVERTER OPENED	CAPACITORS IN BANKS C-4,C-6 HAD FAILED
	W S01	020878A	003	A	CP					"A" INVERTER FAILED (ONE OF TWO FOR CSAS LOGIC)	CAPACITOR AND CHOKE IN OUTPUT SIDE FAILED
	W S01	020878B	003	A	UU		1			"B" INVERTER FOR CSAS TRIPPED ON TRANSFER	TRANSFER SWITCH WAS TOO FAST
	W S01	021743	007	B	CP	G080				DC INPUT FUSE FOR MOV-850C INVERTER OPENED	GE CAPACITOR ZBF5108 AND SCR-2 FAILED
	W S02	179196	2	1	063	IN		A		FAILED VITAL BUS-3 INVERTER/TURB RUMBACK, RX, TRP, SI	STATION BATT INVERTER INDUCTOR SHORTED
	W TR1	033305	025	B	UU		16	C		3 VITAL PREFERRED INSTR BUSES ON SAME EMERG TRAIN	#4 INVERTER APPARENTLY FAILED--NO CAUSE
	W TR1	039071	025	B	RE	G273				LOST PREFERRED INST BUS Y11--STATIC INVERTER OUTPT	//CURRENT SENSG RELAY FAILED. NAT'L EOL
	W TR1	172719	1	5	005	UU		A		INVERTER NO. 2 FAILED. CAUSED INADVERTANT SI	NO CAUSE GIVEN.
	W Z11	025150	004	C	UU	W120				INV 114 TRPD. FOUND 2.5KVA INV SECTION FAULTY.	LOOSE CONTACT IN DC BREAKER
	W Z11	026916	057	B	TR	W120	4			INSTRUMENT INVERTER 114 TRIPPED	5KVA TRANSFORMER REPLACED
	W Z11	037631	022	C	TR	S245		A		INST INVERTER 114 FAILED	XFRMR SHORTED BY HI INVERTER CIRC CURRENT
	W Z12	020356	053	B	TR	S240				INVERTER NO. 213 FAILED (INSTRUMENT INVERTER)	SLAVE TRANSFORMER FAILED BY OVERHEATING
	W Z12	031066	016	B	RC	W120				INSTRUMENT INVERTER 214 FAILED	SCR FAILED IN SLAVE UNIT OF INVERTER
	W Z12	037995	015	C	TR	S245		A		LOST POWER TO INVERTER 213	XFRMR SHORTD BY HI INVERTER CIRC CURRENT
	G BF1	038008	039	B	CL	L295				ALARM PANEL XA-55-8E INVERTER INOPERABLE	FAILED INVERTER CONTROL CARD
	G BF3	027049	015	B	AC	L295				ANNUNC PANEL XA-55-20B INOP INVERTER PRINTED CKT//	CARD FAILED DUE TO NATURAL AGING
	G BP1	022658	040	B	FS	T248				BLOWN FUSE IN POWER SUPPLY INVERTER	XIENT SUP VLTG PROBLEM--NEEDS DUMMY LOAD
	G BP1	025806	015	B	FS	T248				CONTAINMENT VACUUM RELIEF LOOP POWER SUPPLY INVER/	TER FOUND INOPERABLE. BLOWN PS FUSE
	G BP1	026880	021	B	FS	T248				CNTNMNT VACUUM RELIEF PS INVERTER FUSE BLEW	SUSCEPTIBLE TO INPUT SURGE
	G BP1	037801A	013	B	PS		3			RX DEPRESSURIZATION LOOP B INVERTER FOUND INOP.	DEFECTIVE ELECTRONIC COMPONENTS
	G BP1	037801B	013	B	PS		3			RX DEPRESSURIZATION LOOP B INVERTER FOUND INOP.	DEFECTIVE ELECTRONIC COMPONENTS

 ADDITIONAL INFORMATION CONTAINED IN INVERTER ONE-LINE DESCRIPTIONS

UNION	PLANT	CONTROL OR NSIC NUMBER	NSIC		SUB	REPORT TYPE	SUB	MANUFACTURE	REVISION	DATE	FACILITY	MODE DESCRIPTION	CAUSE DESCRIPTION
			VOLUME	NUMBER									
G	BR1	017085*		010	B	UU	T248				A	CNTRL VLTG PS SET BELOW EQUALZG VLTG CAUSED TRIP	I&C TECH ERROR IN EQUALZG PLANT BATTERIES
G	BR2	030364		007	B	UU	T248					STM LEAK DETCTN "A" LOGIC INVERTER'S HV TRPD LOW	NO CAUSE GIVEN
G	CO1	037646		010	B	CF	E355					STATIC INVERTER 1A'S SPIKE SUPPRESSOR CAP FAILED	AGED ELECTROLYTIC CAP/IMPROPR OP PROCEDUR
G	EN1	016840		093	A	CP	T248					RCIC PS INVERTER E51-K603 FAILED	SHORTED CAPACITOR IN OUTPLT TRANSFORMER
G	EN1	033842		092	B	UU	E355				C	B LPCI INVERTER TRPD THUS B LOOP OF RHR INOPERABLE	HI AMBIENT TEMPERATURE IN INVERTER ROOM
G	EN1	032376		102	B	UU	E355					"B" LPCI INVERTER TRIPPED	HI AMBIENT TEMPERATURE IN INVERTER ROOM
G	EN1	037947A		052	B	SW	E355					B LPCI INVERTER R44-5003 TRPD ON HIGH TEMPERATURE	DEFECTIVE SWITCH IN INVERTER LEG
G	EN1	037947D		052	B	UU	E355					B LPCI INVERTER 2R44-5003 TRIPPED	UNKNOWN CAUSE
G	EN1	037947B		052	B	SW	E355					B LPCI INVERTER R44-5003 TRIPPED	DFCTV SWITCHES IN INVERTER LEGS
G	EN1	037947C		052	B	SW	E355					B LPCI INVERTER R44-5003 TRIPPED	DEFECTIVE SWITCH IN INVERTER LEG
G	EN1	177682	1	12	082	CP				72		"A" LPCI INVERTER FAILED. OUTPUT FILTER CAPACITORS	/R INSULATION SPAT, FAILED FUSES & CAP'S
G	EN2	022024		004	B	FB	E355					STATIC INVERTER(2R44-5002) OUTPUT BREAKER TRIPPED	FREQUENCY CARD(EXIDE PART #A13A9) FAILED
G	EN2	023200		077	B	PC	E355					STATIC INVERTER (2R44-5003) DC OUTPUT BRKR TRIPPED	AC/DC PROTECTION CARD(A13A12) FAILED
G	EN2	027611		122	B	RE						"B" LPCI INVERTER TRIPPED	FAILED RELAY IN INVERTER FAILED
G	EN2	027848A		135	B	FS	T248					"A" PS FOR RCIC STEAM LEAK DETECTION FAILED	FUSES BLEW DUE TO CURRENT SURGE
G	EN2	027848B		135	B	FS	T248					"B" PS FOR RCIC STEAM LEAK DETECTION FAILED	FUSES BLEW DUE TO CURRENT SURGE
G	EN2	030041		003	B	UU	T248					HPCI AUTO FLD CNTRL PWR INVERTER'S HV TRPD LOW	INSTRUMENT DRIFT
G	EN2	030241		011	B	CP	T248					RCIC REMOTE FLD CNTRL LOOP POWER INVERTER TRIPPED	DFCTV INPUT FILTER CAPACITORS
G	EN2	030980		071	B	UU	T248					REC'D RCIC LEAK DETECTION LOGIC PWR FAILURE ALARM	COMPONENT FAILURE OF INVERTER
G	EN2	036952		038	B	CL	E355					"A" LPCI INVERTER 2R44-5002 TRPD	LOGIC FAILURE CAUSED TRIP
G	EN2	038501		085	B	VR	E355				8	B LPCI INVERTER 2R44-5003 TRPD	GATE FIRING MODULE VOLTAGE REGULATOR FAIL
G	EN2	171785	1	3	117	CC						B LPCI INVERTER (2R44-5003) GAVE HI PHASE CURRENTS	FAILED: GATE FIRING MODULE
G	EN2	178916	2	1	114	CF						INVERTER(2R44-5003) TRPD DUE TO LEG FAN FAILURE	#4 INVERTER LEG FAN BEARING FAILED
G	FP1	013966		001	A	RS						RCIC STATIC INVERTER(12-801A) FAILED	LEAD TO WIRE WOUND RESISTOR TOUCHED W/STR
G	FP1	015625		053	B	UU	T248					HPCI INVERTER 23-INV-79 TRIPPED AND WOULD NOT RES/	/TART. NO CAUSE FOUND, INVERTER REPLACED
G	FP1	021432		040	B	PC	E355					LPCI INVERTER/CHARGER TRPD LOST B LPCI INDPNDNT //	PWR. FAILED SCR'S IN INVERTER/CHARGER
G	FP1	030177		015	B	CP	G080					LPCI INDPNDNT PS "A" INVERTER TRIPPED	INVERTER CNTRL CKT CAPACITORS FAILED
G	FP1	032373A		072	B	CL	E355					"B" LPCI INVERTER TRIPPED	AC VOLTAGE/CURRENT CNTRL LOGIC CAPD A12

ADDITIONAL INFORMATION CONTAINED IN INVERTER ONE-LINE DESCRIPTIONS

PLANT NUMBER	CONTROL OR NSIC NUMBER	NSIC NUMBER	RECORD NUMBER	RECORD TYPE	RECORD SUMMARY	MODE DESCRIPTION	CAUSE DESCRIPTION
G FPI 012373B		072 B	CL E355		"B" LPCI INVERTER TRIPPED		INVERTER LEG GATE FIRE CNTRL CKT FAILED
G FPI 012373C		072 B	AC E355		"B" LPCI INVERTER TRIPPED		ANNUNCIATOR/CONTROL CARD 2 FAILED
G FPI 012373D		072 B	AC E355		"B" LPCI INVERTER TRIPPED		ANNUNCIATOR/CONTROL CARD 2 FAILED
G FPI 0123718		075 B	CL E355	96	"B" LPCI INVERTER TRIPPED		LOGIC CARD A2 FAILED
G FPI 0137379		041 B	CP E355	24	LPCI MOV INDEPENDENT POWER SUPPLY INVERTER A TRPD		SHORTED CAP IN GATE FIRING MODULE "A1"
G FPI 181727		2 5	CL E355		"A" LPCI INVERTER TRIPPED DUE TO ELECTRICAL FAILURE		GATE TIMING CONTROL CARD FAILED
G P82 017210		013 B	UU T248		RCIC STATIC INVERTER 2-13-90 TRIPPED WITHOUT AUTO/		"A" MATIC RESET. NO CAUSE FOUND
G P82 021247		026 B	TS T248	17	INVERTER FAILD POWERS RCIC'S CNTRLR & INSTRMNTN		DFCTV TRANSISTOR IN AUTO-RESET CIRCUIT
G P82 021248		022 B	UU T248	7	HPCI STATIC INVERTER TRIPPED		NO FAULT COULD BE FOUND WITH THE INVERTER
G P11 038673		050 A	CP T248		FAILED INVERTER CAUSED GROUND FAULT ON 125VDC SYS		FAILED CAP IN DC/AC INVERTER
G VY1 015519		025 B	SW E355		A 250 KVA UPS OUTPUT BREAKER TRIPPED		NOISE IN AN UNUSED STATIC SWITCH
G VY1 015965		034 B	FS E355		MOTOR CONTROL CENTER 89A LOST POWER DUE TO "A" UP/		"S" TRIPPED. BLOWN INVERTER LEG FUSE
G VY1 016272		040 B	CL E355		UPS-1B TRIPPED WHEN OPENING VALVE RHR-278		POSSIBLE LOGIC PROBLEM
G VY1 016485		043 B	VR E355		UPS-1B TRIPPED WHILE TESTING RHR-278 VALVE		VOLTAGE REGULATOR AND SYSTEM LOGIC PROBLEM
G VY1 016500*		046 A	DB E355		UPS-1A AND UPS-1B TRIPPED WHILE TESTING LPCI VALVE		1A HAD FAILED DRIVER BOARD, 1B HAD BAD REG
G VY1 021542		012 B	FS E355		250KVA UNINTERRUPTIBLE PWR SUPPLY TRIPPED		BLOWN INVERTER LEG FUSE(2A18F2)
G VY1 021768		013 B	UU E355		LOSS OF VLTG TO MCC-89B		UNINTERRUPTIBLE POWER SUPPLY(UPS-1B) TRPD
G VY1 021842		019 B	PC E355		250KVA UPS TRPD DUE TO INVERTER LEG FUSE(2A18F2)///		BLEN WHEN GATE INTRFC/PRICIN LOGIC MALFUN
G VY1 032080		024 B	FS E355	5	LOGIC PS BRD FAILED. 250KVA UNINTERRUPTIBLE PS //		TRPD DUE TO BLOWN LOGIC PS FUSE
G VY1 173401		1 7	002 CP		UPS-B AC GROUND AND BLOWN FUSE ALARM WAS RECEIVED		SUPPRESSION CAPACITOR FAILED BLOWING FUSE
G VY1 172682		1 6	005 CP		UPS "B" TRAIN TRIPPED		SHORTED CAPACITOR DUE TO AGE

APPENDIX I
LISTING OF LER NUMBERS

PLANT	LER NUMBER	EVENT DATE	CONTROL	PLANT	LER NUMBER	EVENT DATE	CONTROL
			OR NSIC NUMBER				OR NSIC NUMBER
B CR3	77-020	030277	017321	W DC1	77-022	042177	017804
B CR3	77-115	090277	019021	W DC1	79-022	032379	025643*
B CR3	77-137	102677	019523	W DC1	80-020	033180	032503
B CR3	78-028	042578	021210	W DC1	82-076	082382	182697
B CR3	78-042	081978	022361	W DC2	78-062	061378	022280
B CR3	81-021	041181	037006	W DC2	81-027	061281	037613
B CR3	81-046	071481	038100	W HN1	77-013	071977	018775
B DB1	79-107	110579	027478	W IP2	78-031	102278	022867
B DB1	80-064	082280	032367A	W JF1	78-030	022178	021593
B DB1	80-064	082380	032367B	W JF1	78-031	022378	021592
B DB1	80-081	111280	033270	W JF1	78-029	050978	021594
B DB1	81-066	101881	039149	W JF1	78-032	053078	021591
B DB1	82-020	040982	173542	W JF1	79-002	011679	025439
B DB1	82-029	060882	175395	W JF2	81-040	092381	038879
B DEF1	81-002	011881	036123	W JF2	82-011	031682	173252
B DEF1	81-003	012581	036241A	W JF2	82-032	072282	176542
B DEF1	81-003	012581	036241B	W MG1	82-052	061382	174673
B CF1	81-003	012581	036241C	W MG1	82-053	062482	174671
B DEF3	76-016	091276	016137	W NA1	80-047	052380	031217
B DEF3	79-013	111079	027697	W NA1	80-080	090880	032608
B DEF3	80-008	050780	031182A	W NA2	81-055	060381	037674*
B DEF3	80-008	050980	031182B	W PR1	76-030	061576	015104
B DEF3	80-008	051680	031182C	W PR1	77-008	031477	017425
B RS1	79-003	042279	026111	W PR2	80-029	100480	032962
B TI2	78-021	032978	021952	W SA1	78-051	082178	022426
C CC1	82-068	110982	179674	W SA1	78-057	082778	022420
C CC2	77-009	010677	017009	W SA1	78-073	112778	023232
C FC1	82-055	122882	193012	W SA1	78-076	120878	023230
C MI2	77-042	122577	020085	W SA1	79-074	012679	023513
C MI2	79-001	010579	026871	W SA1	79-072	110579	027523
C MI2	82-002	010682	172670*	W SA1	80-006	012380	030231
C SS1	82-024	060682	175402*	W SA1	81-107	102981	039242
C SS1	76-026	052976	015004	W SA1	81-110	110681	039344
C SS1	82-026	062282	175205A	W SA2	82-145	112982	181466
C SS1	82-026	062382	175205B	W SE1	80-166	092780	032879A
C SS1	82-068	122082	181486	W SE1	80-166	100180	032879B
C SS1	82-067	122582	181729	W SE1	80-169	101480	032977
C SS1	82-071	123082	181038	W SE1	80-185	111180	033295
W BV1	76-029	051076	014672	W SE1	80-187	111880	033296*
W BV1	76-038	052776	015112	W SE1	81-011	013081	036667
W BV1	76-044	062376	015213	W SO1	76-	082376	015998
W BV1	76-074	102276	016280	W SO1	77-008	061477	018440
W BV1	76-081	110676	016360	W SO1	78-003	031578	020878A
W BV1	76-093	121576	017014	W SO1	78-003	031578	020878B
W BV1	78-002	010278	023209	W SO1	78-007	060778	021743
W BV1	79-006	012079	025332	W SU2	82-063	101082	179196
W BV1	79-038	091879	027140	W TR1	80-025	111280	033305
W BV1	79-039	092079	028012	W TR1	81-025	100481	039071
W BV1	80-028	050480	031239	W TR1	82-005	011682	172719
W BV1	82-015	041482	173454	W ZI1	79-004	011279	025150

PLANT	LER NUMBER	EVENT DATE	CONTROL OR NSIC NUMBER	PLANT	LER NUMBER	EVENT DATE	CONTROL OR NSIC NUMBER		
								PLANT	LER NUMBER
W	ZI1	79-057	081379	026916	G	EN2	81-038	042181	036952
W	ZI1	81-022	052861	037631	G	EN2	81-085	090481	038501
W	ZI2	77-053	082077	020356	G	EN2	81-117	112681	171785
W	ZI2	80-016	041180	031066	G	EN2	82-114	100182	178916
W	ZI2	81-015	050781	037995	G	FP1	76-001	010376	013966
G	BF1	81-039	070481	038008	G	FP1	76-053	081576	015625
G	BF3	79-015	091579	027049	G	FP1	78-040	051878	021432
G	BP1	78-040	091078	022658	G	FP1	80-015	012380	030177
G	BP1	79-015	031979	025806	G	FP1	80-072	081280	032373A
G	BP1	79-021	061679	026880	G	FP1	80-072	082280	032373B
G	BP1	81-013	061761	037801A	G	FP1	80-072	090580	032373C
G	BP1	81-013	062381	037801B	G	FP1	80-072	090680	032373D
G	BK1	77-010	011777	017085*	G	FP1	80-075	091380	032718
G	BR2	80-007	020480	030364	G	FP1	81-041	051581	037379
G	CD1	81-010	050581	037646	G	FP1	82-056	121582	181727
G	EN1	76-093	112776	016840	G	PB2	77-013	021977	017210
G	EN1	80-092	073180	033842	G	PB2	78-026	041978	021247
G	EN1	80-102	082180	032376	G	PB2	78-022	042478	021248
G	EN1	81-052	061081	037947A	G	PI1	81-050	091281	038673
G	EN1	81-052	061681	037947D	G	VY1	76-025	081376	015519
G	EN1	81-052	061881	037947B	G	VY1	76-034	092076	015965
G	EN1	81-052	062181	037947C	G	VY1	76-040	101976	016272
G	EN1	82-082	091182	177682	G	VY1	76-043	111876	016485
G	EN2	78-004	071778	022024	G	VY1	76-046	112976	016500*
G	EN2	78-077	120678	023200	G	VY1	78-012	053078	021542
G	EN2	79-122	111779	027611	G	VY1	78-013	061978	021768
G	EN2	79-135	121979	027848A	G	VY1	78-019	062978	021842
G	EN2	79-135	122079	027848B	G	VY1	80-024	071880	032080
G	EN2	80-003	011760	030041	G	VY1	82-002	020682	173401
G	EN2	80-011	020280	030241	G	VY1	82-005	022382	172882
G	EN2	80-071	042480	030980					

APPENDIX J
RESULTS OF THE INVERTER LER RATE ESTIMATIONS

CONTENTS

Essential and LPCI Static Inverters—Inoperable—Command Faults Excluded	J-001
Essential Static Inverters—Inoperable—Command Faults Excluded	J-006
Low Pressure Coolant Injection Static Inverters—Inoperable—Command Faults Excluded	J-011

BABCOCK&WILCOX

ESSENTIAL AND LPCI STATIC INVERTERS-INOP-COMMAND FAULTS EXCLUDED

PLANT	COMPONENT		POPULATION		OPERATING FAILURE RATE (FAILURES/HOUR)
	POPULATION	HOURS	FAILURES	HOURS	
AR1	5	61368	0	306840	7.4E-07
CR3	5	52272	6	261360	2.3E-05
DB1	6	47232	7	283392	2.5E-05
DE1	7	61368	3	429576	7.0E-06
DE2	7	61368	0	429576	5.3E-07
DE3	7	61368	5	429576	1.2E-05
RS1	4	61368	1	245472	4.1E-06
TI1	4	28392	0	113568	2.0E-06
TI2	5	8784	1	43920	2.3E-05
		TOTALS	23	2543280	AVG. 9.0E-06

J-001

COMBUSTION ENGINEERING

ESSENTIAL AND LPCI STATIC INVERTERS-INOP-COMMAND FAULTS EXCLUDED

PLANT	COMPONENT		POPULATION		OPERATING FAILURE RATE (FAILURES/HOUR)
	POPULATION	HOURS	FAILURES	HOURS	
AR?	5	35712	0	178560	1.3E-06
CC1	5	61368	0	306840	7.4E-07
CC2	5	53352	2	266760	7.5E-06
FC1	6	61368	1	368208	2.7E-06
MI2	6	61368	5	368208	1.4E-05
MY1	5	61368	0	306840	7.4E-07
PA1	4	61368	0	245472	9.3E-07
SL1	5	58680	6	293400	2.0E-05
SO2	5	3816	0	19080	1.2E-05
		TOTALS	14	2353368	AVG. 5.9E-06

J-002

WESTINGHOUSE

ESSENTIAL AND LPCI STATIC INVERTERS-INOP-COMMAND FAULTS EXCLUDED

PLANT	COMPONENT		POPULATION		HOURS	POPULATION		HOURS	OPERATING FAILURE RATE (FAILURES/HOUR)
	POPULATION	HOURS	FAILURES	HOURS					
BVI	4	58248	8	232992				3.4E-05	
DC1	4	61368	5	245472				2.0E-05	
DC2	4	42192	2	169768				1.2E-05	
HNL	2	61368	1	122736				8.1E-06	
IP2	2	61368	0	122736				1.1E-06	
IP3	3	59064	0	177192				1.3E-06	
JF1	7	47304	5	331128				1.5E-05	
JF2	7	14944	3	101808				2.9E-05	
KEL	7	61368	0	429876				5.3E-07	
MGL	6	12264	2	73584				2.7E-05	
NA1	5	41568	2	207840				9.6E-06	
NA2	5	22392	0	111960				2.0E-06	
PR1	6	61368	2	368208				5.4E-06	
PR2	6	61368	1	368208				2.7E-06	
PT1	2	61368	0	122736				1.9E-06	
PT2	2	61368	0	122736				1.9E-06	
RG1	2	61368	0	122736				1.9E-06	
RO2	2	61368	0	122736				1.9E-06	
SA1	4	53088	7	212352				3.3E-05	
SA2	4	21024	1	84096				1.2E-05	
SE1	4	21840	1	87360				1.1E-05	
SE2	4	21840	12	87360				1.4E-04	
SM1	6	1704	0	10224				2.2E-05	
SOL	3	61368	2	184104				1.1E-05	
SUI	3	61368	0	184104				1.2E-06	
SU2	3	61368	1	184104				5.4E-06	
TRI	5	61368	3	306840				9.8E-06	
TU3	2	61368	0	122736				1.9E-06	
TU4	2	61368	0	122736				1.9E-06	
ZI1	4	61368	2	245472				8.1E-06	
ZI2	4	61368	3	245472				1.2E-05	
		TOTALS	63	5630112				AVG. 1.1E-05	

GENERAL ELECTRIC

ESSENTIAL AND LPCI STATIC INVERTERS-INOP-COMMAND FAULTS EXCLUDED

PLANT	COMPONENT		POPULATION		OPERATING FAILURE RATE (FAILURES/HOUR)
	POPULATION	HOURS	FAILURES	HOURS	
BR1	2	54624	0	109248	2.1E-06
BR2	2	61368	0	122736	1.9E-06
CO1	2	61368	1	122736	8.1E-06
EN1	3	48008	8	144024	5.6E-05
EN2	3	39408	7	118224	5.9E-05
FP1	2	46152	9	92304	9.8E-05
GG1	6	3672	0	22032	1.0E-05
LS1	1	4656	0	4656	4.9E-05
PB2	1	61368	0	61368	3.7E-06
PB3	1	61368	0	61368	3.7E-06
SQ1	2	2712	0	5424	4.2E-05
VY1	2	56088	12	112176	1.1E-04
		TOTALS	37	976296	AVG. 3.8E-05

J-004

FINAL STATISTICS

ESSENTIAL AND LPCI STATIC INVERTERS-INOP-COMMAND FAULTS EXCLUDED

OPERATING
FAILURE RATE
(FAILURES/HOUR)

BAB.SWIL.	1.4
	9.0E-06
	1.5
COMB.ENG.	1.6
	5.9E-06
	1.7
WESTINGH.	1.2
	1.1E-05
	1.2
PAR'S	1.2
	9.5E-06
	1.2
GE (BMR'S)	1.3
	3.6E-05
	1.3
OVERALL	1.2
	1.2E-05
	1.2

X.X - UPPER 95% CONFIDENCE MULTIPLIER

Y.YE-YY - LER RATE ESTIMATE

Z.Z - LOWER 5% CONFIDENCE DIVISOR

J-005

BABCOCK&WILCOX

ESSENTIAL STATIC INVERTERS-INOOPERABLE-COMMAND FAULTS EXCLUDED

PLANT	COMPONENT		POPULATION		OPERATING FAILURE RATE (FAILURES/HOUR)
	POPULATION	HOURS	FAILURES	HOURS	
ARI	5	61368	0	306840	7.4E-07
CR3	5	52272	6	261360	2.3E-05
DB1	6	47232	7	283392	2.5E-05
DE1	7	61368	3	429576	7.0E-06
DE2	7	61368	0	429576	5.3E-07
DE3	7	61368	5	429576	1.2E-05
RS1	4	61368	1	245472	4.1E-06
T11	4	28392	0	113568	2.0E-06
T12	5	8794	1	43920	2.3E-05
		TOTALS	23	2543280	AVG. 9.0E-06

J-006

COMBUSTION ENGINEERING

ESSENTIAL STATIC INVERTERS--INOPERABLE--COMMAND FAULTS EXCLUDED

PLANT	COMPONENT		POPULATION		OPERATING FAILURE RATE (FAILURES/HOUR)
	POPULATION	HOURS	FAILURES	HOURS	
AR2	5	35712	0	178560	1.3E-06
CC1	5	61368	0	306840	7.4E-07
CC2	5	53352	2	266760	7.5E-06
FC1	6	61368	1	3068208	2.7E-06
M12	6	61368	5	3068208	1.4E-05
MY1	5	61368	0	306840	7.4E-07
PAL	4	61368	0	249472	9.3E-07
SL1	5	58680	6	293400	2.0E-05
SO2	5	3616	0	19080	1.2E-05
TOTALS			14	2353368	5.9E-06

J-007

WESTINGHOUSE

ESSENTIAL STATIC INVERTERS-INOPERABLE-COMMAND FAULTS EXCLUDED

PLANT	COMPONENT		POPULATION		OPERATING FAILURE RATE (FAILURES/HOUR)
	POPULATION	HOURS	FAILURES	HOURS	
BV1	4	58248	8	232992	3.4E-05
DC1	4	61368	5	245472	2.0E-05
DC2	4	42192	2	168768	1.2E-05
HN1	2	61368	1	122736	8.1E-06
IP2	2	61368	0	122736	1.9E-06
IP3	3	59064	0	177192	1.3E-06
JF1	7	47304	5	331128	1.5E-05
JF2	7	14544	3	101904	2.9E-05
KE1	7	61368	0	429576	5.3E-07
MG1	6	12264	2	73584	2.7E-05
NA1	5	41568	2	207840	9.6E-06
NA2	5	22392	0	111960	2.0E-06
PR1	6	61368	2	368208	5.4E-06
PR2	6	61368	1	368208	2.7E-06
PT1	2	61368	0	122736	1.9E-06
PT2	2	61368	0	122736	1.9E-06
RG1	2	61368	0	122736	1.9E-06
RO2	2	61368	0	122736	1.9E-06
SA1	4	53088	7	212352	3.3E-05
SA2	4	21024	1	84096	1.2E-05
SE1	4	21840	1	87360	1.1E-05
SE2	4	21840	12	87360	1.4E-04
SM1	6	1704	0	10224	2.2E-05
SO1	3	61368	2	184104	1.1E-05
SU1	3	61368	0	184104	1.2E-06
SU2	3	61368	1	184104	5.4E-06
TR1	5	61368	3	306840	9.8E-06
TU3	2	61368	0	122736	1.9E-06
TU4	2	61368	0	122736	1.9E-06
ZI1	4	61368	2	245472	8.1E-06
ZI2	4	61368	3	245472	1.2E-05
		TOTALS	63	5630112	AVG. 1.1E-05

GENERAL ELECTRIC

ESSENTIAL STATIC INVERTERS-INDOPERABLE-COMMAND FAULTS EXCLUDED

PLANT	COMPONENT		HOURS	POPULATION		OPERATING FAILURE RATE (FAILURES/HOUR)
	POPULATION	HOURS		FAILURES	HOURS	
BRI	2	54624	0	107248	2.1E-06	
BRI	2	61368	0	122736	1.9E-06	
COI	2	61368	1	122736	8.1E-06	
ENI	1	61368	0	61368	3.7E-05	
ENZ	1	39408	0	39408	5.8E-06	
GGI	6	3672	0	22032	1.0E-05	
LSI	1	4656	0	4656	4.9E-05	
PBI	1	61368	0	61368	3.7E-06	
PBI	1	61368	0	61368	3.7E-06	
SOI	2	2712	0	5424	4.2E-05	
TOTALS			1	610344	1.6E-06	

J-009

FINAL STATISTICS

ESSENTIAL STATIC INVERTERS-UNOPERABLE-COMMAND FAULTS EXCLUDED -
OPERATING
FAILURE RATE
(FAILURES/HOUR)

8AB-SWIL.	1.4	9.0E-06	1.5
COMB-ENG.	1.6	5.9E-06	1.7
WESTINGH.	1.2	1.1E-05	1.2
PWR'S	1.2	9.15E-06	1.2
GE (BWR'S)	4.7	1.6E-06	19.5
OVERALL	1.12	9.1E-06	1.2

X.X - UPPER 95% CONFIDENCE MULTIPLIER
 Y.YE-YY - LOWER RATE ESTIMATE
 Z.Z - LOWER 5% CONFIDENCE DIVISOR
 J-010

GENERAL ELECTRIC

LPCI STATIC INVERTERS--INOPERABLE--COMMAND FAULTS EXCLUDED

PLANT	COMPONENT		POPULATION		OPERATING FAILURE RATE (FAILURES/HOUR)
	POPULATION	HOURS	FAILURES	HOURS	
EM1	7	41328	8	82656	9.7E-05
EN2	2	39408	7	78816	8.9E-05
FP1	2	46152	9	92304	9.8E-05
VY1	2	56088	12	112176	1.1E-04
		TOTALS	36	365952	AVG. 9.8E-05

J-011

FINAL STATISTICS

LPCI STATIC INVERTER--IMPERABLE--COMMAND FAULTS EXCLUDED
OPERATING
FAILURE RATE
(FAILURES/HOUR)

GE (BWR'S) 9.8E-05
1.3
1.3

OVERALL 9.8E-05
1.3
1.3

X.X - UPPER 95% CONFIDENCE MULTIPLIER
Y.YE-YY - LER RATE ESTIMATE
Z.Z - LOWER 5% CONFIDENCE DIVISOR

J-012

NRC FORM 335 (2-84) NRCM 1102 3201, 3202 SEE INSTRUCTIONS ON THE REVERSE		U.S. NUCLEAR REGULATORY COMMISSION		1. REPORT NUMBER (Assigned by TIDC add Vol. No. if any) NUREG/CR-3867 EGG-2324	
2. TITLE AND SUBTITLE Data Summaries of Licensee Event Reports of Inverters at U.S. Commercial Nuclear Power Plants January 1, 1976 to December 31, 1982			3. LEAVE BLANK		
5. AUTHOR(S) Sharon R. Brown Mike Trojovsky			4. DATE REPORT COMPLETED MONTH: June YEAR: 1984		6. DATE REPORT ISSUED MONTH: August YEAR: 1984
7. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) EG&G Idaho, Inc. P. O. Box 1625 Idaho Falls, ID 83415			8. PROJECT/TASK/WORK UNIT NUMBER		
10. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Division of Risk Analysis and Operations Office of Nuclear Regulatory Research U.S. Nuclear Regulatory Commission Washington, DC 20555			9. FIN OR GRANT NUMBER FIN No. A6393		11a. TYPE OF REPORT Technical
12. SUPPLEMENTARY NOTES			b. PERIOD COVERED (Inclusive dates) January 1, 1976 - December 31, 1982		
13. ABSTRACT (200 words or less) <p>This report describes a computer-based data file developed from Licensee Event Reports (LERs) of inverters in U.S. commercial nuclear power plants for the period January 1, 1976 to December 31, 1982. In addition to the creation of the file, summaries of data contained in the file were made to obtain data for risk assessment and statistical purposes. Gross constant failure rates were estimated for inverters found in selected systems. Explanations, figures, and summary tables of the results are provided.</p>					
14. DOCUMENT ANALYSIS - KEYWORDS/DESCRIPTORS Licensee Event Report Inverters Failure rates				15. AVAILABILITY STATEMENT Unlimited	
16. IDENTIFIERS/OPEN ENDED TERMS				16. SECURITY CLASSIFICATION (This page) Unclassified (This report) Unclassified	
				17. NUMBER OF PAGES	
				18. PRICE	

120555079877 1 1ANIRGLIS
US NRC
ADM-DIV OF TIDC
POLICY & PUB MGT BR-PDR NUREG
W-501
WASHINGTON DC 20555

EG&G Idaho, Inc.
P.O. Box 1625
Idaho Falls, Idaho 83415