										ıc	ENSE	E EVE	NT RE	PORT	(LER)				Al	PFRO	VED	OM8	NO			HISSION
FACILITY					170			_									KET		-	-					PAG	
EDWIN I. HATCH, UNIT 2								0	5	0	0	0	13	16	6	1	OF	011								
TITLE (4)	ESF	Sys	te	em A	ctu	ati	on D	ue	to	Pr	oced	ure :	Inadeq	uacy												
EVENT DATE (5) LER NUMBER (6)							REPORT DATE (7) OT						HER FACILITIES INVOLVED (8)													
MONTH DAY YEAR		R	YEAR SEQUENTIAL REVI				HON	MONTH DAY YEAR			FACILITY NAMES					DOCKET NUMBER(S)										
								1												0	15	0	0	0		
0 8	2   1	8	4	8	4 -	q	2 0	-	0	0	0 9	2 0	8 4							0	15	10	0	0		1 1
OPER	RATING			THIS F	REPOR	T IS 84	BMITTE	D PU	RSUA	NT T	O THE R	EQUIREN	ENTS OF 1	CFR § 70	Check one or mo	ere of th	e folio	owin	g) (11	)						
POWER LEVEL (10)	LEVEL 0 0 0			20.402(b) 20.405(a)(1)(i) 20.405(a)(1)(ii) 20.405(a)(1)(iii) 20.405(a)(1)(iv) 20.405(a)(1)(v)							20.405( 50.36(c 50.73(a 50.73(a 50.73(a	)(1) )(2) )(2)(i) )(2)(ii)		X 50.73(a)(2)(iv) 50.73(a)(2)(vii) 50.73(a)(2)(viii) 50.73(a)(2)(viii)(A) 50.73(a)(2)(viii)(B) 50.73(a)(2)(viii)(B)					73.71(b) 73.71(c) OTHER (Specify in Abstract below and in Text, NRC Form 366A)							
										L	ICENSEE	CONTAC	T FOR THIS	LER (12)												
T.	L. E	lto	n,	Ac	tin	g St	uper	int	enc	len	it of	Regu	lator	y Comp	oliance		AREA 91		DDE			I7			8	5 1
					_	COA	MPLETE	ONE	LINE	FOR	EACH CO	DMPONEN	T FAILURE	DESCRIBE	D IN THIS REP	PORT (1	3)			_						
CAUSE SYSTEM COMPO			MPC	NENT	ENT MANUFAC REPORTABLE TO NPROS							CAUSE	E SYSTEM COMPONEN		т	MAN	UFA				PROS					

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

YES (If yes, complete EXPECTED SUBMISSION DATE)

SUPPLEMENTAL REPORT EXPECTED (14)

On 8/21/84 at approximately 1305 CDT, during the performance of "TURBINE FIRST STAGE PRESSURE PERMISSIVE FT&C" procedure (HNP-2-3010) an unplanned full RPS actuation occurred.

Further investigation revealed that a full RPS actuation occurred because links were opened when the turbine was off line when  ${\rm HNP-2-3010}$  step F.5 was performed.

 ${\rm HNP-2-3010}$  will be revised by 10/1/84 so that it can be performed in any turbine condition without causing a full RPS actuation.

8409280263 840920 PDR ADDCK 05000366 S PDR

IE22/1

MONTH

EXPECTED SUBMISSION DATE (15) YEAR

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-0104 EXPIRES 8/31/86

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6) PAGE (3)
		YEAR SEQUENTIAL REVISION NUMBER
EDWIN I. HATCH, UNIT 2	0  5  0  0  0   3   6	6   6   8   4   - 0   2   0   - 0   0   0   2   OF 0   12

TEXT (If more spece is required, use additional NRC Form 366A's) (17)

This 30 day report is required by 10CFR50.73(a)(2)(iv) due to this event's resulting in automatic actuation of an ESF (RPS).

On 08/21/84 at approximately 1305 CDT, the unit was in shutdown in a recirculation pipe outage when an unplanned full RPS actuation occurred. All the control rods were already inserted so a scram did not occur. Personnel were opening links as listed in Table 1 following step F.5 of the "TURBINE FIRST STAGE PRESSURE PERMISSIVE FT&C" procedure (HNP-2-3010) when a full RPS logic actuation occurred.

Further investigation revealed that this event is due to a procedural inadequacy. The RPS actuation occurred because the turbine was off line when HNP-2-3010 step F.5 was performed. During normal performance of this step when the reactor is below 30% power, opening these links will bypass the turbine stop valves' closure. But when this procedure was most recently performed, the turbine stop valves were already closed. Opening these links removed the bypass and caused an RPS actuation.

HNP-2-3010 will be revised by 10/1/84 to allow for procedure performance in any turbine condition without causing a full RPS actuation.

 Georgia Power Company Post Office Box 439 Baxley, Georgia 31513 Telephone 912 367-7781 912 537-9444



Edwin i. Hatch Nuclear Plant

September 20, 1984 GM-84-819

PLANT E. I. HATCH Licensee Event Report Docket No. 50-366

United States Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Attached is Licensee Event Report No. 50-366/1984-020. This report is required by 10CFR 50.73(a)(2)(iv).

H. C. Nix

General Manager

HCN/TLE/V1z

xc: R. J. Kelly

R. E. Conway

J. T. Beckham, Jr.

P. D. Rice

K. M. Gillespie

Superintendent of Regulatory Compliance

R. D. Baker Control Room Document Control

IE22