

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Dresden Nuclear Power Station Unit 3	DOCKET NUMBER (2) 0 5 0 0 0 2 4 0	PAGE (3) 1 OF 0 2
---	--------------------------------------	----------------------

TITLE (4)
Unit 3 Reactor Scram

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0	8	23	8	4	8	4	0	1	N/A		0 5 0 0 0
0	8	23	8	4	8	4	0	1			0 5 0 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

OPERATING MODE (9) N	20.402(b)	20.406(e)	X	50.73(a)(2)(iv)	73.71(x)
POWER LEVEL (10) 0 1 0 4	20.406(a)(1)(i)	50.38(a)(1)		50.73(a)(2)(v)	73.71(e)
	20.406(a)(1)(ii)	50.38(a)(2)		50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
	20.406(a)(1)(iii)	50.73(a)(2)(i)		50.73(a)(2)(vii)(A)	
	20.406(a)(1)(iv)	50.73(a)(2)(ii)		50.73(a)(2)(vii)(B)	
	20.406(a)(1)(v)	50.73(a)(2)(iii)		50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME Mark Leahy (X-422)	TELEPHONE NUMBER AREA CODE: 8 1 5 9 4 2 - 2 9 2 0
----------------------------	---

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS
A				N					

SUPPLEMENTAL REPORT EXPECTED (14)

<input checked="" type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
			0 1	0 1	8 5

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During a manual power reduction, the unit Operator failed to insert the IRM's in a timely manner. When the IRM's were inserted, the unit scrambled on IRM high-high with companion APRM downscale. Safety significance was minimal, as the reactor protection system worked as designed. This was the first reportable occurrence of this type at Dresden Station.

A Professionalism Investigation Committee will be convened to investigate the event, determine the root cause(s) and appropriate corrective action(s). When this committee's findings are issued, a supplemental report will be submitted.

8409280302 840919
PDR ADCK 05000249
S PDR

FE22
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Dresden Nuclear Power Station Unit 3	DOCKET NUMBER (2) 0 5 0 0 0 2 4 9 8 4	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 4	0 1 2	0 0	0 2	OF 0 2

TEXT (If more space is required, use additional NRC Form 308A's) (17)

During a manual power reduction, the unit Operator failed to insert the IRM's prior to the APRM's going downscale. The Operator inserted the IRM's with the IRM range switches on low range, which resulted in a scram due to IRM high-high with companion APRM downscale. Safety significance was minimal as all RPS systems operated properly. This is the first reportable occurrence of this type at Dresden Station.

A Pro Committee will be convened to investigate the event, determine the root cause(s) of the event and appropriate corrective action(s). When this committee's findings are issued, a supplemental report will be submitted.



Commonwealth Edison

Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

September 20, 1984

DJS Ltr #84-944

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Licensee Event Report #84-012-0, Docket #050249 is being submitted
sa required by Technical Specification 6.6, NUREG 1022 and 10 CFR
50.73 (a)(2)(iv).

D.J. Scott
D.J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: J.G. Keppler, Regional Administrator, Region III
File/NRC
File/Numerical

IE22
1/1