NRC Form 386 (IS-83) LICENSEE EVENT REPORT (LER)										IUCLEAR REGULATORY COPINISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85									
FACILITY	NAME (1	1)	-		_				-				-		DOCKET NUMBER	R (2)		P2	AGE (3)
Pilgrim Nuclear Power Station						- Unit 1				0 5 0 0	121913	13 1 OF 012							
TITLE (4)	CRD C	011	et	Ref	rai	ner	Tub	e We	Id	Defe	cts				1-1-1-1-	1	1-1-1-		1012
EVENT DATE (6) LER NUMBER (6)										R FACILITIES INVOLVED (8)									
MONTH DAY		YEA	R	YEAR		SEQUE	NTIAL	REVISION NUMBER		MONTH	DAY	YEAR	FACILITY NAMES			DOCKET NUMBER(S)			
			+			NON	NUMBER	NUM	Meen				1			0	15101	0 0	1.1
0 8	2 2	8	4	3 4	-	oli	10	-0	10	019	210	8 4				0	15101	0 1 0 1	11
OPE	RATING		1	HIS RE	PORT	IS SU	MITTE	D PURSU	ANT	TO THE R	EQUIRE	MENTS OF	10 CFR 8:	(Check one or mai	re of the following) (-			
POWER LEVEL (10) 0 0 0			0	20.405(a)(1)(i) 20.405(a)(1)(ii) 20.405(a)(1)(iii) 20.405(a)(1)(iv) 20.405(a)(1)(iv)					20.405(c) 50.38(c)(1) 50.38(c)(2) 50.73(a)(2)(i) 50.73(a)(2)(ii) 50.73(a)(2)(iii)				50.73(a)(2)(iv) 50.73(a)(2)(vii) 50.73(a)(2)(viii) 50.73(a)(2)(viii)(A) 50.73(a)(2)(viii)(B) 50.73(a)(2)(x)		73,71(b) 73,71(c) OTHER (Specify in Abstract below and in Text, NRC Form 366A)				
									L	ICENSE E	CONTAC	T FOR TH	IS LER (12)						
NAME															AREA CODE	_	EPHONE NU	MBER	
	Rich	naro	M b	. Sc	chi	fone	9								611 17	7	1461	1719	01010
					_	COM	PLETE	ONE LIN	E FOR	EACH CO	OMPONE	NY FAILUR	E DESCRIB	ED IN THIS REP	ORT (13)				
CAUSE	SYSTEM	co	COMPONENT		MANUFAC- TURER		REPORTABLE TO MEROS				CAUS	SE SYSTEM	COMPONENT	MANUFAC- TURER		TO NPROS			
X	AJA	1	RIC	T	G	1018	3 12	Y											
			_	1		L	1						L		111				
SUPPLEMENTAL REPORT EXPECTED (14) EXPEC									ED	MONT	H DAY	YEAR							
YES (If yes, complete EXPECTED SUBMISSION DATE) ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space type					NO NO				SUBMISS	DATE (15)		114	8 4						

On 3/22/84, during a refuel outage, it was determined that a CRD collet retainer tube had a 3/16" to 1/4" transverse through-wall crack. The crack was located in the lower shoulder attachment weld within one inch below the lower shoulder. This is an area of "No Indications Allowed" per GE SIL No. 139, Supplement 4.

This retaining tube is of the improved design manufactured with Cast 304L stainless steel. The immediate corrective action was to declare the retainer tube in nonconformance and schedule it for replacement during the current refueling outage.

The determination of the cause is pending completion of an evaluation by General Electric.

8409280324 840920 PDR ADDCK 05000293 S PDR

TEZZ

NRC Form 368A (9-83)	LICENSEE EVENT REF		U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85					
FACILITY NAME (1)		DOCKET NUMBER (2)	L	ER NUMBER (6)	MBER (6)		PAGE (3)	
Pilgrim Nucl	ear Power Station -		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Unif 1							Mar part	

0 |5 |0 |0 |0 |2 |9 |3 |8 |4 |- 0 | | |0 |- 0 | 0 | 0 | 2 | OF |0 | 2

On 8/22/84, during a refuel outage, it was determined that CRD Collet Retainer Tube (Serial Number 8311) had a 3/16 to 1/4 inch transverse, through-wall crack. The crack was located in the lower shoulder attachment weld, within one inch below the lower shoulder.

The above retainer tube is of the improved design manufactured with Cast 304L stainless steel, which is designated by GE as XM-19. The through-wall crack was discovered while surface conditioning the tubes to determine the extent of liquid penetrant test indications. The indications on #8311 were probed through the root of the weld, and visually rejected per General Electric Service Information Letter #139, Supplement 4.

The determination of the cause is pending completion of an evaluation by General Electric and will be addressed in an update report. The immediate corrective action was to declare #8311 CRD Collet Retainer Tube in nonconformance and schedule it for replacement during the current refueling outage.

There have been no other previously identified significant defects with the improved (Cast 304L/XM-19) CRD Collet Retainer Tubes.

This event did not impact the health and safety of the public.

BOSTON EDISON COMPANY

SOO BOYLSTON STREET BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON SENIOR VICE PRESIDENT NUCLEAR

September 20, 1984

BECo Ltr. #84-151

Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555

> Docket Number 50-293 License DPR-35

Dear Sir:

The attached Licensee Event Report 84-010-00, "CRD Collet Retainer Tube Weld Defect," is hereby submitted in accordance with the requirements of 10CFR50.73.

If there are any questions on this subject, please do not hesitate to contact me.

Respectfully submitted,

W. D. Harrington

RS:caw

Enclosure: LER 84-010-00

cc: Dr. Thomas E. Murley
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Standard BECo LER Distribution

TEXT