NRC For 19-83)	m 364				LIC	ENSE	E EVE	NT RE	U.S. NUCLEAR REGULATORY COMMISSION APPROVED DMS NO. 3150-0104 EXPIRES: 8/31/85										
FACILITY	Y NAME (1	1)									DOCK	ET NU	MBER	(2)			_	PAG	E (3)
Dresden Nuclear Power Station															121	4 19	1	OF	012
TITLE (4	1	2100									0 1	-	1-	-	1-1	1	1	10.	
		Reac	tor S	cram on 1	Low Wate	r Le	ve1												
EV	ENT DATE	-		LER NUMBER	E (7)	OTHER FACILITIES INVOLVED (8)													
MONTH	MONTH DAY YEAR			YEAR YEAR SEQUENTIAL NUMBER			DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)						
				-	NUMBER				N	I/A				0	151	010	0 1 0	1	1 1
						+				-								_	
0 8	2 1	8 4	8 4	010	1-00	0 9	1 0	8 4	N	/A				0	15	0 10	10	1	1 1
OPE	RATING		THIS REP	ORT IS SUBMITTE	D PURSUANT T	O THE R	EQUIREM	ENTE OF 1		Check one or more	of the	fallow	ing) (11	1)	-				
POWER LEVEL (10) 0 19 7		20.4 20.4 20.4 20.4	02(b) 05(a)(1)(i) 05(a)(1)(ii) 05(a)(1)(iii) 05(a)(1)(iv)	20.406(c) 50.36(c)(1) 50.36(c)(2) 50.73(a)(2)(i) 50.73(a)(2)(ii) 50.73(a)(2)(iii)			X	X 80.73(a)(2)(iv) 80.73(a)(2)(v) 90.73(a)(2)(viii) 80.73(a)(2)(viii)(A) 90.73(a)(2)(viii)(B) 50.73(a)(2)(x)					73.7 73.7 0Th 500 366	n Abe	street C Form				
					L	ICENSE	CONTACT	FOR THIS	LER (12)							II.			
NAME														TELE	EPHON	NE NUN	18ER		
		Lawr	ence	Coyle (X	-483)						1	BI 1	15	9 1	141	21-	12	191	12 10
				COMPLETE	ONE LINE FOR	EACH C	OMPONENT	FALURE	DESCRIBE	D IN THIS REPO	AT (13	_							
CAUSE	SYSTEM	COMPO			REPORTABLE TO NPROS			CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER			REPORTABLE TO NPROS					
х	SIJ	LF	ICIV	C1616 5	N								1	I					
				iri					1	111		1 1	1		.le				
				SUPPLEME	ENTAL REPORT	EXPECT	ED (14)	Hij Billion				5~	PECTE	0	T	MONTH	1 04	AY	YEAR
				URMISSION DATE			X NO					SUBMISSION DATE (15)							1

During normal operation, the "A" feedwater regulating valve operator vibrated loose from the valve stem coupling. The valve disc failed in the closed direction, causing the reactor to scram on low water level. Safety significance was minimal, since all emergency systems operated as designed. Previous similar occurrence reported by R.O. 84-09 on Docket 50-237.

The operator and valve stem were reconnected and holes were drilled into the coupling block and locknuts so set screws could be placed to secure the valve stem and valve operator to the coupling block.

8409280586 840910 PDR ADDCK 05000249 S PDR

TEZZ 1/1

NAC Form 366A

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION
APPROVED OMB NO. 3150-0104
EXPIRES 8/31/86

PACILITY NAME (1)	DOCKET NUMBER (2)								100		LE	R NUMBER (6	PAGE (3)					
									YEA	я		SEQUENTIAL NUMBER		REVISION				П
Dresden Nuclear Power Station Unit 3	0	15	10	10	10	12	14	19	8	4		0 1 0	_	010	012	OF	0	2

TEXT IN more space is required, use additional NRC Form 366A's) (17)

During normal operation the "A" feedwater regulating valve (A03-642A) operator separated from the valve stem coupling. The valve disc failed in the closed direction, causing a reactor scram on low water level. Safety significance was minimal, since all emergency systems operated as designed. Previous similar occurrence reported by R.O. 84-09 on Docket 50-237.

The cause of the event was the loosening, due to vibration, of the locknut securing the operator to the coupling block at the top of the valve stem. The loose locknut permitted the operator to vibrate loose from the coupling block allowing the coupling block and the attached valve stem to fall into the closed position. The valve operator was reattached to the coupling block. To prevent a recurrence holes were drilled into the top and bottom side of the coupling block and set screws were installed to wedge against the valve operator and the valve stem. Also, holes were drilled into the top and bottom locknuts and set screws were installed to wedge against the top and bottom of the coupling block to prevent the locknuts from moving. This procedure was repeated on the "B" feedwater regulating valve. Set screws will be installed in the Unit 2 "A" feedwater regulating valve coupling block and associated locknuts during the fall 1984 refuel outage. The 2"B" feedwater regulating valve is of a different type, and will not require set screws.

September 13, 1984

DJS Ltr #84-908

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Licensee Event Report #84-010-0, Docket #050-249 is being submitted as required by Technical Specification 6.6, NUREG 1022 and 10 CFR 50.73 (a)(2)(iv).

D.J. Scott

Station Superintendent Dresden Nuclear Power Station

DJS/kj1

Enclosure

cc: J.G. Keppler, Regional Administrator, Region III
 File/NRC
 File/Numerical