



J. Phillip Bayne  
Executive Vice President  
Nuclear Generation

October 1, 1984  
JPN-84-61

Director of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Attention: Mr. Domenic B. Vassallo  
Operating Reactors Branch No. 2  
Division Of Licensing

Subject: James A. FitzPatrick Nuclear Power Plant  
Docket No. 50-333  
IE Bulletin No. 84-01  
Mark I Containment Vent Headers

References: 1. NRC IE Bulletin No. 84-01, "Cracks In Boiling  
Water Reactor Mark I Containment Vent Headers,"  
dated February 3, 1984.

Dear Sir:

On September 7, 1984, one week prior to a scheduled outage, we were notified that a written report on the subject Bulletin was required immediately.

Attachment I provides our response as requested. This response has been delayed due to the demands of the outage as well as of other current licensing activities.

It should be noted that on April 27, 1984 the Authority received a request for either an oral or a written report. We provided an oral report at that time, and submitted copies of visual inspection reports.


It should also be noted that while the FitzPatrick facility was not in cold shutdown when the Bulletin was issued, and no action was required, nevertheless, a review of the Bulletin and related documents was initiated, and various evaluations, procedure revisions and extensive visual inspections were undertaken.

8410050314 841001  
PDR ADDCK 05000333  
G PDR

*A025*  
*Add: IE/DEPER/EGCB*  
*IE/DEPER/EGCB/S*  
*1st EACH*

If there are any questions, please do not hesitate to call Mr. J.A. Gray, Jr. of my staff.

Very truly yours,



J.P. Bayne  
First Executive Vice President  
Chief Operations Officer

cc: Office of the Resident Inspector  
U.S. Nuclear Regulatory Commission  
P.O. Box 136  
Lycoming, New York 13093

New York Power Authority  
James A. FitzPatrick Nuclear Power Plant

Attachment I

JPN-84-61

A. IE Bulletin No. 84-01:  
Actions to be taken by all BWRs having Mark I Containments  
and Currently Shutdown:

1. Plants that are currently in cold shutdown should visually inspect for cracks in the entire vent header and in the main vents in the region near the intersection with the vent header. To the extent practicable, the inspection should include the entire surfaces of the aforementioned components. The inspection should be completed within 36 hours of receipt of this bulletin.
2. If cracks are found, the containment should be declared inoperable.
3. The results of the inspection are to be reported by telephone to NRC Operations Center within 8 hours after the inspection has been completed. A written report describing the areas inspected and the results should be submitted within seven days of receipt of the bulletin.

Response to IE Bulletin No. 84-01

The James A. FitzPatrick Nuclear Power Plant was operating when IE Bulletin No. 84-01 (IEB-84-01) was issued. Accordingly, it was not practical to inspect the vent header or main vents in the region near the intersection with the vent header at that time.

B. Other inspection activities performed or planned:

While it was not practical to perform an immediate inspection of the vent header and related structures and components as suggested by IEB-84-01, the FitzPatrick plant staff initiated review and/or evaluation of IEB-84-01 and other related documents under the Plant Operating Experience Review Program shortly after they were received at the JAF plant. These related documents are IE Information Notice 84-17, INPO SER 14-84 and GE SIL 402.

As a result of the IEB-84-01 (and the related documents noted above), the following evaluations, inspections, and procedure revisions have been completed or will be completed by the indicated date.

1. An evaluation of drywell to suppression pool differential pressure was conducted to verify that no significant leakage from the drywell to the suppression pool was present.

2. On March 2, 1984, the JAF plant was shut down for scheduled maintenance and modification. During this shutdown period, a visual examination was conducted as indicated below:

Outside of Vent Header - The entire top surface of the vent header was inspected including girth and attachment welds. The nitrogen penetration is in the center of bay O, and bays P and A are adjacent to bay O. In bays P, O, and A, the pipe surface and all associated weldments were inspected approximately 220° around the vent header starting at 2 o'clock and moving counter-clockwise to 6 o'clock. One-half of the downcomer to vent header attachment welds in bays P, O, and A, were also inspected.

Inside of Vent Header - The entire inside surface of the vent header in bays P, O, and A were inspected. This included all girth welds and all downcomer to vent header attachment weldments.

Nitrogen Penetration - The suppression pool (wetwell) I.D. side of the nitrogen penetration to suppression pool shell weldment, and the suppression pool plate materials (approximately 12" all around the penetration) were inspected.

No evidence of cracking was discovered during any of the above inspections. Since none of the original (construction) examinations included ultra-sonic testing (UT), no UT baseline exists. Accordingly, no UT examinations are planned.

3. An evaluation of the inerting system has been conducted. As a result of this evaluation, the applicable procedures have been revised to provide assurance that cold gaseous (or liquid) nitrogen is not introduced into the inerting system or into containment components which are not designed for low temperature operation.
4. A surveillance procedure to test operation of the low temperature isolation function will be implemented by October 10, 1984.
5. Periodic calibration of temperature switches and indication to assure proper operation of the low temperature isolation, and provide the operator with reliable temperature indication, will be implemented by October 10, 1984.
6. During the next scheduled primary containment integrated leak rate test, a drywell to suppression pool (wetwell) bypass leakage test will be conducted. The test is currently scheduled for the end of the 1985 Refueling Outage.

James A. FitzPatrick  
Nuclear Power Plant  
P.O. Box 41  
Lycoming, New York 13093  
315 342 3640



Corbin McNeill  
Resident Manager

MARCH 8, 1984  
JAF-QF-84-030

MEMORANDUM TO: Superintendent of Power

FROM: R. Patch

SUBJECT: JAFNPP  
Quality Assurance  
Visual Inspection of Torus Ring Header

REFERENCE: JOC-84-006 (2/23/84) Visual Inspection of Torus Ring Header

As requested in the referenced memorandum, a visual inspection of the torus ring header was performed on 3/4/84. The inspections were performed by C. Krok, P. Morris, and R. Patch. The areas inspected are as follows:

- Outside of Ring Header - The entire top surface of the ring header was inspected including girth and attachment welds. In bays F, O, and A, the pipe surface and all associated weldments were inspected approximately 220° around the header starting at 2 o'clock and moving counter-clockwise to 6 o'clock. One-half of the downcomer to ring header attachment welds in bays P, O, and A, were also inspected.
- Inside of Ring Header - The entire inside surface of the ring header in bays P, O and A were inspected. This includes all girth welds and all downcomer to ring header attachment weldments.
- Nitrogen Penetration - The torus I.D. side of the nitrogen penetration to torus shell attachment weldment and the torus plate materials approximately 12" all around the penetration.

Conclusion: No evidence of cracking was discovered during any of the above inspections.

Miscellaneous Observations: During the above inspections it was noted that tools and other loose debris were laying inside the vent header piping. The outside of the vent header piping in the area adjacent to the nitrogen penetration entrance to the torus is exhibiting considerable surface rusting.

MEMORANDUM TO: SUPERINTENDENT OF POWER  
FROM: R. PATCH  
SUBJECT: VISUAL INSPECTION OF TORUS RING HEADER

MARCH 8, 1984  
JAF-QF-84-030  
PAGE TWO

The inspection will be formally documented in an Inspection Report to be issued in accordance with the requirements of the Nondestructive Examination Procedures, but this memo is being written to advise you that the results of the inspection were satisfactory.

If you have any questions regarding this memo, please contact the writer.

*Richard L. Patch*

Richard L. Patch  
QA Supt. in Training

cc: M. Cosgrove  
J. Kerfien  
T. Butler  
R. Liseno  
File 3.0.2

RLP:cp

James A. Fitzpatrick Nuclear Power Plant  
WORK REQUEST/EVENT/DEFICIENCY/FORM

1. 27 / No 24580  
Sys. No.

2. Comp. No. 3 Q.C. Cat. 1 4. Safety Rel. Yes No 5. Date 2/27/84 Time 11:30  
7. Equip. Title: RING HEADER ATTACHMENT PIPING (TORUS)  
8. Work Req. Event  
or Def. Description: PERFORM VISUAL INSPECTION OF WELD- (and location) WELDS AS SET FORTH IN JOC-FU-006. THIS INSPECTION MUST BE PERFORMED AS THE RESULT OF PLANT HATCH PROBLEM.  
9. Cause: UNKNOWN

(Sign Line 34)

OCCURRENCE REPORT

- PART I 10.  YES (see AP 8.2)  NO 42. OR No. 49. LER No.  
11. Operating Occurrence  Basic Component Defect  Security Infraction   
12. Means of Discovery: a. Testing Proc No. b. Normal Ops. c. Sys/Equip - S/U or S/D d. Maint e. NRC Insp No. Name f. Other  
13. Power Level MWT MWe 14. Mode Switch Position  
15. Plant Status 16. Tech. Spec. Yes/No Para No.  
17. a) Surv. Test Req. YES/NO 18. Surv. Test Comp. YES/NO Date Time  
b) Surv. Test No. 19. Redundant Sys. Avail. YES/NO/NA  
20. Initial Corrective Action:  
21. Preliminary Classification: a. Reportable Yes No b. 10 CFR 21 Yes No  
22. Notification: Date/Time Date/Time  
Ops. Supt. Res. Manager  
Supt. of Power Other  
23. Completed By (SS/Mtg. Supv.) Date Time

WORK REQUIRED: 24. Yes/No

25. Priority: 1 2 3 4 26. Outage: Yes/Refuel/No 27. Dept: Maint/I&C/Q.C.  
Other

NPRD: 28. Yes/No

29. Stat. Time Fail.	30. Eff. Fail. on Sys. (2)	31. Eff. Fail. Plant, OPS (3)	32. Failure Detection (2)	33. Mode of Failure
A System in Service	A Reduced Power Operat.	A Operational Abnormal.	AA Leak	AA Won't Release
B System in Test	B Unit Off-Line	B Inservice Inspection	AB Crack	AB Out of Limits
C System in Maintenance	C Reactor Trip	C Surveillance Testing	AC Breach	AC Spurious Operation
D System Out of Service	D Personnel Injury	D Preventive Maintenance	AD Physical Distortion	AD False Response
E Subsys./Chan. in Service	E Excess Off-Site Radiat.	E Special Inspection	AE Physical Displacement	AE Other
F Subsys./Chan. in Test	F Damage to Other Equip	F Audio Alarm	AF Collapse	
G Subsys./Chan. in Maint.	G No Significant Effect	G Visual Alarm	AG Fracture/Break	
H Subsys./Chan. Out of Serv.		H Routine Surveillance	AH Won't Start/Move	
A Loss of Syst. Function		I Incidental Observation	AJ Won't Stop	
B Degraded Syst. Oper.		J Other	AK Won't Close	
C Loss of Redundancy			AL Won't Open	
D Loss of Subsys./Chan.			AM Won't Hold	
E No Significant Effect			AN Won't Release	

INITIATION & REVIEW

34. Thomas P. Little 35. Thomas P. Little 36. P. Coffey  
Originator Management Supv. Date SS Mit. Date  
37. Q.C. Inspection Req. Yes/No/NA (Q.C.) 2/27/84 Date

POST WORK CLEARANCE (If Work Tracking Form Not Used)

38. Man Hours: M 1 E 1 IC 1  
Other 1  
39. Work Comp/Def. Corr. 1 40. 1  
Worker Date Dept. Supv. Date  
41. System Restored 1  
SS Acceptance Date

Sys. No. 27 / No 24580



POWER AUTHORITY OF THE STATE OF NEW YORK  
QUALITY CONTROL INSPECTION REPORT 1.0 QCIR # 184-0057

2.0 SITE LOCATION JAFNPP 6.0 W.R.E.D. 27/24580  
3.0 SYSTEM NAME/NO. Contained Page 7.0 QA CLASSIFICATION 1  
3.1 COMPONENT NAME/NO. Torus Ring Header 8.0 MAT. REPLACEMENT REQ'D N/A  
4.0 RESPONSIBLE DEPT./GROUP DC 8.1 MAT. CERTIFICATION REQ'D N/A  
5.0 ACTIVITY LOCATION Torus 8.2 MAT. PURCH. ORDER NO. N/A  
9.0 PROCEDURE TITLE/NO. NDEP 9.5.1  
10.0 PREREQUISITES ACCOMPLISHED YES  NO  (IF NO, EXPLAIN UNDER REMARKS)

11.0 REASONS FOR ACTIVITY: Perform visual inspection of torus ring header in accordance with JOC-84-006, and G.E. Sit No. 402.

11.1 QC INSPECTION REQUIREMENTS:  
Visual Inspection for cracks only in accordance with NDEP 9.5.1

12.0 WORK DESCRIPTION (INCLUDE MATERIAL AND COMPONENTS USED):

Inspection Only

13.0 POST WORK TEST REQUIREMENTS: None

14.0 POST WORK TEST(S) PERFORMED: N/A

15.0 TEST DATA: (Where filed) Attached

16.0 REMARKS: This inspection was limited to examining the Torus Ring Header and Torus Nitrogen Penetration for cracks only. The examination was limited to Torus bays P, O, + A only however other areas were inspected.

17.0 QC INSPECTOR: Richard L. Patch DATE/TIME: 3/4/84 1PM

JAINPP QUALITY CONTROL CHECKLIST

SYSTEM: 27

SUBSYSTEM:

COMPONENT: TORUS Ring Header

WRED: 27/24580

APPROVAL:

J.H. Korbien  
QC Supervisor

1-6-83

Date

CHECKLIST ATTRIBUTES:	SAT.	UNSAT	N/A	QC INSP.	DATE
1. <u>QC Inspection</u> (Prerequisites)				RP	3-4-84
* a) QC Inspector has approved check-list on job and has discussed it with personnel performing the work.	✓				
* b) Ensure administrative procedure prerequisites, including initiation of work request, system mark-up, etc., are completed prior to commencement of work.	✓			RP	3-4-84
* c) Ensure appropriate procedures and/or instructions have been developed, reviewed, and properly approved prior to commencement of activity.	✓			RP	3-4-84
Note 1 d) Procedure and/or instruction manual available at work location.			✓	EW	
e) Proper documentation for replacement parts on file.			✓	RP	

\* Shall be verified by Inspection Coordinator.

*Procedures reviewed prior to performance of test. Due to climate in torus + ring header procedures were not available.*

VISUAL DATA SHEET

UNIT: JAF-82 SYSTEM: 27 Continuant Page COMPONENT: 1111 Ring Header

DESCRIPTION: Inspection of Header Ring & Weldments, Downcomer Attachment Weldments

WELD ID: 1811452 THICKNESS: Varies TEST SURFACE: Painted

NO. POSITIONS: 1 VT# 1  2  3  4  MATERIAL: C/S 18% NEUTRAL GRAY CARD: YES  NO

GOVERNING CODE: B31.1 (1412) BOROSCOPE: YES  NO

ATTACHMENTS: YES  NO  AUXILIARY LIGHTING: YES  NO

#1 REFERENCE: N/A SURFACE PREPARATION: YES  NO

INSULATED  NON-INSULATED

PERFORMED BY: Richard L. Patch LEVEL: II

PERFORMED BY: Chris Ficht LEVEL: III

POSITION	COMPONENT NUMBER	DIRECT VISUAL EXAMINATION	REMOTE VISUAL EXAMINATION	(INCHES)						DIMENSIONING		REMARKS
				INDICATION		DISTANCE		FROM SURFACE IN		POSITION (IN.)	POSITION (IN.)	
A	B			A	B	A	B	1	2	A	B	
	Ring header ID in pipe 2.5 x 4	X										No Cracks
	Ring header 22 in pipe 2.5 x 4	X										No Cracks
	Wagon beam - then inside of 4045	X										No Cracks
	Examination Results Satisfactory No cracks found.											

LIMITED EXAMINATION  NO  YES (IF SO WHY)  
Lim. Heo Gross to one side of 00 torus ring Header.

REVIEWED BY: C. Patch DATE REVIEWED: 3-8-84 WELD NO.: 27/24588

FIGURE NO.: N/A DATA SHEET NO.: