NRC F	LICENSEE EVENT REPORT (LER)					U.S. NUCLEAR REQUIATORY COMMISSION APPROVED OMB NO. 2150-0104 EXPIRES: 8/31/86										
							-		DOCKET MUMBER	2)	PAGE	12				
	The C		ation Unit	2					0 5 0 0		1 OF	013				
TIEM (4)		rearrey eve							-1-1-1-1	-15111						
Read	tor W	ater Clea	anup High I	Differen	tial Tempe	rature	e Isol	Lation								
	NT DATE		LER NUMBER		REPORT DATE				FACILITIES INVOL	VED (E)						
MONTH	DAY	YEAR YEAR	SEQUENTIAL NUMBER	MEVISION NUMBER	MONTH DAY	YEAR		FACILITY NA	MES	DOCKET NUMBER	R(8)					
								NA		0 5 0 0	1011	1				
						. [
0 8	1 6	8 4 8 4	058	00	0919	8 4				0 5 0 0	1011	1				
025	RATING	THIS RE	PORT IS SUBMITTE	D PURBUANT T	THE REQUIREME	NTS OF 10	CFR 6: 10	Sheck one or more	of the followings (11	1						
	DE (9)	4 30	(.4029b)		20.406(a)		X	90,73(a)(2)(iv)		73,7104						
POWE		26	L405(e)(1)(i)		(1)(a)40,08			86.73(a)(2)(v)		73,71 (a)						
(10)	01	010	.405 in)(1)(#)		90.36(e)(2)			90.736)(2)(v2)			Tost, NRC	Form				
*	**		(88)(1)(6)809,4		60.73(a)(2)(i)			80.73(a)(2)(+66)((A)	38KAJ						
			1408 to) (1 Hev)		90,73(a)(2)(8)			80.73(a)(2)(viii)((8)							
	**	25	.408(a)(1)(v)		80,73(a)(2)(N)			80.73(a)(2)(x)								
				L	ICENSEE CONTACT	FOR THIS	LER (12)									
HASTE									AREA CODE	MUM SHCHESIST	etu					
Char	les K	. Sprunge	er, extens:	on 779							باللوث					
- Cinda	200 1	. oh me							and the second s	3 5 7 -	-16171	611				
			COMPLETE	ONE LINE FOR	EACH COMPONENT	FAILURE	DESCRIBE	D IN THIS HEPOI	MY (13)							
CAUSE	SYSTEM	COMPONENT	MANUFAC-	REPORTABLE TO NPROS		CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	TO MPROS						
_				-			-		-	-						
v	JIM	7101010	7 . 0. 0.0	N					1							
Λ	U M	491913	2 9 9 9	14			-		+	-						
							1	1.1.1	1111							
						1			++++	MONT	DAY	YEAR				
			HIJPET ELE	PROMES LATES	EXPECTED (14)											
			HAPLEM	ENTAL REPORT	EXPECTED (14)				SUBMISSI DATE (1)	DN .	1					

On August 26, 1984, at 0830 hours with Unit 2 at 0% power in Mode 4, an isolation of Reactor Water Cleanup occurred due to High Differential Temperature in the "A" pump room. At the time of this isolation the Reactor Building ventilation was shut down to facilitate repairs to the system.

The isolation resulted from a lack of air flow through the room which is required for the present Leak Detection scheme to function. A Technical Specification change will be requested to remove these instruments.

> 5410050509 840919 PDR ADDCK 05000374 PDR S

IEZZ

1000		-
HRC	Form	3064

LICENSEE-EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

EXPIRES: 8/31/85

CILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER IS	PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION		
LaSalle County Station Unit 2	0 5 0 0 0 3 7 4	84	015 18	-010	0 2 OF 0 B	

FEXT III more specia is required, use established MRC Form 368A's/ (17)

I. EVENT DESCRIPTION

On August 26, 1984, at 0830 hours, the Unit 2 Reactor Water Cleanup (RWCU, CE) system High Differential Air Temperature (JM) alarm and trip was received for the "A" RWCU pump room. Valve 2G33-F001 closed as designed, isolating the RWCU system. The Licensed Operator (NSO) acknowledged the alarm and checked the differential air temperature for the room on the unit indicator. At this time the differential temperature between the inlet and outlet air to the room was 9°F. The NSO sent an Operator to check the room for leaks. No leaks were found. NRC notification of the event was made at 0905 hours. When it was apparent the system was not leaking, the isolation was cleared and the "A" RWCU pump and filter demineralizer were placed back on line.

II. CAUSE

At the time of the isolation, Unit 2 was at 0% in Mode 4. The Unit 2 Reactor Building Ventilation (VA) supply and exhaust fans were shut down at 0405 hours on the same day to facilitate repairs to fan 2VR02CB. This caused the air in the "A" RWCU pump room to stagnate. The air near the pump became warmer than the air next to the door of the room. The exhaust air temperature element located above the pump sensed a higher temperature than the supply air temperature located near the door. After approximately four hours of pump operation with no ventilation in operation, the differential temperature exceeded the setpoint of 13°F and the system isolated. When the NSO checked the differential temperature indicator in the Control Room the pump had been off long enough for the differential temperature to fall to 9°F.

III. PROBABLE CONSEQUENCES OF THE OCCURRENCE

The RWCU system shut down and placed the plant in a safe condition after the isolation signal was received. No leaks in the system were found. The loss of the RWCU system did not unduly affect the operation of the unit.

IV. CORRECTIVE ACTIONS

The original Leak Detection system for the RWCU pump rooms was designed to detect leaking water and steam at temperatures near those of reactor water in the vessel. The system was modified prior to initial criticality to allow reactor water to pass through several heat exchangers before reaching the RWCU pumps. The water temperature is now less than 130°F. The present temperature Leak Detection system for the pump rooms is ineffective in detecting leaks due to the coole, water temperatures. The setpoints for these instruments are very near normal Operating Conditions. A Technical Specification change has been requested to remove these instruments. This will eliminate spurious RWCU pump room isolations due to the loss of ventilation.

LICENSEE-EVENT REP	ORT (LER) TEXT CONTINU	APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85							
PACILITY NAME (1)	DOCKET NUMBER (2)		LE	R NUMBER (6)			AGE (30	
		YEAR		SEQUENTIAL	REVERON				
LaSalle County Station Unit 2	0 5 0 0 0 3 7 4	814	_	0 5 8	- 010	0 3	OF	01	3

U.S. NUCLEAR REGULATORY COMMISS

LaSalle County Station Unit 2

PREVIOUS EVENTS

Spurious Unit ? RWCU system isolations due to ventilation problems have occurred previously as described in LER's 374/84-006-00, 84-007-00, and 84-010-00. A spurious Unit 1 system isolation due to ventilation problems has occurred previously as described in LER 373/84-031-00.

NAME AND TELEPHONE NUMBER OF PREPARER VI.

Charles K. Sprunger, 815/357-6761, extension 779.

September 19, 1984

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Dear Sir:

Reportable Occurrence Report #84-058-00, Docket #050-374 is being submitted to your office in accordance with 10CFR 50.73.

G J. Diederich Superintendent

LaSalle County Station

GJD/MLD/kg

Enclosure

xc: NRC, Regional Director INPO - Records Center File/NRC

IE22