



THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

P.O. BOX 5000 - CLEVELAND, OHIO 44101 - TELEPHONE (216) 622-9800 - ILLUMINATING BLDG. - 55 PUBLIC SQUARE

Serving The Best Location in the Nation

MURRAY R. EDELMAN
VICE PRESIDENT
NUCLEAR

October 2, 1984
PY-CEI/NRR-0139 L

Mr. B. J. Youngblood, Chief
Licensing Branch No. 1
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington D.C. 20555

Perry Nuclear Power Plant
Docket Nos. 50-440; 50-441
Response to NRC Question
No. 420.03 through 420.07-
Effects of High Energy Line Breaks
on Control Systems (Open Item No.14)

Dear Mr. Youngblood:

This letter and its attachments are provided in response to your request for additional information (dated January 10, 1984), regarding effects of high energy line breaks on control systems (Open Item No. 14) for the Perry Nuclear Power Plant (Units 1 and 2).

The information provided in the attachments will be incorporated into a future FSAR Amendment. If you have any questions, please feel free to call me.

Very truly yours,

Murray R. Edelman
Vice President
Nuclear Group

MRE:njc

Attachments

cc: Jay Silberg, Esq.
John Stefano
Jack Grobe

8410090335 841002
PDR ADOCK 05000440
A PDR

Boo!
1/1

Q420.03

Provide an identification of the locations (elevations/areas) which contain high energy piping systems and in which components for the nonsafety related control systems are located. Relate these to the adverse conditions discussed in your letter dated March 14, 1983.

Response

The following information identifies the locations (panel, building, elevation and coordinates) of non-safety control systems and high energy lines for adverse conditions #1-#5 discussed in our March 14, 1983 letter. We have referenced layout drawings contained in the FSAR for your convenience in identifying locations.

ADVERSE CONDITION #1

| <u>INSTRUMENT</u> | <u>PANEL</u> | <u>BUILDING</u> | <u>ELEVATION</u> | <u>COORDINATES</u> |
|-------------------|--------------|-----------------|------------------|--------------------|
| 1B33N001A | 1H22-P025 | Containment | 620 | C1/12 |
| 1B33N001B | 1H22-P041 | Containment | 620 | C1/17 |
| 1C34N003B | 1H22-P025 | Containment | 620 | C1/12 |
| 1C34N003D | 1H22-P041 | Containment | 620 | C1/17 |

| <u>HIGH ENERGY LINE</u> | <u>BUILDING</u> | <u>ELEVATION</u> | <u>COORDINATES</u> |
|----------------------------------|-----------------|------------------|--------------------|
| C11-Control Rod Hydraulic System | Containment | 630 | C1/11 |
| C41-Standby Liquid Control | Containment | 602 | C1/17 |

All of the above instruments and high energy lines are located between the drywell and the reactor building wall. Exact locations may be identified by referencing figures 3.6-4, 3.6-6, 3.6-12 and 3.6-14 of the FSAR.

ADVERSE CONDITION #2

| <u>INSTRUMENT</u> | <u>PANEL</u> | <u>BUILDING</u> | <u>ELEVATION</u> | <u>COORDINATES</u> |
|-------------------|--------------|-----------------|------------------|--------------------|
| 1N27N156A | 1H51P1147 | Heater Bay | 600 | B/01 |
| 1N27N156B | 1H51P098 | Heater Bay | 620 | C/02 |
| 1N27N087A | 1H51P098 | Heater Bay | 620 | C/02 |
| 1N27N087B | 1H51P098 | Heater Bay | 620 | C/02 |
| 1N25N263A | Heater 6A | Heater Bay | 600 | D/03 |
| 1N25N263B | Heater 6B | Heater Bay | 600 | D/03 |
| 1N25N303A | Heater 5A | Heater Bay | 600 | D/02 |
| 1N25N303B | Heater 5B | Heater Bay | 600 | D/02 |
| 1N36N030A | 1H51P1305 | Heater Bay | 620 | B/01 |
| 1N36N030B | 1H51P1330 | Heater Bay | 620 | B/01 |
| 1N36N030C | 1H51P1330 | Heater Bay | 620 | B/01 |
| 1N26N153A | Heater 3A | Heater Bay | 647 | D/03 |
| 1N26N153B | Heater 3B | Heater Bay | 647 | D/04 |
| 1N21N339 | Heater 4 | Heater Bay | 580 | C/02 |

Heater Bay High Energy LinesElevation

| | |
|--|--------------------|
| N22 Main, reheat extraction & misc. drains | 580, 600, 620, 647 |
| N25 H.P. Htr. drain & vent | 580, 600, 620 |
| N27 Feedwater system | 580, 600, 620, 647 |
| N33 Steam seal system | 600, 620, 647 |
| N36 Extraction steam system | 600, 620, 647 |
| N11 Main steam system | 620, 647 |
| P61 Auxiliary steam system | 580, 600, 620, 647 |
| N21 Condensate system | 600, 620, 647 |

Refer to plant layout drawings, figures 1.2-4 and 1.2-5 of the FSAR, for the Heater Bay layout.

Note: A break in any of the above lines would not change the conclusions described in our March 14, 1983 letter (Q420.05/#2), which only addressed a feedwater line break in the Heater Bay.

ADVERSE CONDITION #3

| <u>INSTRUMENT</u> | <u>PANEL</u> | <u>BUILDING*</u> | <u>ELEVATION</u> | <u>COORDINATES</u> |
|-------------------|--------------|------------------|------------------|--------------------|
| | 1R25S002 | TP | 620 | A/04 |
| | 1R22S003 | TP | 620 | A/04 |
| | 1R23S003 | TP | 647 | B/05 |
| | 1R23S004 | TP | 647 | B/06 |
| | 1R23S006 | TP | 647 | B/06 |
| | 1R24S034 | TP | 620 | B/06 |
| | 1R42S017 | TP | 620 | C/06 |
| | 1R42S021 | TP | 620 | C/06 |
| | 1R42S022 | TP | 620 | C/06 |
| | 1R42S023 | TP | 620 | C/07 |
| | 1R14S008 | TP | 620 | B/06 |
| 1C85N001A | | TB | 593 | E/16 |
| 1C85N001B | | TB | 593 | E/16 |
| 1C85N002A | 1H51P187 | TB | 647 | G/08 |
| 1C85N002B | 1H51P187 | TB | 647 | G/08 |
| 1C85N002C | 1H51P773 | TB | 647 | G/08 |

* TP - Turbine Power Complex
TB - Turbine Building

High Energy Lines - No high energy lines are located within the 620 and 642 levels of the Turbine Power Complex. No further review was necessary to determine high energy lines in the vicinity of the C85 components. Refer to plant layout drawings, figures 1.2-5 and 1.2-6 of the FSAR.

ADVERSE CONDITION #4

Refer to Adverse Condition # 1.

ADVERSE CONDITION #5

| <u>INSTRUMENT</u> | <u>PANEL</u> | <u>BUILDING*</u> | <u>ELEVATION</u> | <u>COORDINATES</u> |
|-------------------|--------------|------------------|------------------|--------------------|
| | 1R11S004 | TP | 620 | B/04 |
| | 1R11S005 | TP | 620 | B/02 |
| | 1R14S008 | TP | 620 | B/06 |
| | 1R22S002 | TP | 620 | A/04 |
| | 1R22S003 | TP | 620 | A/04 |
| | 1R22S004 | TP | 647 | A/05 |
| | 1R22S005 | TP | 647 | A/04 |
| | 1R23S004 | TP | 647 | B/06 |
| | 1R23S006 | TP | 647 | B/06 |
| | 1R22S016 | TP | 620 | A/03 |
| | 1R23S017 | TP | 647 | A/05 |
| | 1R23S003 | TP | 647 | B/05 |
| | 1R24S034 | TP | 620 | B/06 |
| | 1R42S017 | TP | 620 | C/06 |
| | 1R42S021 | TP | 620 | C/06 |
| | 1R42S023 | TP | 620 | C/07 |
| 1C85N001A | | TB | 593 | E/16 |
| 1C85N001B | | TB | 593 | E/16 |
| 1C85N002A | 1H51P187 | TB | 647 | G/08 |
| 1C85N002B | 1H51P187 | TB | 647 | G/08 |
| 1C85N002C | 1H51P187 | TB | 647 | G/08 |

* TP - Turbine Power Complex
 TB - Turbine Building

High Energy Lines- No high energy lines are located within the 620 and 642 Levels of the Turbine Power Complex. No further review was necessary to determine high energy lines in the vicinity of the C85 components. Refer to plant layout drawings, figures 1.2-5 and 1.2-6 of The FSAR.

NOTE: An error was made in the feedwater pump section of Adverse Condition #5, "1R42S002" should be "1R22S002."

Q420.04

Provide a detailed analysis for the turbine trip without bypass event (FSAR Section 15.2.3) in conjunction with a high energy line break that causes a loss of feedwater heating (and subsequent increase in reactor power level). Without operator action, the staff is concerned that this event could lead to a turbine trip without bypass event from a higher power level than previously analyzed.

Response

A detailed review and walkdown of steam bypass and feedwater heating has determined that there is no single high energy line break (HELB) which could fail both systems. A high energy line break that would result in a loss of feedwater heating is an accident condition and is evaluated under 10 CFR 100 guidelines. Any HELB that could affect feedwater heating would be bounded by the Chapter 15 analysis for "Steam System Piping Break - Outside Containment" (FSAR Section 15.6.4). The radiological dose calculation for the event shows that its consequences are bounded by 10 CFR 100 limits (FSAR table 15.6-8).

The turbine trip without bypass transient has been analyzed under worst expected transient conditions (FSAR 15.2.3). This analysis is consistent with the requirements of SRP 15.2.2, including the requirements for initial reactor power level.

420.05

If used, provide the results of a zone analysis and a plant walkdown. If zone analysis was not used, describe the procedure by which the locations of non-safety related control system components affected by HELB's were determined.

Response

As stated in our March 14, 1983 letter (Question 420.05-approach), CEI identified all major components of systems which could significantly impact reactivity, reactor vessel level, reactor system pressure and decay heat removal. Once these non-safety related control system components were identified, locations were determined from plant layout drawings. Components were then assigned to their respective environmental zones. All equipment within a single zone would be assumed failed and the impact on system alignments was determined. The process was repeated for each environmental zone.

Potential system interactions were identified for further evaluation. A plant walkdown was then performed to determine the location of high energy lines with respect to potentially affected components.

The results of the plant walkdown plus engineering analysis then determined the consequences of each adverse condition. The results of the analysis are contained in the evaluation section, for each adverse condition, in our March 14, 1983 letter. Supplemental information is provided in our September 6, 1983 letter and also contained in this letter.

Q420.06

Verify that no credit was taken in the analysis for non-safety related equipment (e.g., feedwater trip on level 8) to mitigate the effects of the HELB and consequential control system failures.

Response

According to 15.0.1, "only safety grade equipment can be assumed to mitigate an accident and safely shut down the reactor." Our response to 420.04 is bounded by FSAR Chapter 15 accident analyses, which do not take credit for non-safety related equipment.

Q420.07

Verify that the consequences of the worst case event combinations considered in your analysis are bounded by a small fraction (<10%) of 10 CFR 100 guideline doses.

Response

Consequences of the scenario postulated in 420.04 are bounded by 10 CFR 100 limits. This is consistent with the SRP requirements for analysis of HELBs as defined in Branch Technical Position ASB 3-1 Section B.3.a.